

AnalysisDate	CountyCode	ZipCode	Cons_type	Deductible	LMs	LMapp	LMc	LMale	Structure_Loss_Cost	App_Loss_Cost	Contents_Loss_Cost	ALE_Loss_Cost
2007-Jun-21	1	32601	1	1000	100000	10000	50000	20000	0.000396	0.000232	0.000802	0.000178
2007-Jun-21	1	32602	1	1000	100000	10000	50000	20000	0.000442	0.000251	0.000858	0.000197
2007-Jun-21	1	32603	1	1000	100000	10000	50000	20000	0.000381	0.000225	0.000771	0.000172
2007-Jun-21	1	32604	1	1000	100000	10000	50000	20000	0.000418	0.000241	0.000828	0.000187
2007-Jun-21	1	32605	1	1000	100000	10000	50000	20000	0.000346	0.000207	0.000718	0.000156
2007-Jun-21	1	32606	1	1000	100000	10000	50000	20000	0.000335	0.000203	0.000698	0.000153
2007-Jun-21	1	32607	1	1000	100000	10000	50000	20000	0.000322	0.000195	0.000685	0.000145
2007-Jun-21	1	32608	1	1000	100000	10000	50000	20000	0.000376	0.000221	0.000768	0.000169
2007-Jun-21	1	32609	1	1000	100000	10000	50000	20000	0.000323	0.000199	0.000687	0.000148
2007-Jun-21	1	32610	1	1000	100000	10000	50000	20000	0.000397	0.000232	0.000802	0.000178
2007-Jun-21	1	32611	1	1000	100000	10000	50000	20000	0.000431	0.000247	0.000844	0.000193
2007-Jun-21	1	32612	1	1000	100000	10000	50000	20000	0.000371	0.000219	0.000760	0.000167
2007-Jun-21	1	32614	1	1000	100000	10000	50000	20000	0.000380	0.000224	0.000775	0.000171
2007-Jun-21	1	32615	1	1000	100000	10000	50000	20000	0.000372	0.000220	0.000746	0.000169
2007-Jun-21	1	32616	1	1000	100000	10000	50000	20000	0.000390	0.000228	0.000775	0.000176
2007-Jun-21	1	32618	1	1000	100000	10000	50000	20000	0.000313	0.000193	0.000668	0.000144
2007-Jun-21	1	32627	1	1000	100000	10000	50000	20000	0.000400	0.000234	0.000806	0.000180
2007-Jun-21	1	32631	1	1000	100000	10000	50000	20000	0.000307	0.000187	0.000663	0.000139
2007-Jun-21	1	32633	1	1000	100000	10000	50000	20000	0.000369	0.000220	0.000766	0.000166
2007-Jun-21	1	32635	1	1000	100000	10000	50000	20000	0.000405	0.000236	0.000805	0.000183
2007-Jun-21	1	32640	1	1000	100000	10000	50000	20000	0.000349	0.000211	0.000742	0.000157
2007-Jun-21	1	32641	1	1000	100000	10000	50000	20000	0.000311	0.000192	0.000676	0.000141
2007-Jun-21	1	32643	1	1000	100000	10000	50000	20000	0.000388	0.000224	0.000755	0.000175
2007-Jun-21	1	32653	1	1000	100000	10000	50000	20000	0.000405	0.000236	0.000806	0.000183
2007-Jun-21	1	32654	1	1000	100000	10000	50000	20000	0.000366	0.000220	0.000776	0.000164
2007-Jun-21	1	32655	1	1000	100000	10000	50000	20000	0.000386	0.000225	0.000762	0.000174
2007-Jun-21	1	32658	1	1000	100000	10000	50000	20000	0.000320	0.000195	0.000678	0.000146
2007-Jun-21	1	32662	1	1000	100000	10000	50000	20000	0.000335	0.000205	0.000730	0.000151
2007-Jun-21	1	32667	1	1000	100000	10000	50000	20000	0.000286	0.000182	0.000638	0.000132
2007-Jun-21	1	32669	1	1000	100000	10000	50000	20000	0.000441	0.000251	0.000843	0.000198
2007-Jun-21	1	32694	1	1000	100000	10000	50000	20000	0.000349	0.000208	0.000725	0.000157
2007-Jun-21	1	32601	2	1000	100000	10000	50000	20000	0.000353	0.000225	0.000801	0.000172
2007-Jun-21	1	32602	2	1000	100000	10000	50000	20000	0.000392	0.000242	0.000856	0.000190
2007-Jun-21	1	32603	2	1000	100000	10000	50000	20000	0.000339	0.000218	0.000770	0.000167
2007-Jun-21	1	32604	2	1000	100000	10000	50000	20000	0.000371	0.000233	0.000827	0.000181
2007-Jun-21	1	32605	2	1000	100000	10000	50000	20000	0.000309	0.000201	0.000717	0.000152

2007-Jun-21	1	32606	2	1000	100000	10000	50000	20000	0.000299	0.000198	0.000697	0.000149
2007-Jun-21	1	32607	2	1000	100000	10000	50000	20000	0.000288	0.000190	0.000684	0.000142
2007-Jun-21	1	32608	2	1000	100000	10000	50000	20000	0.000335	0.000215	0.000766	0.000164
2007-Jun-21	1	32609	2	1000	100000	10000	50000	20000	0.000290	0.000194	0.000686	0.000144
2007-Jun-21	1	32610	2	1000	100000	10000	50000	20000	0.000354	0.000225	0.000801	0.000172
2007-Jun-21	1	32611	2	1000	100000	10000	50000	20000	0.000382	0.000239	0.000842	0.000186
2007-Jun-21	1	32612	2	1000	100000	10000	50000	20000	0.000330	0.000212	0.000759	0.000161
2007-Jun-21	1	32614	2	1000	100000	10000	50000	20000	0.000339	0.000217	0.000774	0.000165
2007-Jun-21	1	32615	2	1000	100000	10000	50000	20000	0.000331	0.000213	0.000745	0.000164
2007-Jun-21	1	32616	2	1000	100000	10000	50000	20000	0.000347	0.000221	0.000774	0.000170
2007-Jun-21	1	32618	2	1000	100000	10000	50000	20000	0.000281	0.000189	0.000667	0.000140
2007-Jun-21	1	32627	2	1000	100000	10000	50000	20000	0.000356	0.000226	0.000805	0.000174
2007-Jun-21	1	32631	2	1000	100000	10000	50000	20000	0.000275	0.000183	0.000662	0.000135
2007-Jun-21	1	32633	2	1000	100000	10000	50000	20000	0.000329	0.000214	0.000765	0.000161
2007-Jun-21	1	32635	2	1000	100000	10000	50000	20000	0.000360	0.000228	0.000804	0.000176
2007-Jun-21	1	32640	2	1000	100000	10000	50000	20000	0.000313	0.000206	0.000741	0.000153
2007-Jun-21	1	32641	2	1000	100000	10000	50000	20000	0.000279	0.000187	0.000675	0.000138
2007-Jun-21	1	32643	2	1000	100000	10000	50000	20000	0.000344	0.000216	0.000754	0.000169
2007-Jun-21	1	32653	2	1000	100000	10000	50000	20000	0.000360	0.000228	0.000804	0.000176
2007-Jun-21	1	32654	2	1000	100000	10000	50000	20000	0.000327	0.000215	0.000775	0.000160
2007-Jun-21	1	32655	2	1000	100000	10000	50000	20000	0.000343	0.000217	0.000761	0.000168
2007-Jun-21	1	32658	2	1000	100000	10000	50000	20000	0.000286	0.000190	0.000677	0.000142
2007-Jun-21	1	32662	2	1000	100000	10000	50000	20000	0.000301	0.000201	0.000729	0.000148
2007-Jun-21	1	32667	2	1000	100000	10000	50000	20000	0.000258	0.000179	0.000637	0.000130
2007-Jun-21	1	32669	2	1000	100000	10000	50000	20000	0.000391	0.000241	0.000841	0.000190
2007-Jun-21	1	32694	2	1000	100000	10000	50000	20000	0.000312	0.000202	0.000724	0.000153
2007-Jun-21	1	32601	3	1000	100000	10000	50000	20000	0.003437	0.001114	0.000823	0.001084
2007-Jun-21	1	32602	3	1000	100000	10000	50000	20000	0.003885	0.001322	0.000880	0.001300
2007-Jun-21	1	32603	3	1000	100000	10000	50000	20000	0.003264	0.001047	0.000791	0.001015
2007-Jun-21	1	32604	3	1000	100000	10000	50000	20000	0.003620	0.001191	0.000850	0.001164
2007-Jun-21	1	32605	3	1000	100000	10000	50000	20000	0.002973	0.000934	0.000737	0.000902
2007-Jun-21	1	32606	3	1000	100000	10000	50000	20000	0.002804	0.000872	0.000715	0.000833
2007-Jun-21	1	32607	3	1000	100000	10000	50000	20000	0.002769	0.000858	0.000702	0.000824
2007-Jun-21	1	32608	3	1000	100000	10000	50000	20000	0.003270	0.001055	0.000788	0.001025
2007-Jun-21	1	32609	3	1000	100000	10000	50000	20000	0.002672	0.000795	0.000705	0.000752
2007-Jun-21	1	32610	3	1000	100000	10000	50000	20000	0.003437	0.001111	0.000823	0.001081
2007-Jun-21	1	32611	3	1000	100000	10000	50000	20000	0.003745	0.001245	0.000866	0.001220

2007-Jun-21	1	32612	3	1000	100000	10000	50000	20000	0.003207	0.001032	0.000780	0.001002
2007-Jun-21	1	32614	3	1000	100000	10000	50000	20000	0.003268	0.001042	0.000795	0.001011
2007-Jun-21	1	32615	3	1000	100000	10000	50000	20000	0.003132	0.001011	0.000765	0.000976
2007-Jun-21	1	32616	3	1000	100000	10000	50000	20000	0.003323	0.001088	0.000795	0.001057
2007-Jun-21	1	32618	3	1000	100000	10000	50000	20000	0.002601	0.000786	0.000685	0.000744
2007-Jun-21	1	32627	3	1000	100000	10000	50000	20000	0.003454	0.001113	0.000827	0.001083
2007-Jun-21	1	32631	3	1000	100000	10000	50000	20000	0.002629	0.000800	0.000679	0.000765
2007-Jun-21	1	32633	3	1000	100000	10000	50000	20000	0.003166	0.001004	0.000785	0.000969
2007-Jun-21	1	32635	3	1000	100000	10000	50000	20000	0.003493	0.001141	0.000826	0.001112
2007-Jun-21	1	32640	3	1000	100000	10000	50000	20000	0.002993	0.000917	0.000761	0.000882
2007-Jun-21	1	32641	3	1000	100000	10000	50000	20000	0.002649	0.000792	0.000693	0.000754
2007-Jun-21	1	32643	3	1000	100000	10000	50000	20000	0.003325	0.001121	0.000775	0.001095
2007-Jun-21	1	32653	3	1000	100000	10000	50000	20000	0.003504	0.001156	0.000826	0.001127
2007-Jun-21	1	32654	3	1000	100000	10000	50000	20000	0.003131	0.000950	0.000796	0.000915
2007-Jun-21	1	32655	3	1000	100000	10000	50000	20000	0.003296	0.001093	0.000782	0.001063
2007-Jun-21	1	32658	3	1000	100000	10000	50000	20000	0.002721	0.000847	0.000695	0.000811
2007-Jun-21	1	32662	3	1000	100000	10000	50000	20000	0.002866	0.000849	0.000748	0.000810
2007-Jun-21	1	32667	3	1000	100000	10000	50000	20000	0.002346	0.000676	0.000653	0.000629
2007-Jun-21	1	32669	3	1000	100000	10000	50000	20000	0.003801	0.001290	0.000865	0.001265
2007-Jun-21	1	32694	3	1000	100000	10000	50000	20000	0.003019	0.000962	0.000744	0.000931
2007-Jun-21	3	32040	1	1000	100000	10000	50000	20000	0.000261	0.000164	0.000579	0.000120
2007-Jun-21	3	32063	1	1000	100000	10000	50000	20000	0.000279	0.000173	0.000612	0.000127
2007-Jun-21	3	32072	1	1000	100000	10000	50000	20000	0.000227	0.000147	0.000519	0.000105
2007-Jun-21	3	32087	1	1000	100000	10000	50000	20000	0.000148	0.000105	0.000370	0.000071
2007-Jun-21	3	32040	2	1000	100000	10000	50000	20000	0.000235	0.000161	0.000578	0.000117
2007-Jun-21	3	32063	2	1000	100000	10000	50000	20000	0.000251	0.000169	0.000611	0.000124
2007-Jun-21	3	32072	2	1000	100000	10000	50000	20000	0.000205	0.000144	0.000518	0.000103
2007-Jun-21	3	32087	2	1000	100000	10000	50000	20000	0.000135	0.000104	0.000370	0.000071
2007-Jun-21	3	32040	3	1000	100000	10000	50000	20000	0.002200	0.000655	0.000594	0.000619
2007-Jun-21	3	32063	3	1000	100000	10000	50000	20000	0.002372	0.000709	0.000628	0.000673
2007-Jun-21	3	32072	3	1000	100000	10000	50000	20000	0.001860	0.000532	0.000532	0.000493
2007-Jun-21	3	32087	3	1000	100000	10000	50000	20000	0.001135	0.000287	0.000379	0.000246
2007-Jun-21	5	32401	1	1000	100000	10000	50000	20000	0.001038	0.000531	0.001395	0.000489
2007-Jun-21	5	32402	1	1000	100000	10000	50000	20000	0.001011	0.000517	0.001376	0.000474
2007-Jun-21	5	32403	1	1000	100000	10000	50000	20000	0.001225	0.000624	0.001511	0.000586
2007-Jun-21	5	32404	1	1000	100000	10000	50000	20000	0.000784	0.000410	0.001191	0.000361
2007-Jun-21	5	32405	1	1000	100000	10000	50000	20000	0.001042	0.000532	0.001407	0.000489

2007-Jun-21	5	32406	1	1000	100000	10000	50000	20000	0.001092	0.000558	0.001427	0.000517
2007-Jun-21	5	32407	1	1000	100000	10000	50000	20000	0.001138	0.000576	0.001479	0.000536
2007-Jun-21	5	32408	1	1000	100000	10000	50000	20000	0.001679	0.000855	0.001754	0.000831
2007-Jun-21	5	32409	1	1000	100000	10000	50000	20000	0.000432	0.000249	0.000858	0.000195
2007-Jun-21	5	32410	1	1000	100000	10000	50000	20000	0.001425	0.000727	0.001615	0.000695
2007-Jun-21	5	32411	1	1000	100000	10000	50000	20000	0.001400	0.000705	0.001641	0.000673
2007-Jun-21	5	32412	1	1000	100000	10000	50000	20000	0.001011	0.000517	0.001376	0.000474
2007-Jun-21	5	32413	1	1000	100000	10000	50000	20000	0.001263	0.000637	0.001555	0.000602
2007-Jun-21	5	32417	1	1000	100000	10000	50000	20000	0.001288	0.000649	0.001557	0.000616
2007-Jun-21	5	32438	1	1000	100000	10000	50000	20000	0.000585	0.000315	0.001034	0.000263
2007-Jun-21	5	32444	1	1000	100000	10000	50000	20000	0.001069	0.000544	0.001422	0.000503
2007-Jun-21	5	32466	1	1000	100000	10000	50000	20000	0.000718	0.000376	0.001134	0.000328
2007-Jun-21	5	32401	2	1000	100000	10000	50000	20000	0.000898	0.000485	0.001393	0.000447
2007-Jun-21	5	32402	2	1000	100000	10000	50000	20000	0.000875	0.000473	0.001373	0.000434
2007-Jun-21	5	32403	2	1000	100000	10000	50000	20000	0.001054	0.000561	0.001508	0.000530
2007-Jun-21	5	32404	2	1000	100000	10000	50000	20000	0.000683	0.000382	0.001189	0.000336
2007-Jun-21	5	32405	2	1000	100000	10000	50000	20000	0.000901	0.000486	0.001404	0.000448
2007-Jun-21	5	32406	2	1000	100000	10000	50000	20000	0.000943	0.000507	0.001424	0.000471
2007-Jun-21	5	32407	2	1000	100000	10000	50000	20000	0.000983	0.000524	0.001476	0.000490
2007-Jun-21	5	32408	2	1000	100000	10000	50000	20000	0.001434	0.000749	0.001750	0.000737
2007-Jun-21	5	32409	2	1000	100000	10000	50000	20000	0.000384	0.000241	0.000856	0.000188
2007-Jun-21	5	32410	2	1000	100000	10000	50000	20000	0.001222	0.000644	0.001612	0.000621
2007-Jun-21	5	32411	2	1000	100000	10000	50000	20000	0.001202	0.000630	0.001637	0.000606
2007-Jun-21	5	32412	2	1000	100000	10000	50000	20000	0.000875	0.000473	0.001373	0.000434
2007-Jun-21	5	32413	2	1000	100000	10000	50000	20000	0.001087	0.000574	0.001551	0.000545
2007-Jun-21	5	32417	2	1000	100000	10000	50000	20000	0.001109	0.000585	0.001553	0.000558
2007-Jun-21	5	32438	2	1000	100000	10000	50000	20000	0.000514	0.000300	0.001032	0.000249
2007-Jun-21	5	32444	2	1000	100000	10000	50000	20000	0.000924	0.000496	0.001419	0.000460
2007-Jun-21	5	32466	2	1000	100000	10000	50000	20000	0.000627	0.000353	0.001132	0.000308
2007-Jun-21	5	32401	3	1000	100000	10000	50000	20000	0.008276	0.003515	0.001432	0.003540
2007-Jun-21	5	32402	3	1000	100000	10000	50000	20000	0.008121	0.003427	0.001413	0.003453
2007-Jun-21	5	32403	3	1000	100000	10000	50000	20000	0.009430	0.004150	0.001550	0.004184
2007-Jun-21	5	32404	3	1000	100000	10000	50000	20000	0.006475	0.002580	0.001222	0.002590
2007-Jun-21	5	32405	3	1000	100000	10000	50000	20000	0.008358	0.003547	0.001444	0.003575
2007-Jun-21	5	32406	3	1000	100000	10000	50000	20000	0.008578	0.003688	0.001464	0.003714
2007-Jun-21	5	32407	3	1000	100000	10000	50000	20000	0.009030	0.003911	0.001518	0.003944
2007-Jun-21	5	32408	3	1000	100000	10000	50000	20000	0.012000	0.005658	0.001799	0.005693

2007-Jun-21	5	32409	3	1000	100000	10000	50000	20000	0.003755	0.001242	0.000880	0.001223
2007-Jun-21	5	32410	3	1000	100000	10000	50000	20000	0.010556	0.004819	0.001657	0.004855
2007-Jun-21	5	32411	3	1000	100000	10000	50000	20000	0.010664	0.004828	0.001683	0.004871
2007-Jun-21	5	32412	3	1000	100000	10000	50000	20000	0.008121	0.003427	0.001413	0.003453
2007-Jun-21	5	32413	3	1000	100000	10000	50000	20000	0.009832	0.004389	0.001595	0.004429
2007-Jun-21	5	32417	3	1000	100000	10000	50000	20000	0.009899	0.004436	0.001597	0.004471
2007-Jun-21	5	32438	3	1000	100000	10000	50000	20000	0.005116	0.001868	0.001061	0.001871
2007-Jun-21	5	32444	3	1000	100000	10000	50000	20000	0.008543	0.003660	0.001459	0.003689
2007-Jun-21	5	32466	3	1000	100000	10000	50000	20000	0.006060	0.002378	0.001164	0.002388
2007-Jun-21	7	32042	1	1000	100000	10000	50000	20000	0.000343	0.000207	0.000725	0.000155
2007-Jun-21	7	32044	1	1000	100000	10000	50000	20000	0.000321	0.000195	0.000685	0.000145
2007-Jun-21	7	32058	1	1000	100000	10000	50000	20000	0.000285	0.000179	0.000630	0.000130
2007-Jun-21	7	32091	1	1000	100000	10000	50000	20000	0.000288	0.000181	0.000639	0.000132
2007-Jun-21	7	32622	1	1000	100000	10000	50000	20000	0.000394	0.000230	0.000784	0.000178
2007-Jun-21	7	32042	2	1000	100000	10000	50000	20000	0.000307	0.000202	0.000724	0.000151
2007-Jun-21	7	32044	2	1000	100000	10000	50000	20000	0.000287	0.000191	0.000684	0.000142
2007-Jun-21	7	32058	2	1000	100000	10000	50000	20000	0.000256	0.000175	0.000629	0.000128
2007-Jun-21	7	32091	2	1000	100000	10000	50000	20000	0.000259	0.000177	0.000638	0.000129
2007-Jun-21	7	32622	2	1000	100000	10000	50000	20000	0.000351	0.000223	0.000783	0.000172
2007-Jun-21	7	32042	3	1000	100000	10000	50000	20000	0.002936	0.000914	0.000743	0.000879
2007-Jun-21	7	32044	3	1000	100000	10000	50000	20000	0.002727	0.000841	0.000702	0.000804
2007-Jun-21	7	32058	3	1000	100000	10000	50000	20000	0.002383	0.000703	0.000646	0.000662
2007-Jun-21	7	32091	3	1000	100000	10000	50000	20000	0.002404	0.000702	0.000655	0.000661
2007-Jun-21	7	32622	3	1000	100000	10000	50000	20000	0.003372	0.001103	0.000804	0.001071
2007-Jun-21	9	32754	1	1000	100000	10000	50000	20000	0.002552	0.000505	0.001279	0.000402
2007-Jun-21	9	32775	1	1000	100000	10000	50000	20000	0.002449	0.000478	0.001233	0.000378
2007-Jun-21	9	32780	1	1000	100000	10000	50000	20000	0.002405	0.000483	0.001203	0.000384
2007-Jun-21	9	32781	1	1000	100000	10000	50000	20000	0.003238	0.000874	0.001484	0.000760
2007-Jun-21	9	32782	1	1000	100000	10000	50000	20000	0.003642	0.000954	0.001705	0.000838
2007-Jun-21	9	32783	1	1000	100000	10000	50000	20000	0.002327	0.000474	0.001159	0.000378
2007-Jun-21	9	32796	1	1000	100000	10000	50000	20000	0.002567	0.000532	0.001277	0.000430
2007-Jun-21	9	32815	1	1000	100000	10000	50000	20000	0.002298	0.000486	0.001136	0.000393
2007-Jun-21	9	32899	1	1000	100000	10000	50000	20000	0.002552	0.000551	0.001255	0.000453
2007-Jun-21	9	32901	1	1000	100000	10000	50000	20000	0.002837	0.000608	0.001405	0.000505
2007-Jun-21	9	32902	1	1000	100000	10000	50000	20000	0.002813	0.000587	0.001403	0.000483
2007-Jun-21	9	32903	1	1000	100000	10000	50000	20000	0.003040	0.000687	0.001487	0.000583
2007-Jun-21	9	32904	1	1000	100000	10000	50000	20000	0.002684	0.000550	0.001342	0.000447

2007-Jun-21	9	32905	1	1000	100000	10000	50000	20000	0.002848	0.000607	0.001414	0.000503
2007-Jun-21	9	32906	1	1000	100000	10000	50000	20000	0.002806	0.000587	0.001398	0.000482
2007-Jun-21	9	32907	1	1000	100000	10000	50000	20000	0.002945	0.000576	0.001427	0.000468
2007-Jun-21	9	32908	1	1000	100000	10000	50000	20000	0.002805	0.000534	0.001366	0.000428
2007-Jun-21	9	32909	1	1000	100000	10000	50000	20000	0.002860	0.000587	0.001430	0.000480
2007-Jun-21	9	32910	1	1000	100000	10000	50000	20000	0.002691	0.000544	0.001351	0.000440
2007-Jun-21	9	32911	1	1000	100000	10000	50000	20000	0.002728	0.000573	0.001358	0.000470
2007-Jun-21	9	32912	1	1000	100000	10000	50000	20000	0.002619	0.000518	0.001318	0.000415
2007-Jun-21	9	32919	1	1000	100000	10000	50000	20000	0.002580	0.000542	0.001287	0.000443
2007-Jun-21	9	32920	1	1000	100000	10000	50000	20000	0.003267	0.000812	0.001555	0.000703
2007-Jun-21	9	32922	1	1000	100000	10000	50000	20000	0.002635	0.000531	0.001322	0.000430
2007-Jun-21	9	32923	1	1000	100000	10000	50000	20000	0.002617	0.000551	0.001298	0.000452
2007-Jun-21	9	32924	1	1000	100000	10000	50000	20000	0.002439	0.000481	0.001229	0.000383
2007-Jun-21	9	32925	1	1000	100000	10000	50000	20000	0.005333	0.001898	0.002186	0.001727
2007-Jun-21	9	32926	1	1000	100000	10000	50000	20000	0.002171	0.000433	0.001094	0.000342
2007-Jun-21	9	32927	1	1000	100000	10000	50000	20000	0.002432	0.000484	0.001221	0.000386
2007-Jun-21	9	32931	1	1000	100000	10000	50000	20000	0.002869	0.000644	0.001405	0.000543
2007-Jun-21	9	32932	1	1000	100000	10000	50000	20000	0.002981	0.000672	0.001460	0.000569
2007-Jun-21	9	32934	1	1000	100000	10000	50000	20000	0.002697	0.000555	0.001348	0.000453
2007-Jun-21	9	32935	1	1000	100000	10000	50000	20000	0.002670	0.000558	0.001331	0.000457
2007-Jun-21	9	32936	1	1000	100000	10000	50000	20000	0.003482	0.000918	0.001629	0.000806
2007-Jun-21	9	32937	1	1000	100000	10000	50000	20000	0.002723	0.000583	0.001350	0.000482
2007-Jun-21	9	32940	1	1000	100000	10000	50000	20000	0.002836	0.000618	0.001403	0.000515
2007-Jun-21	9	32941	1	1000	100000	10000	50000	20000	0.002557	0.000513	0.001285	0.000412
2007-Jun-21	9	32949	1	1000	100000	10000	50000	20000	0.003034	0.000681	0.001489	0.000575
2007-Jun-21	9	32950	1	1000	100000	10000	50000	20000	0.002965	0.000653	0.001462	0.000548
2007-Jun-21	9	32951	1	1000	100000	10000	50000	20000	0.004915	0.001410	0.002283	0.001287
2007-Jun-21	9	32952	1	1000	100000	10000	50000	20000	0.003573	0.000869	0.001720	0.000759
2007-Jun-21	9	32953	1	1000	100000	10000	50000	20000	0.002572	0.000513	0.001293	0.000412
2007-Jun-21	9	32954	1	1000	100000	10000	50000	20000	0.002580	0.000528	0.001293	0.000428
2007-Jun-21	9	32955	1	1000	100000	10000	50000	20000	0.002749	0.000538	0.001333	0.000435
2007-Jun-21	9	32956	1	1000	100000	10000	50000	20000	0.002677	0.000553	0.001341	0.000452
2007-Jun-21	9	32959	1	1000	100000	10000	50000	20000	0.002955	0.000662	0.001443	0.000558
2007-Jun-21	9	32976	1	1000	100000	10000	50000	20000	0.003329	0.000787	0.001609	0.000677
2007-Jun-21	9	32754	2	1000	100000	10000	50000	20000	0.002134	0.000427	0.001276	0.000328
2007-Jun-21	9	32775	2	1000	100000	10000	50000	20000	0.002050	0.000407	0.001230	0.000309
2007-Jun-21	9	32780	2	1000	100000	10000	50000	20000	0.002012	0.000408	0.001201	0.000312

2007-Jun-21	9	32781	2	1000	100000	10000	50000	20000	0.002643	0.000676	0.001480	0.000581
2007-Jun-21	9	32782	2	1000	100000	10000	50000	20000	0.002968	0.000738	0.001700	0.000640
2007-Jun-21	9	32783	2	1000	100000	10000	50000	20000	0.001944	0.000400	0.001156	0.000307
2007-Jun-21	9	32796	2	1000	100000	10000	50000	20000	0.002140	0.000444	0.001274	0.000347
2007-Jun-21	9	32815	2	1000	100000	10000	50000	20000	0.001914	0.000405	0.001134	0.000316
2007-Jun-21	9	32899	2	1000	100000	10000	50000	20000	0.002120	0.000454	0.001252	0.000362
2007-Jun-21	9	32901	2	1000	100000	10000	50000	20000	0.002352	0.000500	0.001402	0.000401
2007-Jun-21	9	32902	2	1000	100000	10000	50000	20000	0.002337	0.000487	0.001399	0.000387
2007-Jun-21	9	32903	2	1000	100000	10000	50000	20000	0.002508	0.000555	0.001483	0.000457
2007-Jun-21	9	32904	2	1000	100000	10000	50000	20000	0.002236	0.000460	0.001338	0.000360
2007-Jun-21	9	32905	2	1000	100000	10000	50000	20000	0.002362	0.000500	0.001410	0.000400
2007-Jun-21	9	32906	2	1000	100000	10000	50000	20000	0.002332	0.000486	0.001395	0.000386
2007-Jun-21	9	32907	2	1000	100000	10000	50000	20000	0.002446	0.000483	0.001423	0.000378
2007-Jun-21	9	32908	2	1000	100000	10000	50000	20000	0.002336	0.000453	0.001362	0.000348
2007-Jun-21	9	32909	2	1000	100000	10000	50000	20000	0.002380	0.000489	0.001427	0.000385
2007-Jun-21	9	32910	2	1000	100000	10000	50000	20000	0.002243	0.000456	0.001348	0.000355
2007-Jun-21	9	32911	2	1000	100000	10000	50000	20000	0.002267	0.000475	0.001355	0.000376
2007-Jun-21	9	32912	2	1000	100000	10000	50000	20000	0.002188	0.000438	0.001315	0.000337
2007-Jun-21	9	32919	2	1000	100000	10000	50000	20000	0.002145	0.000450	0.001283	0.000355
2007-Jun-21	9	32920	2	1000	100000	10000	50000	20000	0.002676	0.000639	0.001550	0.000543
2007-Jun-21	9	32922	2	1000	100000	10000	50000	20000	0.002197	0.000446	0.001319	0.000347
2007-Jun-21	9	32923	2	1000	100000	10000	50000	20000	0.002175	0.000457	0.001295	0.000362
2007-Jun-21	9	32924	2	1000	100000	10000	50000	20000	0.002039	0.000408	0.001226	0.000312
2007-Jun-21	9	32925	2	1000	100000	10000	50000	20000	0.004241	0.001381	0.002180	0.001270
2007-Jun-21	9	32926	2	1000	100000	10000	50000	20000	0.001816	0.000368	0.001091	0.000280
2007-Jun-21	9	32927	2	1000	100000	10000	50000	20000	0.002034	0.000410	0.001218	0.000314
2007-Jun-21	9	32931	2	1000	100000	10000	50000	20000	0.002370	0.000522	0.001401	0.000428
2007-Jun-21	9	32932	2	1000	100000	10000	50000	20000	0.002460	0.000544	0.001456	0.000447
2007-Jun-21	9	32934	2	1000	100000	10000	50000	20000	0.002245	0.000463	0.001344	0.000364
2007-Jun-21	9	32935	2	1000	100000	10000	50000	20000	0.002220	0.000464	0.001328	0.000366
2007-Jun-21	9	32936	2	1000	100000	10000	50000	20000	0.002836	0.000712	0.001624	0.000617
2007-Jun-21	9	32937	2	1000	100000	10000	50000	20000	0.002259	0.000480	0.001347	0.000384
2007-Jun-21	9	32940	2	1000	100000	10000	50000	20000	0.002349	0.000506	0.001399	0.000408
2007-Jun-21	9	32941	2	1000	100000	10000	50000	20000	0.002134	0.000432	0.001282	0.000334
2007-Jun-21	9	32949	2	1000	100000	10000	50000	20000	0.002504	0.000552	0.001486	0.000453
2007-Jun-21	9	32950	2	1000	100000	10000	50000	20000	0.002452	0.000533	0.001459	0.000433
2007-Jun-21	9	32951	2	1000	100000	10000	50000	20000	0.003945	0.001062	0.002276	0.000965

2007-Jun-21	9	32952	2	1000	100000	10000	50000	20000	0.002923	0.000685	0.001715	0.000586
2007-Jun-21	9	32953	2	1000	100000	10000	50000	20000	0.002147	0.000433	0.001290	0.000334
2007-Jun-21	9	32954	2	1000	100000	10000	50000	20000	0.002150	0.000442	0.001290	0.000345
2007-Jun-21	9	32955	2	1000	100000	10000	50000	20000	0.002284	0.000451	0.001329	0.000352
2007-Jun-21	9	32956	2	1000	100000	10000	50000	20000	0.002227	0.000460	0.001337	0.000363
2007-Jun-21	9	32959	2	1000	100000	10000	50000	20000	0.002442	0.000537	0.001440	0.000439
2007-Jun-21	9	32976	2	1000	100000	10000	50000	20000	0.002734	0.000627	0.001605	0.000527
2007-Jun-21	9	32754	3	1000	100000	10000	50000	20000	0.010902	0.003698	0.001298	0.003816
2007-Jun-21	9	32775	3	1000	100000	10000	50000	20000	0.010430	0.003494	0.001252	0.003606
2007-Jun-21	9	32780	3	1000	100000	10000	50000	20000	0.010143	0.003409	0.001221	0.003503
2007-Jun-21	9	32781	3	1000	100000	10000	50000	20000	0.014140	0.005860	0.001505	0.005971
2007-Jun-21	9	32782	3	1000	100000	10000	50000	20000	0.016657	0.007039	0.001729	0.007231
2007-Jun-21	9	32783	3	1000	100000	10000	50000	20000	0.009770	0.003301	0.001176	0.003383
2007-Jun-21	9	32796	3	1000	100000	10000	50000	20000	0.011013	0.003845	0.001296	0.003956
2007-Jun-21	9	32815	3	1000	100000	10000	50000	20000	0.009712	0.003381	0.001153	0.003458
2007-Jun-21	9	32899	3	1000	100000	10000	50000	20000	0.011010	0.003969	0.001274	0.004074
2007-Jun-21	9	32901	3	1000	100000	10000	50000	20000	0.012558	0.004638	0.001426	0.004781
2007-Jun-21	9	32902	3	1000	100000	10000	50000	20000	0.012437	0.004521	0.001423	0.004665
2007-Jun-21	9	32903	3	1000	100000	10000	50000	20000	0.013679	0.005281	0.001508	0.005441
2007-Jun-21	9	32904	3	1000	100000	10000	50000	20000	0.011670	0.004119	0.001361	0.004248
2007-Jun-21	9	32905	3	1000	100000	10000	50000	20000	0.012610	0.004640	0.001435	0.004784
2007-Jun-21	9	32906	3	1000	100000	10000	50000	20000	0.012356	0.004473	0.001419	0.004616
2007-Jun-21	9	32907	3	1000	100000	10000	50000	20000	0.012492	0.004429	0.001447	0.004584
2007-Jun-21	9	32908	3	1000	100000	10000	50000	20000	0.011732	0.004034	0.001385	0.004175
2007-Jun-21	9	32909	3	1000	100000	10000	50000	20000	0.012592	0.004510	0.001451	0.004664
2007-Jun-21	9	32910	3	1000	100000	10000	50000	20000	0.011741	0.004130	0.001371	0.004265
2007-Jun-21	9	32911	3	1000	100000	10000	50000	20000	0.011958	0.004318	0.001378	0.004449
2007-Jun-21	9	32912	3	1000	100000	10000	50000	20000	0.011302	0.003878	0.001338	0.004006
2007-Jun-21	9	32919	3	1000	100000	10000	50000	20000	0.011254	0.004043	0.001305	0.004156
2007-Jun-21	9	32920	3	1000	100000	10000	50000	20000	0.014765	0.006007	0.001577	0.006170
2007-Jun-21	9	32922	3	1000	100000	10000	50000	20000	0.011475	0.004025	0.001342	0.004157
2007-Jun-21	9	32923	3	1000	100000	10000	50000	20000	0.011401	0.004104	0.001317	0.004223
2007-Jun-21	9	32924	3	1000	100000	10000	50000	20000	0.010431	0.003537	0.001247	0.003645
2007-Jun-21	9	32925	3	1000	100000	10000	50000	20000	0.023712	0.011662	0.002215	0.011819
2007-Jun-21	9	32926	3	1000	100000	10000	50000	20000	0.009129	0.003051	0.001110	0.003124
2007-Jun-21	9	32927	3	1000	100000	10000	50000	20000	0.010332	0.003492	0.001239	0.003593
2007-Jun-21	9	32931	3	1000	100000	10000	50000	20000	0.012798	0.004883	0.001425	0.005025

2007-Jun-21	9	32932	3	1000	100000	10000	50000	20000	0.013370	0.005132	0.001481	0.005289
2007-Jun-21	9	32934	3	1000	100000	10000	50000	20000	0.011789	0.004198	0.001367	0.004331
2007-Jun-21	9	32935	3	1000	100000	10000	50000	20000	0.011681	0.004198	0.001351	0.004324
2007-Jun-21	9	32936	3	1000	100000	10000	50000	20000	0.015827	0.006688	0.001651	0.006843
2007-Jun-21	9	32937	3	1000	100000	10000	50000	20000	0.012000	0.004404	0.001370	0.004535
2007-Jun-21	9	32940	3	1000	100000	10000	50000	20000	0.012578	0.004685	0.001423	0.004827
2007-Jun-21	9	32941	3	1000	100000	10000	50000	20000	0.011049	0.003827	0.001304	0.003944
2007-Jun-21	9	32949	3	1000	100000	10000	50000	20000	0.013604	0.005217	0.001511	0.005367
2007-Jun-21	9	32950	3	1000	100000	10000	50000	20000	0.013250	0.005010	0.001483	0.005161
2007-Jun-21	9	32951	3	1000	100000	10000	50000	20000	0.024133	0.011224	0.002314	0.011541
2007-Jun-21	9	32952	3	1000	100000	10000	50000	20000	0.016586	0.006832	0.001745	0.007046
2007-Jun-21	9	32953	3	1000	100000	10000	50000	20000	0.011120	0.003841	0.001312	0.003965
2007-Jun-21	9	32954	3	1000	100000	10000	50000	20000	0.011216	0.003953	0.001312	0.004074
2007-Jun-21	9	32955	3	1000	100000	10000	50000	20000	0.011577	0.004073	0.001352	0.004207
2007-Jun-21	9	32956	3	1000	100000	10000	50000	20000	0.011756	0.004211	0.001360	0.004346
2007-Jun-21	9	32959	3	1000	100000	10000	50000	20000	0.013127	0.004981	0.001464	0.005129
2007-Jun-21	9	32976	3	1000	100000	10000	50000	20000	0.015143	0.006050	0.001632	0.006224
2007-Jun-21	11	33004	1	1000	100000	10000	50000	20000	0.006232	0.001980	0.002158	0.001875
2007-Jun-21	11	33008	1	1000	100000	10000	50000	20000	0.006023	0.001885	0.002100	0.001781
2007-Jun-21	11	33009	1	1000	100000	10000	50000	20000	0.006311	0.002061	0.002158	0.001950
2007-Jun-21	11	33019	1	1000	100000	10000	50000	20000	0.007989	0.002921	0.002592	0.002781
2007-Jun-21	11	33020	1	1000	100000	10000	50000	20000	0.005903	0.001840	0.002061	0.001737
2007-Jun-21	11	33021	1	1000	100000	10000	50000	20000	0.005949	0.001843	0.002077	0.001741
2007-Jun-21	11	33022	1	1000	100000	10000	50000	20000	0.006232	0.002030	0.002131	0.001922
2007-Jun-21	11	33023	1	1000	100000	10000	50000	20000	0.005956	0.001831	0.002086	0.001728
2007-Jun-21	11	33024	1	1000	100000	10000	50000	20000	0.005896	0.001800	0.002070	0.001699
2007-Jun-21	11	33025	1	1000	100000	10000	50000	20000	0.006054	0.001859	0.002122	0.001758
2007-Jun-21	11	33026	1	1000	100000	10000	50000	20000	0.006254	0.001946	0.002180	0.001841
2007-Jun-21	11	33027	1	1000	100000	10000	50000	20000	0.006373	0.002006	0.002211	0.001901
2007-Jun-21	11	33028	1	1000	100000	10000	50000	20000	0.005917	0.001765	0.002101	0.001667
2007-Jun-21	11	33029	1	1000	100000	10000	50000	20000	0.006139	0.001833	0.002185	0.001737
2007-Jun-21	11	33060	1	1000	100000	10000	50000	20000	0.005406	0.001602	0.001919	0.001496
2007-Jun-21	11	33061	1	1000	100000	10000	50000	20000	0.005705	0.001746	0.001994	0.001634
2007-Jun-21	11	33062	1	1000	100000	10000	50000	20000	0.007438	0.002638	0.002435	0.002500
2007-Jun-21	11	33063	1	1000	100000	10000	50000	20000	0.005764	0.001728	0.002028	0.001617
2007-Jun-21	11	33064	1	1000	100000	10000	50000	20000	0.005388	0.001577	0.001913	0.001470
2007-Jun-21	11	33065	1	1000	100000	10000	50000	20000	0.006032	0.001880	0.002084	0.001760

2007-Jun-21	11	33066	1	1000	100000	10000	50000	20000	0.005934	0.001829	0.002059	0.001713
2007-Jun-21	11	33067	1	1000	100000	10000	50000	20000	0.006195	0.001956	0.002124	0.001833
2007-Jun-21	11	33068	1	1000	100000	10000	50000	20000	0.005640	0.001680	0.001993	0.001571
2007-Jun-21	11	33069	1	1000	100000	10000	50000	20000	0.005898	0.001813	0.002049	0.001696
2007-Jun-21	11	33071	1	1000	100000	10000	50000	20000	0.005963	0.001811	0.002088	0.001696
2007-Jun-21	11	33072	1	1000	100000	10000	50000	20000	0.005457	0.001609	0.001938	0.001502
2007-Jun-21	11	33073	1	1000	100000	10000	50000	20000	0.005802	0.001729	0.002045	0.001620
2007-Jun-21	11	33074	1	1000	100000	10000	50000	20000	0.005675	0.001720	0.001992	0.001613
2007-Jun-21	11	33075	1	1000	100000	10000	50000	20000	0.005626	0.001649	0.001995	0.001539
2007-Jun-21	11	33076	1	1000	100000	10000	50000	20000	0.005671	0.001679	0.002004	0.001568
2007-Jun-21	11	33077	1	1000	100000	10000	50000	20000	0.005696	0.001669	0.002028	0.001563
2007-Jun-21	11	33081	1	1000	100000	10000	50000	20000	0.005850	0.001776	0.002059	0.001675
2007-Jun-21	11	33082	1	1000	100000	10000	50000	20000	0.005733	0.001643	0.002068	0.001549
2007-Jun-21	11	33083	1	1000	100000	10000	50000	20000	0.005498	0.001613	0.001966	0.001516
2007-Jun-21	11	33084	1	1000	100000	10000	50000	20000	0.005780	0.001741	0.002039	0.001638
2007-Jun-21	11	33093	1	1000	100000	10000	50000	20000	0.005679	0.001681	0.002012	0.001574
2007-Jun-21	11	33097	1	1000	100000	10000	50000	20000	0.006067	0.001877	0.002108	0.001765
2007-Jun-21	11	33301	1	1000	100000	10000	50000	20000	0.006192	0.001924	0.002165	0.001817
2007-Jun-21	11	33302	1	1000	100000	10000	50000	20000	0.006259	0.001999	0.002162	0.001890
2007-Jun-21	11	33303	1	1000	100000	10000	50000	20000	0.006534	0.002081	0.002269	0.001977
2007-Jun-21	11	33304	1	1000	100000	10000	50000	20000	0.006050	0.001882	0.002117	0.001777
2007-Jun-21	11	33305	1	1000	100000	10000	50000	20000	0.005859	0.001781	0.002065	0.001676
2007-Jun-21	11	33306	1	1000	100000	10000	50000	20000	0.005919	0.001823	0.002076	0.001716
2007-Jun-21	11	33307	1	1000	100000	10000	50000	20000	0.005471	0.001626	0.001948	0.001523
2007-Jun-21	11	33308	1	1000	100000	10000	50000	20000	0.005740	0.001730	0.002030	0.001624
2007-Jun-21	11	33309	1	1000	100000	10000	50000	20000	0.006904	0.002216	0.002383	0.002105
2007-Jun-21	11	33310	1	1000	100000	10000	50000	20000	0.005469	0.001650	0.001928	0.001541
2007-Jun-21	11	33311	1	1000	100000	10000	50000	20000	0.005423	0.001593	0.001937	0.001491
2007-Jun-21	11	33312	1	1000	100000	10000	50000	20000	0.006172	0.001963	0.002131	0.001855
2007-Jun-21	11	33313	1	1000	100000	10000	50000	20000	0.005732	0.001720	0.002024	0.001614
2007-Jun-21	11	33314	1	1000	100000	10000	50000	20000	0.005744	0.001713	0.002040	0.001612
2007-Jun-21	11	33315	1	1000	100000	10000	50000	20000	0.005728	0.001734	0.002023	0.001631
2007-Jun-21	11	33316	1	1000	100000	10000	50000	20000	0.007616	0.002830	0.002434	0.002686
2007-Jun-21	11	33317	1	1000	100000	10000	50000	20000	0.006073	0.001883	0.002120	0.001775
2007-Jun-21	11	33318	1	1000	100000	10000	50000	20000	0.005755	0.001703	0.002047	0.001600
2007-Jun-21	11	33319	1	1000	100000	10000	50000	20000	0.006223	0.001946	0.002157	0.001830
2007-Jun-21	11	33320	1	1000	100000	10000	50000	20000	0.005707	0.001702	0.002018	0.001593

2007-Jun-21	11	33321	1	1000	100000	10000	50000	20000	0.006106	0.001887	0.002124	0.001772
2007-Jun-21	11	33322	1	1000	100000	10000	50000	20000	0.005864	0.001767	0.002067	0.001660
2007-Jun-21	11	33323	1	1000	100000	10000	50000	20000	0.006185	0.001887	0.002173	0.001779
2007-Jun-21	11	33324	1	1000	100000	10000	50000	20000	0.006344	0.001990	0.002204	0.001881
2007-Jun-21	11	33325	1	1000	100000	10000	50000	20000	0.005824	0.001734	0.002068	0.001632
2007-Jun-21	11	33326	1	1000	100000	10000	50000	20000	0.006172	0.001860	0.002184	0.001760
2007-Jun-21	11	33327	1	1000	100000	10000	50000	20000	0.006003	0.001765	0.002148	0.001667
2007-Jun-21	11	33328	1	1000	100000	10000	50000	20000	0.006174	0.001917	0.002155	0.001810
2007-Jun-21	11	33329	1	1000	100000	10000	50000	20000	0.006080	0.001887	0.002120	0.001779
2007-Jun-21	11	33330	1	1000	100000	10000	50000	20000	0.006274	0.001943	0.002191	0.001839
2007-Jun-21	11	33331	1	1000	100000	10000	50000	20000	0.006427	0.001995	0.002246	0.001891
2007-Jun-21	11	33332	1	1000	100000	10000	50000	20000	0.006397	0.001954	0.002254	0.001854
2007-Jun-21	11	33334	1	1000	100000	10000	50000	20000	0.005063	0.001421	0.001842	0.001323
2007-Jun-21	11	33335	1	1000	100000	10000	50000	20000	0.005471	0.001626	0.001948	0.001523
2007-Jun-21	11	33336	1	1000	100000	10000	50000	20000	0.005440	0.001636	0.001921	0.001529
2007-Jun-21	11	33337	1	1000	100000	10000	50000	20000	0.005993	0.001840	0.002099	0.001733
2007-Jun-21	11	33338	1	1000	100000	10000	50000	20000	0.005572	0.001658	0.001980	0.001557
2007-Jun-21	11	33339	1	1000	100000	10000	50000	20000	0.005579	0.001669	0.001981	0.001566
2007-Jun-21	11	33340	1	1000	100000	10000	50000	20000	0.005469	0.001650	0.001928	0.001541
2007-Jun-21	11	33345	1	1000	100000	10000	50000	20000	0.005903	0.001766	0.002090	0.001661
2007-Jun-21	11	33346	1	1000	100000	10000	50000	20000	0.006062	0.001961	0.002079	0.001853
2007-Jun-21	11	33348	1	1000	100000	10000	50000	20000	0.006658	0.002221	0.002251	0.002100
2007-Jun-21	11	33349	1	1000	100000	10000	50000	20000	0.006259	0.001999	0.002162	0.001890
2007-Jun-21	11	33351	1	1000	100000	10000	50000	20000	0.005913	0.001786	0.002083	0.001678
2007-Jun-21	11	33355	1	1000	100000	10000	50000	20000	0.006110	0.001900	0.002130	0.001792
2007-Jun-21	11	33359	1	1000	100000	10000	50000	20000	0.005990	0.001886	0.002067	0.001771
2007-Jun-21	11	33388	1	1000	100000	10000	50000	20000	0.005572	0.001658	0.001980	0.001557
2007-Jun-21	11	33394	1	1000	100000	10000	50000	20000	0.005449	0.001591	0.001958	0.001493
2007-Jun-21	11	33441	1	1000	100000	10000	50000	20000	0.005604	0.001696	0.001961	0.001583
2007-Jun-21	11	33442	1	1000	100000	10000	50000	20000	0.005721	0.001741	0.001995	0.001627
2007-Jun-21	11	33443	1	1000	100000	10000	50000	20000	0.005730	0.001793	0.001981	0.001674
2007-Jun-21	11	33004	2	1000	100000	10000	50000	20000	0.004227	0.001122	0.002148	0.001057
2007-Jun-21	11	33008	2	1000	100000	10000	50000	20000	0.004097	0.001073	0.002091	0.001006
2007-Jun-21	11	33009	2	1000	100000	10000	50000	20000	0.004279	0.001166	0.002148	0.001101
2007-Jun-21	11	33019	2	1000	100000	10000	50000	20000	0.005348	0.001622	0.002580	0.001564
2007-Jun-21	11	33020	2	1000	100000	10000	50000	20000	0.004018	0.001049	0.002051	0.000982
2007-Jun-21	11	33021	2	1000	100000	10000	50000	20000	0.004051	0.001052	0.002068	0.000984

2007-Jun-21	11	33022	2	1000	100000	10000	50000	20000	0.004222	0.001148	0.002121	0.001084
2007-Jun-21	11	33023	2	1000	100000	10000	50000	20000	0.004060	0.001046	0.002077	0.000977
2007-Jun-21	11	33024	2	1000	100000	10000	50000	20000	0.004021	0.001030	0.002060	0.000960
2007-Jun-21	11	33025	2	1000	100000	10000	50000	20000	0.004121	0.001060	0.002112	0.000991
2007-Jun-21	11	33026	2	1000	100000	10000	50000	20000	0.004252	0.001107	0.002170	0.001038
2007-Jun-21	11	33027	2	1000	100000	10000	50000	20000	0.004321	0.001136	0.002200	0.001069
2007-Jun-21	11	33028	2	1000	100000	10000	50000	20000	0.004038	0.001011	0.002091	0.000940
2007-Jun-21	11	33029	2	1000	100000	10000	50000	20000	0.004176	0.001045	0.002175	0.000975
2007-Jun-21	11	33060	2	1000	100000	10000	50000	20000	0.003726	0.000933	0.001910	0.000857
2007-Jun-21	11	33061	2	1000	100000	10000	50000	20000	0.003921	0.001010	0.001985	0.000935
2007-Jun-21	11	33062	2	1000	100000	10000	50000	20000	0.005014	0.001477	0.002423	0.001413
2007-Jun-21	11	33063	2	1000	100000	10000	50000	20000	0.003967	0.001002	0.002019	0.000925
2007-Jun-21	11	33064	2	1000	100000	10000	50000	20000	0.003722	0.000922	0.001905	0.000844
2007-Jun-21	11	33065	2	1000	100000	10000	50000	20000	0.004145	0.001084	0.002074	0.001007
2007-Jun-21	11	33066	2	1000	100000	10000	50000	20000	0.004077	0.001057	0.002050	0.000980
2007-Jun-21	11	33067	2	1000	100000	10000	50000	20000	0.004252	0.001126	0.002114	0.001049
2007-Jun-21	11	33068	2	1000	100000	10000	50000	20000	0.003884	0.000976	0.001984	0.000899
2007-Jun-21	11	33069	2	1000	100000	10000	50000	20000	0.004058	0.001049	0.002040	0.000972
2007-Jun-21	11	33071	2	1000	100000	10000	50000	20000	0.004099	0.001047	0.002078	0.000969
2007-Jun-21	11	33072	2	1000	100000	10000	50000	20000	0.003763	0.000938	0.001930	0.000861
2007-Jun-21	11	33073	2	1000	100000	10000	50000	20000	0.003989	0.001002	0.002036	0.000925
2007-Jun-21	11	33074	2	1000	100000	10000	50000	20000	0.003891	0.000992	0.001983	0.000920
2007-Jun-21	11	33075	2	1000	100000	10000	50000	20000	0.003884	0.000962	0.001986	0.000883
2007-Jun-21	11	33076	2	1000	100000	10000	50000	20000	0.003912	0.000978	0.001995	0.000899
2007-Jun-21	11	33077	2	1000	100000	10000	50000	20000	0.003921	0.000971	0.002019	0.000893
2007-Jun-21	11	33081	2	1000	100000	10000	50000	20000	0.003994	0.001018	0.002050	0.000948
2007-Jun-21	11	33082	2	1000	100000	10000	50000	20000	0.003927	0.000949	0.002059	0.000875
2007-Jun-21	11	33083	2	1000	100000	10000	50000	20000	0.003771	0.000933	0.001957	0.000861
2007-Jun-21	11	33084	2	1000	100000	10000	50000	20000	0.003957	0.001002	0.002029	0.000929
2007-Jun-21	11	33093	2	1000	100000	10000	50000	20000	0.003908	0.000976	0.002003	0.000900
2007-Jun-21	11	33097	2	1000	100000	10000	50000	20000	0.004149	0.001077	0.002099	0.001004
2007-Jun-21	11	33301	2	1000	100000	10000	50000	20000	0.004215	0.001097	0.002155	0.001027
2007-Jun-21	11	33302	2	1000	100000	10000	50000	20000	0.004249	0.001134	0.002152	0.001067
2007-Jun-21	11	33303	2	1000	100000	10000	50000	20000	0.004416	0.001174	0.002258	0.001109
2007-Jun-21	11	33304	2	1000	100000	10000	50000	20000	0.004117	0.001073	0.002107	0.001003
2007-Jun-21	11	33305	2	1000	100000	10000	50000	20000	0.004006	0.001023	0.002056	0.000951
2007-Jun-21	11	33306	2	1000	100000	10000	50000	20000	0.004046	0.001046	0.002067	0.000973

2007-Jun-21	11	33307	2	1000	100000	10000	50000	20000	0.003757	0.000942	0.001939	0.000868
2007-Jun-21	11	33308	2	1000	100000	10000	50000	20000	0.003936	0.000998	0.002021	0.000923
2007-Jun-21	11	33309	2	1000	100000	10000	50000	20000	0.004661	0.001247	0.002372	0.001181
2007-Jun-21	11	33310	2	1000	100000	10000	50000	20000	0.003767	0.000958	0.001920	0.000883
2007-Jun-21	11	33311	2	1000	100000	10000	50000	20000	0.003731	0.000925	0.001929	0.000850
2007-Jun-21	11	33312	2	1000	100000	10000	50000	20000	0.004194	0.001115	0.002122	0.001048
2007-Jun-21	11	33313	2	1000	100000	10000	50000	20000	0.003936	0.000995	0.002015	0.000920
2007-Jun-21	11	33314	2	1000	100000	10000	50000	20000	0.003932	0.000986	0.002031	0.000914
2007-Jun-21	11	33315	2	1000	100000	10000	50000	20000	0.003919	0.000997	0.002014	0.000925
2007-Jun-21	11	33316	2	1000	100000	10000	50000	20000	0.005112	0.001577	0.002423	0.001520
2007-Jun-21	11	33317	2	1000	100000	10000	50000	20000	0.004142	0.001076	0.002110	0.001005
2007-Jun-21	11	33318	2	1000	100000	10000	50000	20000	0.003946	0.000984	0.002037	0.000909
2007-Jun-21	11	33319	2	1000	100000	10000	50000	20000	0.004255	0.001115	0.002147	0.001041
2007-Jun-21	11	33320	2	1000	100000	10000	50000	20000	0.003929	0.000988	0.002009	0.000911
2007-Jun-21	11	33321	2	1000	100000	10000	50000	20000	0.004183	0.001085	0.002115	0.001010
2007-Jun-21	11	33322	2	1000	100000	10000	50000	20000	0.004018	0.001018	0.002058	0.000944
2007-Jun-21	11	33323	2	1000	100000	10000	50000	20000	0.004221	0.001081	0.002164	0.001007
2007-Jun-21	11	33324	2	1000	100000	10000	50000	20000	0.004317	0.001133	0.002194	0.001063
2007-Jun-21	11	33325	2	1000	100000	10000	50000	20000	0.003986	0.000999	0.002058	0.000925
2007-Jun-21	11	33326	2	1000	100000	10000	50000	20000	0.004201	0.001062	0.002174	0.000991
2007-Jun-21	11	33327	2	1000	100000	10000	50000	20000	0.004098	0.001014	0.002138	0.000940
2007-Jun-21	11	33328	2	1000	100000	10000	50000	20000	0.004204	0.001092	0.002145	0.001022
2007-Jun-21	11	33329	2	1000	100000	10000	50000	20000	0.004147	0.001079	0.002110	0.001008
2007-Jun-21	11	33330	2	1000	100000	10000	50000	20000	0.004264	0.001104	0.002181	0.001036
2007-Jun-21	11	33331	2	1000	100000	10000	50000	20000	0.004362	0.001132	0.002235	0.001064
2007-Jun-21	11	33332	2	1000	100000	10000	50000	20000	0.004339	0.001109	0.002244	0.001040
2007-Jun-21	11	33334	2	1000	100000	10000	50000	20000	0.003506	0.000837	0.001834	0.000759
2007-Jun-21	11	33335	2	1000	100000	10000	50000	20000	0.003757	0.000942	0.001939	0.000868
2007-Jun-21	11	33336	2	1000	100000	10000	50000	20000	0.003745	0.000950	0.001912	0.000875
2007-Jun-21	11	33337	2	1000	100000	10000	50000	20000	0.004093	0.001054	0.002089	0.000983
2007-Jun-21	11	33338	2	1000	100000	10000	50000	20000	0.003820	0.000958	0.001971	0.000885
2007-Jun-21	11	33339	2	1000	100000	10000	50000	20000	0.003826	0.000964	0.001972	0.000890
2007-Jun-21	11	33340	2	1000	100000	10000	50000	20000	0.003768	0.000958	0.001920	0.000883
2007-Jun-21	11	33345	2	1000	100000	10000	50000	20000	0.004045	0.001019	0.002080	0.000944
2007-Jun-21	11	33346	2	1000	100000	10000	50000	20000	0.004118	0.001114	0.002070	0.001048
2007-Jun-21	11	33348	2	1000	100000	10000	50000	20000	0.004511	0.001254	0.002241	0.001187
2007-Jun-21	11	33349	2	1000	100000	10000	50000	20000	0.004249	0.001134	0.002152	0.001067

2007-Jun-21	11	33351	2	1000	100000	10000	50000	20000	0.004053	0.001030	0.002074	0.000955
2007-Jun-21	11	33355	2	1000	100000	10000	50000	20000	0.004164	0.001084	0.002120	0.001014
2007-Jun-21	11	33359	2	1000	100000	10000	50000	20000	0.004101	0.001083	0.002058	0.001010
2007-Jun-21	11	33388	2	1000	100000	10000	50000	20000	0.003820	0.000958	0.001971	0.000885
2007-Jun-21	11	33394	2	1000	100000	10000	50000	20000	0.003739	0.000921	0.001949	0.000848
2007-Jun-21	11	33441	2	1000	100000	10000	50000	20000	0.003862	0.000985	0.001952	0.000908
2007-Jun-21	11	33442	2	1000	100000	10000	50000	20000	0.003941	0.001010	0.001986	0.000933
2007-Jun-21	11	33443	2	1000	100000	10000	50000	20000	0.003947	0.001039	0.001972	0.000962
2007-Jun-21	11	33004	3	1000	100000	10000	50000	20000	0.023801	0.010986	0.002181	0.011566
2007-Jun-21	11	33008	3	1000	100000	10000	50000	20000	0.022980	0.010508	0.002123	0.011068
2007-Jun-21	11	33009	3	1000	100000	10000	50000	20000	0.023927	0.011154	0.002181	0.011723
2007-Jun-21	11	33019	3	1000	100000	10000	50000	20000	0.030272	0.015025	0.002619	0.015739
2007-Jun-21	11	33020	3	1000	100000	10000	50000	20000	0.022474	0.010242	0.002083	0.010783
2007-Jun-21	11	33021	3	1000	100000	10000	50000	20000	0.022622	0.010281	0.002099	0.010824
2007-Jun-21	11	33022	3	1000	100000	10000	50000	20000	0.023638	0.011021	0.002154	0.011579
2007-Jun-21	11	33023	3	1000	100000	10000	50000	20000	0.022674	0.010268	0.002109	0.010819
2007-Jun-21	11	33024	3	1000	100000	10000	50000	20000	0.022428	0.010117	0.002092	0.010659
2007-Jun-21	11	33025	3	1000	100000	10000	50000	20000	0.023141	0.010503	0.002145	0.011074
2007-Jun-21	11	33026	3	1000	100000	10000	50000	20000	0.023903	0.010925	0.002203	0.011515
2007-Jun-21	11	33027	3	1000	100000	10000	50000	20000	0.024398	0.011238	0.002234	0.011840
2007-Jun-21	11	33028	3	1000	100000	10000	50000	20000	0.022703	0.010167	0.002124	0.010738
2007-Jun-21	11	33029	3	1000	100000	10000	50000	20000	0.023782	0.010722	0.002208	0.011339
2007-Jun-21	11	33060	3	1000	100000	10000	50000	20000	0.020145	0.008793	0.001939	0.009247
2007-Jun-21	11	33061	3	1000	100000	10000	50000	20000	0.021216	0.009422	0.002015	0.009896
2007-Jun-21	11	33062	3	1000	100000	10000	50000	20000	0.027829	0.013500	0.002460	0.014129
2007-Jun-21	11	33063	3	1000	100000	10000	50000	20000	0.021511	0.009472	0.002050	0.009964
2007-Jun-21	11	33064	3	1000	100000	10000	50000	20000	0.019981	0.008644	0.001934	0.009086
2007-Jun-21	11	33065	3	1000	100000	10000	50000	20000	0.022332	0.009993	0.002106	0.010491
2007-Jun-21	11	33066	3	1000	100000	10000	50000	20000	0.022016	0.009811	0.002081	0.010304
2007-Jun-21	11	33067	3	1000	100000	10000	50000	20000	0.022887	0.010309	0.002146	0.010817
2007-Jun-21	11	33068	3	1000	100000	10000	50000	20000	0.021054	0.009230	0.002015	0.009712
2007-Jun-21	11	33069	3	1000	100000	10000	50000	20000	0.021842	0.009702	0.002071	0.010191
2007-Jun-21	11	33071	3	1000	100000	10000	50000	20000	0.022273	0.009878	0.002110	0.010392
2007-Jun-21	11	33072	3	1000	100000	10000	50000	20000	0.020336	0.008854	0.001959	0.009314
2007-Jun-21	11	33073	3	1000	100000	10000	50000	20000	0.021725	0.009566	0.002067	0.010069
2007-Jun-21	11	33074	3	1000	100000	10000	50000	20000	0.021237	0.009434	0.002013	0.009913
2007-Jun-21	11	33075	3	1000	100000	10000	50000	20000	0.020938	0.009091	0.002016	0.009567

2007-Jun-21	11	33076	3	1000	100000	10000	50000	20000	0.021105	0.009210	0.002026	0.009691
2007-Jun-21	11	33077	3	1000	100000	10000	50000	20000	0.021413	0.009354	0.002050	0.009859
2007-Jun-21	11	33081	3	1000	100000	10000	50000	20000	0.022266	0.010011	0.002081	0.010554
2007-Jun-21	11	33082	3	1000	100000	10000	50000	20000	0.022083	0.009707	0.002091	0.010279
2007-Jun-21	11	33083	3	1000	100000	10000	50000	20000	0.020915	0.009220	0.001987	0.009729
2007-Jun-21	11	33084	3	1000	100000	10000	50000	20000	0.021900	0.009772	0.002061	0.010301
2007-Jun-21	11	33093	3	1000	100000	10000	50000	20000	0.021284	0.009334	0.002033	0.009827
2007-Jun-21	11	33097	3	1000	100000	10000	50000	20000	0.022744	0.010236	0.002131	0.010759
2007-Jun-21	11	33301	3	1000	100000	10000	50000	20000	0.023614	0.010750	0.002189	0.011327
2007-Jun-21	11	33302	3	1000	100000	10000	50000	20000	0.023787	0.010972	0.002185	0.011540
2007-Jun-21	11	33303	3	1000	100000	10000	50000	20000	0.025216	0.011728	0.002293	0.012363
2007-Jun-21	11	33304	3	1000	100000	10000	50000	20000	0.023049	0.010492	0.002140	0.011047
2007-Jun-21	11	33305	3	1000	100000	10000	50000	20000	0.022198	0.009939	0.002088	0.010471
2007-Jun-21	11	33306	3	1000	100000	10000	50000	20000	0.022389	0.010079	0.002099	0.010612
2007-Jun-21	11	33307	3	1000	100000	10000	50000	20000	0.020619	0.009079	0.001969	0.009560
2007-Jun-21	11	33308	3	1000	100000	10000	50000	20000	0.021674	0.009632	0.002052	0.010145
2007-Jun-21	11	33309	3	1000	100000	10000	50000	20000	0.026622	0.012437	0.002408	0.013110
2007-Jun-21	11	33310	3	1000	100000	10000	50000	20000	0.020357	0.008959	0.001949	0.009418
2007-Jun-21	11	33311	3	1000	100000	10000	50000	20000	0.020421	0.008931	0.001958	0.009410
2007-Jun-21	11	33312	3	1000	100000	10000	50000	20000	0.023394	0.010760	0.002154	0.011311
2007-Jun-21	11	33313	3	1000	100000	10000	50000	20000	0.021564	0.009543	0.002046	0.010053
2007-Jun-21	11	33314	3	1000	100000	10000	50000	20000	0.021844	0.009712	0.002062	0.010244
2007-Jun-21	11	33315	3	1000	100000	10000	50000	20000	0.021700	0.009696	0.002045	0.010215
2007-Jun-21	11	33316	3	1000	100000	10000	50000	20000	0.028330	0.014082	0.002459	0.014698
2007-Jun-21	11	33317	3	1000	100000	10000	50000	20000	0.023012	0.010427	0.002142	0.010977
2007-Jun-21	11	33318	3	1000	100000	10000	50000	20000	0.021816	0.009636	0.002069	0.010163
2007-Jun-21	11	33319	3	1000	100000	10000	50000	20000	0.023378	0.010581	0.002180	0.011128
2007-Jun-21	11	33320	3	1000	100000	10000	50000	20000	0.021365	0.009387	0.002039	0.009887
2007-Jun-21	11	33321	3	1000	100000	10000	50000	20000	0.022876	0.010272	0.002147	0.010802
2007-Jun-21	11	33322	3	1000	100000	10000	50000	20000	0.022138	0.009851	0.002089	0.010377
2007-Jun-21	11	33323	3	1000	100000	10000	50000	20000	0.023533	0.010601	0.002197	0.011176
2007-Jun-21	11	33324	3	1000	100000	10000	50000	20000	0.024128	0.011030	0.002227	0.011615
2007-Jun-21	11	33325	3	1000	100000	10000	50000	20000	0.022154	0.009846	0.002090	0.010387
2007-Jun-21	11	33326	3	1000	100000	10000	50000	20000	0.023730	0.010703	0.002207	0.011298
2007-Jun-21	11	33327	3	1000	100000	10000	50000	20000	0.023120	0.010298	0.002171	0.010886
2007-Jun-21	11	33328	3	1000	100000	10000	50000	20000	0.023511	0.010700	0.002178	0.011273
2007-Jun-21	11	33329	3	1000	100000	10000	50000	20000	0.023027	0.010439	0.002142	0.010990

2007-Jun-21	11	33330	3	1000	100000	10000	50000	20000	0.024011	0.010960	0.002214	0.011555
2007-Jun-21	11	33331	3	1000	100000	10000	50000	20000	0.024701	0.011318	0.002270	0.011938
2007-Jun-21	11	33332	3	1000	100000	10000	50000	20000	0.024737	0.011281	0.002278	0.011913
2007-Jun-21	11	33334	3	1000	100000	10000	50000	20000	0.019005	0.008085	0.001862	0.008527
2007-Jun-21	11	33335	3	1000	100000	10000	50000	20000	0.020619	0.009079	0.001969	0.009560
2007-Jun-21	11	33336	3	1000	100000	10000	50000	20000	0.020283	0.008926	0.001942	0.009384
2007-Jun-21	11	33337	3	1000	100000	10000	50000	20000	0.022677	0.010210	0.002121	0.010750
2007-Jun-21	11	33338	3	1000	100000	10000	50000	20000	0.021070	0.009317	0.002001	0.009814
2007-Jun-21	11	33339	3	1000	100000	10000	50000	20000	0.021064	0.009324	0.002002	0.009818
2007-Jun-21	11	33340	3	1000	100000	10000	50000	20000	0.020358	0.008959	0.001949	0.009419
2007-Jun-21	11	33345	3	1000	100000	10000	50000	20000	0.022358	0.009928	0.002112	0.010468
2007-Jun-21	11	33346	3	1000	100000	10000	50000	20000	0.022878	0.010588	0.002101	0.011115
2007-Jun-21	11	33348	3	1000	100000	10000	50000	20000	0.025083	0.011785	0.002275	0.012365
2007-Jun-21	11	33349	3	1000	100000	10000	50000	20000	0.023787	0.010972	0.002185	0.011540
2007-Jun-21	11	33351	3	1000	100000	10000	50000	20000	0.022299	0.009925	0.002105	0.010454
2007-Jun-21	11	33355	3	1000	100000	10000	50000	20000	0.023173	0.010526	0.002152	0.011081
2007-Jun-21	11	33359	3	1000	100000	10000	50000	20000	0.022323	0.010092	0.002089	0.010595
2007-Jun-21	11	33388	3	1000	100000	10000	50000	20000	0.021070	0.009317	0.002001	0.009814
2007-Jun-21	11	33394	3	1000	100000	10000	50000	20000	0.020736	0.009106	0.001979	0.009611
2007-Jun-21	11	33441	3	1000	100000	10000	50000	20000	0.020711	0.009112	0.001982	0.009564
2007-Jun-21	11	33442	3	1000	100000	10000	50000	20000	0.021132	0.009325	0.002016	0.009787
2007-Jun-21	11	33443	3	1000	100000	10000	50000	20000	0.021070	0.009392	0.002002	0.009844
2007-Jun-21	13	32421	1	1000	100000	10000	50000	20000	0.000325	0.000197	0.000695	0.000148
2007-Jun-21	13	32424	1	1000	100000	10000	50000	20000	0.000425	0.000243	0.000848	0.000189
2007-Jun-21	13	32430	1	1000	100000	10000	50000	20000	0.000356	0.000213	0.000747	0.000161
2007-Jun-21	13	32449	1	1000	100000	10000	50000	20000	0.000485	0.000277	0.000935	0.000226
2007-Jun-21	13	32421	2	1000	100000	10000	50000	20000	0.000291	0.000192	0.000694	0.000144
2007-Jun-21	13	32424	2	1000	100000	10000	50000	20000	0.000378	0.000235	0.000847	0.000183
2007-Jun-21	13	32430	2	1000	100000	10000	50000	20000	0.000319	0.000207	0.000745	0.000157
2007-Jun-21	13	32449	2	1000	100000	10000	50000	20000	0.000428	0.000266	0.000933	0.000216
2007-Jun-21	13	32421	3	1000	100000	10000	50000	20000	0.002750	0.000837	0.000712	0.000806
2007-Jun-21	13	32424	3	1000	100000	10000	50000	20000	0.003723	0.001201	0.000870	0.001186
2007-Jun-21	13	32430	3	1000	100000	10000	50000	20000	0.003039	0.000939	0.000766	0.000910
2007-Jun-21	13	32449	3	1000	100000	10000	50000	20000	0.004430	0.001545	0.000960	0.001541
2007-Jun-21	15	33927	1	1000	100000	10000	50000	20000	0.003648	0.000946	0.001755	0.000845
2007-Jun-21	15	33938	1	1000	100000	10000	50000	20000	0.002855	0.000580	0.001447	0.000480
2007-Jun-21	15	33946	1	1000	100000	10000	50000	20000	0.005145	0.001732	0.002214	0.001600

2007-Jun-21	15	33947	1	1000	100000	10000	50000	20000	0.003721	0.000948	0.001804	0.000846
2007-Jun-21	15	33948	1	1000	100000	10000	50000	20000	0.003443	0.000822	0.001696	0.000721
2007-Jun-21	15	33949	1	1000	100000	10000	50000	20000	0.003201	0.000676	0.001618	0.000573
2007-Jun-21	15	33950	1	1000	100000	10000	50000	20000	0.003041	0.000632	0.001540	0.000530
2007-Jun-21	15	33951	1	1000	100000	10000	50000	20000	0.003214	0.000659	0.001640	0.000555
2007-Jun-21	15	33952	1	1000	100000	10000	50000	20000	0.002891	0.000581	0.001468	0.000479
2007-Jun-21	15	33953	1	1000	100000	10000	50000	20000	0.003247	0.000734	0.001622	0.000635
2007-Jun-21	15	33954	1	1000	100000	10000	50000	20000	0.003335	0.000745	0.001674	0.000644
2007-Jun-21	15	33955	1	1000	100000	10000	50000	20000	0.003473	0.000764	0.001746	0.000661
2007-Jun-21	15	33980	1	1000	100000	10000	50000	20000	0.003233	0.000708	0.001621	0.000607
2007-Jun-21	15	33981	1	1000	100000	10000	50000	20000	0.003454	0.000807	0.001717	0.000706
2007-Jun-21	15	33982	1	1000	100000	10000	50000	20000	0.003272	0.000646	0.001613	0.000539
2007-Jun-21	15	33983	1	1000	100000	10000	50000	20000	0.003394	0.000750	0.001708	0.000648
2007-Jun-21	15	34224	1	1000	100000	10000	50000	20000	0.003402	0.000806	0.001683	0.000708
2007-Jun-21	15	33927	2	1000	100000	10000	50000	20000	0.002959	0.000731	0.001751	0.000643
2007-Jun-21	15	33938	2	1000	100000	10000	50000	20000	0.002372	0.000482	0.001443	0.000383
2007-Jun-21	15	33946	2	1000	100000	10000	50000	20000	0.004078	0.001266	0.002207	0.001180
2007-Jun-21	15	33947	2	1000	100000	10000	50000	20000	0.003021	0.000735	0.001799	0.000645
2007-Jun-21	15	33948	2	1000	100000	10000	50000	20000	0.002814	0.000649	0.001691	0.000555
2007-Jun-21	15	33949	2	1000	100000	10000	50000	20000	0.002645	0.000553	0.001613	0.000452
2007-Jun-21	15	33950	2	1000	100000	10000	50000	20000	0.002518	0.000520	0.001536	0.000420
2007-Jun-21	15	33951	2	1000	100000	10000	50000	20000	0.002660	0.000543	0.001636	0.000440
2007-Jun-21	15	33952	2	1000	100000	10000	50000	20000	0.002403	0.000484	0.001465	0.000384
2007-Jun-21	15	33953	2	1000	100000	10000	50000	20000	0.002665	0.000588	0.001618	0.000494
2007-Jun-21	15	33954	2	1000	100000	10000	50000	20000	0.002739	0.000599	0.001669	0.000502
2007-Jun-21	15	33955	2	1000	100000	10000	50000	20000	0.002855	0.000616	0.001741	0.000516
2007-Jun-21	15	33980	2	1000	100000	10000	50000	20000	0.002663	0.000574	0.001617	0.000476
2007-Jun-21	15	33981	2	1000	100000	10000	50000	20000	0.002825	0.000640	0.001712	0.000545
2007-Jun-21	15	33982	2	1000	100000	10000	50000	20000	0.002704	0.000535	0.001609	0.000429
2007-Jun-21	15	33983	2	1000	100000	10000	50000	20000	0.002789	0.000605	0.001703	0.000506
2007-Jun-21	15	34224	2	1000	100000	10000	50000	20000	0.002780	0.000637	0.001678	0.000545
2007-Jun-21	15	33927	3	1000	100000	10000	50000	20000	0.018462	0.008082	0.001781	0.008348
2007-Jun-21	15	33938	3	1000	100000	10000	50000	20000	0.013645	0.005031	0.001469	0.005250
2007-Jun-21	15	33946	3	1000	100000	10000	50000	20000	0.025578	0.012739	0.002243	0.012967
2007-Jun-21	15	33947	3	1000	100000	10000	50000	20000	0.018982	0.008288	0.001830	0.008577
2007-Jun-21	15	33948	3	1000	100000	10000	50000	20000	0.017284	0.007215	0.001720	0.007488
2007-Jun-21	15	33949	3	1000	100000	10000	50000	20000	0.015730	0.006080	0.001642	0.006347

2007-Jun-21	15	33950	3	1000	100000	10000	50000	20000	0.014776	0.005601	0.001564	0.005846
2007-Jun-21	15	33951	3	1000	100000	10000	50000	20000	0.015900	0.006092	0.001665	0.006377
2007-Jun-21	15	33952	3	1000	100000	10000	50000	20000	0.013819	0.005069	0.001491	0.005296
2007-Jun-21	15	33953	3	1000	100000	10000	50000	20000	0.016226	0.006570	0.001647	0.006838
2007-Jun-21	15	33954	3	1000	100000	10000	50000	20000	0.016716	0.006748	0.001699	0.007028
2007-Jun-21	15	33955	3	1000	100000	10000	50000	20000	0.017493	0.007057	0.001772	0.007362
2007-Jun-21	15	33980	3	1000	100000	10000	50000	20000	0.015955	0.006304	0.001645	0.006563
2007-Jun-21	15	33981	3	1000	100000	10000	50000	20000	0.017489	0.007269	0.001743	0.007562
2007-Jun-21	15	33982	3	1000	100000	10000	50000	20000	0.015428	0.005815	0.001637	0.006085
2007-Jun-21	15	33983	3	1000	100000	10000	50000	20000	0.017038	0.006859	0.001733	0.007148
2007-Jun-21	15	34224	3	1000	100000	10000	50000	20000	0.017210	0.007205	0.001708	0.007485
2007-Jun-21	17	34423	1	1000	100000	10000	50000	20000	0.002239	0.000406	0.001084	0.000312
2007-Jun-21	17	34428	1	1000	100000	10000	50000	20000	0.001854	0.000327	0.000901	0.000243
2007-Jun-21	17	34429	1	1000	100000	10000	50000	20000	0.002122	0.000399	0.001028	0.000308
2007-Jun-21	17	34433	1	1000	100000	10000	50000	20000	0.002468	0.000478	0.001191	0.000382
2007-Jun-21	17	34434	1	1000	100000	10000	50000	20000	0.002260	0.000411	0.001096	0.000315
2007-Jun-21	17	34436	1	1000	100000	10000	50000	20000	0.002390	0.000430	0.001172	0.000331
2007-Jun-21	17	34442	1	1000	100000	10000	50000	20000	0.002237	0.000407	0.001085	0.000312
2007-Jun-21	17	34445	1	1000	100000	10000	50000	20000	0.002183	0.000410	0.001054	0.000317
2007-Jun-21	17	34446	1	1000	100000	10000	50000	20000	0.002486	0.000479	0.001205	0.000381
2007-Jun-21	17	34447	1	1000	100000	10000	50000	20000	0.002109	0.000385	0.001025	0.000294
2007-Jun-21	17	34448	1	1000	100000	10000	50000	20000	0.002167	0.000387	0.001054	0.000293
2007-Jun-21	17	34450	1	1000	100000	10000	50000	20000	0.002325	0.000420	0.001135	0.000322
2007-Jun-21	17	34451	1	1000	100000	10000	50000	20000	0.001941	0.000346	0.000953	0.000258
2007-Jun-21	17	34452	1	1000	100000	10000	50000	20000	0.002300	0.000419	0.001121	0.000322
2007-Jun-21	17	34453	1	1000	100000	10000	50000	20000	0.002366	0.000435	0.001150	0.000337
2007-Jun-21	17	34460	1	1000	100000	10000	50000	20000	0.002047	0.000368	0.000990	0.000277
2007-Jun-21	17	34461	1	1000	100000	10000	50000	20000	0.001751	0.000299	0.000855	0.000215
2007-Jun-21	17	34464	1	1000	100000	10000	50000	20000	0.001839	0.000311	0.000898	0.000223
2007-Jun-21	17	34465	1	1000	100000	10000	50000	20000	0.002274	0.000416	0.001100	0.000321
2007-Jun-21	17	34487	1	1000	100000	10000	50000	20000	0.002161	0.000396	0.001050	0.000304
2007-Jun-21	17	34423	2	1000	100000	10000	50000	20000	0.001879	0.000352	0.001081	0.000259
2007-Jun-21	17	34428	2	1000	100000	10000	50000	20000	0.001561	0.000289	0.000899	0.000206
2007-Jun-21	17	34429	2	1000	100000	10000	50000	20000	0.001778	0.000342	0.001025	0.000255
2007-Jun-21	17	34433	2	1000	100000	10000	50000	20000	0.002057	0.000404	0.001188	0.000311
2007-Jun-21	17	34434	2	1000	100000	10000	50000	20000	0.001895	0.000356	0.001093	0.000262
2007-Jun-21	17	34436	2	1000	100000	10000	50000	20000	0.002003	0.000373	0.001169	0.000275

2007-Jun-21	17	34442	2	1000	100000	10000	50000	20000	0.001877	0.000353	0.001083	0.000260
2007-Jun-21	17	34445	2	1000	100000	10000	50000	20000	0.001828	0.000351	0.001051	0.000262
2007-Jun-21	17	34446	2	1000	100000	10000	50000	20000	0.002074	0.000405	0.001202	0.000310
2007-Jun-21	17	34447	2	1000	100000	10000	50000	20000	0.001771	0.000334	0.001022	0.000245
2007-Jun-21	17	34448	2	1000	100000	10000	50000	20000	0.001821	0.000338	0.001051	0.000246
2007-Jun-21	17	34450	2	1000	100000	10000	50000	20000	0.001949	0.000364	0.001132	0.000268
2007-Jun-21	17	34451	2	1000	100000	10000	50000	20000	0.001633	0.000303	0.000951	0.000217
2007-Jun-21	17	34452	2	1000	100000	10000	50000	20000	0.001928	0.000362	0.001118	0.000268
2007-Jun-21	17	34453	2	1000	100000	10000	50000	20000	0.001982	0.000374	0.001147	0.000279
2007-Jun-21	17	34460	2	1000	100000	10000	50000	20000	0.001721	0.000321	0.000988	0.000233
2007-Jun-21	17	34461	2	1000	100000	10000	50000	20000	0.001480	0.000268	0.000853	0.000185
2007-Jun-21	17	34464	2	1000	100000	10000	50000	20000	0.001555	0.000279	0.000896	0.000192
2007-Jun-21	17	34465	2	1000	100000	10000	50000	20000	0.001906	0.000360	0.001098	0.000266
2007-Jun-21	17	34487	2	1000	100000	10000	50000	20000	0.001813	0.000343	0.001048	0.000252
2007-Jun-21	17	34423	3	1000	100000	10000	50000	20000	0.008816	0.002735	0.001099	0.002819
2007-Jun-21	17	34428	3	1000	100000	10000	50000	20000	0.007017	0.002027	0.000914	0.002066
2007-Jun-21	17	34429	3	1000	100000	10000	50000	20000	0.008385	0.002654	0.001043	0.002727
2007-Jun-21	17	34433	3	1000	100000	10000	50000	20000	0.010157	0.003450	0.001208	0.003568
2007-Jun-21	17	34434	3	1000	100000	10000	50000	20000	0.008924	0.002779	0.001112	0.002865
2007-Jun-21	17	34436	3	1000	100000	10000	50000	20000	0.009663	0.003078	0.001189	0.003190
2007-Jun-21	17	34442	3	1000	100000	10000	50000	20000	0.008802	0.002726	0.001101	0.002808
2007-Jun-21	17	34445	3	1000	100000	10000	50000	20000	0.008608	0.002722	0.001069	0.002797
2007-Jun-21	17	34446	3	1000	100000	10000	50000	20000	0.010240	0.003462	0.001223	0.003583
2007-Jun-21	17	34447	3	1000	100000	10000	50000	20000	0.008272	0.002550	0.001040	0.002624
2007-Jun-21	17	34448	3	1000	100000	10000	50000	20000	0.008469	0.002570	0.001069	0.002647
2007-Jun-21	17	34450	3	1000	100000	10000	50000	20000	0.009298	0.002927	0.001152	0.003027
2007-Jun-21	17	34451	3	1000	100000	10000	50000	20000	0.007529	0.002243	0.000967	0.002303
2007-Jun-21	17	34452	3	1000	100000	10000	50000	20000	0.009192	0.002906	0.001137	0.003002
2007-Jun-21	17	34453	3	1000	100000	10000	50000	20000	0.009490	0.003030	0.001167	0.003132
2007-Jun-21	17	34460	3	1000	100000	10000	50000	20000	0.007859	0.002339	0.001005	0.002396
2007-Jun-21	17	34461	3	1000	100000	10000	50000	20000	0.006439	0.001732	0.000868	0.001757
2007-Jun-21	17	34464	3	1000	100000	10000	50000	20000	0.006789	0.001820	0.000912	0.001854
2007-Jun-21	17	34465	3	1000	100000	10000	50000	20000	0.009004	0.002827	0.001116	0.002915
2007-Jun-21	17	34487	3	1000	100000	10000	50000	20000	0.008518	0.002650	0.001065	0.002728
2007-Jun-21	19	32003	1	1000	100000	10000	50000	20000	0.000336	0.000201	0.000671	0.000154
2007-Jun-21	19	32006	1	1000	100000	10000	50000	20000	0.000340	0.000203	0.000681	0.000156
2007-Jun-21	19	32030	1	1000	100000	10000	50000	20000	0.000276	0.000174	0.000609	0.000127

2007-Jun-21	19	32043	1	1000	100000	10000	50000	20000	0.000374	0.000219	0.000751	0.000169
2007-Jun-21	19	32050	1	1000	100000	10000	50000	20000	0.000276	0.000174	0.000609	0.000127
2007-Jun-21	19	32065	1	1000	100000	10000	50000	20000	0.000357	0.000211	0.000712	0.000163
2007-Jun-21	19	32067	1	1000	100000	10000	50000	20000	0.000344	0.000205	0.000689	0.000157
2007-Jun-21	19	32068	1	1000	100000	10000	50000	20000	0.000277	0.000174	0.000611	0.000127
2007-Jun-21	19	32073	1	1000	100000	10000	50000	20000	0.000351	0.000208	0.000699	0.000161
2007-Jun-21	19	32079	1	1000	100000	10000	50000	20000	0.000277	0.000175	0.000614	0.000127
2007-Jun-21	19	32160	1	1000	100000	10000	50000	20000	0.000459	0.000259	0.000883	0.000204
2007-Jun-21	19	32656	1	1000	100000	10000	50000	20000	0.000410	0.000237	0.000819	0.000183
2007-Jun-21	19	32003	2	1000	100000	10000	50000	20000	0.000299	0.000194	0.000670	0.000149
2007-Jun-21	19	32006	2	1000	100000	10000	50000	20000	0.000303	0.000196	0.000680	0.000150
2007-Jun-21	19	32030	2	1000	100000	10000	50000	20000	0.000248	0.000170	0.000608	0.000124
2007-Jun-21	19	32043	2	1000	100000	10000	50000	20000	0.000333	0.000213	0.000750	0.000163
2007-Jun-21	19	32050	2	1000	100000	10000	50000	20000	0.000248	0.000170	0.000608	0.000124
2007-Jun-21	19	32065	2	1000	100000	10000	50000	20000	0.000318	0.000204	0.000711	0.000157
2007-Jun-21	19	32067	2	1000	100000	10000	50000	20000	0.000306	0.000198	0.000688	0.000152
2007-Jun-21	19	32068	2	1000	100000	10000	50000	20000	0.000249	0.000170	0.000610	0.000124
2007-Jun-21	19	32073	2	1000	100000	10000	50000	20000	0.000313	0.000201	0.000698	0.000155
2007-Jun-21	19	32079	2	1000	100000	10000	50000	20000	0.000250	0.000172	0.000613	0.000125
2007-Jun-21	19	32160	2	1000	100000	10000	50000	20000	0.000406	0.000250	0.000882	0.000196
2007-Jun-21	19	32656	2	1000	100000	10000	50000	20000	0.000365	0.000230	0.000817	0.000177
2007-Jun-21	19	32003	3	1000	100000	10000	50000	20000	0.002801	0.000923	0.000688	0.000887
2007-Jun-21	19	32006	3	1000	100000	10000	50000	20000	0.002839	0.000923	0.000698	0.000887
2007-Jun-21	19	32030	3	1000	100000	10000	50000	20000	0.002292	0.000676	0.000623	0.000634
2007-Jun-21	19	32043	3	1000	100000	10000	50000	20000	0.003214	0.001047	0.000770	0.001017
2007-Jun-21	19	32050	3	1000	100000	10000	50000	20000	0.002292	0.000676	0.000623	0.000634
2007-Jun-21	19	32065	3	1000	100000	10000	50000	20000	0.003024	0.000999	0.000730	0.000965
2007-Jun-21	19	32067	3	1000	100000	10000	50000	20000	0.002873	0.000931	0.000706	0.000895
2007-Jun-21	19	32068	3	1000	100000	10000	50000	20000	0.002319	0.000684	0.000626	0.000644
2007-Jun-21	19	32073	3	1000	100000	10000	50000	20000	0.002964	0.000974	0.000716	0.000940
2007-Jun-21	19	32079	3	1000	100000	10000	50000	20000	0.002283	0.000668	0.000629	0.000624
2007-Jun-21	19	32160	3	1000	100000	10000	50000	20000	0.004010	0.001365	0.000907	0.001343
2007-Jun-21	19	32656	3	1000	100000	10000	50000	20000	0.003560	0.001163	0.000840	0.001135
2007-Jun-21	21	34101	1	1000	100000	10000	50000	20000	0.003772	0.000839	0.001897	0.000731
2007-Jun-21	21	34102	1	1000	100000	10000	50000	20000	0.003957	0.000904	0.001986	0.000797
2007-Jun-21	21	34103	1	1000	100000	10000	50000	20000	0.003855	0.000868	0.001938	0.000760
2007-Jun-21	21	34104	1	1000	100000	10000	50000	20000	0.003801	0.000859	0.001906	0.000752

2007-Jun-21	21	34105	1	1000	100000	10000	50000	20000	0.003758	0.000835	0.001897	0.000728
2007-Jun-21	21	34106	1	1000	100000	10000	50000	20000	0.003772	0.000839	0.001897	0.000731
2007-Jun-21	21	34107	1	1000	100000	10000	50000	20000	0.003772	0.000839	0.001897	0.000731
2007-Jun-21	21	34108	1	1000	100000	10000	50000	20000	0.003827	0.000858	0.001924	0.000751
2007-Jun-21	21	34109	1	1000	100000	10000	50000	20000	0.003858	0.000873	0.001938	0.000765
2007-Jun-21	21	34110	1	1000	100000	10000	50000	20000	0.003699	0.000819	0.001855	0.000711
2007-Jun-21	21	34112	1	1000	100000	10000	50000	20000	0.003967	0.000927	0.001982	0.000821
2007-Jun-21	21	34113	1	1000	100000	10000	50000	20000	0.003819	0.000856	0.001918	0.000748
2007-Jun-21	21	34114	1	1000	100000	10000	50000	20000	0.004197	0.001016	0.002087	0.000910
2007-Jun-21	21	34116	1	1000	100000	10000	50000	20000	0.003687	0.000809	0.001864	0.000701
2007-Jun-21	21	34117	1	1000	100000	10000	50000	20000	0.003924	0.000889	0.001982	0.000781
2007-Jun-21	21	34119	1	1000	100000	10000	50000	20000	0.003790	0.000841	0.001918	0.000734
2007-Jun-21	21	34120	1	1000	100000	10000	50000	20000	0.004076	0.000956	0.002048	0.000849
2007-Jun-21	21	34137	1	1000	100000	10000	50000	20000	0.004422	0.001105	0.002192	0.001003
2007-Jun-21	21	34138	1	1000	100000	10000	50000	20000	0.005415	0.001588	0.002560	0.001485
2007-Jun-21	21	34139	1	1000	100000	10000	50000	20000	0.004500	0.001148	0.002216	0.001043
2007-Jun-21	21	34140	1	1000	100000	10000	50000	20000	0.005181	0.001489	0.002463	0.001385
2007-Jun-21	21	34142	1	1000	100000	10000	50000	20000	0.003405	0.000671	0.001750	0.000556
2007-Jun-21	21	34143	1	1000	100000	10000	50000	20000	0.003611	0.000743	0.001850	0.000629
2007-Jun-21	21	34145	1	1000	100000	10000	50000	20000	0.004312	0.001090	0.002104	0.000981
2007-Jun-21	21	34146	1	1000	100000	10000	50000	20000	0.004149	0.001010	0.002052	0.000904
2007-Jun-21	21	34101	2	1000	100000	10000	50000	20000	0.003095	0.000672	0.001892	0.000568
2007-Jun-21	21	34102	2	1000	100000	10000	50000	20000	0.003235	0.000718	0.001981	0.000615
2007-Jun-21	21	34103	2	1000	100000	10000	50000	20000	0.003158	0.000692	0.001933	0.000589
2007-Jun-21	21	34104	2	1000	100000	10000	50000	20000	0.003115	0.000685	0.001901	0.000582
2007-Jun-21	21	34105	2	1000	100000	10000	50000	20000	0.003083	0.000669	0.001892	0.000566
2007-Jun-21	21	34106	2	1000	100000	10000	50000	20000	0.003095	0.000672	0.001892	0.000568
2007-Jun-21	21	34107	2	1000	100000	10000	50000	20000	0.003095	0.000672	0.001892	0.000568
2007-Jun-21	21	34108	2	1000	100000	10000	50000	20000	0.003137	0.000686	0.001918	0.000582
2007-Jun-21	21	34109	2	1000	100000	10000	50000	20000	0.003159	0.000696	0.001933	0.000592
2007-Jun-21	21	34110	2	1000	100000	10000	50000	20000	0.003038	0.000658	0.001850	0.000554
2007-Jun-21	21	34112	2	1000	100000	10000	50000	20000	0.003237	0.000731	0.001976	0.000631
2007-Jun-21	21	34113	2	1000	100000	10000	50000	20000	0.003131	0.000684	0.001913	0.000580
2007-Jun-21	21	34114	2	1000	100000	10000	50000	20000	0.003411	0.000793	0.002081	0.000695
2007-Jun-21	21	34116	2	1000	100000	10000	50000	20000	0.003029	0.000651	0.001859	0.000546
2007-Jun-21	21	34117	2	1000	100000	10000	50000	20000	0.003210	0.000707	0.001977	0.000603
2007-Jun-21	21	34119	2	1000	100000	10000	50000	20000	0.003107	0.000673	0.001913	0.000570

2007-Jun-21	21	34120	2	1000	100000	10000	50000	20000	0.003321	0.000753	0.002043	0.000652
2007-Jun-21	21	34137	2	1000	100000	10000	50000	20000	0.003575	0.000855	0.002186	0.000761
2007-Jun-21	21	34138	2	1000	100000	10000	50000	20000	0.004305	0.001182	0.002552	0.001103
2007-Jun-21	21	34139	2	1000	100000	10000	50000	20000	0.003634	0.000884	0.002209	0.000789
2007-Jun-21	21	34140	2	1000	100000	10000	50000	20000	0.004131	0.001114	0.002455	0.001031
2007-Jun-21	21	34142	2	1000	100000	10000	50000	20000	0.002829	0.000559	0.001745	0.000445
2007-Jun-21	21	34143	2	1000	100000	10000	50000	20000	0.002985	0.000610	0.001844	0.000497
2007-Jun-21	21	34145	2	1000	100000	10000	50000	20000	0.003496	0.000843	0.002098	0.000745
2007-Jun-21	21	34146	2	1000	100000	10000	50000	20000	0.003372	0.000787	0.002046	0.000690
2007-Jun-21	21	34101	3	1000	100000	10000	50000	20000	0.019302	0.007908	0.001925	0.008272
2007-Jun-21	21	34102	3	1000	100000	10000	50000	20000	0.020565	0.008638	0.002015	0.009026
2007-Jun-21	21	34103	3	1000	100000	10000	50000	20000	0.019843	0.008218	0.001967	0.008590
2007-Jun-21	21	34104	3	1000	100000	10000	50000	20000	0.019497	0.008059	0.001935	0.008425
2007-Jun-21	21	34105	3	1000	100000	10000	50000	20000	0.019302	0.007923	0.001926	0.008286
2007-Jun-21	21	34106	3	1000	100000	10000	50000	20000	0.019302	0.007908	0.001925	0.008272
2007-Jun-21	21	34107	3	1000	100000	10000	50000	20000	0.019302	0.007908	0.001925	0.008272
2007-Jun-21	21	34108	3	1000	100000	10000	50000	20000	0.019633	0.008097	0.001952	0.008461
2007-Jun-21	21	34109	3	1000	100000	10000	50000	20000	0.019860	0.008240	0.001967	0.008610
2007-Jun-21	21	34110	3	1000	100000	10000	50000	20000	0.018695	0.007580	0.001883	0.007914
2007-Jun-21	21	34112	3	1000	100000	10000	50000	20000	0.020642	0.008760	0.002011	0.009147
2007-Jun-21	21	34113	3	1000	100000	10000	50000	20000	0.019589	0.008069	0.001946	0.008442
2007-Jun-21	21	34114	3	1000	100000	10000	50000	20000	0.022172	0.009666	0.002118	0.010086
2007-Jun-21	21	34116	3	1000	100000	10000	50000	20000	0.018805	0.007624	0.001892	0.007982
2007-Jun-21	21	34117	3	1000	100000	10000	50000	20000	0.020406	0.008528	0.002012	0.008920
2007-Jun-21	21	34119	3	1000	100000	10000	50000	20000	0.019569	0.008061	0.001947	0.008436
2007-Jun-21	21	34120	3	1000	100000	10000	50000	20000	0.021435	0.009183	0.002079	0.009586
2007-Jun-21	21	34137	3	1000	100000	10000	50000	20000	0.023769	0.010666	0.002224	0.011097
2007-Jun-21	21	34138	3	1000	100000	10000	50000	20000	0.029701	0.014537	0.002595	0.014995
2007-Jun-21	21	34139	3	1000	100000	10000	50000	20000	0.024119	0.010893	0.002248	0.011324
2007-Jun-21	21	34140	3	1000	100000	10000	50000	20000	0.028241	0.013620	0.002497	0.014078
2007-Jun-21	21	34142	3	1000	100000	10000	50000	20000	0.016717	0.006222	0.001776	0.006541
2007-Jun-21	21	34143	3	1000	100000	10000	50000	20000	0.018102	0.007015	0.001878	0.007364
2007-Jun-21	21	34145	3	1000	100000	10000	50000	20000	0.022528	0.009954	0.002135	0.010350
2007-Jun-21	21	34146	3	1000	100000	10000	50000	20000	0.021800	0.009498	0.002082	0.009901
2007-Jun-21	23	32024	1	1000	100000	10000	50000	20000	0.000309	0.000186	0.000635	0.000141
2007-Jun-21	23	32025	1	1000	100000	10000	50000	20000	0.000297	0.000180	0.000623	0.000135
2007-Jun-21	23	32038	1	1000	100000	10000	50000	20000	0.000282	0.000176	0.000604	0.000130

2007-Jun-21	23	32055	1	1000	100000	10000	50000	20000	0.000218	0.000143	0.000504	0.000102
2007-Jun-21	23	32056	1	1000	100000	10000	50000	20000	0.000260	0.000163	0.000570	0.000120
2007-Jun-21	23	32061	1	1000	100000	10000	50000	20000	0.000157	0.000112	0.000393	0.000076
2007-Jun-21	23	32024	2	1000	100000	10000	50000	20000	0.000276	0.000181	0.000634	0.000137
2007-Jun-21	23	32025	2	1000	100000	10000	50000	20000	0.000266	0.000175	0.000622	0.000131
2007-Jun-21	23	32038	2	1000	100000	10000	50000	20000	0.000253	0.000171	0.000603	0.000127
2007-Jun-21	23	32055	2	1000	100000	10000	50000	20000	0.000197	0.000141	0.000503	0.000100
2007-Jun-21	23	32056	2	1000	100000	10000	50000	20000	0.000234	0.000160	0.000569	0.000117
2007-Jun-21	23	32061	2	1000	100000	10000	50000	20000	0.000144	0.000111	0.000393	0.000076
2007-Jun-21	23	32024	3	1000	100000	10000	50000	20000	0.002602	0.000831	0.000651	0.000796
2007-Jun-21	23	32025	3	1000	100000	10000	50000	20000	0.002508	0.000789	0.000638	0.000755
2007-Jun-21	23	32038	3	1000	100000	10000	50000	20000	0.002329	0.000716	0.000619	0.000676
2007-Jun-21	23	32055	3	1000	100000	10000	50000	20000	0.001768	0.000499	0.000516	0.000458
2007-Jun-21	23	32056	3	1000	100000	10000	50000	20000	0.002165	0.000649	0.000584	0.000611
2007-Jun-21	23	32061	3	1000	100000	10000	50000	20000	0.001203	0.000310	0.000402	0.000266
2007-Jun-21	27	34265	1	1000	100000	10000	50000	20000	0.002812	0.000491	0.001390	0.000381
2007-Jun-21	27	34266	1	1000	100000	10000	50000	20000	0.002932	0.000548	0.001443	0.000441
2007-Jun-21	27	34267	1	1000	100000	10000	50000	20000	0.002812	0.000491	0.001390	0.000381
2007-Jun-21	27	34268	1	1000	100000	10000	50000	20000	0.002812	0.000491	0.001390	0.000381
2007-Jun-21	27	34269	1	1000	100000	10000	50000	20000	0.003252	0.000652	0.001600	0.000547
2007-Jun-21	27	34265	2	1000	100000	10000	50000	20000	0.002355	0.000426	0.001386	0.000316
2007-Jun-21	27	34266	2	1000	100000	10000	50000	20000	0.002441	0.000465	0.001439	0.000359
2007-Jun-21	27	34267	2	1000	100000	10000	50000	20000	0.002355	0.000426	0.001386	0.000316
2007-Jun-21	27	34268	2	1000	100000	10000	50000	20000	0.002355	0.000426	0.001386	0.000316
2007-Jun-21	27	34269	2	1000	100000	10000	50000	20000	0.002684	0.000538	0.001596	0.000435
2007-Jun-21	27	34265	3	1000	100000	10000	50000	20000	0.011738	0.003832	0.001410	0.004010
2007-Jun-21	27	34266	3	1000	100000	10000	50000	20000	0.012610	0.004413	0.001464	0.004605
2007-Jun-21	27	34267	3	1000	100000	10000	50000	20000	0.011738	0.003832	0.001410	0.004010
2007-Jun-21	27	34268	3	1000	100000	10000	50000	20000	0.011738	0.003832	0.001410	0.004010
2007-Jun-21	27	34269	3	1000	100000	10000	50000	20000	0.014740	0.005619	0.001623	0.005865
2007-Jun-21	29	32628	1	1000	100000	10000	50000	20000	0.000494	0.000275	0.000823	0.000229
2007-Jun-21	29	32648	1	1000	100000	10000	50000	20000	0.000435	0.000254	0.000755	0.000211
2007-Jun-21	29	32680	1	1000	100000	10000	50000	20000	0.000363	0.000212	0.000667	0.000169
2007-Jun-21	29	32692	1	1000	100000	10000	50000	20000	0.000916	0.000493	0.001163	0.000446
2007-Jun-21	29	32628	2	1000	100000	10000	50000	20000	0.000434	0.000259	0.000821	0.000216
2007-Jun-21	29	32648	2	1000	100000	10000	50000	20000	0.000381	0.000239	0.000754	0.000198
2007-Jun-21	29	32680	2	1000	100000	10000	50000	20000	0.000321	0.000202	0.000666	0.000161

2007-Jun-21	29	32692	2	1000	100000	10000	50000	20000	0.000789	0.000439	0.001160	0.000399
2007-Jun-21	29	32628	3	1000	100000	10000	50000	20000	0.003974	0.001476	0.000844	0.001449
2007-Jun-21	29	32648	3	1000	100000	10000	50000	20000	0.003580	0.001331	0.000775	0.001299
2007-Jun-21	29	32680	3	1000	100000	10000	50000	20000	0.002929	0.001016	0.000684	0.000982
2007-Jun-21	29	32692	3	1000	100000	10000	50000	20000	0.006758	0.002871	0.001193	0.002852
2007-Jun-21	31	32099	1	1000	100000	10000	50000	20000	0.000213	0.000136	0.000467	0.000100
2007-Jun-21	31	32201	1	1000	100000	10000	50000	20000	0.000252	0.000157	0.000535	0.000117
2007-Jun-21	31	32202	1	1000	100000	10000	50000	20000	0.000257	0.000160	0.000540	0.000119
2007-Jun-21	31	32203	1	1000	100000	10000	50000	20000	0.000295	0.000178	0.000589	0.000137
2007-Jun-21	31	32204	1	1000	100000	10000	50000	20000	0.000323	0.000193	0.000646	0.000148
2007-Jun-21	31	32205	1	1000	100000	10000	50000	20000	0.000357	0.000209	0.000692	0.000164
2007-Jun-21	31	32206	1	1000	100000	10000	50000	20000	0.000307	0.000185	0.000613	0.000142
2007-Jun-21	31	32207	1	1000	100000	10000	50000	20000	0.000347	0.000204	0.000665	0.000160
2007-Jun-21	31	32208	1	1000	100000	10000	50000	20000	0.000370	0.000215	0.000685	0.000171
2007-Jun-21	31	32209	1	1000	100000	10000	50000	20000	0.000343	0.000202	0.000661	0.000158
2007-Jun-21	31	32210	1	1000	100000	10000	50000	20000	0.000340	0.000202	0.000678	0.000156
2007-Jun-21	31	32211	1	1000	100000	10000	50000	20000	0.000329	0.000200	0.000643	0.000159
2007-Jun-21	31	32212	1	1000	100000	10000	50000	20000	0.000385	0.000223	0.000727	0.000177
2007-Jun-21	31	32214	1	1000	100000	10000	50000	20000	0.000337	0.000201	0.000671	0.000155
2007-Jun-21	31	32215	1	1000	100000	10000	50000	20000	0.000149	0.000106	0.000374	0.000072
2007-Jun-21	31	32216	1	1000	100000	10000	50000	20000	0.000315	0.000194	0.000632	0.000152
2007-Jun-21	31	32217	1	1000	100000	10000	50000	20000	0.000373	0.000218	0.000709	0.000171
2007-Jun-21	31	32218	1	1000	100000	10000	50000	20000	0.000321	0.000190	0.000619	0.000149
2007-Jun-21	31	32219	1	1000	100000	10000	50000	20000	0.000276	0.000168	0.000564	0.000128
2007-Jun-21	31	32220	1	1000	100000	10000	50000	20000	0.000288	0.000176	0.000608	0.000132
2007-Jun-21	31	32221	1	1000	100000	10000	50000	20000	0.000232	0.000150	0.000526	0.000108
2007-Jun-21	31	32222	1	1000	100000	10000	50000	20000	0.000327	0.000196	0.000674	0.000149
2007-Jun-21	31	32223	1	1000	100000	10000	50000	20000	0.000346	0.000205	0.000676	0.000159
2007-Jun-21	31	32224	1	1000	100000	10000	50000	20000	0.000367	0.000220	0.000698	0.000176
2007-Jun-21	31	32225	1	1000	100000	10000	50000	20000	0.000330	0.000200	0.000640	0.000159
2007-Jun-21	31	32226	1	1000	100000	10000	50000	20000	0.000189	0.000125	0.000428	0.000092
2007-Jun-21	31	32227	1	1000	100000	10000	50000	20000	0.000917	0.000514	0.000942	0.000483
2007-Jun-21	31	32228	1	1000	100000	10000	50000	20000	0.000539	0.000296	0.000812	0.000256
2007-Jun-21	31	32229	1	1000	100000	10000	50000	20000	0.000233	0.000145	0.000493	0.000108
2007-Jun-21	31	32231	1	1000	100000	10000	50000	20000	0.000345	0.000203	0.000661	0.000159
2007-Jun-21	31	32232	1	1000	100000	10000	50000	20000	0.000295	0.000178	0.000589	0.000137
2007-Jun-21	31	32233	1	1000	100000	10000	50000	20000	0.000505	0.000288	0.000799	0.000248

2007-Jun-21	31	32234	1	1000	100000	10000	50000	20000	0.000207	0.000136	0.000480	0.000096
2007-Jun-21	31	32235	1	1000	100000	10000	50000	20000	0.000338	0.000198	0.000639	0.000156
2007-Jun-21	31	32236	1	1000	100000	10000	50000	20000	0.000289	0.000176	0.000602	0.000133
2007-Jun-21	31	32237	1	1000	100000	10000	50000	20000	0.000340	0.000202	0.000663	0.000157
2007-Jun-21	31	32238	1	1000	100000	10000	50000	20000	0.000316	0.000191	0.000641	0.000146
2007-Jun-21	31	32239	1	1000	100000	10000	50000	20000	0.000343	0.000202	0.000648	0.000159
2007-Jun-21	31	32240	1	1000	100000	10000	50000	20000	0.000468	0.000262	0.000752	0.000221
2007-Jun-21	31	32241	1	1000	100000	10000	50000	20000	0.000330	0.000198	0.000662	0.000152
2007-Jun-21	31	32244	1	1000	100000	10000	50000	20000	0.000271	0.000167	0.000568	0.000125
2007-Jun-21	31	32245	1	1000	100000	10000	50000	20000	0.000334	0.000198	0.000643	0.000155
2007-Jun-21	31	32246	1	1000	100000	10000	50000	20000	0.000324	0.000197	0.000628	0.000156
2007-Jun-21	31	32247	1	1000	100000	10000	50000	20000	0.000345	0.000203	0.000661	0.000159
2007-Jun-21	31	32250	1	1000	100000	10000	50000	20000	0.000382	0.000226	0.000697	0.000184
2007-Jun-21	31	32254	1	1000	100000	10000	50000	20000	0.000339	0.000200	0.000663	0.000156
2007-Jun-21	31	32255	1	1000	100000	10000	50000	20000	0.000365	0.000213	0.000669	0.000170
2007-Jun-21	31	32256	1	1000	100000	10000	50000	20000	0.000380	0.000227	0.000719	0.000182
2007-Jun-21	31	32257	1	1000	100000	10000	50000	20000	0.000360	0.000212	0.000697	0.000165
2007-Jun-21	31	32258	1	1000	100000	10000	50000	20000	0.000341	0.000203	0.000669	0.000157
2007-Jun-21	31	32266	1	1000	100000	10000	50000	20000	0.000408	0.000239	0.000713	0.000198
2007-Jun-21	31	32267	1	1000	100000	10000	50000	20000	0.000507	0.000281	0.000797	0.000240
2007-Jun-21	31	32276	1	1000	100000	10000	50000	20000	0.000294	0.000177	0.000588	0.000136
2007-Jun-21	31	32277	1	1000	100000	10000	50000	20000	0.000346	0.000208	0.000662	0.000167
2007-Jun-21	31	32290	1	1000	100000	10000	50000	20000	0.000252	0.000157	0.000534	0.000117
2007-Jun-21	31	32099	2	1000	100000	10000	50000	20000	0.000191	0.000133	0.000466	0.000097
2007-Jun-21	31	32201	2	1000	100000	10000	50000	20000	0.000226	0.000153	0.000534	0.000114
2007-Jun-21	31	32202	2	1000	100000	10000	50000	20000	0.000230	0.000155	0.000539	0.000116
2007-Jun-21	31	32203	2	1000	100000	10000	50000	20000	0.000263	0.000172	0.000588	0.000132
2007-Jun-21	31	32204	2	1000	100000	10000	50000	20000	0.000288	0.000187	0.000645	0.000143
2007-Jun-21	31	32205	2	1000	100000	10000	50000	20000	0.000317	0.000202	0.000691	0.000157
2007-Jun-21	31	32206	2	1000	100000	10000	50000	20000	0.000274	0.000178	0.000612	0.000137
2007-Jun-21	31	32207	2	1000	100000	10000	50000	20000	0.000308	0.000196	0.000664	0.000153
2007-Jun-21	31	32208	2	1000	100000	10000	50000	20000	0.000328	0.000205	0.000684	0.000163
2007-Jun-21	31	32209	2	1000	100000	10000	50000	20000	0.000305	0.000194	0.000660	0.000151
2007-Jun-21	31	32210	2	1000	100000	10000	50000	20000	0.000303	0.000195	0.000677	0.000150
2007-Jun-21	31	32211	2	1000	100000	10000	50000	20000	0.000291	0.000192	0.000642	0.000151
2007-Jun-21	31	32212	2	1000	100000	10000	50000	20000	0.000341	0.000214	0.000726	0.000169
2007-Jun-21	31	32214	2	1000	100000	10000	50000	20000	0.000300	0.000194	0.000670	0.000149

2007-Jun-21	31	32215	2	1000	100000	10000	50000	20000	0.000137	0.000105	0.000374	0.000072
2007-Jun-21	31	32216	2	1000	100000	10000	50000	20000	0.000280	0.000187	0.000631	0.000145
2007-Jun-21	31	32217	2	1000	100000	10000	50000	20000	0.000331	0.000209	0.000708	0.000164
2007-Jun-21	31	32218	2	1000	100000	10000	50000	20000	0.000285	0.000183	0.000618	0.000142
2007-Jun-21	31	32219	2	1000	100000	10000	50000	20000	0.000246	0.000163	0.000563	0.000123
2007-Jun-21	31	32220	2	1000	100000	10000	50000	20000	0.000258	0.000172	0.000607	0.000128
2007-Jun-21	31	32221	2	1000	100000	10000	50000	20000	0.000209	0.000147	0.000526	0.000106
2007-Jun-21	31	32222	2	1000	100000	10000	50000	20000	0.000292	0.000191	0.000673	0.000144
2007-Jun-21	31	32223	2	1000	100000	10000	50000	20000	0.000308	0.000198	0.000675	0.000153
2007-Jun-21	31	32224	2	1000	100000	10000	50000	20000	0.000324	0.000210	0.000697	0.000167
2007-Jun-21	31	32225	2	1000	100000	10000	50000	20000	0.000292	0.000191	0.000639	0.000151
2007-Jun-21	31	32226	2	1000	100000	10000	50000	20000	0.000170	0.000122	0.000428	0.000089
2007-Jun-21	31	32227	2	1000	100000	10000	50000	20000	0.000777	0.000441	0.000940	0.000419
2007-Jun-21	31	32228	2	1000	100000	10000	50000	20000	0.000469	0.000273	0.000811	0.000236
2007-Jun-21	31	32229	2	1000	100000	10000	50000	20000	0.000209	0.000141	0.000492	0.000105
2007-Jun-21	31	32231	2	1000	100000	10000	50000	20000	0.000306	0.000195	0.000660	0.000153
2007-Jun-21	31	32232	2	1000	100000	10000	50000	20000	0.000263	0.000172	0.000588	0.000132
2007-Jun-21	31	32233	2	1000	100000	10000	50000	20000	0.000440	0.000266	0.000797	0.000228
2007-Jun-21	31	32234	2	1000	100000	10000	50000	20000	0.000187	0.000134	0.000479	0.000095
2007-Jun-21	31	32235	2	1000	100000	10000	50000	20000	0.000300	0.000190	0.000638	0.000149
2007-Jun-21	31	32236	2	1000	100000	10000	50000	20000	0.000259	0.000171	0.000601	0.000129
2007-Jun-21	31	32237	2	1000	100000	10000	50000	20000	0.000302	0.000194	0.000662	0.000150
2007-Jun-21	31	32238	2	1000	100000	10000	50000	20000	0.000282	0.000185	0.000640	0.000141
2007-Jun-21	31	32239	2	1000	100000	10000	50000	20000	0.000304	0.000193	0.000647	0.000152
2007-Jun-21	31	32240	2	1000	100000	10000	50000	20000	0.000409	0.000245	0.000750	0.000206
2007-Jun-21	31	32241	2	1000	100000	10000	50000	20000	0.000295	0.000192	0.000661	0.000147
2007-Jun-21	31	32244	2	1000	100000	10000	50000	20000	0.000242	0.000163	0.000568	0.000122
2007-Jun-21	31	32245	2	1000	100000	10000	50000	20000	0.000297	0.000190	0.000642	0.000148
2007-Jun-21	31	32246	2	1000	100000	10000	50000	20000	0.000286	0.000188	0.000627	0.000148
2007-Jun-21	31	32247	2	1000	100000	10000	50000	20000	0.000306	0.000195	0.000660	0.000153
2007-Jun-21	31	32250	2	1000	100000	10000	50000	20000	0.000336	0.000214	0.000696	0.000174
2007-Jun-21	31	32254	2	1000	100000	10000	50000	20000	0.000302	0.000193	0.000662	0.000150
2007-Jun-21	31	32255	2	1000	100000	10000	50000	20000	0.000323	0.000203	0.000668	0.000162
2007-Jun-21	31	32256	2	1000	100000	10000	50000	20000	0.000335	0.000216	0.000718	0.000173
2007-Jun-21	31	32257	2	1000	100000	10000	50000	20000	0.000320	0.000204	0.000696	0.000159
2007-Jun-21	31	32258	2	1000	100000	10000	50000	20000	0.000304	0.000196	0.000668	0.000151
2007-Jun-21	31	32266	2	1000	100000	10000	50000	20000	0.000358	0.000224	0.000712	0.000185

2007-Jun-21	31	32267	2	1000	100000	10000	50000	20000	0.000443	0.000261	0.000795	0.000222
2007-Jun-21	31	32276	2	1000	100000	10000	50000	20000	0.000262	0.000171	0.000587	0.000131
2007-Jun-21	31	32277	2	1000	100000	10000	50000	20000	0.000306	0.000199	0.000660	0.000158
2007-Jun-21	31	32290	2	1000	100000	10000	50000	20000	0.000226	0.000153	0.000533	0.000114
2007-Jun-21	31	32099	3	1000	100000	10000	50000	20000	0.001706	0.000520	0.000478	0.000482
2007-Jun-21	31	32201	3	1000	100000	10000	50000	20000	0.002041	0.000638	0.000548	0.000599
2007-Jun-21	31	32202	3	1000	100000	10000	50000	20000	0.002083	0.000656	0.000553	0.000618
2007-Jun-21	31	32203	3	1000	100000	10000	50000	20000	0.002418	0.000802	0.000603	0.000767
2007-Jun-21	31	32204	3	1000	100000	10000	50000	20000	0.002685	0.000877	0.000662	0.000842
2007-Jun-21	31	32205	3	1000	100000	10000	50000	20000	0.002996	0.001011	0.000710	0.000979
2007-Jun-21	31	32206	3	1000	100000	10000	50000	20000	0.002527	0.000833	0.000628	0.000798
2007-Jun-21	31	32207	3	1000	100000	10000	50000	20000	0.002867	0.000973	0.000681	0.000940
2007-Jun-21	31	32208	3	1000	100000	10000	50000	20000	0.003055	0.001070	0.000703	0.001039
2007-Jun-21	31	32209	3	1000	100000	10000	50000	20000	0.002845	0.000966	0.000678	0.000933
2007-Jun-21	31	32210	3	1000	100000	10000	50000	20000	0.002856	0.000941	0.000695	0.000907
2007-Jun-21	31	32211	3	1000	100000	10000	50000	20000	0.002777	0.000958	0.000660	0.000924
2007-Jun-21	31	32212	3	1000	100000	10000	50000	20000	0.003217	0.001104	0.000745	0.001072
2007-Jun-21	31	32214	3	1000	100000	10000	50000	20000	0.002799	0.000917	0.000687	0.000881
2007-Jun-21	31	32215	3	1000	100000	10000	50000	20000	0.001126	0.000291	0.000382	0.000247
2007-Jun-21	31	32216	3	1000	100000	10000	50000	20000	0.002670	0.000897	0.000648	0.000862
2007-Jun-21	31	32217	3	1000	100000	10000	50000	20000	0.003099	0.001053	0.000727	0.001022
2007-Jun-21	31	32218	3	1000	100000	10000	50000	20000	0.002640	0.000904	0.000634	0.000871
2007-Jun-21	31	32219	3	1000	100000	10000	50000	20000	0.002276	0.000744	0.000577	0.000709
2007-Jun-21	31	32220	3	1000	100000	10000	50000	20000	0.002423	0.000752	0.000623	0.000717
2007-Jun-21	31	32221	3	1000	100000	10000	50000	20000	0.001897	0.000539	0.000539	0.000498
2007-Jun-21	31	32222	3	1000	100000	10000	50000	20000	0.002784	0.000883	0.000691	0.000849
2007-Jun-21	31	32223	3	1000	100000	10000	50000	20000	0.002846	0.000945	0.000693	0.000910
2007-Jun-21	31	32224	3	1000	100000	10000	50000	20000	0.003121	0.001096	0.000716	0.001065
2007-Jun-21	31	32225	3	1000	100000	10000	50000	20000	0.002795	0.000973	0.000656	0.000942
2007-Jun-21	31	32226	3	1000	100000	10000	50000	20000	0.001587	0.000489	0.000439	0.000455
2007-Jun-21	31	32227	3	1000	100000	10000	50000	20000	0.005925	0.002824	0.000964	0.002771
2007-Jun-21	31	32228	3	1000	100000	10000	50000	20000	0.004229	0.001700	0.000833	0.001676
2007-Jun-21	31	32229	3	1000	100000	10000	50000	20000	0.001901	0.000610	0.000504	0.000575
2007-Jun-21	31	32231	3	1000	100000	10000	50000	20000	0.002843	0.000963	0.000678	0.000930
2007-Jun-21	31	32232	3	1000	100000	10000	50000	20000	0.002418	0.000802	0.000603	0.000767
2007-Jun-21	31	32233	3	1000	100000	10000	50000	20000	0.004063	0.001618	0.000819	0.001589
2007-Jun-21	31	32234	3	1000	100000	10000	50000	20000	0.001672	0.000467	0.000491	0.000427

2007-Jun-21	31	32235	3	1000	100000	10000	50000	20000	0.002760	0.000951	0.000655	0.000919
2007-Jun-21	31	32236	3	1000	100000	10000	50000	20000	0.002399	0.000759	0.000617	0.000723
2007-Jun-21	31	32237	3	1000	100000	10000	50000	20000	0.002787	0.000930	0.000679	0.000893
2007-Jun-21	31	32238	3	1000	100000	10000	50000	20000	0.002629	0.000846	0.000657	0.000809
2007-Jun-21	31	32239	3	1000	100000	10000	50000	20000	0.002797	0.000961	0.000664	0.000928
2007-Jun-21	31	32240	3	1000	100000	10000	50000	20000	0.003687	0.001420	0.000771	0.001391
2007-Jun-21	31	32241	3	1000	100000	10000	50000	20000	0.002714	0.000880	0.000678	0.000842
2007-Jun-21	31	32244	3	1000	100000	10000	50000	20000	0.002223	0.000700	0.000582	0.000662
2007-Jun-21	31	32245	3	1000	100000	10000	50000	20000	0.002732	0.000921	0.000659	0.000887
2007-Jun-21	31	32246	3	1000	100000	10000	50000	20000	0.002735	0.000948	0.000644	0.000915
2007-Jun-21	31	32247	3	1000	100000	10000	50000	20000	0.002843	0.000963	0.000678	0.000930
2007-Jun-21	31	32250	3	1000	100000	10000	50000	20000	0.003194	0.001162	0.000715	0.001131
2007-Jun-21	31	32254	3	1000	100000	10000	50000	20000	0.002828	0.000952	0.000680	0.000919
2007-Jun-21	31	32255	3	1000	100000	10000	50000	20000	0.002959	0.001048	0.000685	0.001014
2007-Jun-21	31	32256	3	1000	100000	10000	50000	20000	0.003213	0.001129	0.000738	0.001097
2007-Jun-21	31	32257	3	1000	100000	10000	50000	20000	0.002971	0.000985	0.000715	0.000950
2007-Jun-21	31	32258	3	1000	100000	10000	50000	20000	0.002797	0.000923	0.000686	0.000886
2007-Jun-21	31	32266	3	1000	100000	10000	50000	20000	0.003371	0.001263	0.000731	0.001233
2007-Jun-21	31	32267	3	1000	100000	10000	50000	20000	0.004014	0.001586	0.000817	0.001558
2007-Jun-21	31	32276	3	1000	100000	10000	50000	20000	0.002416	0.000799	0.000603	0.000764
2007-Jun-21	31	32277	3	1000	100000	10000	50000	20000	0.002924	0.001028	0.000679	0.000995
2007-Jun-21	31	32290	3	1000	100000	10000	50000	20000	0.002038	0.000640	0.000546	0.000601
2007-Jun-21	33	32501	1	1000	100000	10000	50000	20000	0.001489	0.000753	0.001731	0.000736
2007-Jun-21	33	32502	1	1000	100000	10000	50000	20000	0.002029	0.001046	0.001894	0.001045
2007-Jun-21	33	32503	1	1000	100000	10000	50000	20000	0.002556	0.001369	0.002033	0.001364
2007-Jun-21	33	32504	1	1000	100000	10000	50000	20000	0.001482	0.000748	0.001712	0.000732
2007-Jun-21	33	32505	1	1000	100000	10000	50000	20000	0.001592	0.000804	0.001768	0.000793
2007-Jun-21	33	32506	1	1000	100000	10000	50000	20000	0.001634	0.000825	0.001793	0.000815
2007-Jun-21	33	32507	1	1000	100000	10000	50000	20000	0.002236	0.001166	0.001971	0.001165
2007-Jun-21	33	32508	1	1000	100000	10000	50000	20000	0.001926	0.000973	0.001949	0.000972
2007-Jun-21	33	32509	1	1000	100000	10000	50000	20000	0.001289	0.000656	0.001574	0.000634
2007-Jun-21	33	32511	1	1000	100000	10000	50000	20000	0.001627	0.000827	0.001765	0.000815
2007-Jun-21	33	32512	1	1000	100000	10000	50000	20000	0.001597	0.000809	0.001764	0.000797
2007-Jun-21	33	32513	1	1000	100000	10000	50000	20000	0.001947	0.000997	0.001900	0.000994
2007-Jun-21	33	32514	1	1000	100000	10000	50000	20000	0.001445	0.000732	0.001669	0.000715
2007-Jun-21	33	32516	1	1000	100000	10000	50000	20000	0.001863	0.000950	0.001876	0.000945
2007-Jun-21	33	32520	1	1000	100000	10000	50000	20000	0.001717	0.000870	0.001830	0.000861

2007-Jun-21	33	32521	1	1000	100000	10000	50000	20000	0.003694	0.001998	0.002488	0.002012
2007-Jun-21	33	32522	1	1000	100000	10000	50000	20000	0.001674	0.000854	0.001772	0.000844
2007-Jun-21	33	32523	1	1000	100000	10000	50000	20000	0.001556	0.000787	0.001752	0.000773
2007-Jun-21	33	32524	1	1000	100000	10000	50000	20000	0.001556	0.000787	0.001752	0.000773
2007-Jun-21	33	32526	1	1000	100000	10000	50000	20000	0.001377	0.000699	0.001641	0.000679
2007-Jun-21	33	32533	1	1000	100000	10000	50000	20000	0.001329	0.000671	0.001610	0.000651
2007-Jun-21	33	32534	1	1000	100000	10000	50000	20000	0.001421	0.000717	0.001671	0.000701
2007-Jun-21	33	32535	1	1000	100000	10000	50000	20000	0.000733	0.000379	0.001179	0.000340
2007-Jun-21	33	32559	1	1000	100000	10000	50000	20000	0.001289	0.000656	0.001574	0.000634
2007-Jun-21	33	32560	1	1000	100000	10000	50000	20000	0.001232	0.000626	0.001530	0.000603
2007-Jun-21	33	32568	1	1000	100000	10000	50000	20000	0.001181	0.000598	0.001472	0.000577
2007-Jun-21	33	32577	1	1000	100000	10000	50000	20000	0.001466	0.000739	0.001653	0.000728
2007-Jun-21	33	32591	1	1000	100000	10000	50000	20000	0.001556	0.000787	0.001752	0.000773
2007-Jun-21	33	32501	2	1000	100000	10000	50000	20000	0.001271	0.000673	0.001727	0.000662
2007-Jun-21	33	32502	2	1000	100000	10000	50000	20000	0.001717	0.000904	0.001890	0.000918
2007-Jun-21	33	32503	2	1000	100000	10000	50000	20000	0.002144	0.001139	0.002028	0.001163
2007-Jun-21	33	32504	2	1000	100000	10000	50000	20000	0.001265	0.000668	0.001708	0.000659
2007-Jun-21	33	32505	2	1000	100000	10000	50000	20000	0.001357	0.000715	0.001764	0.000710
2007-Jun-21	33	32506	2	1000	100000	10000	50000	20000	0.001392	0.000733	0.001789	0.000730
2007-Jun-21	33	32507	2	1000	100000	10000	50000	20000	0.001887	0.000993	0.001966	0.001012
2007-Jun-21	33	32508	2	1000	100000	10000	50000	20000	0.001635	0.000854	0.001944	0.000864
2007-Jun-21	33	32509	2	1000	100000	10000	50000	20000	0.001104	0.000591	0.001571	0.000573
2007-Jun-21	33	32511	2	1000	100000	10000	50000	20000	0.001386	0.000732	0.001761	0.000728
2007-Jun-21	33	32512	2	1000	100000	10000	50000	20000	0.001361	0.000719	0.001760	0.000714
2007-Jun-21	33	32513	2	1000	100000	10000	50000	20000	0.001651	0.000867	0.001896	0.000877
2007-Jun-21	33	32514	2	1000	100000	10000	50000	20000	0.001233	0.000653	0.001666	0.000643
2007-Jun-21	33	32516	2	1000	100000	10000	50000	20000	0.001581	0.000831	0.001872	0.000837
2007-Jun-21	33	32520	2	1000	100000	10000	50000	20000	0.001461	0.000768	0.001826	0.000768
2007-Jun-21	33	32521	2	1000	100000	10000	50000	20000	0.003081	0.001627	0.002481	0.001690
2007-Jun-21	33	32522	2	1000	100000	10000	50000	20000	0.001425	0.000752	0.001768	0.000751
2007-Jun-21	33	32523	2	1000	100000	10000	50000	20000	0.001327	0.000700	0.001748	0.000693
2007-Jun-21	33	32524	2	1000	100000	10000	50000	20000	0.001327	0.000700	0.001748	0.000693
2007-Jun-21	33	32526	2	1000	100000	10000	50000	20000	0.001178	0.000628	0.001638	0.000613
2007-Jun-21	33	32533	2	1000	100000	10000	50000	20000	0.001136	0.000603	0.001607	0.000588
2007-Jun-21	33	32534	2	1000	100000	10000	50000	20000	0.001214	0.000642	0.001667	0.000631
2007-Jun-21	33	32535	2	1000	100000	10000	50000	20000	0.000635	0.000354	0.001177	0.000316
2007-Jun-21	33	32559	2	1000	100000	10000	50000	20000	0.001104	0.000591	0.001571	0.000573

2007-Jun-21	33	32560	2	1000	100000	10000	50000	20000	0.001055	0.000565	0.001527	0.000545
2007-Jun-21	33	32568	2	1000	100000	10000	50000	20000	0.001011	0.000539	0.001469	0.000522
2007-Jun-21	33	32577	2	1000	100000	10000	50000	20000	0.001250	0.000658	0.001649	0.000653
2007-Jun-21	33	32591	2	1000	100000	10000	50000	20000	0.001327	0.000700	0.001748	0.000693
2007-Jun-21	33	32501	3	1000	100000	10000	50000	20000	0.011806	0.005590	0.001776	0.005639
2007-Jun-21	33	32502	3	1000	100000	10000	50000	20000	0.013957	0.007053	0.001940	0.007064
2007-Jun-21	33	32503	3	1000	100000	10000	50000	20000	0.015620	0.008116	0.002081	0.008095
2007-Jun-21	33	32504	3	1000	100000	10000	50000	20000	0.011749	0.005583	0.001756	0.005635
2007-Jun-21	33	32505	3	1000	100000	10000	50000	20000	0.012315	0.005928	0.001813	0.005974
2007-Jun-21	33	32506	3	1000	100000	10000	50000	20000	0.012548	0.006068	0.001838	0.006112
2007-Jun-21	33	32507	3	1000	100000	10000	50000	20000	0.014785	0.007513	0.002019	0.007525
2007-Jun-21	33	32508	3	1000	100000	10000	50000	20000	0.014161	0.007020	0.001997	0.007059
2007-Jun-21	33	32509	3	1000	100000	10000	50000	20000	0.010399	0.004830	0.001615	0.004873
2007-Jun-21	33	32511	3	1000	100000	10000	50000	20000	0.012277	0.005925	0.001810	0.005963
2007-Jun-21	33	32512	3	1000	100000	10000	50000	20000	0.012229	0.005880	0.001809	0.005922
2007-Jun-21	33	32513	3	1000	100000	10000	50000	20000	0.013866	0.006916	0.001947	0.006942
2007-Jun-21	33	32514	3	1000	100000	10000	50000	20000	0.011379	0.005396	0.001712	0.005443
2007-Jun-21	33	32516	3	1000	100000	10000	50000	20000	0.013511	0.006677	0.001923	0.006709
2007-Jun-21	33	32520	3	1000	100000	10000	50000	20000	0.012940	0.006303	0.001876	0.006342
2007-Jun-21	33	32521	3	1000	100000	10000	50000	20000	0.020697	0.011265	0.002543	0.011203
2007-Jun-21	33	32522	3	1000	100000	10000	50000	20000	0.012460	0.006071	0.001816	0.006103
2007-Jun-21	33	32523	3	1000	100000	10000	50000	20000	0.012129	0.005812	0.001797	0.005858
2007-Jun-21	33	32524	3	1000	100000	10000	50000	20000	0.012129	0.005812	0.001797	0.005858
2007-Jun-21	33	32526	3	1000	100000	10000	50000	20000	0.010988	0.005140	0.001684	0.005185
2007-Jun-21	33	32533	3	1000	100000	10000	50000	20000	0.010798	0.005040	0.001652	0.005092
2007-Jun-21	33	32534	3	1000	100000	10000	50000	20000	0.011379	0.005378	0.001714	0.005430
2007-Jun-21	33	32535	3	1000	100000	10000	50000	20000	0.006865	0.002812	0.001212	0.002865
2007-Jun-21	33	32559	3	1000	100000	10000	50000	20000	0.010399	0.004830	0.001615	0.004873
2007-Jun-21	33	32560	3	1000	100000	10000	50000	20000	0.010062	0.004642	0.001570	0.004686
2007-Jun-21	33	32568	3	1000	100000	10000	50000	20000	0.009749	0.004523	0.001511	0.004574
2007-Jun-21	33	32577	3	1000	100000	10000	50000	20000	0.011467	0.005520	0.001695	0.005566
2007-Jun-21	33	32591	3	1000	100000	10000	50000	20000	0.012129	0.005812	0.001797	0.005858
2007-Jun-21	35	32110	1	1000	100000	10000	50000	20000	0.002136	0.000372	0.001062	0.000282
2007-Jun-21	35	32135	1	1000	100000	10000	50000	20000	0.002760	0.000657	0.001353	0.000568
2007-Jun-21	35	32136	1	1000	100000	10000	50000	20000	0.002935	0.000706	0.001438	0.000614
2007-Jun-21	35	32137	1	1000	100000	10000	50000	20000	0.002353	0.000503	0.001181	0.000417
2007-Jun-21	35	32142	1	1000	100000	10000	50000	20000	0.002760	0.000657	0.001353	0.000568

2007-Jun-21	35	32164	1	1000	100000	10000	50000	20000	0.002129	0.000404	0.001094	0.000316
2007-Jun-21	35	32110	2	1000	100000	10000	50000	20000	0.001792	0.000326	0.001059	0.000236
2007-Jun-21	35	32135	2	1000	100000	10000	50000	20000	0.002262	0.000523	0.001349	0.000441
2007-Jun-21	35	32136	2	1000	100000	10000	50000	20000	0.002402	0.000559	0.001434	0.000475
2007-Jun-21	35	32137	2	1000	100000	10000	50000	20000	0.001950	0.000415	0.001178	0.000332
2007-Jun-21	35	32142	2	1000	100000	10000	50000	20000	0.002262	0.000523	0.001349	0.000441
2007-Jun-21	35	32164	2	1000	100000	10000	50000	20000	0.001785	0.000347	0.001091	0.000260
2007-Jun-21	35	32110	3	1000	100000	10000	50000	20000	0.008676	0.002728	0.001078	0.002828
2007-Jun-21	35	32135	3	1000	100000	10000	50000	20000	0.012806	0.005196	0.001373	0.005352
2007-Jun-21	35	32136	3	1000	100000	10000	50000	20000	0.013782	0.005674	0.001459	0.005854
2007-Jun-21	35	32137	3	1000	100000	10000	50000	20000	0.010521	0.003900	0.001199	0.004020
2007-Jun-21	35	32142	3	1000	100000	10000	50000	20000	0.012806	0.005196	0.001373	0.005352
2007-Jun-21	35	32164	3	1000	100000	10000	50000	20000	0.009204	0.003072	0.001110	0.003183
2007-Jun-21	37	32320	1	1000	100000	10000	50000	20000	0.000957	0.000505	0.001267	0.000469
2007-Jun-21	37	32322	1	1000	100000	10000	50000	20000	0.002331	0.001292	0.001743	0.001272
2007-Jun-21	37	32323	1	1000	100000	10000	50000	20000	0.001838	0.001004	0.001553	0.000984
2007-Jun-21	37	32328	1	1000	100000	10000	50000	20000	0.001374	0.000726	0.001456	0.000703
2007-Jun-21	37	32329	1	1000	100000	10000	50000	20000	0.001356	0.000707	0.001507	0.000683
2007-Jun-21	37	32320	2	1000	100000	10000	50000	20000	0.000822	0.000456	0.001265	0.000425
2007-Jun-21	37	32322	2	1000	100000	10000	50000	20000	0.001947	0.001056	0.001739	0.001068
2007-Jun-21	37	32323	2	1000	100000	10000	50000	20000	0.001544	0.000838	0.001550	0.000839
2007-Jun-21	37	32328	2	1000	100000	10000	50000	20000	0.001168	0.000633	0.001453	0.000619
2007-Jun-21	37	32329	2	1000	100000	10000	50000	20000	0.001156	0.000623	0.001504	0.000607
2007-Jun-21	37	32320	3	1000	100000	10000	50000	20000	0.007344	0.003203	0.001300	0.003215
2007-Jun-21	37	32322	3	1000	100000	10000	50000	20000	0.012681	0.006640	0.001782	0.006584
2007-Jun-21	37	32323	3	1000	100000	10000	50000	20000	0.010792	0.005474	0.001589	0.005441
2007-Jun-21	37	32328	3	1000	100000	10000	50000	20000	0.009396	0.004490	0.001492	0.004492
2007-Jun-21	37	32329	3	1000	100000	10000	50000	20000	0.009658	0.004545	0.001545	0.004559
2007-Jun-21	39	32324	1	1000	100000	10000	50000	20000	0.000259	0.000165	0.000588	0.000119
2007-Jun-21	39	32330	1	1000	100000	10000	50000	20000	0.000366	0.000213	0.000748	0.000164
2007-Jun-21	39	32332	1	1000	100000	10000	50000	20000	0.000219	0.000144	0.000508	0.000102
2007-Jun-21	39	32333	1	1000	100000	10000	50000	20000	0.000266	0.000164	0.000570	0.000123
2007-Jun-21	39	32343	1	1000	100000	10000	50000	20000	0.000228	0.000146	0.000512	0.000106
2007-Jun-21	39	32351	1	1000	100000	10000	50000	20000	0.000228	0.000147	0.000519	0.000106
2007-Jun-21	39	32352	1	1000	100000	10000	50000	20000	0.000217	0.000142	0.000504	0.000101
2007-Jun-21	39	32353	1	1000	100000	10000	50000	20000	0.000260	0.000164	0.000575	0.000120
2007-Jun-21	39	32324	2	1000	100000	10000	50000	20000	0.000234	0.000162	0.000587	0.000117

2007-Jun-21	39	32330	2	1000	100000	10000	50000	20000	0.000326	0.000207	0.000747	0.000159
2007-Jun-21	39	32332	2	1000	100000	10000	50000	20000	0.000198	0.000141	0.000507	0.000101
2007-Jun-21	39	32333	2	1000	100000	10000	50000	20000	0.000238	0.000160	0.000569	0.000120
2007-Jun-21	39	32343	2	1000	100000	10000	50000	20000	0.000205	0.000143	0.000512	0.000104
2007-Jun-21	39	32351	2	1000	100000	10000	50000	20000	0.000206	0.000145	0.000518	0.000105
2007-Jun-21	39	32352	2	1000	100000	10000	50000	20000	0.000197	0.000140	0.000503	0.000100
2007-Jun-21	39	32353	2	1000	100000	10000	50000	20000	0.000234	0.000160	0.000574	0.000118
2007-Jun-21	39	32324	3	1000	100000	10000	50000	20000	0.002133	0.000595	0.000603	0.000558
2007-Jun-21	39	32330	3	1000	100000	10000	50000	20000	0.003166	0.001009	0.000767	0.000988
2007-Jun-21	39	32332	3	1000	100000	10000	50000	20000	0.001743	0.000475	0.000520	0.000435
2007-Jun-21	39	32333	3	1000	100000	10000	50000	20000	0.002206	0.000668	0.000584	0.000637
2007-Jun-21	39	32343	3	1000	100000	10000	50000	20000	0.001848	0.000521	0.000525	0.000485
2007-Jun-21	39	32351	3	1000	100000	10000	50000	20000	0.001843	0.000516	0.000531	0.000478
2007-Jun-21	39	32352	3	1000	100000	10000	50000	20000	0.001737	0.000473	0.000516	0.000434
2007-Jun-21	39	32353	3	1000	100000	10000	50000	20000	0.002127	0.000615	0.000589	0.000578
2007-Jun-21	41	32619	1	1000	100000	10000	50000	20000	0.000298	0.000183	0.000614	0.000138
2007-Jun-21	41	32693	1	1000	100000	10000	50000	20000	0.000490	0.000271	0.000869	0.000222
2007-Jun-21	41	32619	2	1000	100000	10000	50000	20000	0.000267	0.000177	0.000613	0.000134
2007-Jun-21	41	32693	2	1000	100000	10000	50000	20000	0.000431	0.000258	0.000868	0.000211
2007-Jun-21	41	32619	3	1000	100000	10000	50000	20000	0.002450	0.000782	0.000629	0.000743
2007-Jun-21	41	32693	3	1000	100000	10000	50000	20000	0.004177	0.001513	0.000892	0.001494
2007-Jun-21	43	33471	1	1000	100000	10000	50000	20000	0.003375	0.000619	0.001665	0.000497
2007-Jun-21	43	33944	1	1000	100000	10000	50000	20000	0.003221	0.000569	0.001596	0.000447
2007-Jun-21	43	33471	2	1000	100000	10000	50000	20000	0.002810	0.000527	0.001661	0.000405
2007-Jun-21	43	33944	2	1000	100000	10000	50000	20000	0.002693	0.000491	0.001592	0.000369
2007-Jun-21	43	33471	3	1000	100000	10000	50000	20000	0.014565	0.005082	0.001689	0.005313
2007-Jun-21	43	33944	3	1000	100000	10000	50000	20000	0.013677	0.004584	0.001619	0.004803
2007-Jun-21	45	32456	1	1000	100000	10000	50000	20000	0.000948	0.000504	0.001334	0.000460
2007-Jun-21	45	32457	1	1000	100000	10000	50000	20000	0.000858	0.000460	0.001264	0.000414
2007-Jun-21	45	32465	1	1000	100000	10000	50000	20000	0.000514	0.000290	0.000945	0.000242
2007-Jun-21	45	32456	2	1000	100000	10000	50000	20000	0.000816	0.000457	0.001331	0.000418
2007-Jun-21	45	32457	2	1000	100000	10000	50000	20000	0.000742	0.000421	0.001261	0.000378
2007-Jun-21	45	32465	2	1000	100000	10000	50000	20000	0.000451	0.000276	0.000943	0.000229
2007-Jun-21	45	32456	3	1000	100000	10000	50000	20000	0.007551	0.003178	0.001369	0.003200
2007-Jun-21	45	32457	3	1000	100000	10000	50000	20000	0.006933	0.002843	0.001298	0.002858
2007-Jun-21	45	32465	3	1000	100000	10000	50000	20000	0.004483	0.001651	0.000970	0.001645
2007-Jun-21	47	32052	1	1000	100000	10000	50000	20000	0.000246	0.000152	0.000525	0.000113

2007-Jun-21	47	32053	1	1000	100000	10000	50000	20000	0.000140	0.000099	0.000347	0.000068
2007-Jun-21	47	32096	1	1000	100000	10000	50000	20000	0.000160	0.000112	0.000392	0.000077
2007-Jun-21	47	32052	2	1000	100000	10000	50000	20000	0.000221	0.000148	0.000524	0.000110
2007-Jun-21	47	32053	2	1000	100000	10000	50000	20000	0.000128	0.000098	0.000347	0.000067
2007-Jun-21	47	32096	2	1000	100000	10000	50000	20000	0.000146	0.000110	0.000391	0.000076
2007-Jun-21	47	32052	3	1000	100000	10000	50000	20000	0.002063	0.000640	0.000538	0.000608
2007-Jun-21	47	32053	3	1000	100000	10000	50000	20000	0.001074	0.000277	0.000355	0.000239
2007-Jun-21	47	32096	3	1000	100000	10000	50000	20000	0.001242	0.000330	0.000401	0.000288
2007-Jun-21	49	33834	1	1000	100000	10000	50000	20000	0.002973	0.000532	0.001479	0.000424
2007-Jun-21	49	33865	1	1000	100000	10000	50000	20000	0.003196	0.000619	0.001582	0.000513
2007-Jun-21	49	33873	1	1000	100000	10000	50000	20000	0.002847	0.000494	0.001416	0.000384
2007-Jun-21	49	33890	1	1000	100000	10000	50000	20000	0.003047	0.000540	0.001511	0.000426
2007-Jun-21	49	33834	2	1000	100000	10000	50000	20000	0.002479	0.000456	0.001476	0.000347
2007-Jun-21	49	33865	2	1000	100000	10000	50000	20000	0.002644	0.000516	0.001578	0.000410
2007-Jun-21	49	33873	2	1000	100000	10000	50000	20000	0.002383	0.000430	0.001412	0.000319
2007-Jun-21	49	33890	2	1000	100000	10000	50000	20000	0.002545	0.000465	0.001507	0.000350
2007-Jun-21	49	33834	3	1000	100000	10000	50000	20000	0.012905	0.004465	0.001501	0.004681
2007-Jun-21	49	33865	3	1000	100000	10000	50000	20000	0.014400	0.005377	0.001606	0.005624
2007-Jun-21	49	33873	3	1000	100000	10000	50000	20000	0.012000	0.003949	0.001436	0.004138
2007-Jun-21	49	33890	3	1000	100000	10000	50000	20000	0.013012	0.004396	0.001534	0.004608
2007-Jun-21	51	33440	1	1000	100000	10000	50000	20000	0.003927	0.000801	0.001922	0.000679
2007-Jun-21	51	33930	1	1000	100000	10000	50000	20000	0.003769	0.000749	0.001864	0.000630
2007-Jun-21	51	33935	1	1000	100000	10000	50000	20000	0.003485	0.000653	0.001726	0.000533
2007-Jun-21	51	33975	1	1000	100000	10000	50000	20000	0.003328	0.000607	0.001652	0.000488
2007-Jun-21	51	33440	2	1000	100000	10000	50000	20000	0.003234	0.000656	0.001917	0.000536
2007-Jun-21	51	33930	2	1000	100000	10000	50000	20000	0.003110	0.000617	0.001859	0.000500
2007-Jun-21	51	33935	2	1000	100000	10000	50000	20000	0.002894	0.000550	0.001722	0.000430
2007-Jun-21	51	33975	2	1000	100000	10000	50000	20000	0.002771	0.000517	0.001648	0.000397
2007-Jun-21	51	33440	3	1000	100000	10000	50000	20000	0.018783	0.007305	0.001949	0.007629
2007-Jun-21	51	33930	3	1000	100000	10000	50000	20000	0.018142	0.006979	0.001892	0.007322
2007-Jun-21	51	33935	3	1000	100000	10000	50000	20000	0.016179	0.005857	0.001752	0.006148
2007-Jun-21	51	33975	3	1000	100000	10000	50000	20000	0.015213	0.005344	0.001677	0.005614
2007-Jun-21	53	34601	1	1000	100000	10000	50000	20000	0.002140	0.000378	0.001060	0.000286
2007-Jun-21	53	34602	1	1000	100000	10000	50000	20000	0.001984	0.000328	0.000984	0.000234
2007-Jun-21	53	34603	1	1000	100000	10000	50000	20000	0.001994	0.000340	0.000987	0.000249
2007-Jun-21	53	34604	1	1000	100000	10000	50000	20000	0.002520	0.000482	0.001237	0.000387
2007-Jun-21	53	34605	1	1000	100000	10000	50000	20000	0.001994	0.000340	0.000987	0.000249

2007-Jun-21	53	34606	1	1000	100000	10000	50000	20000	0.002444	0.000475	0.001191	0.000381
2007-Jun-21	53	34607	1	1000	100000	10000	50000	20000	0.002148	0.000385	0.001055	0.000294
2007-Jun-21	53	34608	1	1000	100000	10000	50000	20000	0.002388	0.000455	0.001167	0.000361
2007-Jun-21	53	34609	1	1000	100000	10000	50000	20000	0.002297	0.000442	0.001124	0.000352
2007-Jun-21	53	34611	1	1000	100000	10000	50000	20000	0.002418	0.000475	0.001175	0.000382
2007-Jun-21	53	34613	1	1000	100000	10000	50000	20000	0.002295	0.000428	0.001125	0.000335
2007-Jun-21	53	34614	1	1000	100000	10000	50000	20000	0.002184	0.000406	0.001071	0.000316
2007-Jun-21	53	34636	1	1000	100000	10000	50000	20000	0.002135	0.000366	0.001058	0.000271
2007-Jun-21	53	34661	1	1000	100000	10000	50000	20000	0.002091	0.000353	0.001036	0.000258
2007-Jun-21	53	34601	2	1000	100000	10000	50000	20000	0.001797	0.000331	0.001057	0.000240
2007-Jun-21	53	34602	2	1000	100000	10000	50000	20000	0.001678	0.000296	0.000982	0.000203
2007-Jun-21	53	34603	2	1000	100000	10000	50000	20000	0.001681	0.000303	0.000985	0.000212
2007-Jun-21	53	34604	2	1000	100000	10000	50000	20000	0.002097	0.000407	0.001234	0.000314
2007-Jun-21	53	34605	2	1000	100000	10000	50000	20000	0.001681	0.000303	0.000985	0.000212
2007-Jun-21	53	34606	2	1000	100000	10000	50000	20000	0.002034	0.000400	0.001188	0.000309
2007-Jun-21	53	34607	2	1000	100000	10000	50000	20000	0.001802	0.000335	0.001052	0.000245
2007-Jun-21	53	34608	2	1000	100000	10000	50000	20000	0.001991	0.000386	0.001164	0.000294
2007-Jun-21	53	34609	2	1000	100000	10000	50000	20000	0.001914	0.000375	0.001121	0.000287
2007-Jun-21	53	34611	2	1000	100000	10000	50000	20000	0.002011	0.000399	0.001172	0.000309
2007-Jun-21	53	34613	2	1000	100000	10000	50000	20000	0.001918	0.000366	0.001122	0.000276
2007-Jun-21	53	34614	2	1000	100000	10000	50000	20000	0.001827	0.000349	0.001068	0.000260
2007-Jun-21	53	34636	2	1000	100000	10000	50000	20000	0.001798	0.000324	0.001056	0.000230
2007-Jun-21	53	34661	2	1000	100000	10000	50000	20000	0.001764	0.000315	0.001033	0.000220
2007-Jun-21	53	34601	3	1000	100000	10000	50000	20000	0.008593	0.002674	0.001075	0.002766
2007-Jun-21	53	34602	3	1000	100000	10000	50000	20000	0.007525	0.002065	0.000999	0.002126
2007-Jun-21	53	34603	3	1000	100000	10000	50000	20000	0.007725	0.002231	0.001002	0.002304
2007-Jun-21	53	34604	3	1000	100000	10000	50000	20000	0.010701	0.003731	0.001255	0.003872
2007-Jun-21	53	34605	3	1000	100000	10000	50000	20000	0.007725	0.002231	0.001002	0.002304
2007-Jun-21	53	34606	3	1000	100000	10000	50000	20000	0.010274	0.003571	0.001208	0.003698
2007-Jun-21	53	34607	3	1000	100000	10000	50000	20000	0.008585	0.002685	0.001070	0.002774
2007-Jun-21	53	34608	3	1000	100000	10000	50000	20000	0.009925	0.003368	0.001185	0.003486
2007-Jun-21	53	34609	3	1000	100000	10000	50000	20000	0.009548	0.003258	0.001140	0.003366
2007-Jun-21	53	34611	3	1000	100000	10000	50000	20000	0.010133	0.003531	0.001192	0.003651
2007-Jun-21	53	34613	3	1000	100000	10000	50000	20000	0.009426	0.003117	0.001142	0.003225
2007-Jun-21	53	34614	3	1000	100000	10000	50000	20000	0.008852	0.002875	0.001086	0.002967
2007-Jun-21	53	34636	3	1000	100000	10000	50000	20000	0.008386	0.002484	0.001074	0.002569
2007-Jun-21	53	34661	3	1000	100000	10000	50000	20000	0.008098	0.002329	0.001051	0.002405

2007-Jun-21	55	33825	1	1000	100000	10000	50000	20000	0.002827	0.000477	0.001407	0.000361
2007-Jun-21	55	33826	1	1000	100000	10000	50000	20000	0.002782	0.000463	0.001384	0.000348
2007-Jun-21	55	33852	1	1000	100000	10000	50000	20000	0.003142	0.000551	0.001561	0.000430
2007-Jun-21	55	33857	1	1000	100000	10000	50000	20000	0.003190	0.000559	0.001586	0.000437
2007-Jun-21	55	33862	1	1000	100000	10000	50000	20000	0.002980	0.000507	0.001481	0.000387
2007-Jun-21	55	33870	1	1000	100000	10000	50000	20000	0.002679	0.000437	0.001335	0.000322
2007-Jun-21	55	33871	1	1000	100000	10000	50000	20000	0.002623	0.000424	0.001308	0.000308
2007-Jun-21	55	33872	1	1000	100000	10000	50000	20000	0.002742	0.000450	0.001364	0.000334
2007-Jun-21	55	33875	1	1000	100000	10000	50000	20000	0.002756	0.000454	0.001373	0.000338
2007-Jun-21	55	33876	1	1000	100000	10000	50000	20000	0.002779	0.000460	0.001386	0.000344
2007-Jun-21	55	33960	1	1000	100000	10000	50000	20000	0.003257	0.000582	0.001615	0.000460
2007-Jun-21	55	33825	2	1000	100000	10000	50000	20000	0.002375	0.000420	0.001404	0.000303
2007-Jun-21	55	33826	2	1000	100000	10000	50000	20000	0.002340	0.000410	0.001381	0.000294
2007-Jun-21	55	33852	2	1000	100000	10000	50000	20000	0.002628	0.000477	0.001557	0.000355
2007-Jun-21	55	33857	2	1000	100000	10000	50000	20000	0.002668	0.000484	0.001582	0.000361
2007-Jun-21	55	33862	2	1000	100000	10000	50000	20000	0.002501	0.000445	0.001477	0.000324
2007-Jun-21	55	33870	2	1000	100000	10000	50000	20000	0.002259	0.000391	0.001332	0.000275
2007-Jun-21	55	33871	2	1000	100000	10000	50000	20000	0.002215	0.000381	0.001305	0.000265
2007-Jun-21	55	33872	2	1000	100000	10000	50000	20000	0.002310	0.000401	0.001361	0.000284
2007-Jun-21	55	33875	2	1000	100000	10000	50000	20000	0.002321	0.000404	0.001370	0.000287
2007-Jun-21	55	33876	2	1000	100000	10000	50000	20000	0.002339	0.000408	0.001382	0.000291
2007-Jun-21	55	33960	2	1000	100000	10000	50000	20000	0.002719	0.000500	0.001611	0.000378
2007-Jun-21	55	33825	3	1000	100000	10000	50000	20000	0.011613	0.003639	0.001428	0.003809
2007-Jun-21	55	33826	3	1000	100000	10000	50000	20000	0.011351	0.003504	0.001405	0.003669
2007-Jun-21	55	33852	3	1000	100000	10000	50000	20000	0.013299	0.004418	0.001584	0.004631
2007-Jun-21	55	33857	3	1000	100000	10000	50000	20000	0.013520	0.004500	0.001609	0.004713
2007-Jun-21	55	33862	3	1000	100000	10000	50000	20000	0.012316	0.003910	0.001503	0.004095
2007-Jun-21	55	33870	3	1000	100000	10000	50000	20000	0.010732	0.003189	0.001355	0.003336
2007-Jun-21	55	33871	3	1000	100000	10000	50000	20000	0.010376	0.003005	0.001328	0.003138
2007-Jun-21	55	33872	3	1000	100000	10000	50000	20000	0.011063	0.003334	0.001385	0.003490
2007-Jun-21	55	33875	3	1000	100000	10000	50000	20000	0.011156	0.003385	0.001393	0.003542
2007-Jun-21	55	33876	3	1000	100000	10000	50000	20000	0.011310	0.003468	0.001406	0.003629
2007-Jun-21	55	33960	3	1000	100000	10000	50000	20000	0.013953	0.004751	0.001638	0.004976
2007-Jun-21	57	33503	1	1000	100000	10000	50000	20000	0.002977	0.000613	0.001462	0.000518
2007-Jun-21	57	33508	1	1000	100000	10000	50000	20000	0.002561	0.000494	0.001261	0.000401
2007-Jun-21	57	33509	1	1000	100000	10000	50000	20000	0.002539	0.000481	0.001254	0.000387
2007-Jun-21	57	33510	1	1000	100000	10000	50000	20000	0.002707	0.000530	0.001336	0.000436

2007-Jun-21	57	33511	1	1000	100000	10000	50000	20000	0.002670	0.000513	0.001321	0.000418
2007-Jun-21	57	33527	1	1000	100000	10000	50000	20000	0.002739	0.000526	0.001351	0.000428
2007-Jun-21	57	33530	1	1000	100000	10000	50000	20000	0.002892	0.000559	0.001428	0.000460
2007-Jun-21	57	33534	1	1000	100000	10000	50000	20000	0.002880	0.000601	0.001407	0.000507
2007-Jun-21	57	33547	1	1000	100000	10000	50000	20000	0.002894	0.000575	0.001425	0.000478
2007-Jun-21	57	33548	1	1000	100000	10000	50000	20000	0.002772	0.000568	0.001348	0.000476
2007-Jun-21	57	33549	1	1000	100000	10000	50000	20000	0.002633	0.000521	0.001290	0.000429
2007-Jun-21	57	33550	1	1000	100000	10000	50000	20000	0.002617	0.000504	0.001292	0.000410
2007-Jun-21	57	33556	1	1000	100000	10000	50000	20000	0.002502	0.000477	0.001222	0.000385
2007-Jun-21	57	33558	1	1000	100000	10000	50000	20000	0.002643	0.000530	0.001287	0.000439
2007-Jun-21	57	33559	1	1000	100000	10000	50000	20000	0.002682	0.000533	0.001312	0.000440
2007-Jun-21	57	33563	1	1000	100000	10000	50000	20000	0.002579	0.000455	0.001279	0.000354
2007-Jun-21	57	33564	1	1000	100000	10000	50000	20000	0.002593	0.000468	0.001283	0.000369
2007-Jun-21	57	33565	1	1000	100000	10000	50000	20000	0.002809	0.000531	0.001389	0.000431
2007-Jun-21	57	33566	1	1000	100000	10000	50000	20000	0.002713	0.000506	0.001338	0.000406
2007-Jun-21	57	33567	1	1000	100000	10000	50000	20000	0.002909	0.000560	0.001434	0.000460
2007-Jun-21	57	33568	1	1000	100000	10000	50000	20000	0.002604	0.000505	0.001282	0.000412
2007-Jun-21	57	33569	1	1000	100000	10000	50000	20000	0.002802	0.000572	0.001374	0.000479
2007-Jun-21	57	33570	1	1000	100000	10000	50000	20000	0.002996	0.000684	0.001499	0.000593
2007-Jun-21	57	33571	1	1000	100000	10000	50000	20000	0.002536	0.000491	0.001255	0.000403
2007-Jun-21	57	33572	1	1000	100000	10000	50000	20000	0.002838	0.000580	0.001390	0.000487
2007-Jun-21	57	33573	1	1000	100000	10000	50000	20000	0.002695	0.000538	0.001328	0.000448
2007-Jun-21	57	33575	1	1000	100000	10000	50000	20000	0.002868	0.000594	0.001402	0.000503
2007-Jun-21	57	33583	1	1000	100000	10000	50000	20000	0.002631	0.000496	0.001304	0.000400
2007-Jun-21	57	33584	1	1000	100000	10000	50000	20000	0.002656	0.000507	0.001313	0.000411
2007-Jun-21	57	33586	1	1000	100000	10000	50000	20000	0.003117	0.000687	0.001510	0.000594
2007-Jun-21	57	33587	1	1000	100000	10000	50000	20000	0.002904	0.000573	0.001430	0.000474
2007-Jun-21	57	33592	1	1000	100000	10000	50000	20000	0.002735	0.000537	0.001343	0.000441
2007-Jun-21	57	33594	1	1000	100000	10000	50000	20000	0.002695	0.000522	0.001328	0.000426
2007-Jun-21	57	33595	1	1000	100000	10000	50000	20000	0.002610	0.000498	0.001289	0.000403
2007-Jun-21	57	33598	1	1000	100000	10000	50000	20000	0.003039	0.000661	0.001485	0.000571
2007-Jun-21	57	33601	1	1000	100000	10000	50000	20000	0.002179	0.000394	0.001077	0.000306
2007-Jun-21	57	33602	1	1000	100000	10000	50000	20000	0.002284	0.000419	0.001125	0.000330
2007-Jun-21	57	33603	1	1000	100000	10000	50000	20000	0.002583	0.000506	0.001268	0.000414
2007-Jun-21	57	33604	1	1000	100000	10000	50000	20000	0.002490	0.000486	0.001221	0.000396
2007-Jun-21	57	33605	1	1000	100000	10000	50000	20000	0.002504	0.000485	0.001232	0.000394
2007-Jun-21	57	33606	1	1000	100000	10000	50000	20000	0.003125	0.000765	0.001472	0.000673

2007-Jun-21	57	33607	1	1000	100000	10000	50000	20000	0.002525	0.000500	0.001234	0.000411
2007-Jun-21	57	33608	1	1000	100000	10000	50000	20000	0.003759	0.000967	0.001779	0.000877
2007-Jun-21	57	33609	1	1000	100000	10000	50000	20000	0.002576	0.000531	0.001254	0.000443
2007-Jun-21	57	33610	1	1000	100000	10000	50000	20000	0.002553	0.000502	0.001253	0.000411
2007-Jun-21	57	33611	1	1000	100000	10000	50000	20000	0.002555	0.000517	0.001249	0.000429
2007-Jun-21	57	33612	1	1000	100000	10000	50000	20000	0.002383	0.000457	0.001171	0.000368
2007-Jun-21	57	33613	1	1000	100000	10000	50000	20000	0.002505	0.000478	0.001234	0.000387
2007-Jun-21	57	33614	1	1000	100000	10000	50000	20000	0.002547	0.000513	0.001242	0.000425
2007-Jun-21	57	33615	1	1000	100000	10000	50000	20000	0.002484	0.000529	0.001245	0.000441
2007-Jun-21	57	33616	1	1000	100000	10000	50000	20000	0.002722	0.000589	0.001370	0.000497
2007-Jun-21	57	33617	1	1000	100000	10000	50000	20000	0.002419	0.000450	0.001195	0.000358
2007-Jun-21	57	33618	1	1000	100000	10000	50000	20000	0.002651	0.000534	0.001291	0.000444
2007-Jun-21	57	33619	1	1000	100000	10000	50000	20000	0.002612	0.000497	0.001287	0.000402
2007-Jun-21	57	33620	1	1000	100000	10000	50000	20000	0.002434	0.000461	0.001200	0.000370
2007-Jun-21	57	33621	1	1000	100000	10000	50000	20000	0.002533	0.000499	0.001244	0.000408
2007-Jun-21	57	33622	1	1000	100000	10000	50000	20000	0.002528	0.000502	0.001237	0.000413
2007-Jun-21	57	33623	1	1000	100000	10000	50000	20000	0.002547	0.000506	0.001246	0.000416
2007-Jun-21	57	33624	1	1000	100000	10000	50000	20000	0.002622	0.000530	0.001275	0.000441
2007-Jun-21	57	33625	1	1000	100000	10000	50000	20000	0.002624	0.000530	0.001279	0.000440
2007-Jun-21	57	33626	1	1000	100000	10000	50000	20000	0.002578	0.000584	0.001269	0.000495
2007-Jun-21	57	33629	1	1000	100000	10000	50000	20000	0.002771	0.000592	0.001341	0.000502
2007-Jun-21	57	33630	1	1000	100000	10000	50000	20000	0.002504	0.000495	0.001227	0.000407
2007-Jun-21	57	33631	1	1000	100000	10000	50000	20000	0.002547	0.000506	0.001246	0.000416
2007-Jun-21	57	33633	1	1000	100000	10000	50000	20000	0.002533	0.000510	0.001238	0.000421
2007-Jun-21	57	33634	1	1000	100000	10000	50000	20000	0.002464	0.000479	0.001205	0.000391
2007-Jun-21	57	33635	1	1000	100000	10000	50000	20000	0.002453	0.000514	0.001234	0.000427
2007-Jun-21	57	33637	1	1000	100000	10000	50000	20000	0.002677	0.000530	0.001313	0.000436
2007-Jun-21	57	33647	1	1000	100000	10000	50000	20000	0.002594	0.000498	0.001278	0.000404
2007-Jun-21	57	33650	1	1000	100000	10000	50000	20000	0.002547	0.000506	0.001246	0.000416
2007-Jun-21	57	33655	1	1000	100000	10000	50000	20000	0.002254	0.000411	0.001111	0.000322
2007-Jun-21	57	33660	1	1000	100000	10000	50000	20000	0.002525	0.000491	0.001243	0.000399
2007-Jun-21	57	33661	1	1000	100000	10000	50000	20000	0.002525	0.000491	0.001243	0.000399
2007-Jun-21	57	33662	1	1000	100000	10000	50000	20000	0.002525	0.000491	0.001243	0.000399
2007-Jun-21	57	33663	1	1000	100000	10000	50000	20000	0.002523	0.000499	0.001236	0.000410
2007-Jun-21	57	33664	1	1000	100000	10000	50000	20000	0.002547	0.000506	0.001246	0.000416
2007-Jun-21	57	33672	1	1000	100000	10000	50000	20000	0.002239	0.000403	0.001107	0.000314
2007-Jun-21	57	33673	1	1000	100000	10000	50000	20000	0.002507	0.000484	0.001232	0.000394

2007-Jun-21	57	33674	1	1000	100000	10000	50000	20000	0.002616	0.000524	0.001279	0.000433
2007-Jun-21	57	33675	1	1000	100000	10000	50000	20000	0.002274	0.000415	0.001125	0.000325
2007-Jun-21	57	33677	1	1000	100000	10000	50000	20000	0.002367	0.000449	0.001167	0.000360
2007-Jun-21	57	33679	1	1000	100000	10000	50000	20000	0.002529	0.000512	0.001233	0.000423
2007-Jun-21	57	33680	1	1000	100000	10000	50000	20000	0.002314	0.000427	0.001142	0.000337
2007-Jun-21	57	33681	1	1000	100000	10000	50000	20000	0.002478	0.000469	0.001218	0.000377
2007-Jun-21	57	33682	1	1000	100000	10000	50000	20000	0.002344	0.000430	0.001157	0.000339
2007-Jun-21	57	33684	1	1000	100000	10000	50000	20000	0.002441	0.000487	0.001191	0.000401
2007-Jun-21	57	33685	1	1000	100000	10000	50000	20000	0.002368	0.000447	0.001162	0.000359
2007-Jun-21	57	33686	1	1000	100000	10000	50000	20000	0.002858	0.000609	0.001386	0.000517
2007-Jun-21	57	33687	1	1000	100000	10000	50000	20000	0.002489	0.000472	0.001230	0.000380
2007-Jun-21	57	33688	1	1000	100000	10000	50000	20000	0.002489	0.000477	0.001226	0.000388
2007-Jun-21	57	33689	1	1000	100000	10000	50000	20000	0.002526	0.000479	0.001246	0.000385
2007-Jun-21	57	33690	1	1000	100000	10000	50000	20000	0.002901	0.000672	0.001372	0.000580
2007-Jun-21	57	33694	1	1000	100000	10000	50000	20000	0.002549	0.000506	0.001243	0.000417
2007-Jun-21	57	33697	1	1000	100000	10000	50000	20000	0.002344	0.000430	0.001157	0.000339
2007-Jun-21	57	33503	2	1000	100000	10000	50000	20000	0.002452	0.000502	0.001458	0.000409
2007-Jun-21	57	33508	2	1000	100000	10000	50000	20000	0.002127	0.000416	0.001258	0.000324
2007-Jun-21	57	33509	2	1000	100000	10000	50000	20000	0.002111	0.000407	0.001251	0.000314
2007-Jun-21	57	33510	2	1000	100000	10000	50000	20000	0.002242	0.000443	0.001332	0.000350
2007-Jun-21	57	33511	2	1000	100000	10000	50000	20000	0.002216	0.000431	0.001317	0.000337
2007-Jun-21	57	33527	2	1000	100000	10000	50000	20000	0.002274	0.000442	0.001348	0.000345
2007-Jun-21	57	33530	2	1000	100000	10000	50000	20000	0.002396	0.000468	0.001424	0.000369
2007-Jun-21	57	33534	2	1000	100000	10000	50000	20000	0.002372	0.000491	0.001403	0.000401
2007-Jun-21	57	33547	2	1000	100000	10000	50000	20000	0.002393	0.000477	0.001421	0.000381
2007-Jun-21	57	33548	2	1000	100000	10000	50000	20000	0.002288	0.000468	0.001345	0.000378
2007-Jun-21	57	33549	2	1000	100000	10000	50000	20000	0.002180	0.000434	0.001287	0.000344
2007-Jun-21	57	33550	2	1000	100000	10000	50000	20000	0.002172	0.000424	0.001289	0.000331
2007-Jun-21	57	33556	2	1000	100000	10000	50000	20000	0.002082	0.000403	0.001219	0.000312
2007-Jun-21	57	33558	2	1000	100000	10000	50000	20000	0.002186	0.000440	0.001283	0.000351
2007-Jun-21	57	33559	2	1000	100000	10000	50000	20000	0.002220	0.000444	0.001308	0.000352
2007-Jun-21	57	33563	2	1000	100000	10000	50000	20000	0.002158	0.000394	0.001276	0.000293
2007-Jun-21	57	33564	2	1000	100000	10000	50000	20000	0.002165	0.000403	0.001280	0.000303
2007-Jun-21	57	33565	2	1000	100000	10000	50000	20000	0.002334	0.000449	0.001385	0.000348
2007-Jun-21	57	33566	2	1000	100000	10000	50000	20000	0.002258	0.000430	0.001335	0.000330
2007-Jun-21	57	33567	2	1000	100000	10000	50000	20000	0.002411	0.000469	0.001431	0.000369
2007-Jun-21	57	33568	2	1000	100000	10000	50000	20000	0.002160	0.000424	0.001278	0.000332

2007-Jun-21	57	33569	2	1000	100000	10000	50000	20000	0.002311	0.000470	0.001371	0.000380
2007-Jun-21	57	33570	2	1000	100000	10000	50000	20000	0.002457	0.000547	0.001495	0.000461
2007-Jun-21	57	33571	2	1000	100000	10000	50000	20000	0.002102	0.000411	0.001252	0.000324
2007-Jun-21	57	33572	2	1000	100000	10000	50000	20000	0.002342	0.000476	0.001386	0.000386
2007-Jun-21	57	33573	2	1000	100000	10000	50000	20000	0.002228	0.000446	0.001324	0.000357
2007-Jun-21	57	33575	2	1000	100000	10000	50000	20000	0.002363	0.000486	0.001399	0.000397
2007-Jun-21	57	33583	2	1000	100000	10000	50000	20000	0.002187	0.000420	0.001300	0.000324
2007-Jun-21	57	33584	2	1000	100000	10000	50000	20000	0.002206	0.000427	0.001310	0.000332
2007-Jun-21	57	33586	2	1000	100000	10000	50000	20000	0.002554	0.000551	0.001505	0.000463
2007-Jun-21	57	33587	2	1000	100000	10000	50000	20000	0.002403	0.000476	0.001426	0.000379
2007-Jun-21	57	33592	2	1000	100000	10000	50000	20000	0.002266	0.000448	0.001339	0.000354
2007-Jun-21	57	33594	2	1000	100000	10000	50000	20000	0.002235	0.000438	0.001325	0.000343
2007-Jun-21	57	33595	2	1000	100000	10000	50000	20000	0.002168	0.000420	0.001285	0.000326
2007-Jun-21	57	33598	2	1000	100000	10000	50000	20000	0.002490	0.000533	0.001481	0.000445
2007-Jun-21	57	33601	2	1000	100000	10000	50000	20000	0.001823	0.000340	0.001074	0.000253
2007-Jun-21	57	33602	2	1000	100000	10000	50000	20000	0.001908	0.000360	0.001123	0.000271
2007-Jun-21	57	33603	2	1000	100000	10000	50000	20000	0.002141	0.000423	0.001265	0.000333
2007-Jun-21	57	33604	2	1000	100000	10000	50000	20000	0.002066	0.000408	0.001218	0.000319
2007-Jun-21	57	33605	2	1000	100000	10000	50000	20000	0.002079	0.000407	0.001229	0.000318
2007-Jun-21	57	33606	2	1000	100000	10000	50000	20000	0.002544	0.000599	0.001468	0.000517
2007-Jun-21	57	33607	2	1000	100000	10000	50000	20000	0.002092	0.000417	0.001231	0.000330
2007-Jun-21	57	33608	2	1000	100000	10000	50000	20000	0.003030	0.000744	0.001774	0.000664
2007-Jun-21	57	33609	2	1000	100000	10000	50000	20000	0.002127	0.000437	0.001250	0.000352
2007-Jun-21	57	33610	2	1000	100000	10000	50000	20000	0.002117	0.000420	0.001250	0.000330
2007-Jun-21	57	33611	2	1000	100000	10000	50000	20000	0.002113	0.000428	0.001246	0.000342
2007-Jun-21	57	33612	2	1000	100000	10000	50000	20000	0.001981	0.000386	0.001168	0.000299
2007-Jun-21	57	33613	2	1000	100000	10000	50000	20000	0.002082	0.000404	0.001231	0.000313
2007-Jun-21	57	33614	2	1000	100000	10000	50000	20000	0.002107	0.000426	0.001239	0.000339
2007-Jun-21	57	33615	2	1000	100000	10000	50000	20000	0.002058	0.000435	0.001242	0.000351
2007-Jun-21	57	33616	2	1000	100000	10000	50000	20000	0.002248	0.000480	0.001367	0.000392
2007-Jun-21	57	33617	2	1000	100000	10000	50000	20000	0.002015	0.000384	0.001192	0.000292
2007-Jun-21	57	33618	2	1000	100000	10000	50000	20000	0.002192	0.000442	0.001288	0.000354
2007-Jun-21	57	33619	2	1000	100000	10000	50000	20000	0.002171	0.000419	0.001284	0.000325
2007-Jun-21	57	33620	2	1000	100000	10000	50000	20000	0.002025	0.000390	0.001197	0.000301
2007-Jun-21	57	33621	2	1000	100000	10000	50000	20000	0.002101	0.000416	0.001240	0.000328
2007-Jun-21	57	33622	2	1000	100000	10000	50000	20000	0.002095	0.000418	0.001234	0.000331
2007-Jun-21	57	33623	2	1000	100000	10000	50000	20000	0.002110	0.000421	0.001243	0.000333

2007-Jun-21	57	33624	2	1000	100000	10000	50000	20000	0.002168	0.000439	0.001271	0.000351
2007-Jun-21	57	33625	2	1000	100000	10000	50000	20000	0.002171	0.000439	0.001276	0.000351
2007-Jun-21	57	33626	2	1000	100000	10000	50000	20000	0.002127	0.000472	0.001266	0.000388
2007-Jun-21	57	33629	2	1000	100000	10000	50000	20000	0.002281	0.000481	0.001337	0.000395
2007-Jun-21	57	33630	2	1000	100000	10000	50000	20000	0.002075	0.000413	0.001224	0.000326
2007-Jun-21	57	33631	2	1000	100000	10000	50000	20000	0.002110	0.000421	0.001243	0.000333
2007-Jun-21	57	33633	2	1000	100000	10000	50000	20000	0.002097	0.000423	0.001235	0.000337
2007-Jun-21	57	33634	2	1000	100000	10000	50000	20000	0.002045	0.000402	0.001202	0.000315
2007-Jun-21	57	33635	2	1000	100000	10000	50000	20000	0.002035	0.000425	0.001231	0.000340
2007-Jun-21	57	33637	2	1000	100000	10000	50000	20000	0.002217	0.000442	0.001310	0.000350
2007-Jun-21	57	33647	2	1000	100000	10000	50000	20000	0.002154	0.000419	0.001275	0.000327
2007-Jun-21	57	33650	2	1000	100000	10000	50000	20000	0.002110	0.000421	0.001243	0.000333
2007-Jun-21	57	33655	2	1000	100000	10000	50000	20000	0.001883	0.000354	0.001108	0.000265
2007-Jun-21	57	33660	2	1000	100000	10000	50000	20000	0.002095	0.000412	0.001240	0.000322
2007-Jun-21	57	33661	2	1000	100000	10000	50000	20000	0.002095	0.000412	0.001240	0.000322
2007-Jun-21	57	33662	2	1000	100000	10000	50000	20000	0.002095	0.000412	0.001240	0.000322
2007-Jun-21	57	33663	2	1000	100000	10000	50000	20000	0.002091	0.000416	0.001233	0.000329
2007-Jun-21	57	33664	2	1000	100000	10000	50000	20000	0.002110	0.000421	0.001243	0.000333
2007-Jun-21	57	33672	2	1000	100000	10000	50000	20000	0.001873	0.000348	0.001104	0.000259
2007-Jun-21	57	33673	2	1000	100000	10000	50000	20000	0.002082	0.000407	0.001228	0.000318
2007-Jun-21	57	33674	2	1000	100000	10000	50000	20000	0.002165	0.000435	0.001276	0.000346
2007-Jun-21	57	33675	2	1000	100000	10000	50000	20000	0.001900	0.000357	0.001123	0.000268
2007-Jun-21	57	33677	2	1000	100000	10000	50000	20000	0.001970	0.000380	0.001165	0.000292
2007-Jun-21	57	33679	2	1000	100000	10000	50000	20000	0.002093	0.000424	0.001230	0.000338
2007-Jun-21	57	33680	2	1000	100000	10000	50000	20000	0.001931	0.000366	0.001139	0.000276
2007-Jun-21	57	33681	2	1000	100000	10000	50000	20000	0.002062	0.000396	0.001215	0.000306
2007-Jun-21	57	33682	2	1000	100000	10000	50000	20000	0.001956	0.000368	0.001154	0.000278
2007-Jun-21	57	33684	2	1000	100000	10000	50000	20000	0.002022	0.000406	0.001188	0.000321
2007-Jun-21	57	33685	2	1000	100000	10000	50000	20000	0.001970	0.000379	0.001159	0.000292
2007-Jun-21	57	33686	2	1000	100000	10000	50000	20000	0.002351	0.000495	0.001382	0.000407
2007-Jun-21	57	33687	2	1000	100000	10000	50000	20000	0.002070	0.000399	0.001227	0.000308
2007-Jun-21	57	33688	2	1000	100000	10000	50000	20000	0.002067	0.000402	0.001223	0.000313
2007-Jun-21	57	33689	2	1000	100000	10000	50000	20000	0.002100	0.000405	0.001243	0.000313
2007-Jun-21	57	33690	2	1000	100000	10000	50000	20000	0.002376	0.000535	0.001368	0.000451
2007-Jun-21	57	33694	2	1000	100000	10000	50000	20000	0.002111	0.000422	0.001240	0.000334
2007-Jun-21	57	33697	2	1000	100000	10000	50000	20000	0.001956	0.000368	0.001154	0.000278
2007-Jun-21	57	33503	3	1000	100000	10000	50000	20000	0.013517	0.005227	0.001483	0.005438

2007-Jun-21	57	33508	3	1000	100000	10000	50000	20000	0.011066	0.003952	0.001280	0.004106
2007-Jun-21	57	33509	3	1000	100000	10000	50000	20000	0.010928	0.003850	0.001272	0.004005
2007-Jun-21	57	33510	3	1000	100000	10000	50000	20000	0.011934	0.004385	0.001355	0.004561
2007-Jun-21	57	33511	3	1000	100000	10000	50000	20000	0.011703	0.004230	0.001340	0.004406
2007-Jun-21	57	33527	3	1000	100000	10000	50000	20000	0.011924	0.004281	0.001371	0.004457
2007-Jun-21	57	33530	3	1000	100000	10000	50000	20000	0.012820	0.004715	0.001448	0.004912
2007-Jun-21	57	33534	3	1000	100000	10000	50000	20000	0.012976	0.005010	0.001427	0.005208
2007-Jun-21	57	33547	3	1000	100000	10000	50000	20000	0.012919	0.004839	0.001445	0.005035
2007-Jun-21	57	33548	3	1000	100000	10000	50000	20000	0.012291	0.004660	0.001368	0.004834
2007-Jun-21	57	33549	3	1000	100000	10000	50000	20000	0.011546	0.004252	0.001309	0.004415
2007-Jun-21	57	33550	3	1000	100000	10000	50000	20000	0.011400	0.004103	0.001311	0.004267
2007-Jun-21	57	33556	3	1000	100000	10000	50000	20000	0.010645	0.003729	0.001240	0.003871
2007-Jun-21	57	33558	3	1000	100000	10000	50000	20000	0.011557	0.004280	0.001305	0.004436
2007-Jun-21	57	33559	3	1000	100000	10000	50000	20000	0.011768	0.004349	0.001331	0.004514
2007-Jun-21	57	33563	3	1000	100000	10000	50000	20000	0.010808	0.003570	0.001298	0.003721
2007-Jun-21	57	33564	3	1000	100000	10000	50000	20000	0.010953	0.003696	0.001302	0.003848
2007-Jun-21	57	33565	3	1000	100000	10000	50000	20000	0.012243	0.004373	0.001409	0.004556
2007-Jun-21	57	33566	3	1000	100000	10000	50000	20000	0.011659	0.004079	0.001358	0.004246
2007-Jun-21	57	33567	3	1000	100000	10000	50000	20000	0.012837	0.004693	0.001455	0.004887
2007-Jun-21	57	33568	3	1000	100000	10000	50000	20000	0.011316	0.004073	0.001300	0.004236
2007-Jun-21	57	33569	3	1000	100000	10000	50000	20000	0.012567	0.004785	0.001394	0.004974
2007-Jun-21	57	33570	3	1000	100000	10000	50000	20000	0.014356	0.005847	0.001521	0.006072
2007-Jun-21	57	33571	3	1000	100000	10000	50000	20000	0.011178	0.004079	0.001274	0.004248
2007-Jun-21	57	33572	3	1000	100000	10000	50000	20000	0.012751	0.004863	0.001410	0.005064
2007-Jun-21	57	33573	3	1000	100000	10000	50000	20000	0.012020	0.004507	0.001347	0.004689
2007-Jun-21	57	33575	3	1000	100000	10000	50000	20000	0.012990	0.005030	0.001423	0.005233
2007-Jun-21	57	33583	3	1000	100000	10000	50000	20000	0.011414	0.004044	0.001323	0.004214
2007-Jun-21	57	33584	3	1000	100000	10000	50000	20000	0.011565	0.004141	0.001332	0.004312
2007-Jun-21	57	33586	3	1000	100000	10000	50000	20000	0.014402	0.005831	0.001531	0.006061
2007-Jun-21	57	33587	3	1000	100000	10000	50000	20000	0.012915	0.004806	0.001451	0.005002
2007-Jun-21	57	33592	3	1000	100000	10000	50000	20000	0.011991	0.004393	0.001362	0.004568
2007-Jun-21	57	33594	3	1000	100000	10000	50000	20000	0.011769	0.004258	0.001348	0.004429
2007-Jun-21	57	33595	3	1000	100000	10000	50000	20000	0.011309	0.004028	0.001307	0.004191
2007-Jun-21	57	33598	3	1000	100000	10000	50000	20000	0.014118	0.005708	0.001507	0.005926
2007-Jun-21	57	33601	3	1000	100000	10000	50000	20000	0.009011	0.002957	0.001093	0.003070
2007-Jun-21	57	33602	3	1000	100000	10000	50000	20000	0.009528	0.003188	0.001142	0.003312
2007-Jun-21	57	33603	3	1000	100000	10000	50000	20000	0.011270	0.004103	0.001286	0.004265

2007-Jun-21	57	33604	3	1000	100000	10000	50000	20000	0.010772	0.003883	0.001239	0.004031
2007-Jun-21	57	33605	3	1000	100000	10000	50000	20000	0.010852	0.003896	0.001250	0.004051
2007-Jun-21	57	33606	3	1000	100000	10000	50000	20000	0.014346	0.006074	0.001492	0.006256
2007-Jun-21	57	33607	3	1000	100000	10000	50000	20000	0.010981	0.004009	0.001252	0.004162
2007-Jun-21	57	33608	3	1000	100000	10000	50000	20000	0.018341	0.008291	0.001803	0.008563
2007-Jun-21	57	33609	3	1000	100000	10000	50000	20000	0.011357	0.004283	0.001272	0.004438
2007-Jun-21	57	33610	3	1000	100000	10000	50000	20000	0.011115	0.004043	0.001272	0.004200
2007-Jun-21	57	33611	3	1000	100000	10000	50000	20000	0.011240	0.004184	0.001268	0.004345
2007-Jun-21	57	33612	3	1000	100000	10000	50000	20000	0.010187	0.003592	0.001188	0.003727
2007-Jun-21	57	33613	3	1000	100000	10000	50000	20000	0.010813	0.003843	0.001252	0.003995
2007-Jun-21	57	33614	3	1000	100000	10000	50000	20000	0.011142	0.004126	0.001260	0.004279
2007-Jun-21	57	33615	3	1000	100000	10000	50000	20000	0.011259	0.004223	0.001264	0.004372
2007-Jun-21	57	33616	3	1000	100000	10000	50000	20000	0.012643	0.004885	0.001391	0.005072
2007-Jun-21	57	33617	3	1000	100000	10000	50000	20000	0.010293	0.003551	0.001213	0.003693
2007-Jun-21	57	33618	3	1000	100000	10000	50000	20000	0.011638	0.004333	0.001310	0.004495
2007-Jun-21	57	33619	3	1000	100000	10000	50000	20000	0.011295	0.004010	0.001306	0.004177
2007-Jun-21	57	33620	3	1000	100000	10000	50000	20000	0.010439	0.003670	0.001218	0.003813
2007-Jun-21	57	33621	3	1000	100000	10000	50000	20000	0.011029	0.004005	0.001262	0.004165
2007-Jun-21	57	33622	3	1000	100000	10000	50000	20000	0.011032	0.004039	0.001255	0.004194
2007-Jun-21	57	33623	3	1000	100000	10000	50000	20000	0.011122	0.004075	0.001265	0.004233
2007-Jun-21	57	33624	3	1000	100000	10000	50000	20000	0.011476	0.004268	0.001293	0.004425
2007-Jun-21	57	33625	3	1000	100000	10000	50000	20000	0.011510	0.004277	0.001298	0.004439
2007-Jun-21	57	33626	3	1000	100000	10000	50000	20000	0.011654	0.004504	0.001288	0.004645
2007-Jun-21	57	33629	3	1000	100000	10000	50000	20000	0.012402	0.004825	0.001360	0.005001
2007-Jun-21	57	33630	3	1000	100000	10000	50000	20000	0.010920	0.003986	0.001245	0.004141
2007-Jun-21	57	33631	3	1000	100000	10000	50000	20000	0.011122	0.004075	0.001265	0.004233
2007-Jun-21	57	33633	3	1000	100000	10000	50000	20000	0.011077	0.004091	0.001256	0.004246
2007-Jun-21	57	33634	3	1000	100000	10000	50000	20000	0.010621	0.003809	0.001223	0.003953
2007-Jun-21	57	33635	3	1000	100000	10000	50000	20000	0.011074	0.004106	0.001252	0.004252
2007-Jun-21	57	33637	3	1000	100000	10000	50000	20000	0.011744	0.004323	0.001332	0.004492
2007-Jun-21	57	33647	3	1000	100000	10000	50000	20000	0.011272	0.004047	0.001297	0.004208
2007-Jun-21	57	33650	3	1000	100000	10000	50000	20000	0.011122	0.004075	0.001265	0.004233
2007-Jun-21	57	33655	3	1000	100000	10000	50000	20000	0.009373	0.003117	0.001128	0.003237
2007-Jun-21	57	33660	3	1000	100000	10000	50000	20000	0.010938	0.003931	0.001261	0.004085
2007-Jun-21	57	33661	3	1000	100000	10000	50000	20000	0.010938	0.003931	0.001261	0.004085
2007-Jun-21	57	33662	3	1000	100000	10000	50000	20000	0.010938	0.003931	0.001261	0.004085
2007-Jun-21	57	33663	3	1000	100000	10000	50000	20000	0.011010	0.004022	0.001254	0.004179

2007-Jun-21	57	33664	3	1000	100000	10000	50000	20000	0.011122	0.004075	0.001265	0.004233
2007-Jun-21	57	33672	3	1000	100000	10000	50000	20000	0.009288	0.003055	0.001123	0.003175
2007-Jun-21	57	33673	3	1000	100000	10000	50000	20000	0.010840	0.003882	0.001250	0.004034
2007-Jun-21	57	33674	3	1000	100000	10000	50000	20000	0.011491	0.004259	0.001298	0.004423
2007-Jun-21	57	33675	3	1000	100000	10000	50000	20000	0.009514	0.003180	0.001142	0.003306
2007-Jun-21	57	33677	3	1000	100000	10000	50000	20000	0.010112	0.003533	0.001185	0.003670
2007-Jun-21	57	33679	3	1000	100000	10000	50000	20000	0.011041	0.004083	0.001251	0.004234
2007-Jun-21	57	33680	3	1000	100000	10000	50000	20000	0.009738	0.003303	0.001159	0.003432
2007-Jun-21	57	33681	3	1000	100000	10000	50000	20000	0.010619	0.003726	0.001236	0.003879
2007-Jun-21	57	33682	3	1000	100000	10000	50000	20000	0.009867	0.003340	0.001174	0.003472
2007-Jun-21	57	33684	3	1000	100000	10000	50000	20000	0.010583	0.003867	0.001208	0.004007
2007-Jun-21	57	33685	3	1000	100000	10000	50000	20000	0.010068	0.003503	0.001179	0.003639
2007-Jun-21	57	33686	3	1000	100000	10000	50000	20000	0.012861	0.005018	0.001406	0.005207
2007-Jun-21	57	33687	3	1000	100000	10000	50000	20000	0.010728	0.003788	0.001248	0.003940
2007-Jun-21	57	33688	3	1000	100000	10000	50000	20000	0.010783	0.003858	0.001244	0.004009
2007-Jun-21	57	33689	3	1000	100000	10000	50000	20000	0.010856	0.003822	0.001264	0.003976
2007-Jun-21	57	33690	3	1000	100000	10000	50000	20000	0.012941	0.005220	0.001392	0.005380
2007-Jun-21	57	33694	3	1000	100000	10000	50000	20000	0.011071	0.004049	0.001261	0.004198
2007-Jun-21	57	33697	3	1000	100000	10000	50000	20000	0.009867	0.003340	0.001174	0.003472
2007-Jun-21	59	32425	1	1000	100000	10000	50000	20000	0.000430	0.000244	0.000848	0.000192
2007-Jun-21	59	32452	1	1000	100000	10000	50000	20000	0.000432	0.000242	0.000841	0.000192
2007-Jun-21	59	32455	1	1000	100000	10000	50000	20000	0.000684	0.000361	0.001099	0.000313
2007-Jun-21	59	32464	1	1000	100000	10000	50000	20000	0.000470	0.000257	0.000873	0.000209
2007-Jun-21	59	32425	2	1000	100000	10000	50000	20000	0.000382	0.000236	0.000847	0.000185
2007-Jun-21	59	32452	2	1000	100000	10000	50000	20000	0.000383	0.000234	0.000840	0.000185
2007-Jun-21	59	32455	2	1000	100000	10000	50000	20000	0.000598	0.000339	0.001097	0.000293
2007-Jun-21	59	32464	2	1000	100000	10000	50000	20000	0.000415	0.000246	0.000871	0.000199
2007-Jun-21	59	32425	3	1000	100000	10000	50000	20000	0.003801	0.001261	0.000870	0.001249
2007-Jun-21	59	32452	3	1000	100000	10000	50000	20000	0.003841	0.001298	0.000864	0.001292
2007-Jun-21	59	32455	3	1000	100000	10000	50000	20000	0.005809	0.002273	0.001128	0.002281
2007-Jun-21	59	32464	3	1000	100000	10000	50000	20000	0.004192	0.001462	0.000897	0.001464
2007-Jun-21	61	32948	1	1000	100000	10000	50000	20000	0.002901	0.000588	0.001453	0.000477
2007-Jun-21	61	32957	1	1000	100000	10000	50000	20000	0.003458	0.000823	0.001670	0.000713
2007-Jun-21	61	32958	1	1000	100000	10000	50000	20000	0.003495	0.000842	0.001679	0.000730
2007-Jun-21	61	32960	1	1000	100000	10000	50000	20000	0.003079	0.000682	0.001515	0.000573
2007-Jun-21	61	32961	1	1000	100000	10000	50000	20000	0.003094	0.000700	0.001513	0.000592
2007-Jun-21	61	32962	1	1000	100000	10000	50000	20000	0.003377	0.000775	0.001644	0.000661

2007-Jun-21	61	32963	1	1000	100000	10000	50000	20000	0.004156	0.001097	0.001949	0.000974
2007-Jun-21	61	32964	1	1000	100000	10000	50000	20000	0.003094	0.000700	0.001513	0.000592
2007-Jun-21	61	32965	1	1000	100000	10000	50000	20000	0.003230	0.000718	0.001585	0.000606
2007-Jun-21	61	32966	1	1000	100000	10000	50000	20000	0.003371	0.000760	0.001652	0.000646
2007-Jun-21	61	32967	1	1000	100000	10000	50000	20000	0.003959	0.000997	0.001883	0.000877
2007-Jun-21	61	32968	1	1000	100000	10000	50000	20000	0.003128	0.000662	0.001555	0.000550
2007-Jun-21	61	32969	1	1000	100000	10000	50000	20000	0.002972	0.000617	0.001481	0.000508
2007-Jun-21	61	32970	1	1000	100000	10000	50000	20000	0.003782	0.000955	0.001796	0.000839
2007-Jun-21	61	32971	1	1000	100000	10000	50000	20000	0.003717	0.000941	0.001766	0.000827
2007-Jun-21	61	32978	1	1000	100000	10000	50000	20000	0.005225	0.001815	0.002167	0.001648
2007-Jun-21	61	32948	2	1000	100000	10000	50000	20000	0.002417	0.000492	0.001449	0.000385
2007-Jun-21	61	32957	2	1000	100000	10000	50000	20000	0.002836	0.000653	0.001666	0.000553
2007-Jun-21	61	32958	2	1000	100000	10000	50000	20000	0.002865	0.000667	0.001674	0.000565
2007-Jun-21	61	32960	2	1000	100000	10000	50000	20000	0.002544	0.000555	0.001511	0.000452
2007-Jun-21	61	32961	2	1000	100000	10000	50000	20000	0.002553	0.000566	0.001509	0.000465
2007-Jun-21	61	32962	2	1000	100000	10000	50000	20000	0.002782	0.000622	0.001640	0.000517
2007-Jun-21	61	32963	2	1000	100000	10000	50000	20000	0.003377	0.000845	0.001943	0.000741
2007-Jun-21	61	32964	2	1000	100000	10000	50000	20000	0.002553	0.000566	0.001509	0.000465
2007-Jun-21	61	32965	2	1000	100000	10000	50000	20000	0.002668	0.000583	0.001581	0.000477
2007-Jun-21	61	32966	2	1000	100000	10000	50000	20000	0.002779	0.000613	0.001647	0.000507
2007-Jun-21	61	32967	2	1000	100000	10000	50000	20000	0.003229	0.000778	0.001878	0.000672
2007-Jun-21	61	32968	2	1000	100000	10000	50000	20000	0.002594	0.000545	0.001551	0.000438
2007-Jun-21	61	32969	2	1000	100000	10000	50000	20000	0.002470	0.000513	0.001478	0.000406
2007-Jun-21	61	32970	2	1000	100000	10000	50000	20000	0.003085	0.000745	0.001791	0.000643
2007-Jun-21	61	32971	2	1000	100000	10000	50000	20000	0.003031	0.000734	0.001761	0.000634
2007-Jun-21	61	32978	2	1000	100000	10000	50000	20000	0.004163	0.001324	0.002160	0.001215
2007-Jun-21	61	32948	3	1000	100000	10000	50000	20000	0.012696	0.004484	0.001474	0.004639
2007-Jun-21	61	32957	3	1000	100000	10000	50000	20000	0.015883	0.006426	0.001694	0.006615
2007-Jun-21	61	32958	3	1000	100000	10000	50000	20000	0.015981	0.006481	0.001703	0.006671
2007-Jun-21	61	32960	3	1000	100000	10000	50000	20000	0.013801	0.005251	0.001537	0.005412
2007-Jun-21	61	32961	3	1000	100000	10000	50000	20000	0.013864	0.005334	0.001535	0.005491
2007-Jun-21	61	32962	3	1000	100000	10000	50000	20000	0.015295	0.005983	0.001668	0.006173
2007-Jun-21	61	32963	3	1000	100000	10000	50000	20000	0.019436	0.008395	0.001976	0.008637
2007-Jun-21	61	32964	3	1000	100000	10000	50000	20000	0.013864	0.005334	0.001535	0.005491
2007-Jun-21	61	32965	3	1000	100000	10000	50000	20000	0.014526	0.005558	0.001608	0.005735
2007-Jun-21	61	32966	3	1000	100000	10000	50000	20000	0.015314	0.005958	0.001675	0.006148
2007-Jun-21	61	32967	3	1000	100000	10000	50000	20000	0.018463	0.007778	0.001910	0.008013

2007-Jun-21	61	32968	3	1000	100000	10000	50000	20000	0.013999	0.005190	0.001578	0.005367
2007-Jun-21	61	32969	3	1000	100000	10000	50000	20000	0.013128	0.004759	0.001503	0.004915
2007-Jun-21	61	32970	3	1000	100000	10000	50000	20000	0.017527	0.007357	0.001821	0.007571
2007-Jun-21	61	32971	3	1000	100000	10000	50000	20000	0.017240	0.007254	0.001790	0.007460
2007-Jun-21	61	32978	3	1000	100000	10000	50000	20000	0.023333	0.011366	0.002196	0.011527
2007-Jun-21	63	32420	1	1000	100000	10000	50000	20000	0.000368	0.000218	0.000767	0.000166
2007-Jun-21	63	32423	1	1000	100000	10000	50000	20000	0.000277	0.000174	0.000618	0.000127
2007-Jun-21	63	32426	1	1000	100000	10000	50000	20000	0.000210	0.000142	0.000508	0.000099
2007-Jun-21	63	32431	1	1000	100000	10000	50000	20000	0.000328	0.000200	0.000716	0.000148
2007-Jun-21	63	32432	1	1000	100000	10000	50000	20000	0.000392	0.000227	0.000802	0.000174
2007-Jun-21	63	32440	1	1000	100000	10000	50000	20000	0.000471	0.000260	0.000893	0.000209
2007-Jun-21	63	32442	1	1000	100000	10000	50000	20000	0.000290	0.000182	0.000650	0.000133
2007-Jun-21	63	32443	1	1000	100000	10000	50000	20000	0.000394	0.000227	0.000794	0.000176
2007-Jun-21	63	32445	1	1000	100000	10000	50000	20000	0.000352	0.000206	0.000717	0.000159
2007-Jun-21	63	32446	1	1000	100000	10000	50000	20000	0.000236	0.000156	0.000555	0.000110
2007-Jun-21	63	32447	1	1000	100000	10000	50000	20000	0.000205	0.000140	0.000496	0.000098
2007-Jun-21	63	32448	1	1000	100000	10000	50000	20000	0.000399	0.000231	0.000809	0.000179
2007-Jun-21	63	32460	1	1000	100000	10000	50000	20000	0.000381	0.000221	0.000778	0.000171
2007-Jun-21	63	32420	2	1000	100000	10000	50000	20000	0.000329	0.000212	0.000766	0.000161
2007-Jun-21	63	32423	2	1000	100000	10000	50000	20000	0.000249	0.000170	0.000617	0.000125
2007-Jun-21	63	32426	2	1000	100000	10000	50000	20000	0.000192	0.000141	0.000507	0.000098
2007-Jun-21	63	32431	2	1000	100000	10000	50000	20000	0.000294	0.000195	0.000714	0.000145
2007-Jun-21	63	32432	2	1000	100000	10000	50000	20000	0.000349	0.000220	0.000801	0.000169
2007-Jun-21	63	32440	2	1000	100000	10000	50000	20000	0.000416	0.000250	0.000892	0.000200
2007-Jun-21	63	32442	2	1000	100000	10000	50000	20000	0.000261	0.000179	0.000649	0.000130
2007-Jun-21	63	32443	2	1000	100000	10000	50000	20000	0.000351	0.000220	0.000793	0.000170
2007-Jun-21	63	32445	2	1000	100000	10000	50000	20000	0.000314	0.000200	0.000716	0.000154
2007-Jun-21	63	32446	2	1000	100000	10000	50000	20000	0.000214	0.000154	0.000555	0.000109
2007-Jun-21	63	32447	2	1000	100000	10000	50000	20000	0.000187	0.000139	0.000495	0.000097
2007-Jun-21	63	32448	2	1000	100000	10000	50000	20000	0.000356	0.000224	0.000808	0.000173
2007-Jun-21	63	32460	2	1000	100000	10000	50000	20000	0.000339	0.000215	0.000777	0.000166
2007-Jun-21	63	32420	3	1000	100000	10000	50000	20000	0.003159	0.000973	0.000787	0.000945
2007-Jun-21	63	32423	3	1000	100000	10000	50000	20000	0.002315	0.000663	0.000634	0.000628
2007-Jun-21	63	32426	3	1000	100000	10000	50000	20000	0.001662	0.000424	0.000520	0.000379
2007-Jun-21	63	32431	3	1000	100000	10000	50000	20000	0.002818	0.000826	0.000734	0.000796
2007-Jun-21	63	32432	3	1000	100000	10000	50000	20000	0.003441	0.001077	0.000823	0.001060
2007-Jun-21	63	32440	3	1000	100000	10000	50000	20000	0.004197	0.001450	0.000917	0.001448

2007-Jun-21	63	32442	3	1000	100000	10000	50000	20000	0.002423	0.000682	0.000666	0.000645
2007-Jun-21	63	32443	3	1000	100000	10000	50000	20000	0.003452	0.001107	0.000815	0.001092
2007-Jun-21	63	32445	3	1000	100000	10000	50000	20000	0.003056	0.000987	0.000736	0.000967
2007-Jun-21	63	32446	3	1000	100000	10000	50000	20000	0.001878	0.000501	0.000569	0.000456
2007-Jun-21	63	32447	3	1000	100000	10000	50000	20000	0.001590	0.000406	0.000507	0.000359
2007-Jun-21	63	32448	3	1000	100000	10000	50000	20000	0.003492	0.001114	0.000831	0.001096
2007-Jun-21	63	32460	3	1000	100000	10000	50000	20000	0.003327	0.001064	0.000798	0.001045
2007-Jun-21	65	32336	1	1000	100000	10000	50000	20000	0.000280	0.000164	0.000531	0.000130
2007-Jun-21	65	32337	1	1000	100000	10000	50000	20000	0.000218	0.000137	0.000471	0.000101
2007-Jun-21	65	32344	1	1000	100000	10000	50000	20000	0.000200	0.000127	0.000436	0.000093
2007-Jun-21	65	32345	1	1000	100000	10000	50000	20000	0.000254	0.000155	0.000525	0.000117
2007-Jun-21	65	32361	1	1000	100000	10000	50000	20000	0.000269	0.000161	0.000540	0.000123
2007-Jun-21	65	32336	2	1000	100000	10000	50000	20000	0.000249	0.000158	0.000530	0.000124
2007-Jun-21	65	32337	2	1000	100000	10000	50000	20000	0.000196	0.000134	0.000471	0.000098
2007-Jun-21	65	32344	2	1000	100000	10000	50000	20000	0.000180	0.000124	0.000436	0.000091
2007-Jun-21	65	32345	2	1000	100000	10000	50000	20000	0.000227	0.000150	0.000525	0.000113
2007-Jun-21	65	32361	2	1000	100000	10000	50000	20000	0.000240	0.000156	0.000540	0.000119
2007-Jun-21	65	32336	3	1000	100000	10000	50000	20000	0.002316	0.000806	0.000544	0.000779
2007-Jun-21	65	32337	3	1000	100000	10000	50000	20000	0.001768	0.000536	0.000483	0.000501
2007-Jun-21	65	32344	3	1000	100000	10000	50000	20000	0.001634	0.000500	0.000447	0.000467
2007-Jun-21	65	32345	3	1000	100000	10000	50000	20000	0.002115	0.000678	0.000538	0.000647
2007-Jun-21	65	32361	3	1000	100000	10000	50000	20000	0.002235	0.000727	0.000554	0.000698
2007-Jun-21	67	32013	1	1000	100000	10000	50000	20000	0.000237	0.000147	0.000493	0.000110
2007-Jun-21	67	32066	1	1000	100000	10000	50000	20000	0.000306	0.000182	0.000607	0.000141
2007-Jun-21	67	32013	2	1000	100000	10000	50000	20000	0.000212	0.000142	0.000493	0.000107
2007-Jun-21	67	32066	2	1000	100000	10000	50000	20000	0.000272	0.000176	0.000606	0.000136
2007-Jun-21	67	32013	3	1000	100000	10000	50000	20000	0.001942	0.000620	0.000505	0.000587
2007-Jun-21	67	32066	3	1000	100000	10000	50000	20000	0.002552	0.000851	0.000622	0.000820
2007-Jun-21	69	32102	1	1000	100000	10000	50000	20000	0.001610	0.000256	0.000808	0.000171
2007-Jun-21	69	32158	1	1000	100000	10000	50000	20000	0.002255	0.000370	0.001117	0.000269
2007-Jun-21	69	32159	1	1000	100000	10000	50000	20000	0.002135	0.000346	0.001055	0.000246
2007-Jun-21	69	32702	1	1000	100000	10000	50000	20000	0.001685	0.000261	0.000835	0.000170
2007-Jun-21	69	32726	1	1000	100000	10000	50000	20000	0.002438	0.000401	0.001217	0.000295
2007-Jun-21	69	32727	1	1000	100000	10000	50000	20000	0.002311	0.000376	0.001153	0.000272
2007-Jun-21	69	32735	1	1000	100000	10000	50000	20000	0.002557	0.000427	0.001274	0.000320
2007-Jun-21	69	32736	1	1000	100000	10000	50000	20000	0.002514	0.000415	0.001252	0.000308
2007-Jun-21	69	32756	1	1000	100000	10000	50000	20000	0.002535	0.000415	0.001262	0.000306

2007-Jun-21	69	32757	1	1000	100000	10000	50000	20000	0.002561	0.000421	0.001275	0.000312
2007-Jun-21	69	32767	1	1000	100000	10000	50000	20000	0.002001	0.000318	0.000996	0.000220
2007-Jun-21	69	32776	1	1000	100000	10000	50000	20000	0.002574	0.000425	0.001281	0.000317
2007-Jun-21	69	32778	1	1000	100000	10000	50000	20000	0.003124	0.000612	0.001535	0.000505
2007-Jun-21	69	32784	1	1000	100000	10000	50000	20000	0.002633	0.000454	0.001309	0.000348
2007-Jun-21	69	34705	1	1000	100000	10000	50000	20000	0.002633	0.000445	0.001317	0.000336
2007-Jun-21	69	34711	1	1000	100000	10000	50000	20000	0.002879	0.000521	0.001432	0.000411
2007-Jun-21	69	34712	1	1000	100000	10000	50000	20000	0.002818	0.000500	0.001403	0.000391
2007-Jun-21	69	34713	1	1000	100000	10000	50000	20000	0.002577	0.000422	0.001282	0.000311
2007-Jun-21	69	34729	1	1000	100000	10000	50000	20000	0.002519	0.000415	0.001257	0.000307
2007-Jun-21	69	34731	1	1000	100000	10000	50000	20000	0.002314	0.000379	0.001147	0.000275
2007-Jun-21	69	34736	1	1000	100000	10000	50000	20000	0.002590	0.000439	0.001287	0.000331
2007-Jun-21	69	34737	1	1000	100000	10000	50000	20000	0.002587	0.000437	0.001293	0.000328
2007-Jun-21	69	34748	1	1000	100000	10000	50000	20000	0.002287	0.000373	0.001137	0.000269
2007-Jun-21	69	34749	1	1000	100000	10000	50000	20000	0.002234	0.000366	0.001112	0.000265
2007-Jun-21	69	34753	1	1000	100000	10000	50000	20000	0.002676	0.000463	0.001331	0.000355
2007-Jun-21	69	34755	1	1000	100000	10000	50000	20000	0.002734	0.000466	0.001363	0.000356
2007-Jun-21	69	34756	1	1000	100000	10000	50000	20000	0.002495	0.000416	0.001247	0.000309
2007-Jun-21	69	34762	1	1000	100000	10000	50000	20000	0.002416	0.000399	0.001201	0.000293
2007-Jun-21	69	34788	1	1000	100000	10000	50000	20000	0.002356	0.000385	0.001169	0.000281
2007-Jun-21	69	34789	1	1000	100000	10000	50000	20000	0.002422	0.000398	0.001203	0.000293
2007-Jun-21	69	34797	1	1000	100000	10000	50000	20000	0.002342	0.000386	0.001165	0.000281
2007-Jun-21	69	32102	2	1000	100000	10000	50000	20000	0.001370	0.000237	0.000806	0.000153
2007-Jun-21	69	32158	2	1000	100000	10000	50000	20000	0.001904	0.000333	0.001115	0.000231
2007-Jun-21	69	32159	2	1000	100000	10000	50000	20000	0.001807	0.000314	0.001053	0.000214
2007-Jun-21	69	32702	2	1000	100000	10000	50000	20000	0.001438	0.000244	0.000833	0.000155
2007-Jun-21	69	32726	2	1000	100000	10000	50000	20000	0.002055	0.000358	0.001214	0.000252
2007-Jun-21	69	32727	2	1000	100000	10000	50000	20000	0.001951	0.000338	0.001151	0.000234
2007-Jun-21	69	32735	2	1000	100000	10000	50000	20000	0.002151	0.000378	0.001270	0.000271
2007-Jun-21	69	32736	2	1000	100000	10000	50000	20000	0.002117	0.000370	0.001248	0.000262
2007-Jun-21	69	32756	2	1000	100000	10000	50000	20000	0.002137	0.000370	0.001259	0.000261
2007-Jun-21	69	32757	2	1000	100000	10000	50000	20000	0.002157	0.000375	0.001272	0.000265
2007-Jun-21	69	32767	2	1000	100000	10000	50000	20000	0.001698	0.000291	0.000994	0.000194
2007-Jun-21	69	32776	2	1000	100000	10000	50000	20000	0.002166	0.000378	0.001278	0.000269
2007-Jun-21	69	32778	2	1000	100000	10000	50000	20000	0.002586	0.000510	0.001531	0.000405
2007-Jun-21	69	32784	2	1000	100000	10000	50000	20000	0.002208	0.000397	0.001306	0.000290
2007-Jun-21	69	34705	2	1000	100000	10000	50000	20000	0.002212	0.000392	0.001314	0.000282

2007-Jun-21	69	34711	2	1000	100000	10000	50000	20000	0.002403	0.000448	0.001429	0.000337
2007-Jun-21	69	34712	2	1000	100000	10000	50000	20000	0.002356	0.000432	0.001399	0.000322
2007-Jun-21	69	34713	2	1000	100000	10000	50000	20000	0.002173	0.000377	0.001279	0.000266
2007-Jun-21	69	34729	2	1000	100000	10000	50000	20000	0.002123	0.000371	0.001254	0.000261
2007-Jun-21	69	34731	2	1000	100000	10000	50000	20000	0.001954	0.000340	0.001144	0.000236
2007-Jun-21	69	34736	2	1000	100000	10000	50000	20000	0.002177	0.000387	0.001283	0.000279
2007-Jun-21	69	34737	2	1000	100000	10000	50000	20000	0.002175	0.000386	0.001290	0.000277
2007-Jun-21	69	34748	2	1000	100000	10000	50000	20000	0.001933	0.000336	0.001134	0.000232
2007-Jun-21	69	34749	2	1000	100000	10000	50000	20000	0.001887	0.000330	0.001109	0.000228
2007-Jun-21	69	34753	2	1000	100000	10000	50000	20000	0.002244	0.000404	0.001327	0.000296
2007-Jun-21	69	34755	2	1000	100000	10000	50000	20000	0.002294	0.000409	0.001360	0.000298
2007-Jun-21	69	34756	2	1000	100000	10000	50000	20000	0.002101	0.000370	0.001244	0.000262
2007-Jun-21	69	34762	2	1000	100000	10000	50000	20000	0.002037	0.000356	0.001198	0.000250
2007-Jun-21	69	34788	2	1000	100000	10000	50000	20000	0.001989	0.000345	0.001166	0.000241
2007-Jun-21	69	34789	2	1000	100000	10000	50000	20000	0.002042	0.000356	0.001200	0.000250
2007-Jun-21	69	34797	2	1000	100000	10000	50000	20000	0.001977	0.000346	0.001162	0.000241
2007-Jun-21	69	32102	3	1000	100000	10000	50000	20000	0.005759	0.001364	0.000820	0.001381
2007-Jun-21	69	32158	3	1000	100000	10000	50000	20000	0.008768	0.002499	0.001134	0.002596
2007-Jun-21	69	32159	3	1000	100000	10000	50000	20000	0.008088	0.002195	0.001071	0.002270
2007-Jun-21	69	32702	3	1000	100000	10000	50000	20000	0.005830	0.001269	0.000847	0.001279
2007-Jun-21	69	32726	3	1000	100000	10000	50000	20000	0.009748	0.002898	0.001235	0.003025
2007-Jun-21	69	32727	3	1000	100000	10000	50000	20000	0.009110	0.002632	0.001171	0.002742
2007-Jun-21	69	32735	3	1000	100000	10000	50000	20000	0.010400	0.003202	0.001293	0.003347
2007-Jun-21	69	32736	3	1000	100000	10000	50000	20000	0.010135	0.003063	0.001270	0.003202
2007-Jun-21	69	32756	3	1000	100000	10000	50000	20000	0.010179	0.003045	0.001281	0.003184
2007-Jun-21	69	32757	3	1000	100000	10000	50000	20000	0.010321	0.003110	0.001294	0.003253
2007-Jun-21	69	32767	3	1000	100000	10000	50000	20000	0.007448	0.001924	0.001011	0.001981
2007-Jun-21	69	32776	3	1000	100000	10000	50000	20000	0.010417	0.003167	0.001300	0.003313
2007-Jun-21	69	32778	3	1000	100000	10000	50000	20000	0.013815	0.005104	0.001558	0.005315
2007-Jun-21	69	32784	3	1000	100000	10000	50000	20000	0.010889	0.003485	0.001329	0.003641
2007-Jun-21	69	34705	3	1000	100000	10000	50000	20000	0.010841	0.003404	0.001337	0.003559
2007-Jun-21	69	34711	3	1000	100000	10000	50000	20000	0.012262	0.004168	0.001453	0.004346
2007-Jun-21	69	34712	3	1000	100000	10000	50000	20000	0.011932	0.003983	0.001424	0.004165
2007-Jun-21	69	34713	3	1000	100000	10000	50000	20000	0.010314	0.003068	0.001301	0.003209
2007-Jun-21	69	34729	3	1000	100000	10000	50000	20000	0.010104	0.003021	0.001276	0.003155
2007-Jun-21	69	34731	3	1000	100000	10000	50000	20000	0.009017	0.002577	0.001164	0.002679
2007-Jun-21	69	34736	3	1000	100000	10000	50000	20000	0.010554	0.003284	0.001306	0.003429

2007-Jun-21	69	34737	3	1000	100000	10000	50000	20000	0.010570	0.003281	0.001312	0.003428
2007-Jun-21	69	34748	3	1000	100000	10000	50000	20000	0.008878	0.002508	0.001154	0.002608
2007-Jun-21	69	34749	3	1000	100000	10000	50000	20000	0.008686	0.002469	0.001128	0.002562
2007-Jun-21	69	34753	3	1000	100000	10000	50000	20000	0.011082	0.003557	0.001350	0.003715
2007-Jun-21	69	34755	3	1000	100000	10000	50000	20000	0.011342	0.003624	0.001383	0.003790
2007-Jun-21	69	34756	3	1000	100000	10000	50000	20000	0.010066	0.003049	0.001266	0.003182
2007-Jun-21	69	34762	3	1000	100000	10000	50000	20000	0.009602	0.002839	0.001219	0.002960
2007-Jun-21	69	34788	3	1000	100000	10000	50000	20000	0.009239	0.002662	0.001187	0.002773
2007-Jun-21	69	34789	3	1000	100000	10000	50000	20000	0.009606	0.002827	0.001221	0.002949
2007-Jun-21	69	34797	3	1000	100000	10000	50000	20000	0.009184	0.002654	0.001182	0.002759
2007-Jun-21	71	33901	1	1000	100000	10000	50000	20000	0.003231	0.000657	0.001641	0.000549
2007-Jun-21	71	33902	1	1000	100000	10000	50000	20000	0.003062	0.000611	0.001557	0.000505
2007-Jun-21	71	33903	1	1000	100000	10000	50000	20000	0.003125	0.000636	0.001587	0.000529
2007-Jun-21	71	33904	1	1000	100000	10000	50000	20000	0.003464	0.000749	0.001749	0.000643
2007-Jun-21	71	33905	1	1000	100000	10000	50000	20000	0.003451	0.000694	0.001694	0.000584
2007-Jun-21	71	33906	1	1000	100000	10000	50000	20000	0.003253	0.000675	0.001649	0.000568
2007-Jun-21	71	33907	1	1000	100000	10000	50000	20000	0.003373	0.000703	0.001713	0.000595
2007-Jun-21	71	33908	1	1000	100000	10000	50000	20000	0.003461	0.000734	0.001750	0.000624
2007-Jun-21	71	33909	1	1000	100000	10000	50000	20000	0.003638	0.000805	0.001834	0.000699
2007-Jun-21	71	33910	1	1000	100000	10000	50000	20000	0.003181	0.000646	0.001613	0.000539
2007-Jun-21	71	33911	1	1000	100000	10000	50000	20000	0.003062	0.000611	0.001557	0.000505
2007-Jun-21	71	33912	1	1000	100000	10000	50000	20000	0.003464	0.000730	0.001760	0.000622
2007-Jun-21	71	33913	1	1000	100000	10000	50000	20000	0.003618	0.000785	0.001830	0.000675
2007-Jun-21	71	33914	1	1000	100000	10000	50000	20000	0.003511	0.000770	0.001766	0.000664
2007-Jun-21	71	33915	1	1000	100000	10000	50000	20000	0.003181	0.000646	0.001613	0.000539
2007-Jun-21	71	33916	1	1000	100000	10000	50000	20000	0.003185	0.000630	0.001626	0.000521
2007-Jun-21	71	33917	1	1000	100000	10000	50000	20000	0.003586	0.000747	0.001755	0.000639
2007-Jun-21	71	33918	1	1000	100000	10000	50000	20000	0.004059	0.001045	0.001962	0.000938
2007-Jun-21	71	33919	1	1000	100000	10000	50000	20000	0.003451	0.000737	0.001745	0.000629
2007-Jun-21	71	33920	1	1000	100000	10000	50000	20000	0.003357	0.000630	0.001665	0.000515
2007-Jun-21	71	33921	1	1000	100000	10000	50000	20000	0.004435	0.001229	0.002112	0.001123
2007-Jun-21	71	33922	1	1000	100000	10000	50000	20000	0.003795	0.000893	0.001888	0.000789
2007-Jun-21	71	33924	1	1000	100000	10000	50000	20000	0.004875	0.001435	0.002278	0.001324
2007-Jun-21	71	33928	1	1000	100000	10000	50000	20000	0.003531	0.000748	0.001793	0.000639
2007-Jun-21	71	33931	1	1000	100000	10000	50000	20000	0.003873	0.000898	0.001933	0.000790
2007-Jun-21	71	33932	1	1000	100000	10000	50000	20000	0.004333	0.001130	0.002087	0.001015
2007-Jun-21	71	33936	1	1000	100000	10000	50000	20000	0.003683	0.000748	0.001808	0.000636

2007-Jun-21	71	33945	1	1000	100000	10000	50000	20000	0.003611	0.000840	0.001794	0.000735
2007-Jun-21	71	33956	1	1000	100000	10000	50000	20000	0.003597	0.000822	0.001800	0.000716
2007-Jun-21	71	33957	1	1000	100000	10000	50000	20000	0.003904	0.000936	0.001943	0.000831
2007-Jun-21	71	33965	1	1000	100000	10000	50000	20000	0.003540	0.000763	0.001794	0.000656
2007-Jun-21	71	33970	1	1000	100000	10000	50000	20000	0.003356	0.000673	0.001714	0.000561
2007-Jun-21	71	33971	1	1000	100000	10000	50000	20000	0.003648	0.000743	0.001793	0.000632
2007-Jun-21	71	33972	1	1000	100000	10000	50000	20000	0.003612	0.000715	0.001782	0.000601
2007-Jun-21	71	33990	1	1000	100000	10000	50000	20000	0.003243	0.000670	0.001642	0.000564
2007-Jun-21	71	33991	1	1000	100000	10000	50000	20000	0.003573	0.000792	0.001799	0.000687
2007-Jun-21	71	33993	1	1000	100000	10000	50000	20000	0.003815	0.000875	0.001913	0.000771
2007-Jun-21	71	33994	1	1000	100000	10000	50000	20000	0.003383	0.000702	0.001721	0.000594
2007-Jun-21	71	34133	1	1000	100000	10000	50000	20000	0.003563	0.000770	0.001799	0.000661
2007-Jun-21	71	34134	1	1000	100000	10000	50000	20000	0.003726	0.000815	0.001880	0.000706
2007-Jun-21	71	34135	1	1000	100000	10000	50000	20000	0.003694	0.000802	0.001874	0.000695
2007-Jun-21	71	34136	1	1000	100000	10000	50000	20000	0.003537	0.000746	0.001799	0.000638
2007-Jun-21	71	33901	2	1000	100000	10000	50000	20000	0.002680	0.000543	0.001636	0.000437
2007-Jun-21	71	33902	2	1000	100000	10000	50000	20000	0.002545	0.000509	0.001553	0.000404
2007-Jun-21	71	33903	2	1000	100000	10000	50000	20000	0.002593	0.000527	0.001583	0.000422
2007-Jun-21	71	33904	2	1000	100000	10000	50000	20000	0.002853	0.000606	0.001745	0.000503
2007-Jun-21	71	33905	2	1000	100000	10000	50000	20000	0.002848	0.000571	0.001689	0.000463
2007-Jun-21	71	33906	2	1000	100000	10000	50000	20000	0.002692	0.000554	0.001645	0.000450
2007-Jun-21	71	33907	2	1000	100000	10000	50000	20000	0.002789	0.000576	0.001709	0.000470
2007-Jun-21	71	33908	2	1000	100000	10000	50000	20000	0.002858	0.000597	0.001745	0.000491
2007-Jun-21	71	33909	2	1000	100000	10000	50000	20000	0.002987	0.000647	0.001829	0.000544
2007-Jun-21	71	33910	2	1000	100000	10000	50000	20000	0.002639	0.000535	0.001609	0.000429
2007-Jun-21	71	33911	2	1000	100000	10000	50000	20000	0.002545	0.000509	0.001553	0.000404
2007-Jun-21	71	33912	2	1000	100000	10000	50000	20000	0.002860	0.000596	0.001755	0.000489
2007-Jun-21	71	33913	2	1000	100000	10000	50000	20000	0.002978	0.000635	0.001825	0.000528
2007-Jun-21	71	33914	2	1000	100000	10000	50000	20000	0.002888	0.000620	0.001761	0.000518
2007-Jun-21	71	33915	2	1000	100000	10000	50000	20000	0.002639	0.000535	0.001609	0.000429
2007-Jun-21	71	33916	2	1000	100000	10000	50000	20000	0.002648	0.000525	0.001622	0.000417
2007-Jun-21	71	33917	2	1000	100000	10000	50000	20000	0.002948	0.000607	0.001750	0.000502
2007-Jun-21	71	33918	2	1000	100000	10000	50000	20000	0.003288	0.000807	0.001957	0.000713
2007-Jun-21	71	33919	2	1000	100000	10000	50000	20000	0.002846	0.000599	0.001741	0.000494
2007-Jun-21	71	33920	2	1000	100000	10000	50000	20000	0.002786	0.000530	0.001661	0.000415
2007-Jun-21	71	33921	2	1000	100000	10000	50000	20000	0.003563	0.000932	0.002106	0.000843
2007-Jun-21	71	33922	2	1000	100000	10000	50000	20000	0.003099	0.000705	0.001882	0.000607

2007-Jun-21	71	33924	2	1000	100000	10000	50000	20000	0.003892	0.001072	0.002271	0.000986
2007-Jun-21	71	33928	2	1000	100000	10000	50000	20000	0.002912	0.000609	0.001788	0.000502
2007-Jun-21	71	33931	2	1000	100000	10000	50000	20000	0.003166	0.000711	0.001928	0.000609
2007-Jun-21	71	33932	2	1000	100000	10000	50000	20000	0.003510	0.000870	0.002081	0.000769
2007-Jun-21	71	33936	2	1000	100000	10000	50000	20000	0.003033	0.000612	0.001803	0.000502
2007-Jun-21	71	33945	2	1000	100000	10000	50000	20000	0.002955	0.000666	0.001789	0.000568
2007-Jun-21	71	33956	2	1000	100000	10000	50000	20000	0.002949	0.000655	0.001795	0.000554
2007-Jun-21	71	33957	2	1000	100000	10000	50000	20000	0.003180	0.000734	0.001937	0.000637
2007-Jun-21	71	33965	2	1000	100000	10000	50000	20000	0.002915	0.000618	0.001789	0.000513
2007-Jun-21	71	33970	2	1000	100000	10000	50000	20000	0.002785	0.000559	0.001710	0.000447
2007-Jun-21	71	33971	2	1000	100000	10000	50000	20000	0.003004	0.000608	0.001788	0.000498
2007-Jun-21	71	33972	2	1000	100000	10000	50000	20000	0.002982	0.000590	0.001777	0.000477
2007-Jun-21	71	33990	2	1000	100000	10000	50000	20000	0.002685	0.000551	0.001638	0.000446
2007-Jun-21	71	33991	2	1000	100000	10000	50000	20000	0.002934	0.000635	0.001794	0.000535
2007-Jun-21	71	33993	2	1000	100000	10000	50000	20000	0.003119	0.000695	0.001907	0.000595
2007-Jun-21	71	33994	2	1000	100000	10000	50000	20000	0.002798	0.000576	0.001716	0.000469
2007-Jun-21	71	34133	2	1000	100000	10000	50000	20000	0.002934	0.000623	0.001794	0.000518
2007-Jun-21	71	34134	2	1000	100000	10000	50000	20000	0.003062	0.000656	0.001874	0.000551
2007-Jun-21	71	34135	2	1000	100000	10000	50000	20000	0.003036	0.000647	0.001869	0.000542
2007-Jun-21	71	34136	2	1000	100000	10000	50000	20000	0.002917	0.000607	0.001794	0.000501
2007-Jun-21	71	33901	3	1000	100000	10000	50000	20000	0.015729	0.005910	0.001666	0.006190
2007-Jun-21	71	33902	3	1000	100000	10000	50000	20000	0.014728	0.005421	0.001581	0.005677
2007-Jun-21	71	33903	3	1000	100000	10000	50000	20000	0.015115	0.005644	0.001611	0.005904
2007-Jun-21	71	33904	3	1000	100000	10000	50000	20000	0.017403	0.006926	0.001776	0.007248
2007-Jun-21	71	33905	3	1000	100000	10000	50000	20000	0.016387	0.006278	0.001718	0.006564
2007-Jun-21	71	33906	3	1000	100000	10000	50000	20000	0.015958	0.006103	0.001674	0.006383
2007-Jun-21	71	33907	3	1000	100000	10000	50000	20000	0.016715	0.006457	0.001739	0.006762
2007-Jun-21	71	33908	3	1000	100000	10000	50000	20000	0.017216	0.006724	0.001777	0.007044
2007-Jun-21	71	33909	3	1000	100000	10000	50000	20000	0.018521	0.007542	0.001861	0.007883
2007-Jun-21	71	33910	3	1000	100000	10000	50000	20000	0.015450	0.005789	0.001638	0.006067
2007-Jun-21	71	33911	3	1000	100000	10000	50000	20000	0.014728	0.005421	0.001581	0.005677
2007-Jun-21	71	33912	3	1000	100000	10000	50000	20000	0.017326	0.006782	0.001786	0.007104
2007-Jun-21	71	33913	3	1000	100000	10000	50000	20000	0.018241	0.007294	0.001857	0.007624
2007-Jun-21	71	33914	3	1000	100000	10000	50000	20000	0.017668	0.007093	0.001793	0.007418
2007-Jun-21	71	33915	3	1000	100000	10000	50000	20000	0.015450	0.005789	0.001638	0.006067
2007-Jun-21	71	33916	3	1000	100000	10000	50000	20000	0.015421	0.005686	0.001651	0.005965
2007-Jun-21	71	33917	3	1000	100000	10000	50000	20000	0.017361	0.006876	0.001780	0.007185

2007-Jun-21	71	33918	3	1000	100000	10000	50000	20000	0.020873	0.009230	0.001991	0.009545
2007-Jun-21	71	33919	3	1000	100000	10000	50000	20000	0.017225	0.006774	0.001772	0.007090
2007-Jun-21	71	33920	3	1000	100000	10000	50000	20000	0.015614	0.005668	0.001690	0.005948
2007-Jun-21	71	33921	3	1000	100000	10000	50000	20000	0.023320	0.010813	0.002142	0.011173
2007-Jun-21	71	33922	3	1000	100000	10000	50000	20000	0.019540	0.008254	0.001916	0.008606
2007-Jun-21	71	33924	3	1000	100000	10000	50000	20000	0.025809	0.012361	0.002310	0.012751
2007-Jun-21	71	33928	3	1000	100000	10000	50000	20000	0.017737	0.006989	0.001820	0.007321
2007-Jun-21	71	33931	3	1000	100000	10000	50000	20000	0.019917	0.008348	0.001962	0.008712
2007-Jun-21	71	33932	3	1000	100000	10000	50000	20000	0.022260	0.009856	0.002117	0.010214
2007-Jun-21	71	33936	3	1000	100000	10000	50000	20000	0.017734	0.006912	0.001834	0.007233
2007-Jun-21	71	33945	3	1000	100000	10000	50000	20000	0.018315	0.007605	0.001820	0.007927
2007-Jun-21	71	33956	3	1000	100000	10000	50000	20000	0.018245	0.007492	0.001827	0.007825
2007-Jun-21	71	33957	3	1000	100000	10000	50000	20000	0.020359	0.008746	0.001972	0.009120
2007-Jun-21	71	33965	3	1000	100000	10000	50000	20000	0.017860	0.007124	0.001821	0.007452
2007-Jun-21	71	33970	3	1000	100000	10000	50000	20000	0.016431	0.006166	0.001740	0.006463
2007-Jun-21	71	33971	3	1000	100000	10000	50000	20000	0.017622	0.006894	0.001819	0.007215
2007-Jun-21	71	33972	3	1000	100000	10000	50000	20000	0.017259	0.006594	0.001808	0.006911
2007-Jun-21	71	33990	3	1000	100000	10000	50000	20000	0.015882	0.006050	0.001667	0.006336
2007-Jun-21	71	33991	3	1000	100000	10000	50000	20000	0.018168	0.007395	0.001826	0.007730
2007-Jun-21	71	33993	3	1000	100000	10000	50000	20000	0.019741	0.008290	0.001941	0.008654
2007-Jun-21	71	33994	3	1000	100000	10000	50000	20000	0.016775	0.006481	0.001747	0.006783
2007-Jun-21	71	34133	3	1000	100000	10000	50000	20000	0.017891	0.007114	0.001826	0.007440
2007-Jun-21	71	34134	3	1000	100000	10000	50000	20000	0.018955	0.007674	0.001908	0.008029
2007-Jun-21	71	34135	3	1000	100000	10000	50000	20000	0.018906	0.007658	0.001902	0.008019
2007-Jun-21	71	34136	3	1000	100000	10000	50000	20000	0.017843	0.007046	0.001826	0.007386
2007-Jun-21	73	32301	1	1000	100000	10000	50000	20000	0.000284	0.000172	0.000590	0.000129
2007-Jun-21	73	32302	1	1000	100000	10000	50000	20000	0.000327	0.000192	0.000647	0.000148
2007-Jun-21	73	32303	1	1000	100000	10000	50000	20000	0.000274	0.000167	0.000579	0.000125
2007-Jun-21	73	32304	1	1000	100000	10000	50000	20000	0.000338	0.000197	0.000662	0.000153
2007-Jun-21	73	32305	1	1000	100000	10000	50000	20000	0.000323	0.000189	0.000636	0.000147
2007-Jun-21	73	32306	1	1000	100000	10000	50000	20000	0.000326	0.000191	0.000646	0.000148
2007-Jun-21	73	32307	1	1000	100000	10000	50000	20000	0.000339	0.000198	0.000665	0.000153
2007-Jun-21	73	32308	1	1000	100000	10000	50000	20000	0.000296	0.000177	0.000606	0.000135
2007-Jun-21	73	32309	1	1000	100000	10000	50000	20000	0.000249	0.000155	0.000536	0.000114
2007-Jun-21	73	32310	1	1000	100000	10000	50000	20000	0.000275	0.000167	0.000573	0.000126
2007-Jun-21	73	32311	1	1000	100000	10000	50000	20000	0.000249	0.000154	0.000530	0.000114
2007-Jun-21	73	32312	1	1000	100000	10000	50000	20000	0.000152	0.000106	0.000369	0.000073

2007-Jun-21	73	32313	1	1000	100000	10000	50000	20000	0.000327	0.000192	0.000647	0.000148
2007-Jun-21	73	32314	1	1000	100000	10000	50000	20000	0.000304	0.000181	0.000613	0.000139
2007-Jun-21	73	32315	1	1000	100000	10000	50000	20000	0.000298	0.000178	0.000608	0.000136
2007-Jun-21	73	32316	1	1000	100000	10000	50000	20000	0.000334	0.000195	0.000659	0.000151
2007-Jun-21	73	32317	1	1000	100000	10000	50000	20000	0.000243	0.000151	0.000521	0.000112
2007-Jun-21	73	32318	1	1000	100000	10000	50000	20000	0.000304	0.000181	0.000613	0.000139
2007-Jun-21	73	32362	1	1000	100000	10000	50000	20000	0.000252	0.000155	0.000528	0.000116
2007-Jun-21	73	32395	1	1000	100000	10000	50000	20000	0.000296	0.000178	0.000606	0.000135
2007-Jun-21	73	32399	1	1000	100000	10000	50000	20000	0.000304	0.000181	0.000615	0.000138
2007-Jun-21	73	32301	2	1000	100000	10000	50000	20000	0.000254	0.000167	0.000589	0.000125
2007-Jun-21	73	32302	2	1000	100000	10000	50000	20000	0.000291	0.000185	0.000646	0.000143
2007-Jun-21	73	32303	2	1000	100000	10000	50000	20000	0.000246	0.000163	0.000579	0.000122
2007-Jun-21	73	32304	2	1000	100000	10000	50000	20000	0.000300	0.000190	0.000661	0.000147
2007-Jun-21	73	32305	2	1000	100000	10000	50000	20000	0.000288	0.000183	0.000635	0.000142
2007-Jun-21	73	32306	2	1000	100000	10000	50000	20000	0.000290	0.000185	0.000645	0.000143
2007-Jun-21	73	32307	2	1000	100000	10000	50000	20000	0.000301	0.000191	0.000664	0.000148
2007-Jun-21	73	32308	2	1000	100000	10000	50000	20000	0.000265	0.000172	0.000605	0.000131
2007-Jun-21	73	32309	2	1000	100000	10000	50000	20000	0.000224	0.000151	0.000536	0.000111
2007-Jun-21	73	32310	2	1000	100000	10000	50000	20000	0.000246	0.000163	0.000572	0.000122
2007-Jun-21	73	32311	2	1000	100000	10000	50000	20000	0.000223	0.000151	0.000529	0.000112
2007-Jun-21	73	32312	2	1000	100000	10000	50000	20000	0.000139	0.000105	0.000369	0.000073
2007-Jun-21	73	32313	2	1000	100000	10000	50000	20000	0.000291	0.000185	0.000646	0.000143
2007-Jun-21	73	32314	2	1000	100000	10000	50000	20000	0.000271	0.000176	0.000612	0.000134
2007-Jun-21	73	32315	2	1000	100000	10000	50000	20000	0.000266	0.000173	0.000607	0.000131
2007-Jun-21	73	32316	2	1000	100000	10000	50000	20000	0.000297	0.000188	0.000658	0.000146
2007-Jun-21	73	32317	2	1000	100000	10000	50000	20000	0.000218	0.000148	0.000521	0.000109
2007-Jun-21	73	32318	2	1000	100000	10000	50000	20000	0.000271	0.000176	0.000612	0.000134
2007-Jun-21	73	32362	2	1000	100000	10000	50000	20000	0.000226	0.000151	0.000527	0.000113
2007-Jun-21	73	32395	2	1000	100000	10000	50000	20000	0.000264	0.000172	0.000606	0.000131
2007-Jun-21	73	32399	2	1000	100000	10000	50000	20000	0.000271	0.000175	0.000615	0.000134
2007-Jun-21	73	32301	3	1000	100000	10000	50000	20000	0.002368	0.000730	0.000605	0.000698
2007-Jun-21	73	32302	3	1000	100000	10000	50000	20000	0.002759	0.000898	0.000664	0.000870
2007-Jun-21	73	32303	3	1000	100000	10000	50000	20000	0.002290	0.000697	0.000594	0.000662
2007-Jun-21	73	32304	3	1000	100000	10000	50000	20000	0.002871	0.000945	0.000680	0.000918
2007-Jun-21	73	32305	3	1000	100000	10000	50000	20000	0.002738	0.000904	0.000652	0.000877
2007-Jun-21	73	32306	3	1000	100000	10000	50000	20000	0.002748	0.000893	0.000663	0.000864
2007-Jun-21	73	32307	3	1000	100000	10000	50000	20000	0.002875	0.000943	0.000682	0.000916

2007-Jun-21	73	32308	3	1000	100000	10000	50000	20000	0.002493	0.000788	0.000621	0.000757
2007-Jun-21	73	32309	3	1000	100000	10000	50000	20000	0.002055	0.000615	0.000550	0.000581
2007-Jun-21	73	32310	3	1000	100000	10000	50000	20000	0.002288	0.000711	0.000587	0.000679
2007-Jun-21	73	32311	3	1000	100000	10000	50000	20000	0.002036	0.000616	0.000543	0.000580
2007-Jun-21	73	32312	3	1000	100000	10000	50000	20000	0.001154	0.000309	0.000377	0.000268
2007-Jun-21	73	32313	3	1000	100000	10000	50000	20000	0.002757	0.000897	0.000663	0.000869
2007-Jun-21	73	32314	3	1000	100000	10000	50000	20000	0.002538	0.000812	0.000628	0.000781
2007-Jun-21	73	32315	3	1000	100000	10000	50000	20000	0.002496	0.000788	0.000624	0.000757
2007-Jun-21	73	32316	3	1000	100000	10000	50000	20000	0.002841	0.000931	0.000676	0.000904
2007-Jun-21	73	32317	3	1000	100000	10000	50000	20000	0.001999	0.000600	0.000534	0.000565
2007-Jun-21	73	32318	3	1000	100000	10000	50000	20000	0.002538	0.000812	0.000628	0.000781
2007-Jun-21	73	32362	3	1000	100000	10000	50000	20000	0.002070	0.000645	0.000541	0.000610
2007-Jun-21	73	32395	3	1000	100000	10000	50000	20000	0.002469	0.000777	0.000622	0.000746
2007-Jun-21	73	32399	3	1000	100000	10000	50000	20000	0.002559	0.000812	0.000631	0.000782
2007-Jun-21	75	32621	1	1000	100000	10000	50000	20000	0.000620	0.000333	0.001017	0.000282
2007-Jun-21	75	32625	1	1000	100000	10000	50000	20000	0.000651	0.000363	0.000965	0.000318
2007-Jun-21	75	32626	1	1000	100000	10000	50000	20000	0.000292	0.000184	0.000625	0.000140
2007-Jun-21	75	32639	1	1000	100000	10000	50000	20000	0.000563	0.000309	0.000918	0.000260
2007-Jun-21	75	32644	1	1000	100000	10000	50000	20000	0.000511	0.000282	0.000882	0.000233
2007-Jun-21	75	32668	1	1000	100000	10000	50000	20000	0.000686	0.000366	0.001046	0.000318
2007-Jun-21	75	32683	1	1000	100000	10000	50000	20000	0.000377	0.000220	0.000719	0.000172
2007-Jun-21	75	32696	1	1000	100000	10000	50000	20000	0.000484	0.000271	0.000898	0.000218
2007-Jun-21	75	34449	1	1000	100000	10000	50000	20000	0.000591	0.000324	0.000926	0.000276
2007-Jun-21	75	34498	1	1000	100000	10000	50000	20000	0.000706	0.000374	0.001071	0.000326
2007-Jun-21	75	32621	2	1000	100000	10000	50000	20000	0.000543	0.000313	0.001015	0.000264
2007-Jun-21	75	32625	2	1000	100000	10000	50000	20000	0.000563	0.000330	0.000963	0.000289
2007-Jun-21	75	32626	2	1000	100000	10000	50000	20000	0.000260	0.000179	0.000624	0.000135
2007-Jun-21	75	32639	2	1000	100000	10000	50000	20000	0.000493	0.000289	0.000916	0.000243
2007-Jun-21	75	32644	2	1000	100000	10000	50000	20000	0.000449	0.000267	0.000880	0.000220
2007-Jun-21	75	32668	2	1000	100000	10000	50000	20000	0.000598	0.000340	0.001044	0.000295
2007-Jun-21	75	32683	2	1000	100000	10000	50000	20000	0.000334	0.000211	0.000718	0.000165
2007-Jun-21	75	32696	2	1000	100000	10000	50000	20000	0.000428	0.000260	0.000896	0.000208
2007-Jun-21	75	34449	2	1000	100000	10000	50000	20000	0.000516	0.000301	0.000924	0.000257
2007-Jun-21	75	34498	2	1000	100000	10000	50000	20000	0.000615	0.000348	0.001069	0.000303
2007-Jun-21	75	32621	3	1000	100000	10000	50000	20000	0.005206	0.001958	0.001044	0.001946
2007-Jun-21	75	32625	3	1000	100000	10000	50000	20000	0.005206	0.002099	0.000991	0.002079
2007-Jun-21	75	32626	3	1000	100000	10000	50000	20000	0.002513	0.000798	0.000641	0.000760

2007-Jun-21	75	32639	3	1000	100000	10000	50000	20000	0.004590	0.001713	0.000942	0.001690
2007-Jun-21	75	32644	3	1000	100000	10000	50000	20000	0.004272	0.001561	0.000905	0.001540
2007-Jun-21	75	32668	3	1000	100000	10000	50000	20000	0.005587	0.002202	0.001073	0.002188
2007-Jun-21	75	32683	3	1000	100000	10000	50000	20000	0.003079	0.001026	0.000737	0.000992
2007-Jun-21	75	32696	3	1000	100000	10000	50000	20000	0.004156	0.001438	0.000922	0.001414
2007-Jun-21	75	34449	3	1000	100000	10000	50000	20000	0.004697	0.001816	0.000950	0.001788
2007-Jun-21	75	34498	3	1000	100000	10000	50000	20000	0.005746	0.002270	0.001099	0.002257
2007-Jun-21	77	32321	1	1000	100000	10000	50000	20000	0.000304	0.000189	0.000666	0.000140
2007-Jun-21	77	32334	1	1000	100000	10000	50000	20000	0.000336	0.000198	0.000674	0.000154
2007-Jun-21	77	32360	1	1000	100000	10000	50000	20000	0.000340	0.000201	0.000704	0.000154
2007-Jun-21	77	32321	2	1000	100000	10000	50000	20000	0.000274	0.000185	0.000665	0.000137
2007-Jun-21	77	32334	2	1000	100000	10000	50000	20000	0.000299	0.000192	0.000673	0.000149
2007-Jun-21	77	32360	2	1000	100000	10000	50000	20000	0.000303	0.000196	0.000703	0.000149
2007-Jun-21	77	32321	3	1000	100000	10000	50000	20000	0.002539	0.000748	0.000682	0.000713
2007-Jun-21	77	32334	3	1000	100000	10000	50000	20000	0.002828	0.000921	0.000691	0.000894
2007-Jun-21	77	32360	3	1000	100000	10000	50000	20000	0.002894	0.000914	0.000722	0.000888
2007-Jun-21	79	32059	1	1000	100000	10000	50000	20000	0.000184	0.000120	0.000410	0.000087
2007-Jun-21	79	32331	1	1000	100000	10000	50000	20000	0.000193	0.000123	0.000431	0.000090
2007-Jun-21	79	32340	1	1000	100000	10000	50000	20000	0.000238	0.000147	0.000507	0.000109
2007-Jun-21	79	32341	1	1000	100000	10000	50000	20000	0.000246	0.000150	0.000511	0.000113
2007-Jun-21	79	32350	1	1000	100000	10000	50000	20000	0.000156	0.000105	0.000367	0.000073
2007-Jun-21	79	32059	2	1000	100000	10000	50000	20000	0.000166	0.000117	0.000410	0.000085
2007-Jun-21	79	32331	2	1000	100000	10000	50000	20000	0.000174	0.000121	0.000431	0.000088
2007-Jun-21	79	32340	2	1000	100000	10000	50000	20000	0.000213	0.000143	0.000506	0.000106
2007-Jun-21	79	32341	2	1000	100000	10000	50000	20000	0.000220	0.000146	0.000511	0.000110
2007-Jun-21	79	32350	2	1000	100000	10000	50000	20000	0.000141	0.000103	0.000367	0.000072
2007-Jun-21	79	32059	3	1000	100000	10000	50000	20000	0.001472	0.000433	0.000420	0.000397
2007-Jun-21	79	32331	3	1000	100000	10000	50000	20000	0.001609	0.000483	0.000442	0.000452
2007-Jun-21	79	32340	3	1000	100000	10000	50000	20000	0.001994	0.000613	0.000520	0.000582
2007-Jun-21	79	32341	3	1000	100000	10000	50000	20000	0.002063	0.000650	0.000524	0.000621
2007-Jun-21	79	32350	3	1000	100000	10000	50000	20000	0.001227	0.000333	0.000376	0.000298
2007-Jun-21	81	34201	1	1000	100000	10000	50000	20000	0.002934	0.000666	0.001471	0.000577
2007-Jun-21	81	34202	1	1000	100000	10000	50000	20000	0.003005	0.000701	0.001501	0.000614
2007-Jun-21	81	34203	1	1000	100000	10000	50000	20000	0.002931	0.000689	0.001457	0.000601
2007-Jun-21	81	34204	1	1000	100000	10000	50000	20000	0.002839	0.000640	0.001427	0.000552
2007-Jun-21	81	34205	1	1000	100000	10000	50000	20000	0.002764	0.000612	0.001386	0.000522
2007-Jun-21	81	34206	1	1000	100000	10000	50000	20000	0.002708	0.000573	0.001372	0.000484

2007-Jun-21	81	34207	1	1000	100000	10000	50000	20000	0.002637	0.000565	0.001333	0.000477
2007-Jun-21	81	34208	1	1000	100000	10000	50000	20000	0.002841	0.000645	0.001425	0.000558
2007-Jun-21	81	34209	1	1000	100000	10000	50000	20000	0.002769	0.000630	0.001388	0.000543
2007-Jun-21	81	34210	1	1000	100000	10000	50000	20000	0.003340	0.000881	0.001603	0.000785
2007-Jun-21	81	34211	1	1000	100000	10000	50000	20000	0.003227	0.000783	0.001598	0.000693
2007-Jun-21	81	34212	1	1000	100000	10000	50000	20000	0.003074	0.000720	0.001535	0.000631
2007-Jun-21	81	34215	1	1000	100000	10000	50000	20000	0.003659	0.000992	0.001764	0.000897
2007-Jun-21	81	34216	1	1000	100000	10000	50000	20000	0.003461	0.000944	0.001650	0.000849
2007-Jun-21	81	34217	1	1000	100000	10000	50000	20000	0.004371	0.001440	0.001912	0.001305
2007-Jun-21	81	34218	1	1000	100000	10000	50000	20000	0.004665	0.001567	0.002037	0.001430
2007-Jun-21	81	34219	1	1000	100000	10000	50000	20000	0.003040	0.000669	0.001480	0.000581
2007-Jun-21	81	34220	1	1000	100000	10000	50000	20000	0.003022	0.000747	0.001477	0.000657
2007-Jun-21	81	34221	1	1000	100000	10000	50000	20000	0.003050	0.000733	0.001513	0.000644
2007-Jun-21	81	34222	1	1000	100000	10000	50000	20000	0.002740	0.000608	0.001376	0.000520
2007-Jun-21	81	34228	1	1000	100000	10000	50000	20000	0.004074	0.001221	0.001867	0.001109
2007-Jun-21	81	34243	1	1000	100000	10000	50000	20000	0.002824	0.000634	0.001418	0.000545
2007-Jun-21	81	34250	1	1000	100000	10000	50000	20000	0.003022	0.000747	0.001477	0.000657
2007-Jun-21	81	34251	1	1000	100000	10000	50000	20000	0.003259	0.000724	0.001587	0.000632
2007-Jun-21	81	34260	1	1000	100000	10000	50000	20000	0.002801	0.000631	0.001406	0.000543
2007-Jun-21	81	34264	1	1000	100000	10000	50000	20000	0.002768	0.000629	0.001385	0.000543
2007-Jun-21	81	34270	1	1000	100000	10000	50000	20000	0.002998	0.000718	0.001487	0.000631
2007-Jun-21	81	34280	1	1000	100000	10000	50000	20000	0.002781	0.000614	0.001397	0.000524
2007-Jun-21	81	34281	1	1000	100000	10000	50000	20000	0.002746	0.000604	0.001384	0.000516
2007-Jun-21	81	34282	1	1000	100000	10000	50000	20000	0.002746	0.000604	0.001384	0.000516
2007-Jun-21	81	34201	2	1000	100000	10000	50000	20000	0.002408	0.000533	0.001467	0.000448
2007-Jun-21	81	34202	2	1000	100000	10000	50000	20000	0.002458	0.000557	0.001497	0.000474
2007-Jun-21	81	34203	2	1000	100000	10000	50000	20000	0.002399	0.000547	0.001453	0.000464
2007-Jun-21	81	34204	2	1000	100000	10000	50000	20000	0.002332	0.000514	0.001423	0.000430
2007-Jun-21	81	34205	2	1000	100000	10000	50000	20000	0.002278	0.000494	0.001382	0.000409
2007-Jun-21	81	34206	2	1000	100000	10000	50000	20000	0.002239	0.000469	0.001368	0.000382
2007-Jun-21	81	34207	2	1000	100000	10000	50000	20000	0.002179	0.000461	0.001330	0.000376
2007-Jun-21	81	34208	2	1000	100000	10000	50000	20000	0.002332	0.000517	0.001422	0.000434
2007-Jun-21	81	34209	2	1000	100000	10000	50000	20000	0.002274	0.000505	0.001384	0.000423
2007-Jun-21	81	34210	2	1000	100000	10000	50000	20000	0.002709	0.000679	0.001599	0.000596
2007-Jun-21	81	34211	2	1000	100000	10000	50000	20000	0.002628	0.000615	0.001594	0.000532
2007-Jun-21	81	34212	2	1000	100000	10000	50000	20000	0.002513	0.000571	0.001530	0.000487
2007-Jun-21	81	34215	2	1000	100000	10000	50000	20000	0.002951	0.000757	0.001759	0.000676

2007-Jun-21	81	34216	2	1000	100000	10000	50000	20000	0.002794	0.000721	0.001645	0.000642
2007-Jun-21	81	34217	2	1000	100000	10000	50000	20000	0.003491	0.001061	0.001906	0.000966
2007-Jun-21	81	34218	2	1000	100000	10000	50000	20000	0.003713	0.001149	0.002031	0.001055
2007-Jun-21	81	34219	2	1000	100000	10000	50000	20000	0.002488	0.000537	0.001476	0.000452
2007-Jun-21	81	34220	2	1000	100000	10000	50000	20000	0.002465	0.000586	0.001473	0.000505
2007-Jun-21	81	34221	2	1000	100000	10000	50000	20000	0.002490	0.000577	0.001509	0.000495
2007-Jun-21	81	34222	2	1000	100000	10000	50000	20000	0.002257	0.000491	0.001372	0.000407
2007-Jun-21	81	34228	2	1000	100000	10000	50000	20000	0.003267	0.000913	0.001861	0.000828
2007-Jun-21	81	34243	2	1000	100000	10000	50000	20000	0.002322	0.000510	0.001414	0.000425
2007-Jun-21	81	34250	2	1000	100000	10000	50000	20000	0.002464	0.000586	0.001472	0.000505
2007-Jun-21	81	34251	2	1000	100000	10000	50000	20000	0.002661	0.000578	0.001583	0.000491
2007-Jun-21	81	34260	2	1000	100000	10000	50000	20000	0.002302	0.000507	0.001402	0.000424
2007-Jun-21	81	34264	2	1000	100000	10000	50000	20000	0.002274	0.000504	0.001381	0.000422
2007-Jun-21	81	34270	2	1000	100000	10000	50000	20000	0.002447	0.000567	0.001483	0.000486
2007-Jun-21	81	34280	2	1000	100000	10000	50000	20000	0.002292	0.000497	0.001393	0.000410
2007-Jun-21	81	34281	2	1000	100000	10000	50000	20000	0.002262	0.000489	0.001380	0.000404
2007-Jun-21	81	34282	2	1000	100000	10000	50000	20000	0.002262	0.000489	0.001380	0.000404
2007-Jun-21	81	34201	3	1000	100000	10000	50000	20000	0.014726	0.005990	0.001493	0.006234
2007-Jun-21	81	34202	3	1000	100000	10000	50000	20000	0.015241	0.006342	0.001524	0.006588
2007-Jun-21	81	34203	3	1000	100000	10000	50000	20000	0.014690	0.006071	0.001479	0.006299
2007-Jun-21	81	34204	3	1000	100000	10000	50000	20000	0.014175	0.005721	0.001448	0.005950
2007-Jun-21	81	34205	3	1000	100000	10000	50000	20000	0.013567	0.005348	0.001407	0.005567
2007-Jun-21	81	34206	3	1000	100000	10000	50000	20000	0.013275	0.005113	0.001393	0.005338
2007-Jun-21	81	34207	3	1000	100000	10000	50000	20000	0.012876	0.004966	0.001354	0.005177
2007-Jun-21	81	34208	3	1000	100000	10000	50000	20000	0.014206	0.005757	0.001447	0.005989
2007-Jun-21	81	34209	3	1000	100000	10000	50000	20000	0.013778	0.005566	0.001409	0.005787
2007-Jun-21	81	34210	3	1000	100000	10000	50000	20000	0.016762	0.007340	0.001627	0.007575
2007-Jun-21	81	34211	3	1000	100000	10000	50000	20000	0.016552	0.007081	0.001622	0.007343
2007-Jun-21	81	34212	3	1000	100000	10000	50000	20000	0.015619	0.006520	0.001557	0.006770
2007-Jun-21	81	34215	3	1000	100000	10000	50000	20000	0.019040	0.008649	0.001789	0.008938
2007-Jun-21	81	34216	3	1000	100000	10000	50000	20000	0.017603	0.007917	0.001674	0.008158
2007-Jun-21	81	34217	3	1000	100000	10000	50000	20000	0.021182	0.010160	0.001939	0.010374
2007-Jun-21	81	34218	3	1000	100000	10000	50000	20000	0.022977	0.011251	0.002066	0.011483
2007-Jun-21	81	34219	3	1000	100000	10000	50000	20000	0.014832	0.006060	0.001501	0.006300
2007-Jun-21	81	34220	3	1000	100000	10000	50000	20000	0.015073	0.006368	0.001499	0.006584
2007-Jun-21	81	34221	3	1000	100000	10000	50000	20000	0.015480	0.006528	0.001536	0.006773
2007-Jun-21	81	34222	3	1000	100000	10000	50000	20000	0.013485	0.005338	0.001397	0.005547

2007-Jun-21	81	34228	3	1000	100000	10000	50000	20000	0.020494	0.009591	0.001893	0.009845
2007-Jun-21	81	34243	3	1000	100000	10000	50000	20000	0.014025	0.005618	0.001439	0.005844
2007-Jun-21	81	34250	3	1000	100000	10000	50000	20000	0.015072	0.006368	0.001498	0.006583
2007-Jun-21	81	34251	3	1000	100000	10000	50000	20000	0.016098	0.006677	0.001610	0.006947
2007-Jun-21	81	34260	3	1000	100000	10000	50000	20000	0.013928	0.005599	0.001427	0.005824
2007-Jun-21	81	34264	3	1000	100000	10000	50000	20000	0.013752	0.005551	0.001406	0.005767
2007-Jun-21	81	34270	3	1000	100000	10000	50000	20000	0.015181	0.006384	0.001509	0.006622
2007-Jun-21	81	34280	3	1000	100000	10000	50000	20000	0.013673	0.005389	0.001418	0.005610
2007-Jun-21	81	34281	3	1000	100000	10000	50000	20000	0.013580	0.005367	0.001405	0.005592
2007-Jun-21	81	34282	3	1000	100000	10000	50000	20000	0.013580	0.005367	0.001405	0.005592
2007-Jun-21	83	32111	1	1000	100000	10000	50000	20000	0.002096	0.000333	0.001036	0.000234
2007-Jun-21	83	32113	1	1000	100000	10000	50000	20000	0.001614	0.000252	0.000804	0.000166
2007-Jun-21	83	32133	1	1000	100000	10000	50000	20000	0.002229	0.000371	0.001103	0.000271
2007-Jun-21	83	32134	1	1000	100000	10000	50000	20000	0.001416	0.000220	0.000710	0.000141
2007-Jun-21	83	32179	1	1000	100000	10000	50000	20000	0.002317	0.000382	0.001146	0.000279
2007-Jun-21	83	32182	1	1000	100000	10000	50000	20000	0.001555	0.000243	0.000778	0.000159
2007-Jun-21	83	32183	1	1000	100000	10000	50000	20000	0.002423	0.000419	0.001187	0.000315
2007-Jun-21	83	32192	1	1000	100000	10000	50000	20000	0.002050	0.000331	0.001007	0.000234
2007-Jun-21	83	32195	1	1000	100000	10000	50000	20000	0.002310	0.000380	0.001143	0.000277
2007-Jun-21	83	32617	1	1000	100000	10000	50000	20000	0.002213	0.000362	0.001091	0.000262
2007-Jun-21	83	32634	1	1000	100000	10000	50000	20000	0.001809	0.000303	0.000885	0.000215
2007-Jun-21	83	32663	1	1000	100000	10000	50000	20000	0.001953	0.000315	0.000968	0.000222
2007-Jun-21	83	32664	1	1000	100000	10000	50000	20000	0.001874	0.000301	0.000929	0.000208
2007-Jun-21	83	32681	1	1000	100000	10000	50000	20000	0.001924	0.000317	0.000951	0.000225
2007-Jun-21	83	32686	1	1000	100000	10000	50000	20000	0.001698	0.000271	0.000844	0.000184
2007-Jun-21	83	34420	1	1000	100000	10000	50000	20000	0.002257	0.000371	0.001113	0.000270
2007-Jun-21	83	34421	1	1000	100000	10000	50000	20000	0.002067	0.000335	0.001021	0.000237
2007-Jun-21	83	34430	1	1000	100000	10000	50000	20000	0.002102	0.000380	0.001022	0.000288
2007-Jun-21	83	34431	1	1000	100000	10000	50000	20000	0.002500	0.000472	0.001207	0.000374
2007-Jun-21	83	34432	1	1000	100000	10000	50000	20000	0.002044	0.000349	0.001001	0.000256
2007-Jun-21	83	34470	1	1000	100000	10000	50000	20000	0.002139	0.000351	0.001052	0.000253
2007-Jun-21	83	34471	1	1000	100000	10000	50000	20000	0.001947	0.000311	0.000962	0.000217
2007-Jun-21	83	34472	1	1000	100000	10000	50000	20000	0.002137	0.000343	0.001056	0.000243
2007-Jun-21	83	34473	1	1000	100000	10000	50000	20000	0.002153	0.000358	0.001059	0.000260
2007-Jun-21	83	34474	1	1000	100000	10000	50000	20000	0.002047	0.000335	0.001007	0.000239
2007-Jun-21	83	34475	1	1000	100000	10000	50000	20000	0.001804	0.000289	0.000893	0.000198
2007-Jun-21	83	34476	1	1000	100000	10000	50000	20000	0.002097	0.000350	0.001027	0.000255

2007-Jun-21	83	34477	1	1000	100000	10000	50000	20000	0.002012	0.000326	0.000990	0.000231
2007-Jun-21	83	34478	1	1000	100000	10000	50000	20000	0.002012	0.000327	0.000990	0.000231
2007-Jun-21	83	34479	1	1000	100000	10000	50000	20000	0.001963	0.000315	0.000972	0.000221
2007-Jun-21	83	34480	1	1000	100000	10000	50000	20000	0.001977	0.000317	0.000974	0.000221
2007-Jun-21	83	34481	1	1000	100000	10000	50000	20000	0.002317	0.000398	0.001138	0.000299
2007-Jun-21	83	34482	1	1000	100000	10000	50000	20000	0.001703	0.000273	0.000842	0.000186
2007-Jun-21	83	34483	1	1000	100000	10000	50000	20000	0.002251	0.000370	0.001113	0.000270
2007-Jun-21	83	34488	1	1000	100000	10000	50000	20000	0.001279	0.000199	0.000640	0.000123
2007-Jun-21	83	34489	1	1000	100000	10000	50000	20000	0.001779	0.000279	0.000876	0.000188
2007-Jun-21	83	34491	1	1000	100000	10000	50000	20000	0.002393	0.000403	0.001186	0.000299
2007-Jun-21	83	34492	1	1000	100000	10000	50000	20000	0.002213	0.000369	0.001093	0.000269
2007-Jun-21	83	32111	2	1000	100000	10000	50000	20000	0.001776	0.000304	0.001034	0.000205
2007-Jun-21	83	32113	2	1000	100000	10000	50000	20000	0.001376	0.000236	0.000802	0.000150
2007-Jun-21	83	32133	2	1000	100000	10000	50000	20000	0.001881	0.000332	0.001100	0.000232
2007-Jun-21	83	32134	2	1000	100000	10000	50000	20000	0.001209	0.000208	0.000709	0.000129
2007-Jun-21	83	32179	2	1000	100000	10000	50000	20000	0.001956	0.000342	0.001143	0.000239
2007-Jun-21	83	32182	2	1000	100000	10000	50000	20000	0.001326	0.000227	0.000777	0.000144
2007-Jun-21	83	32183	2	1000	100000	10000	50000	20000	0.002039	0.000368	0.001184	0.000265
2007-Jun-21	83	32192	2	1000	100000	10000	50000	20000	0.001737	0.000300	0.001005	0.000204
2007-Jun-21	83	32195	2	1000	100000	10000	50000	20000	0.001950	0.000340	0.001140	0.000238
2007-Jun-21	83	32617	2	1000	100000	10000	50000	20000	0.001869	0.000325	0.001089	0.000225
2007-Jun-21	83	32634	2	1000	100000	10000	50000	20000	0.001531	0.000273	0.000883	0.000186
2007-Jun-21	83	32663	2	1000	100000	10000	50000	20000	0.001654	0.000287	0.000966	0.000193
2007-Jun-21	83	32664	2	1000	100000	10000	50000	20000	0.001590	0.000275	0.000927	0.000183
2007-Jun-21	83	32681	2	1000	100000	10000	50000	20000	0.001628	0.000286	0.000949	0.000195
2007-Jun-21	83	32686	2	1000	100000	10000	50000	20000	0.001442	0.000250	0.000842	0.000163
2007-Jun-21	83	34420	2	1000	100000	10000	50000	20000	0.001906	0.000333	0.001110	0.000232
2007-Jun-21	83	34421	2	1000	100000	10000	50000	20000	0.001750	0.000304	0.001019	0.000206
2007-Jun-21	83	34430	2	1000	100000	10000	50000	20000	0.001765	0.000331	0.001020	0.000241
2007-Jun-21	83	34431	2	1000	100000	10000	50000	20000	0.002087	0.000402	0.001204	0.000306
2007-Jun-21	83	34432	2	1000	100000	10000	50000	20000	0.001724	0.000310	0.000999	0.000218
2007-Jun-21	83	34470	2	1000	100000	10000	50000	20000	0.001808	0.000316	0.001049	0.000218
2007-Jun-21	83	34471	2	1000	100000	10000	50000	20000	0.001651	0.000285	0.000960	0.000190
2007-Jun-21	83	34472	2	1000	100000	10000	50000	20000	0.001810	0.000312	0.001054	0.000211
2007-Jun-21	83	34473	2	1000	100000	10000	50000	20000	0.001818	0.000321	0.001056	0.000224
2007-Jun-21	83	34474	2	1000	100000	10000	50000	20000	0.001731	0.000302	0.001005	0.000207
2007-Jun-21	83	34475	2	1000	100000	10000	50000	20000	0.001532	0.000266	0.000891	0.000175

2007-Jun-21	83	34476	2	1000	100000	10000	50000	20000	0.001770	0.000314	0.001025	0.000219
2007-Jun-21	83	34477	2	1000	100000	10000	50000	20000	0.001704	0.000296	0.000988	0.000201
2007-Jun-21	83	34478	2	1000	100000	10000	50000	20000	0.001704	0.000296	0.000987	0.000201
2007-Jun-21	83	34479	2	1000	100000	10000	50000	20000	0.001664	0.000288	0.000970	0.000193
2007-Jun-21	83	34480	2	1000	100000	10000	50000	20000	0.001677	0.000289	0.000972	0.000194
2007-Jun-21	83	34481	2	1000	100000	10000	50000	20000	0.001949	0.000351	0.001136	0.000252
2007-Jun-21	83	34482	2	1000	100000	10000	50000	20000	0.001447	0.000252	0.000840	0.000165
2007-Jun-21	83	34483	2	1000	100000	10000	50000	20000	0.001901	0.000332	0.001110	0.000231
2007-Jun-21	83	34488	2	1000	100000	10000	50000	20000	0.001096	0.000190	0.000639	0.000114
2007-Jun-21	83	34489	2	1000	100000	10000	50000	20000	0.001514	0.000259	0.000874	0.000168
2007-Jun-21	83	34491	2	1000	100000	10000	50000	20000	0.002015	0.000357	0.001183	0.000254
2007-Jun-21	83	34492	2	1000	100000	10000	50000	20000	0.001868	0.000330	0.001090	0.000231
2007-Jun-21	83	32111	3	1000	100000	10000	50000	20000	0.007876	0.002081	0.001052	0.002154
2007-Jun-21	83	32113	3	1000	100000	10000	50000	20000	0.005654	0.001269	0.000816	0.001282
2007-Jun-21	83	32133	3	1000	100000	10000	50000	20000	0.008681	0.002501	0.001120	0.002595
2007-Jun-21	83	32134	3	1000	100000	10000	50000	20000	0.004854	0.001024	0.000722	0.001023
2007-Jun-21	83	32179	3	1000	100000	10000	50000	20000	0.009054	0.002608	0.001163	0.002713
2007-Jun-21	83	32182	3	1000	100000	10000	50000	20000	0.005443	0.001214	0.000790	0.001225
2007-Jun-21	83	32183	3	1000	100000	10000	50000	20000	0.009589	0.002896	0.001204	0.003010
2007-Jun-21	83	32192	3	1000	100000	10000	50000	20000	0.007644	0.002023	0.001022	0.002082
2007-Jun-21	83	32195	3	1000	100000	10000	50000	20000	0.009039	0.002608	0.001160	0.002715
2007-Jun-21	83	32617	3	1000	100000	10000	50000	20000	0.008539	0.002410	0.001108	0.002499
2007-Jun-21	83	32634	3	1000	100000	10000	50000	20000	0.006627	0.001742	0.000898	0.001770
2007-Jun-21	83	32663	3	1000	100000	10000	50000	20000	0.007321	0.001944	0.000982	0.002000
2007-Jun-21	83	32664	3	1000	100000	10000	50000	20000	0.006921	0.001778	0.000943	0.001822
2007-Jun-21	83	32681	3	1000	100000	10000	50000	20000	0.007238	0.001963	0.000965	0.002015
2007-Jun-21	83	32686	3	1000	100000	10000	50000	20000	0.006153	0.001517	0.000857	0.001544
2007-Jun-21	83	34420	3	1000	100000	10000	50000	20000	0.008740	0.002488	0.001129	0.002582
2007-Jun-21	83	34421	3	1000	100000	10000	50000	20000	0.007779	0.002087	0.001036	0.002153
2007-Jun-21	83	34430	3	1000	100000	10000	50000	20000	0.008195	0.002496	0.001037	0.002562
2007-Jun-21	83	34431	3	1000	100000	10000	50000	20000	0.010222	0.003405	0.001224	0.003524
2007-Jun-21	83	34432	3	1000	100000	10000	50000	20000	0.007807	0.002229	0.001016	0.002290
2007-Jun-21	83	34470	3	1000	100000	10000	50000	20000	0.008156	0.002266	0.001067	0.002341
2007-Jun-21	83	34471	3	1000	100000	10000	50000	20000	0.007211	0.001867	0.000976	0.001918
2007-Jun-21	83	34472	3	1000	100000	10000	50000	20000	0.008097	0.002186	0.001072	0.002262
2007-Jun-21	83	34473	3	1000	100000	10000	50000	20000	0.008249	0.002327	0.001074	0.002403
2007-Jun-21	83	34474	3	1000	100000	10000	50000	20000	0.007718	0.002096	0.001022	0.002160

2007-Jun-21	83	34475	3	1000	100000	10000	50000	20000	0.006521	0.001605	0.000906	0.001635
2007-Jun-21	83	34476	3	1000	100000	10000	50000	20000	0.008012	0.002261	0.001043	0.002331
2007-Jun-21	83	34477	3	1000	100000	10000	50000	20000	0.007511	0.001995	0.001005	0.002051
2007-Jun-21	83	34478	3	1000	100000	10000	50000	20000	0.007509	0.001994	0.001004	0.002050
2007-Jun-21	83	34479	3	1000	100000	10000	50000	20000	0.007319	0.001917	0.000987	0.001973
2007-Jun-21	83	34480	3	1000	100000	10000	50000	20000	0.007296	0.001880	0.000988	0.001930
2007-Jun-21	83	34481	3	1000	100000	10000	50000	20000	0.009194	0.002789	0.001155	0.002891
2007-Jun-21	83	34482	3	1000	100000	10000	50000	20000	0.006071	0.001458	0.000855	0.001476
2007-Jun-21	83	34483	3	1000	100000	10000	50000	20000	0.008770	0.002517	0.001130	0.002614
2007-Jun-21	83	34488	3	1000	100000	10000	50000	20000	0.004139	0.000746	0.000650	0.000716
2007-Jun-21	83	34489	3	1000	100000	10000	50000	20000	0.006301	0.001474	0.000889	0.001497
2007-Jun-21	83	34491	3	1000	100000	10000	50000	20000	0.009546	0.002870	0.001203	0.002988
2007-Jun-21	83	34492	3	1000	100000	10000	50000	20000	0.008601	0.002476	0.001109	0.002568
2007-Jun-21	85	33455	1	1000	100000	10000	50000	20000	0.004749	0.001185	0.001845	0.001083
2007-Jun-21	85	33475	1	1000	100000	10000	50000	20000	0.004845	0.001241	0.001865	0.001138
2007-Jun-21	85	34956	1	1000	100000	10000	50000	20000	0.004618	0.001068	0.001832	0.000963
2007-Jun-21	85	34957	1	1000	100000	10000	50000	20000	0.007456	0.002626	0.002510	0.002485
2007-Jun-21	85	34958	1	1000	100000	10000	50000	20000	0.004264	0.000974	0.001703	0.000877
2007-Jun-21	85	34990	1	1000	100000	10000	50000	20000	0.004149	0.000918	0.001670	0.000819
2007-Jun-21	85	34991	1	1000	100000	10000	50000	20000	0.004751	0.001183	0.001843	0.001080
2007-Jun-21	85	34992	1	1000	100000	10000	50000	20000	0.005118	0.001382	0.001931	0.001274
2007-Jun-21	85	34994	1	1000	100000	10000	50000	20000	0.004361	0.001006	0.001736	0.000909
2007-Jun-21	85	34995	1	1000	100000	10000	50000	20000	0.004263	0.001000	0.001685	0.000903
2007-Jun-21	85	34996	1	1000	100000	10000	50000	20000	0.006026	0.001718	0.002234	0.001614
2007-Jun-21	85	34997	1	1000	100000	10000	50000	20000	0.004589	0.001104	0.001802	0.001004
2007-Jun-21	85	33455	2	1000	100000	10000	50000	20000	0.003360	0.000731	0.001837	0.000636
2007-Jun-21	85	33475	2	1000	100000	10000	50000	20000	0.003420	0.000761	0.001857	0.000667
2007-Jun-21	85	34956	2	1000	100000	10000	50000	20000	0.003301	0.000677	0.001824	0.000573
2007-Jun-21	85	34957	2	1000	100000	10000	50000	20000	0.005047	0.001484	0.002498	0.001414
2007-Jun-21	85	34958	2	1000	100000	10000	50000	20000	0.003050	0.000620	0.001696	0.000522
2007-Jun-21	85	34990	2	1000	100000	10000	50000	20000	0.002987	0.000594	0.001663	0.000493
2007-Jun-21	85	34991	2	1000	100000	10000	50000	20000	0.003364	0.000730	0.001835	0.000634
2007-Jun-21	85	34992	2	1000	100000	10000	50000	20000	0.003591	0.000834	0.001922	0.000743
2007-Jun-21	85	34994	2	1000	100000	10000	50000	20000	0.003113	0.000637	0.001728	0.000539
2007-Jun-21	85	34995	2	1000	100000	10000	50000	20000	0.003044	0.000633	0.001678	0.000537
2007-Jun-21	85	34996	2	1000	100000	10000	50000	20000	0.004157	0.001005	0.002224	0.000920
2007-Jun-21	85	34997	2	1000	100000	10000	50000	20000	0.003261	0.000689	0.001794	0.000592

2007-Jun-21	85	33455	3	1000	100000	10000	50000	20000	0.018117	0.007092	0.001867	0.007543
2007-Jun-21	85	33475	3	1000	100000	10000	50000	20000	0.018444	0.007308	0.001887	0.007763
2007-Jun-21	85	34956	3	1000	100000	10000	50000	20000	0.017491	0.006535	0.001853	0.006966
2007-Jun-21	85	34957	3	1000	100000	10000	50000	20000	0.028384	0.013573	0.002537	0.014236
2007-Jun-21	85	34958	3	1000	100000	10000	50000	20000	0.016166	0.006002	0.001723	0.006396
2007-Jun-21	85	34990	3	1000	100000	10000	50000	20000	0.015589	0.005635	0.001691	0.006006
2007-Jun-21	85	34991	3	1000	100000	10000	50000	20000	0.018039	0.007039	0.001864	0.007476
2007-Jun-21	85	34992	3	1000	100000	10000	50000	20000	0.019447	0.007934	0.001953	0.008406
2007-Jun-21	85	34994	3	1000	100000	10000	50000	20000	0.016577	0.006209	0.001756	0.006615
2007-Jun-21	85	34995	3	1000	100000	10000	50000	20000	0.016062	0.006022	0.001705	0.006400
2007-Jun-21	85	34996	3	1000	100000	10000	50000	20000	0.023554	0.010154	0.002259	0.010774
2007-Jun-21	85	34997	3	1000	100000	10000	50000	20000	0.017454	0.006689	0.001823	0.007118
2007-Jun-21	86	33002	1	1000	100000	10000	50000	20000	0.005845	0.001797	0.002042	0.001695
2007-Jun-21	86	33010	1	1000	100000	10000	50000	20000	0.005191	0.001484	0.001879	0.001392
2007-Jun-21	86	33011	1	1000	100000	10000	50000	20000	0.005193	0.001457	0.001892	0.001366
2007-Jun-21	86	33012	1	1000	100000	10000	50000	20000	0.005385	0.001538	0.001945	0.001445
2007-Jun-21	86	33013	1	1000	100000	10000	50000	20000	0.005340	0.001533	0.001923	0.001439
2007-Jun-21	86	33014	1	1000	100000	10000	50000	20000	0.006160	0.001927	0.002135	0.001823
2007-Jun-21	86	33015	1	1000	100000	10000	50000	20000	0.006209	0.001940	0.002155	0.001838
2007-Jun-21	86	33016	1	1000	100000	10000	50000	20000	0.005077	0.001375	0.001869	0.001284
2007-Jun-21	86	33017	1	1000	100000	10000	50000	20000	0.005946	0.001796	0.002096	0.001696
2007-Jun-21	86	33018	1	1000	100000	10000	50000	20000	0.005279	0.001493	0.001909	0.001400
2007-Jun-21	86	33030	1	1000	100000	10000	50000	20000	0.006267	0.001986	0.002183	0.001896
2007-Jun-21	86	33031	1	1000	100000	10000	50000	20000	0.007150	0.002405	0.002424	0.002307
2007-Jun-21	86	33032	1	1000	100000	10000	50000	20000	0.006926	0.002331	0.002346	0.002233
2007-Jun-21	86	33033	1	1000	100000	10000	50000	20000	0.006580	0.002133	0.002271	0.002041
2007-Jun-21	86	33034	1	1000	100000	10000	50000	20000	0.006728	0.002189	0.002322	0.002100
2007-Jun-21	86	33035	1	1000	100000	10000	50000	20000	0.006741	0.002242	0.002302	0.002146
2007-Jun-21	86	33039	1	1000	100000	10000	50000	20000	0.007425	0.002668	0.002441	0.002554
2007-Jun-21	86	33054	1	1000	100000	10000	50000	20000	0.005424	0.001613	0.001925	0.001516
2007-Jun-21	86	33055	1	1000	100000	10000	50000	20000	0.005680	0.001697	0.002006	0.001601
2007-Jun-21	86	33056	1	1000	100000	10000	50000	20000	0.005671	0.001716	0.001996	0.001617
2007-Jun-21	86	33090	1	1000	100000	10000	50000	20000	0.005842	0.001787	0.002065	0.001700
2007-Jun-21	86	33092	1	1000	100000	10000	50000	20000	0.006846	0.002273	0.002336	0.002177
2007-Jun-21	86	33101	1	1000	100000	10000	50000	20000	0.005527	0.001629	0.001978	0.001535
2007-Jun-21	86	33102	1	1000	100000	10000	50000	20000	0.005349	0.001515	0.001942	0.001422
2007-Jun-21	86	33107	1	1000	100000	10000	50000	20000	0.005349	0.001515	0.001942	0.001422

2007-Jun-21	86	33109	1	1000	100000	10000	50000	20000	0.010360	0.004360	0.003078	0.004156
2007-Jun-21	86	33110	1	1000	100000	10000	50000	20000	0.005598	0.001681	0.001984	0.001585
2007-Jun-21	86	33111	1	1000	100000	10000	50000	20000	0.007879	0.002895	0.002551	0.002761
2007-Jun-21	86	33112	1	1000	100000	10000	50000	20000	0.005349	0.001515	0.001942	0.001422
2007-Jun-21	86	33114	1	1000	100000	10000	50000	20000	0.005429	0.001501	0.001994	0.001412
2007-Jun-21	86	33116	1	1000	100000	10000	50000	20000	0.006257	0.001961	0.002180	0.001864
2007-Jun-21	86	33119	1	1000	100000	10000	50000	20000	0.006780	0.002333	0.002266	0.002218
2007-Jun-21	86	33121	1	1000	100000	10000	50000	20000	0.007594	0.002707	0.002498	0.002579
2007-Jun-21	86	33122	1	1000	100000	10000	50000	20000	0.004783	0.001274	0.001779	0.001186
2007-Jun-21	86	33124	1	1000	100000	10000	50000	20000	0.006757	0.002280	0.002272	0.002165
2007-Jun-21	86	33125	1	1000	100000	10000	50000	20000	0.005495	0.001607	0.001968	0.001513
2007-Jun-21	86	33126	1	1000	100000	10000	50000	20000	0.005662	0.001701	0.002006	0.001605
2007-Jun-21	86	33127	1	1000	100000	10000	50000	20000	0.005688	0.001738	0.002003	0.001641
2007-Jun-21	86	33128	1	1000	100000	10000	50000	20000	0.005465	0.001617	0.001952	0.001523
2007-Jun-21	86	33129	1	1000	100000	10000	50000	20000	0.007847	0.002773	0.002603	0.002653
2007-Jun-21	86	33130	1	1000	100000	10000	50000	20000	0.005615	0.001669	0.002002	0.001575
2007-Jun-21	86	33131	1	1000	100000	10000	50000	20000	0.008166	0.003029	0.002632	0.002889
2007-Jun-21	86	33132	1	1000	100000	10000	50000	20000	0.010243	0.004519	0.002942	0.004265
2007-Jun-21	86	33133	1	1000	100000	10000	50000	20000	0.007976	0.002816	0.002647	0.002699
2007-Jun-21	86	33134	1	1000	100000	10000	50000	20000	0.006470	0.002048	0.002246	0.001946
2007-Jun-21	86	33135	1	1000	100000	10000	50000	20000	0.005458	0.001562	0.001973	0.001468
2007-Jun-21	86	33136	1	1000	100000	10000	50000	20000	0.005503	0.001637	0.001962	0.001543
2007-Jun-21	86	33137	1	1000	100000	10000	50000	20000	0.008051	0.002985	0.002589	0.002849
2007-Jun-21	86	33138	1	1000	100000	10000	50000	20000	0.006169	0.001957	0.002133	0.001854
2007-Jun-21	86	33139	1	1000	100000	10000	50000	20000	0.006434	0.002092	0.002212	0.001989
2007-Jun-21	86	33140	1	1000	100000	10000	50000	20000	0.008398	0.003258	0.002616	0.003101
2007-Jun-21	86	33141	1	1000	100000	10000	50000	20000	0.007671	0.002932	0.002409	0.002771
2007-Jun-21	86	33142	1	1000	100000	10000	50000	20000	0.005590	0.001688	0.001977	0.001591
2007-Jun-21	86	33143	1	1000	100000	10000	50000	20000	0.006633	0.002123	0.002295	0.002024
2007-Jun-21	86	33144	1	1000	100000	10000	50000	20000	0.005569	0.001661	0.001983	0.001567
2007-Jun-21	86	33145	1	1000	100000	10000	50000	20000	0.005963	0.001807	0.002110	0.001713
2007-Jun-21	86	33146	1	1000	100000	10000	50000	20000	0.006814	0.002236	0.002333	0.002134
2007-Jun-21	86	33147	1	1000	100000	10000	50000	20000	0.005898	0.001805	0.002069	0.001707
2007-Jun-21	86	33148	1	1000	100000	10000	50000	20000	0.006706	0.002224	0.002283	0.002114
2007-Jun-21	86	33149	1	1000	100000	10000	50000	20000	0.007321	0.002614	0.002398	0.002493
2007-Jun-21	86	33150	1	1000	100000	10000	50000	20000	0.005976	0.001892	0.002069	0.001790
2007-Jun-21	86	33151	1	1000	100000	10000	50000	20000	0.005500	0.001614	0.001966	0.001519

2007-Jun-21	86	33152	1	1000	100000	10000	50000	20000	0.005349	0.001515	0.001942	0.001422
2007-Jun-21	86	33153	1	1000	100000	10000	50000	20000	0.006303	0.002031	0.002164	0.001925
2007-Jun-21	86	33154	1	1000	100000	10000	50000	20000	0.006994	0.002402	0.002330	0.002281
2007-Jun-21	86	33155	1	1000	100000	10000	50000	20000	0.006169	0.001885	0.002175	0.001791
2007-Jun-21	86	33156	1	1000	100000	10000	50000	20000	0.007061	0.002369	0.002391	0.002262
2007-Jun-21	86	33157	1	1000	100000	10000	50000	20000	0.006582	0.002143	0.002263	0.002042
2007-Jun-21	86	33158	1	1000	100000	10000	50000	20000	0.006562	0.002145	0.002245	0.002045
2007-Jun-21	86	33159	1	1000	100000	10000	50000	20000	0.007852	0.002932	0.002511	0.002792
2007-Jun-21	86	33160	1	1000	100000	10000	50000	20000	0.010180	0.004401	0.002965	0.004166
2007-Jun-21	86	33161	1	1000	100000	10000	50000	20000	0.005930	0.001826	0.002078	0.001725
2007-Jun-21	86	33162	1	1000	100000	10000	50000	20000	0.006033	0.001905	0.002089	0.001801
2007-Jun-21	86	33163	1	1000	100000	10000	50000	20000	0.006075	0.001899	0.002116	0.001794
2007-Jun-21	86	33164	1	1000	100000	10000	50000	20000	0.005758	0.001725	0.002040	0.001628
2007-Jun-21	86	33165	1	1000	100000	10000	50000	20000	0.006072	0.001877	0.002128	0.001779
2007-Jun-21	86	33166	1	1000	100000	10000	50000	20000	0.006168	0.001925	0.002149	0.001824
2007-Jun-21	86	33167	1	1000	100000	10000	50000	20000	0.006220	0.001940	0.002167	0.001838
2007-Jun-21	86	33168	1	1000	100000	10000	50000	20000	0.005651	0.001701	0.001997	0.001604
2007-Jun-21	86	33169	1	1000	100000	10000	50000	20000	0.005937	0.001843	0.002067	0.001739
2007-Jun-21	86	33170	1	1000	100000	10000	50000	20000	0.007106	0.002398	0.002405	0.002297
2007-Jun-21	86	33172	1	1000	100000	10000	50000	20000	0.006172	0.001919	0.002159	0.001820
2007-Jun-21	86	33173	1	1000	100000	10000	50000	20000	0.006457	0.002079	0.002223	0.001978
2007-Jun-21	86	33174	1	1000	100000	10000	50000	20000	0.005784	0.001723	0.002060	0.001628
2007-Jun-21	86	33175	1	1000	100000	10000	50000	20000	0.006207	0.001919	0.002178	0.001823
2007-Jun-21	86	33176	1	1000	100000	10000	50000	20000	0.006532	0.002109	0.002247	0.002008
2007-Jun-21	86	33177	1	1000	100000	10000	50000	20000	0.006763	0.002216	0.002314	0.002117
2007-Jun-21	86	33178	1	1000	100000	10000	50000	20000	0.005896	0.001757	0.002097	0.001660
2007-Jun-21	86	33179	1	1000	100000	10000	50000	20000	0.006392	0.002035	0.002207	0.001927
2007-Jun-21	86	33180	1	1000	100000	10000	50000	20000	0.008360	0.003210	0.002630	0.003045
2007-Jun-21	86	33181	1	1000	100000	10000	50000	20000	0.006576	0.002169	0.002235	0.002059
2007-Jun-21	86	33182	1	1000	100000	10000	50000	20000	0.006513	0.002069	0.002264	0.001968
2007-Jun-21	86	33183	1	1000	100000	10000	50000	20000	0.006264	0.001935	0.002195	0.001840
2007-Jun-21	86	33184	1	1000	100000	10000	50000	20000	0.006032	0.001833	0.002134	0.001738
2007-Jun-21	86	33185	1	1000	100000	10000	50000	20000	0.006267	0.001924	0.002205	0.001828
2007-Jun-21	86	33186	1	1000	100000	10000	50000	20000	0.006452	0.002049	0.002238	0.001951
2007-Jun-21	86	33187	1	1000	100000	10000	50000	20000	0.007340	0.002507	0.002469	0.002400
2007-Jun-21	86	33189	1	1000	100000	10000	50000	20000	0.006689	0.002170	0.002304	0.002072
2007-Jun-21	86	33190	1	1000	100000	10000	50000	20000	0.008253	0.003067	0.002672	0.002938

2007-Jun-21	86	33193	1	1000	100000	10000	50000	20000	0.006199	0.001901	0.002180	0.001808
2007-Jun-21	86	33194	1	1000	100000	10000	50000	20000	0.006971	0.002278	0.002389	0.002174
2007-Jun-21	86	33195	1	1000	100000	10000	50000	20000	0.005400	0.001547	0.001952	0.001456
2007-Jun-21	86	33196	1	1000	100000	10000	50000	20000	0.006608	0.002068	0.002309	0.001974
2007-Jun-21	86	33197	1	1000	100000	10000	50000	20000	0.005675	0.001707	0.002017	0.001618
2007-Jun-21	86	33199	1	1000	100000	10000	50000	20000	0.005889	0.001754	0.002100	0.001659
2007-Jun-21	86	33231	1	1000	100000	10000	50000	20000	0.007566	0.002712	0.002476	0.002582
2007-Jun-21	86	33233	1	1000	100000	10000	50000	20000	0.007982	0.002793	0.002663	0.002683
2007-Jun-21	86	33234	1	1000	100000	10000	50000	20000	0.005429	0.001501	0.001994	0.001412
2007-Jun-21	86	33238	1	1000	100000	10000	50000	20000	0.006117	0.001952	0.002110	0.001848
2007-Jun-21	86	33239	1	1000	100000	10000	50000	20000	0.006186	0.002040	0.002105	0.001934
2007-Jun-21	86	33242	1	1000	100000	10000	50000	20000	0.005406	0.001579	0.001939	0.001485
2007-Jun-21	86	33243	1	1000	100000	10000	50000	20000	0.005826	0.001765	0.002068	0.001673
2007-Jun-21	86	33245	1	1000	100000	10000	50000	20000	0.006340	0.001963	0.002226	0.001867
2007-Jun-21	86	33247	1	1000	100000	10000	50000	20000	0.005349	0.001515	0.001942	0.001422
2007-Jun-21	86	33255	1	1000	100000	10000	50000	20000	0.005935	0.001819	0.002096	0.001725
2007-Jun-21	86	33256	1	1000	100000	10000	50000	20000	0.006380	0.002015	0.002218	0.001920
2007-Jun-21	86	33257	1	1000	100000	10000	50000	20000	0.005844	0.001741	0.002081	0.001650
2007-Jun-21	86	33261	1	1000	100000	10000	50000	20000	0.005868	0.001780	0.002067	0.001681
2007-Jun-21	86	33265	1	1000	100000	10000	50000	20000	0.005903	0.001771	0.002095	0.001677
2007-Jun-21	86	33266	1	1000	100000	10000	50000	20000	0.005571	0.001603	0.002008	0.001509
2007-Jun-21	86	33269	1	1000	100000	10000	50000	20000	0.005783	0.001787	0.002021	0.001687
2007-Jun-21	86	33280	1	1000	100000	10000	50000	20000	0.006542	0.002174	0.002217	0.002063
2007-Jun-21	86	33283	1	1000	100000	10000	50000	20000	0.006122	0.001876	0.002154	0.001781
2007-Jun-21	86	33296	1	1000	100000	10000	50000	20000	0.006380	0.002015	0.002218	0.001920
2007-Jun-21	86	33299	1	1000	100000	10000	50000	20000	0.004668	0.001238	0.001742	0.001150
2007-Jun-21	86	34141	1	1000	100000	10000	50000	20000	0.006699	0.001932	0.002469	0.001862
2007-Jun-21	86	33002	2	1000	100000	10000	50000	20000	0.003987	0.001028	0.002032	0.000960
2007-Jun-21	86	33010	2	1000	100000	10000	50000	20000	0.003568	0.000863	0.001871	0.000791
2007-Jun-21	86	33011	2	1000	100000	10000	50000	20000	0.003575	0.000850	0.001884	0.000776
2007-Jun-21	86	33012	2	1000	100000	10000	50000	20000	0.003698	0.000892	0.001936	0.000819
2007-Jun-21	86	33013	2	1000	100000	10000	50000	20000	0.003670	0.000891	0.001914	0.000818
2007-Jun-21	86	33014	2	1000	100000	10000	50000	20000	0.004187	0.001095	0.002126	0.001029
2007-Jun-21	86	33015	2	1000	100000	10000	50000	20000	0.004215	0.001101	0.002145	0.001035
2007-Jun-21	86	33016	2	1000	100000	10000	50000	20000	0.003511	0.000810	0.001861	0.000733
2007-Jun-21	86	33017	2	1000	100000	10000	50000	20000	0.004055	0.001028	0.002086	0.000958
2007-Jun-21	86	33018	2	1000	100000	10000	50000	20000	0.003633	0.000870	0.001900	0.000796

2007-Jun-21	86	33030	2	1000	100000	10000	50000	20000	0.004215	0.001112	0.002173	0.001056
2007-Jun-21	86	33031	2	1000	100000	10000	50000	20000	0.004767	0.001329	0.002412	0.001280
2007-Jun-21	86	33032	2	1000	100000	10000	50000	20000	0.004626	0.001291	0.002335	0.001241
2007-Jun-21	86	33033	2	1000	100000	10000	50000	20000	0.004411	0.001188	0.002260	0.001134
2007-Jun-21	86	33034	2	1000	100000	10000	50000	20000	0.004493	0.001213	0.002311	0.001162
2007-Jun-21	86	33035	2	1000	100000	10000	50000	20000	0.004508	0.001244	0.002291	0.001192
2007-Jun-21	86	33039	2	1000	100000	10000	50000	20000	0.004937	0.001468	0.002429	0.001422
2007-Jun-21	86	33054	2	1000	100000	10000	50000	20000	0.003716	0.000932	0.001916	0.000861
2007-Jun-21	86	33055	2	1000	100000	10000	50000	20000	0.003881	0.000975	0.001997	0.000906
2007-Jun-21	86	33056	2	1000	100000	10000	50000	20000	0.003874	0.000985	0.001987	0.000916
2007-Jun-21	86	33090	2	1000	100000	10000	50000	20000	0.003952	0.001010	0.002055	0.000950
2007-Jun-21	86	33092	2	1000	100000	10000	50000	20000	0.004576	0.001260	0.002324	0.001209
2007-Jun-21	86	33101	2	1000	100000	10000	50000	20000	0.003780	0.000938	0.001969	0.000868
2007-Jun-21	86	33102	2	1000	100000	10000	50000	20000	0.003677	0.000881	0.001933	0.000807
2007-Jun-21	86	33107	2	1000	100000	10000	50000	20000	0.003677	0.000881	0.001933	0.000807
2007-Jun-21	86	33109	2	1000	100000	10000	50000	20000	0.006860	0.002393	0.003063	0.002348
2007-Jun-21	86	33110	2	1000	100000	10000	50000	20000	0.003824	0.000965	0.001975	0.000896
2007-Jun-21	86	33111	2	1000	100000	10000	50000	20000	0.005262	0.001605	0.002539	0.001551
2007-Jun-21	86	33112	2	1000	100000	10000	50000	20000	0.003677	0.000881	0.001933	0.000807
2007-Jun-21	86	33114	2	1000	100000	10000	50000	20000	0.003733	0.000875	0.001985	0.000799
2007-Jun-21	86	33116	2	1000	100000	10000	50000	20000	0.004232	0.001107	0.002170	0.001045
2007-Jun-21	86	33119	2	1000	100000	10000	50000	20000	0.004563	0.001306	0.002255	0.001247
2007-Jun-21	86	33121	2	1000	100000	10000	50000	20000	0.005087	0.001507	0.002486	0.001449
2007-Jun-21	86	33122	2	1000	100000	10000	50000	20000	0.003320	0.000756	0.001771	0.000678
2007-Jun-21	86	33124	2	1000	100000	10000	50000	20000	0.004555	0.001278	0.002262	0.001218
2007-Jun-21	86	33125	2	1000	100000	10000	50000	20000	0.003762	0.000927	0.001959	0.000856
2007-Jun-21	86	33126	2	1000	100000	10000	50000	20000	0.003864	0.000975	0.001997	0.000907
2007-Jun-21	86	33127	2	1000	100000	10000	50000	20000	0.003877	0.000994	0.001994	0.000926
2007-Jun-21	86	33128	2	1000	100000	10000	50000	20000	0.003739	0.000931	0.001943	0.000861
2007-Jun-21	86	33129	2	1000	100000	10000	50000	20000	0.005232	0.001534	0.002590	0.001480
2007-Jun-21	86	33130	2	1000	100000	10000	50000	20000	0.003835	0.000958	0.001993	0.000889
2007-Jun-21	86	33131	2	1000	100000	10000	50000	20000	0.005450	0.001679	0.002619	0.001624
2007-Jun-21	86	33132	2	1000	100000	10000	50000	20000	0.006870	0.002521	0.002928	0.002452
2007-Jun-21	86	33133	2	1000	100000	10000	50000	20000	0.005308	0.001554	0.002634	0.001502
2007-Jun-21	86	33134	2	1000	100000	10000	50000	20000	0.004375	0.001156	0.002235	0.001091
2007-Jun-21	86	33135	2	1000	100000	10000	50000	20000	0.003747	0.000906	0.001964	0.000832
2007-Jun-21	86	33136	2	1000	100000	10000	50000	20000	0.003760	0.000941	0.001953	0.000872

2007-Jun-21	86	33137	2	1000	100000	10000	50000	20000	0.005367	0.001649	0.002577	0.001599
2007-Jun-21	86	33138	2	1000	100000	10000	50000	20000	0.004186	0.001110	0.002123	0.001044
2007-Jun-21	86	33139	2	1000	100000	10000	50000	20000	0.004342	0.001177	0.002202	0.001115
2007-Jun-21	86	33140	2	1000	100000	10000	50000	20000	0.005601	0.001799	0.002603	0.001749
2007-Jun-21	86	33141	2	1000	100000	10000	50000	20000	0.005171	0.001642	0.002398	0.001578
2007-Jun-21	86	33142	2	1000	100000	10000	50000	20000	0.003817	0.000969	0.001968	0.000900
2007-Jun-21	86	33143	2	1000	100000	10000	50000	20000	0.004467	0.001191	0.002284	0.001130
2007-Jun-21	86	33144	2	1000	100000	10000	50000	20000	0.003801	0.000953	0.001974	0.000884
2007-Jun-21	86	33145	2	1000	100000	10000	50000	20000	0.004054	0.001030	0.002100	0.000962
2007-Jun-21	86	33146	2	1000	100000	10000	50000	20000	0.004579	0.001249	0.002322	0.001191
2007-Jun-21	86	33147	2	1000	100000	10000	50000	20000	0.004015	0.001030	0.002060	0.000963
2007-Jun-21	86	33148	2	1000	100000	10000	50000	20000	0.004525	0.001251	0.002272	0.001188
2007-Jun-21	86	33149	2	1000	100000	10000	50000	20000	0.004900	0.001451	0.002386	0.001398
2007-Jun-21	86	33150	2	1000	100000	10000	50000	20000	0.004058	0.001075	0.002059	0.001010
2007-Jun-21	86	33151	2	1000	100000	10000	50000	20000	0.003768	0.000932	0.001957	0.000860
2007-Jun-21	86	33152	2	1000	100000	10000	50000	20000	0.003677	0.000881	0.001933	0.000807
2007-Jun-21	86	33153	2	1000	100000	10000	50000	20000	0.004270	0.001149	0.002154	0.001084
2007-Jun-21	86	33154	2	1000	100000	10000	50000	20000	0.004710	0.001345	0.002319	0.001285
2007-Jun-21	86	33155	2	1000	100000	10000	50000	20000	0.004182	0.001070	0.002165	0.001003
2007-Jun-21	86	33156	2	1000	100000	10000	50000	20000	0.004733	0.001318	0.002380	0.001262
2007-Jun-21	86	33157	2	1000	100000	10000	50000	20000	0.004433	0.001201	0.002252	0.001141
2007-Jun-21	86	33158	2	1000	100000	10000	50000	20000	0.004416	0.001201	0.002234	0.001143
2007-Jun-21	86	33159	2	1000	100000	10000	50000	20000	0.005245	0.001623	0.002499	0.001571
2007-Jun-21	86	33160	2	1000	100000	10000	50000	20000	0.006800	0.002440	0.002951	0.002380
2007-Jun-21	86	33161	2	1000	100000	10000	50000	20000	0.004037	0.001041	0.002069	0.000973
2007-Jun-21	86	33162	2	1000	100000	10000	50000	20000	0.004099	0.001082	0.002080	0.001017
2007-Jun-21	86	33163	2	1000	100000	10000	50000	20000	0.004134	0.001081	0.002106	0.001013
2007-Jun-21	86	33164	2	1000	100000	10000	50000	20000	0.003930	0.000990	0.002031	0.000920
2007-Jun-21	86	33165	2	1000	100000	10000	50000	20000	0.004121	0.001066	0.002118	0.001000
2007-Jun-21	86	33166	2	1000	100000	10000	50000	20000	0.004187	0.001092	0.002139	0.001026
2007-Jun-21	86	33167	2	1000	100000	10000	50000	20000	0.004221	0.001101	0.002157	0.001035
2007-Jun-21	86	33168	2	1000	100000	10000	50000	20000	0.003859	0.000977	0.001988	0.000908
2007-Jun-21	86	33169	2	1000	100000	10000	50000	20000	0.004046	0.001052	0.002057	0.000984
2007-Jun-21	86	33170	2	1000	100000	10000	50000	20000	0.004746	0.001328	0.002393	0.001276
2007-Jun-21	86	33172	2	1000	100000	10000	50000	20000	0.004185	0.001088	0.002149	0.001022
2007-Jun-21	86	33173	2	1000	100000	10000	50000	20000	0.004358	0.001170	0.002213	0.001109
2007-Jun-21	86	33174	2	1000	100000	10000	50000	20000	0.003946	0.000988	0.002050	0.000918

2007-Jun-21	86	33175	2	1000	100000	10000	50000	20000	0.004206	0.001087	0.002168	0.001022
2007-Jun-21	86	33176	2	1000	100000	10000	50000	20000	0.004401	0.001183	0.002236	0.001123
2007-Jun-21	86	33177	2	1000	100000	10000	50000	20000	0.004539	0.001235	0.002303	0.001179
2007-Jun-21	86	33178	2	1000	100000	10000	50000	20000	0.004022	0.001006	0.002087	0.000936
2007-Jun-21	86	33179	2	1000	100000	10000	50000	20000	0.004338	0.001154	0.002196	0.001087
2007-Jun-21	86	33180	2	1000	100000	10000	50000	20000	0.005605	0.001786	0.002617	0.001726
2007-Jun-21	86	33181	2	1000	100000	10000	50000	20000	0.004440	0.001220	0.002224	0.001158
2007-Jun-21	86	33182	2	1000	100000	10000	50000	20000	0.004401	0.001166	0.002253	0.001102
2007-Jun-21	86	33183	2	1000	100000	10000	50000	20000	0.004240	0.001094	0.002184	0.001030
2007-Jun-21	86	33184	2	1000	100000	10000	50000	20000	0.004097	0.001043	0.002124	0.000975
2007-Jun-21	86	33185	2	1000	100000	10000	50000	20000	0.004244	0.001089	0.002195	0.001024
2007-Jun-21	86	33186	2	1000	100000	10000	50000	20000	0.004352	0.001152	0.002227	0.001091
2007-Jun-21	86	33187	2	1000	100000	10000	50000	20000	0.004900	0.001386	0.002457	0.001334
2007-Jun-21	86	33189	2	1000	100000	10000	50000	20000	0.004496	0.001213	0.002293	0.001155
2007-Jun-21	86	33190	2	1000	100000	10000	50000	20000	0.005473	0.001686	0.002659	0.001640
2007-Jun-21	86	33193	2	1000	100000	10000	50000	20000	0.004198	0.001076	0.002170	0.001012
2007-Jun-21	86	33194	2	1000	100000	10000	50000	20000	0.004683	0.001272	0.002377	0.001213
2007-Jun-21	86	33195	2	1000	100000	10000	50000	20000	0.003704	0.000896	0.001943	0.000824
2007-Jun-21	86	33196	2	1000	100000	10000	50000	20000	0.004451	0.001161	0.002298	0.001099
2007-Jun-21	86	33197	2	1000	100000	10000	50000	20000	0.003859	0.000973	0.002007	0.000908
2007-Jun-21	86	33199	2	1000	100000	10000	50000	20000	0.004013	0.001004	0.002090	0.000933
2007-Jun-21	86	33231	2	1000	100000	10000	50000	20000	0.005070	0.001510	0.002464	0.001452
2007-Jun-21	86	33233	2	1000	100000	10000	50000	20000	0.005299	0.001537	0.002650	0.001488
2007-Jun-21	86	33234	2	1000	100000	10000	50000	20000	0.003733	0.000875	0.001985	0.000799
2007-Jun-21	86	33238	2	1000	100000	10000	50000	20000	0.004148	0.001106	0.002100	0.001042
2007-Jun-21	86	33239	2	1000	100000	10000	50000	20000	0.004181	0.001150	0.002096	0.001089
2007-Jun-21	86	33242	2	1000	100000	10000	50000	20000	0.003706	0.000913	0.001930	0.000842
2007-Jun-21	86	33243	2	1000	100000	10000	50000	20000	0.003958	0.001005	0.002058	0.000939
2007-Jun-21	86	33245	2	1000	100000	10000	50000	20000	0.004291	0.001111	0.002215	0.001046
2007-Jun-21	86	33247	2	1000	100000	10000	50000	20000	0.003677	0.000881	0.001933	0.000807
2007-Jun-21	86	33255	2	1000	100000	10000	50000	20000	0.004028	0.001034	0.002086	0.000968
2007-Jun-21	86	33256	2	1000	100000	10000	50000	20000	0.004303	0.001133	0.002208	0.001072
2007-Jun-21	86	33257	2	1000	100000	10000	50000	20000	0.003979	0.000994	0.002071	0.000926
2007-Jun-21	86	33261	2	1000	100000	10000	50000	20000	0.004001	0.001018	0.002057	0.000950
2007-Jun-21	86	33265	2	1000	100000	10000	50000	20000	0.004017	0.001011	0.002085	0.000943
2007-Jun-21	86	33266	2	1000	100000	10000	50000	20000	0.003821	0.000929	0.001999	0.000855
2007-Jun-21	86	33269	2	1000	100000	10000	50000	20000	0.003940	0.001021	0.002012	0.000954

2007-Jun-21	86	33280	2	1000	100000	10000	50000	20000	0.004416	0.001222	0.002207	0.001161
2007-Jun-21	86	33283	2	1000	100000	10000	50000	20000	0.004153	0.001065	0.002144	0.000999
2007-Jun-21	86	33296	2	1000	100000	10000	50000	20000	0.004303	0.001133	0.002208	0.001072
2007-Jun-21	86	33299	2	1000	100000	10000	50000	20000	0.003242	0.000736	0.001734	0.000659
2007-Jun-21	86	34141	2	1000	100000	10000	50000	20000	0.004488	0.001082	0.002457	0.001018
2007-Jun-21	86	33002	3	1000	100000	10000	50000	20000	0.022182	0.010036	0.002063	0.010567
2007-Jun-21	86	33010	3	1000	100000	10000	50000	20000	0.019807	0.008625	0.001899	0.009113
2007-Jun-21	86	33011	3	1000	100000	10000	50000	20000	0.019869	0.008581	0.001913	0.009081
2007-Jun-21	86	33012	3	1000	100000	10000	50000	20000	0.020594	0.008985	0.001966	0.009503
2007-Jun-21	86	33013	3	1000	100000	10000	50000	20000	0.020352	0.008882	0.001944	0.009387
2007-Jun-21	86	33014	3	1000	100000	10000	50000	20000	0.023457	0.010738	0.002158	0.011310
2007-Jun-21	86	33015	3	1000	100000	10000	50000	20000	0.023719	0.010881	0.002178	0.011459
2007-Jun-21	86	33016	3	1000	100000	10000	50000	20000	0.019387	0.008211	0.001890	0.008704
2007-Jun-21	86	33017	3	1000	100000	10000	50000	20000	0.022728	0.010227	0.002118	0.010791
2007-Jun-21	86	33018	3	1000	100000	10000	50000	20000	0.020094	0.008699	0.001929	0.009195
2007-Jun-21	86	33030	3	1000	100000	10000	50000	20000	0.024567	0.011514	0.002206	0.012170
2007-Jun-21	86	33031	3	1000	100000	10000	50000	20000	0.028068	0.013604	0.002449	0.014346
2007-Jun-21	86	33032	3	1000	100000	10000	50000	20000	0.027063	0.013084	0.002371	0.013789
2007-Jun-21	86	33033	3	1000	100000	10000	50000	20000	0.025840	0.012272	0.002295	0.012962
2007-Jun-21	86	33034	3	1000	100000	10000	50000	20000	0.026614	0.012731	0.002346	0.013453
2007-Jun-21	86	33035	3	1000	100000	10000	50000	20000	0.026410	0.012690	0.002326	0.013389
2007-Jun-21	86	33039	3	1000	100000	10000	50000	20000	0.028756	0.014318	0.002465	0.015043
2007-Jun-21	86	33054	3	1000	100000	10000	50000	20000	0.020557	0.009118	0.001945	0.009607
2007-Jun-21	86	33055	3	1000	100000	10000	50000	20000	0.021623	0.009657	0.002028	0.010183
2007-Jun-21	86	33056	3	1000	100000	10000	50000	20000	0.021543	0.009667	0.002018	0.010184
2007-Jun-21	86	33090	3	1000	100000	10000	50000	20000	0.022847	0.010494	0.002087	0.011103
2007-Jun-21	86	33092	3	1000	100000	10000	50000	20000	0.026830	0.012894	0.002360	0.013604
2007-Jun-21	86	33101	3	1000	100000	10000	50000	20000	0.021215	0.009428	0.001999	0.009963
2007-Jun-21	86	33102	3	1000	100000	10000	50000	20000	0.020506	0.008916	0.001963	0.009439
2007-Jun-21	86	33107	3	1000	100000	10000	50000	20000	0.020506	0.008916	0.001963	0.009439
2007-Jun-21	86	33109	3	1000	100000	10000	50000	20000	0.038195	0.020384	0.003108	0.021184
2007-Jun-21	86	33110	3	1000	100000	10000	50000	20000	0.021380	0.009572	0.002006	0.010098
2007-Jun-21	86	33111	3	1000	100000	10000	50000	20000	0.029939	0.014924	0.002577	0.015634
2007-Jun-21	86	33112	3	1000	100000	10000	50000	20000	0.020506	0.008916	0.001963	0.009439
2007-Jun-21	86	33114	3	1000	100000	10000	50000	20000	0.021066	0.009114	0.002016	0.009681
2007-Jun-21	86	33116	3	1000	100000	10000	50000	20000	0.024221	0.011207	0.002203	0.011829
2007-Jun-21	86	33119	3	1000	100000	10000	50000	20000	0.025789	0.012409	0.002289	0.013020

2007-Jun-21	86	33121	3	1000	100000	10000	50000	20000	0.028974	0.014223	0.002523	0.014927
2007-Jun-21	86	33122	3	1000	100000	10000	50000	20000	0.018229	0.007625	0.001799	0.008085
2007-Jun-21	86	33124	3	1000	100000	10000	50000	20000	0.025696	0.012240	0.002296	0.012854
2007-Jun-21	86	33125	3	1000	100000	10000	50000	20000	0.021054	0.009317	0.001989	0.009845
2007-Jun-21	86	33126	3	1000	100000	10000	50000	20000	0.021680	0.009734	0.002028	0.010272
2007-Jun-21	86	33127	3	1000	100000	10000	50000	20000	0.021726	0.009823	0.002024	0.010353
2007-Jun-21	86	33128	3	1000	100000	10000	50000	20000	0.020923	0.009306	0.001972	0.009827
2007-Jun-21	86	33129	3	1000	100000	10000	50000	20000	0.030387	0.014970	0.002629	0.015739
2007-Jun-21	86	33130	3	1000	100000	10000	50000	20000	0.021571	0.009636	0.002024	0.010183
2007-Jun-21	86	33131	3	1000	100000	10000	50000	20000	0.031039	0.015551	0.002659	0.016294
2007-Jun-21	86	33132	3	1000	100000	10000	50000	20000	0.036169	0.019424	0.002970	0.020090
2007-Jun-21	86	33133	3	1000	100000	10000	50000	20000	0.031044	0.015345	0.002674	0.016141
2007-Jun-21	86	33134	3	1000	100000	10000	50000	20000	0.024998	0.011608	0.002269	0.012248
2007-Jun-21	86	33135	3	1000	100000	10000	50000	20000	0.020961	0.009172	0.001994	0.009711
2007-Jun-21	86	33136	3	1000	100000	10000	50000	20000	0.021086	0.009412	0.001983	0.009936
2007-Jun-21	86	33137	3	1000	100000	10000	50000	20000	0.030572	0.015334	0.002615	0.016053
2007-Jun-21	86	33138	3	1000	100000	10000	50000	20000	0.023543	0.010867	0.002155	0.011440
2007-Jun-21	86	33139	3	1000	100000	10000	50000	20000	0.024766	0.011645	0.002236	0.012259
2007-Jun-21	86	33140	3	1000	100000	10000	50000	20000	0.031246	0.015959	0.002641	0.016637
2007-Jun-21	86	33141	3	1000	100000	10000	50000	20000	0.028040	0.014016	0.002433	0.014596
2007-Jun-21	86	33142	3	1000	100000	10000	50000	20000	0.021319	0.009568	0.001998	0.010088
2007-Jun-21	86	33143	3	1000	100000	10000	50000	20000	0.025804	0.012105	0.002319	0.012776
2007-Jun-21	86	33144	3	1000	100000	10000	50000	20000	0.021380	0.009569	0.002004	0.010104
2007-Jun-21	86	33145	3	1000	100000	10000	50000	20000	0.023060	0.010462	0.002133	0.011055
2007-Jun-21	86	33146	3	1000	100000	10000	50000	20000	0.026450	0.012556	0.002357	0.013234
2007-Jun-21	86	33147	3	1000	100000	10000	50000	20000	0.022567	0.010234	0.002091	0.010793
2007-Jun-21	86	33148	3	1000	100000	10000	50000	20000	0.025706	0.012154	0.002307	0.012792
2007-Jun-21	86	33149	3	1000	100000	10000	50000	20000	0.027883	0.013720	0.002422	0.014383
2007-Jun-21	86	33150	3	1000	100000	10000	50000	20000	0.022740	0.010465	0.002090	0.011008
2007-Jun-21	86	33151	3	1000	100000	10000	50000	20000	0.021014	0.009298	0.001987	0.009821
2007-Jun-21	86	33152	3	1000	100000	10000	50000	20000	0.020506	0.008916	0.001963	0.009439
2007-Jun-21	86	33153	3	1000	100000	10000	50000	20000	0.024039	0.011186	0.002187	0.011768
2007-Jun-21	86	33154	3	1000	100000	10000	50000	20000	0.026513	0.012735	0.002354	0.013363
2007-Jun-21	86	33155	3	1000	100000	10000	50000	20000	0.023951	0.010948	0.002198	0.011574
2007-Jun-21	86	33156	3	1000	100000	10000	50000	20000	0.027362	0.013132	0.002416	0.013828
2007-Jun-21	86	33157	3	1000	100000	10000	50000	20000	0.025544	0.012059	0.002286	0.012723
2007-Jun-21	86	33158	3	1000	100000	10000	50000	20000	0.025381	0.012005	0.002269	0.012652

2007-Jun-21	86	33159	3	1000	100000	10000	50000	20000	0.029564	0.014824	0.002536	0.015497
2007-Jun-21	86	33160	3	1000	100000	10000	50000	20000	0.036468	0.019502	0.002994	0.020194
2007-Jun-21	86	33161	3	1000	100000	10000	50000	20000	0.022658	0.010287	0.002100	0.010845
2007-Jun-21	86	33162	3	1000	100000	10000	50000	20000	0.022945	0.010537	0.002111	0.011087
2007-Jun-21	86	33163	3	1000	100000	10000	50000	20000	0.023142	0.010571	0.002139	0.011134
2007-Jun-21	86	33164	3	1000	100000	10000	50000	20000	0.022030	0.009869	0.002062	0.010415
2007-Jun-21	86	33165	3	1000	100000	10000	50000	20000	0.023391	0.010704	0.002150	0.011297
2007-Jun-21	86	33166	3	1000	100000	10000	50000	20000	0.023665	0.010862	0.002172	0.011451
2007-Jun-21	86	33167	3	1000	100000	10000	50000	20000	0.023878	0.010965	0.002190	0.011563
2007-Jun-21	86	33168	3	1000	100000	10000	50000	20000	0.021550	0.009661	0.002018	0.010190
2007-Jun-21	86	33169	3	1000	100000	10000	50000	20000	0.022523	0.010235	0.002089	0.010775
2007-Jun-21	86	33170	3	1000	100000	10000	50000	20000	0.027756	0.013431	0.002430	0.014154
2007-Jun-21	86	33172	3	1000	100000	10000	50000	20000	0.023778	0.010914	0.002181	0.011516
2007-Jun-21	86	33173	3	1000	100000	10000	50000	20000	0.024905	0.011660	0.002246	0.012290
2007-Jun-21	86	33174	3	1000	100000	10000	50000	20000	0.022273	0.009981	0.002082	0.010550
2007-Jun-21	86	33175	3	1000	100000	10000	50000	20000	0.024033	0.011030	0.002201	0.011652
2007-Jun-21	86	33176	3	1000	100000	10000	50000	20000	0.025277	0.011881	0.002270	0.012527
2007-Jun-21	86	33177	3	1000	100000	10000	50000	20000	0.026321	0.012511	0.002339	0.013195
2007-Jun-21	86	33178	3	1000	100000	10000	50000	20000	0.022703	0.010179	0.002119	0.010760
2007-Jun-21	86	33179	3	1000	100000	10000	50000	20000	0.024400	0.011280	0.002230	0.011880
2007-Jun-21	86	33180	3	1000	100000	10000	50000	20000	0.030998	0.015647	0.002656	0.016329
2007-Jun-21	86	33181	3	1000	100000	10000	50000	20000	0.025091	0.011832	0.002258	0.012438
2007-Jun-21	86	33182	3	1000	100000	10000	50000	20000	0.025237	0.011742	0.002288	0.012395
2007-Jun-21	86	33183	3	1000	100000	10000	50000	20000	0.024305	0.011179	0.002218	0.011812
2007-Jun-21	86	33184	3	1000	100000	10000	50000	20000	0.023348	0.010613	0.002157	0.011216
2007-Jun-21	86	33185	3	1000	100000	10000	50000	20000	0.024348	0.011163	0.002228	0.011801
2007-Jun-21	86	33186	3	1000	100000	10000	50000	20000	0.025043	0.011687	0.002261	0.012335
2007-Jun-21	86	33187	3	1000	100000	10000	50000	20000	0.028587	0.013900	0.002494	0.014636
2007-Jun-21	86	33189	3	1000	100000	10000	50000	20000	0.026111	0.012354	0.002328	0.013044
2007-Jun-21	86	33190	3	1000	100000	10000	50000	20000	0.031905	0.016149	0.002699	0.016949
2007-Jun-21	86	33193	3	1000	100000	10000	50000	20000	0.024084	0.011041	0.002203	0.011671
2007-Jun-21	86	33194	3	1000	100000	10000	50000	20000	0.027095	0.012848	0.002414	0.013547
2007-Jun-21	86	33195	3	1000	100000	10000	50000	20000	0.020744	0.009093	0.001973	0.009621
2007-Jun-21	86	33196	3	1000	100000	10000	50000	20000	0.025884	0.012059	0.002333	0.012749
2007-Jun-21	86	33197	3	1000	100000	10000	50000	20000	0.022025	0.009974	0.002038	0.010550
2007-Jun-21	86	33199	3	1000	100000	10000	50000	20000	0.022772	0.010228	0.002122	0.010821
2007-Jun-21	86	33231	3	1000	100000	10000	50000	20000	0.028755	0.014141	0.002501	0.014829

2007-Jun-21	86	33233	3	1000	100000	10000	50000	20000	0.031289	0.015468	0.002690	0.016278
2007-Jun-21	86	33234	3	1000	100000	10000	50000	20000	0.021066	0.009114	0.002016	0.009681
2007-Jun-21	86	33238	3	1000	100000	10000	50000	20000	0.023309	0.010786	0.002132	0.011347
2007-Jun-21	86	33239	3	1000	100000	10000	50000	20000	0.023515	0.011068	0.002127	0.011620
2007-Jun-21	86	33242	3	1000	100000	10000	50000	20000	0.020661	0.009114	0.001960	0.009628
2007-Jun-21	86	33243	3	1000	100000	10000	50000	20000	0.022594	0.010261	0.002090	0.010847
2007-Jun-21	86	33245	3	1000	100000	10000	50000	20000	0.024643	0.011346	0.002249	0.011990
2007-Jun-21	86	33247	3	1000	100000	10000	50000	20000	0.020506	0.008916	0.001963	0.009439
2007-Jun-21	86	33255	3	1000	100000	10000	50000	20000	0.022980	0.010491	0.002118	0.011082
2007-Jun-21	86	33256	3	1000	100000	10000	50000	20000	0.024822	0.011572	0.002241	0.012217
2007-Jun-21	86	33257	3	1000	100000	10000	50000	20000	0.022686	0.010220	0.002104	0.010824
2007-Jun-21	86	33261	3	1000	100000	10000	50000	20000	0.022429	0.010110	0.002089	0.010665
2007-Jun-21	86	33265	3	1000	100000	10000	50000	20000	0.022805	0.010290	0.002117	0.010878
2007-Jun-21	86	33266	3	1000	100000	10000	50000	20000	0.021389	0.009391	0.002030	0.009940
2007-Jun-21	86	33269	3	1000	100000	10000	50000	20000	0.021965	0.009961	0.002043	0.010482
2007-Jun-21	86	33280	3	1000	100000	10000	50000	20000	0.024910	0.011773	0.002241	0.012367
2007-Jun-21	86	33283	3	1000	100000	10000	50000	20000	0.023710	0.010838	0.002177	0.011453
2007-Jun-21	86	33296	3	1000	100000	10000	50000	20000	0.024822	0.011572	0.002241	0.012217
2007-Jun-21	86	33299	3	1000	100000	10000	50000	20000	0.017783	0.007413	0.001761	0.007860
2007-Jun-21	86	34141	3	1000	100000	10000	50000	20000	0.027580	0.012690	0.002495	0.013539
2007-Jun-21	87	33001	1	1000	100000	10000	50000	20000	0.009710	0.003889	0.002689	0.003880
2007-Jun-21	87	33036	1	1000	100000	10000	50000	20000	0.008752	0.003197	0.002550	0.003199
2007-Jun-21	87	33037	1	1000	100000	10000	50000	20000	0.009845	0.003623	0.002867	0.003640
2007-Jun-21	87	33040	1	1000	100000	10000	50000	20000	0.005842	0.001547	0.001940	0.001550
2007-Jun-21	87	33041	1	1000	100000	10000	50000	20000	0.005357	0.001323	0.001817	0.001319
2007-Jun-21	87	33042	1	1000	100000	10000	50000	20000	0.009488	0.003688	0.002660	0.003678
2007-Jun-21	87	33043	1	1000	100000	10000	50000	20000	0.008576	0.003322	0.002428	0.003284
2007-Jun-21	87	33045	1	1000	100000	10000	50000	20000	0.005357	0.001323	0.001817	0.001319
2007-Jun-21	87	33050	1	1000	100000	10000	50000	20000	0.008266	0.002864	0.002502	0.002890
2007-Jun-21	87	33051	1	1000	100000	10000	50000	20000	0.007465	0.002527	0.002281	0.002550
2007-Jun-21	87	33052	1	1000	100000	10000	50000	20000	0.007465	0.002527	0.002281	0.002550
2007-Jun-21	87	33070	1	1000	100000	10000	50000	20000	0.007637	0.002471	0.002368	0.002483
2007-Jun-21	87	33001	2	1000	100000	10000	50000	20000	0.008739	0.003180	0.002687	0.003272
2007-Jun-21	87	33036	2	1000	100000	10000	50000	20000	0.007990	0.002665	0.002548	0.002746
2007-Jun-21	87	33037	2	1000	100000	10000	50000	20000	0.008977	0.003024	0.002865	0.003130
2007-Jun-21	87	33040	2	1000	100000	10000	50000	20000	0.005553	0.001386	0.001940	0.001415
2007-Jun-21	87	33041	2	1000	100000	10000	50000	20000	0.005128	0.001201	0.001816	0.001216

2007-Jun-21	87	33042	2	1000	100000	10000	50000	20000	0.008581	0.003030	0.002658	0.003114
2007-Jun-21	87	33043	2	1000	100000	10000	50000	20000	0.007760	0.002704	0.002426	0.002751
2007-Jun-21	87	33045	2	1000	100000	10000	50000	20000	0.005128	0.001201	0.001816	0.001216
2007-Jun-21	87	33050	2	1000	100000	10000	50000	20000	0.007607	0.002434	0.002501	0.002525
2007-Jun-21	87	33051	2	1000	100000	10000	50000	20000	0.006892	0.002159	0.002280	0.002239
2007-Jun-21	87	33052	2	1000	100000	10000	50000	20000	0.006892	0.002159	0.002280	0.002239
2007-Jun-21	87	33070	2	1000	100000	10000	50000	20000	0.007092	0.002119	0.002367	0.002185
2007-Jun-21	87	33001	3	1000	100000	10000	50000	20000	0.033889	0.018000	0.002713	0.019534
2007-Jun-21	87	33036	3	1000	100000	10000	50000	20000	0.031302	0.016035	0.002573	0.017493
2007-Jun-21	87	33037	3	1000	100000	10000	50000	20000	0.035710	0.018475	0.002892	0.020178
2007-Jun-21	87	33040	3	1000	100000	10000	50000	20000	0.021707	0.009810	0.001959	0.010876
2007-Jun-21	87	33041	3	1000	100000	10000	50000	20000	0.019766	0.008634	0.001835	0.009596
2007-Jun-21	87	33042	3	1000	100000	10000	50000	20000	0.033131	0.017322	0.002684	0.018828
2007-Jun-21	87	33043	3	1000	100000	10000	50000	20000	0.029421	0.015101	0.002450	0.016447
2007-Jun-21	87	33045	3	1000	100000	10000	50000	20000	0.019766	0.008634	0.001835	0.009596
2007-Jun-21	87	33050	3	1000	100000	10000	50000	20000	0.030609	0.015533	0.002525	0.017010
2007-Jun-21	87	33051	3	1000	100000	10000	50000	20000	0.027705	0.013946	0.002302	0.015276
2007-Jun-21	87	33052	3	1000	100000	10000	50000	20000	0.027705	0.013946	0.002302	0.015276
2007-Jun-21	87	33070	3	1000	100000	10000	50000	20000	0.028134	0.013790	0.002390	0.015150
2007-Jun-21	89	32009	1	1000	100000	10000	50000	20000	0.000193	0.000129	0.000457	0.000090
2007-Jun-21	89	32011	1	1000	100000	10000	50000	20000	0.000242	0.000151	0.000521	0.000112
2007-Jun-21	89	32034	1	1000	100000	10000	50000	20000	0.000300	0.000181	0.000583	0.000144
2007-Jun-21	89	32035	1	1000	100000	10000	50000	20000	0.000351	0.000201	0.000615	0.000164
2007-Jun-21	89	32041	1	1000	100000	10000	50000	20000	0.000227	0.000141	0.000486	0.000105
2007-Jun-21	89	32046	1	1000	100000	10000	50000	20000	0.000200	0.000129	0.000448	0.000093
2007-Jun-21	89	32097	1	1000	100000	10000	50000	20000	0.000170	0.000116	0.000408	0.000083
2007-Jun-21	89	32009	2	1000	100000	10000	50000	20000	0.000175	0.000127	0.000456	0.000089
2007-Jun-21	89	32011	2	1000	100000	10000	50000	20000	0.000217	0.000148	0.000521	0.000109
2007-Jun-21	89	32034	2	1000	100000	10000	50000	20000	0.000266	0.000174	0.000582	0.000137
2007-Jun-21	89	32035	2	1000	100000	10000	50000	20000	0.000309	0.000190	0.000614	0.000155
2007-Jun-21	89	32041	2	1000	100000	10000	50000	20000	0.000203	0.000137	0.000485	0.000102
2007-Jun-21	89	32046	2	1000	100000	10000	50000	20000	0.000180	0.000126	0.000447	0.000091
2007-Jun-21	89	32097	2	1000	100000	10000	50000	20000	0.000153	0.000114	0.000407	0.000081
2007-Jun-21	89	32009	3	1000	100000	10000	50000	20000	0.001549	0.000413	0.000468	0.000373
2007-Jun-21	89	32011	3	1000	100000	10000	50000	20000	0.001990	0.000602	0.000534	0.000567
2007-Jun-21	89	32034	3	1000	100000	10000	50000	20000	0.002566	0.000907	0.000598	0.000879
2007-Jun-21	89	32035	3	1000	100000	10000	50000	20000	0.002850	0.001067	0.000630	0.001038

2007-Jun-21	89	32041	3	1000	100000	10000	50000	20000	0.001895	0.000602	0.000498	0.000570
2007-Jun-21	89	32046	3	1000	100000	10000	50000	20000	0.001639	0.000486	0.000458	0.000452
2007-Jun-21	89	32097	3	1000	100000	10000	50000	20000	0.001427	0.000412	0.000418	0.000378
2007-Jun-21	91	32531	1	1000	100000	10000	50000	20000	0.001024	0.000508	0.001364	0.000477
2007-Jun-21	91	32536	1	1000	100000	10000	50000	20000	0.001045	0.000521	0.001349	0.000492
2007-Jun-21	91	32537	1	1000	100000	10000	50000	20000	0.000676	0.000357	0.001114	0.000315
2007-Jun-21	91	32539	1	1000	100000	10000	50000	20000	0.000852	0.000428	0.001233	0.000391
2007-Jun-21	91	32540	1	1000	100000	10000	50000	20000	0.001835	0.000930	0.001881	0.000926
2007-Jun-21	91	32541	1	1000	100000	10000	50000	20000	0.002102	0.001068	0.002007	0.001071
2007-Jun-21	91	32542	1	1000	100000	10000	50000	20000	0.001746	0.000906	0.001775	0.000889
2007-Jun-21	91	32544	1	1000	100000	10000	50000	20000	0.001653	0.000833	0.001821	0.000823
2007-Jun-21	91	32547	1	1000	100000	10000	50000	20000	0.001799	0.000908	0.001872	0.000905
2007-Jun-21	91	32548	1	1000	100000	10000	50000	20000	0.001613	0.000811	0.001805	0.000800
2007-Jun-21	91	32549	1	1000	100000	10000	50000	20000	0.001533	0.000773	0.001749	0.000759
2007-Jun-21	91	32564	1	1000	100000	10000	50000	20000	0.000928	0.000475	0.001340	0.000441
2007-Jun-21	91	32567	1	1000	100000	10000	50000	20000	0.000794	0.000400	0.001184	0.000362
2007-Jun-21	91	32569	1	1000	100000	10000	50000	20000	0.001806	0.000918	0.001854	0.000913
2007-Jun-21	91	32578	1	1000	100000	10000	50000	20000	0.001401	0.000713	0.001669	0.000690
2007-Jun-21	91	32579	1	1000	100000	10000	50000	20000	0.001819	0.000924	0.001854	0.000920
2007-Jun-21	91	32580	1	1000	100000	10000	50000	20000	0.001958	0.000997	0.001909	0.000997
2007-Jun-21	91	32588	1	1000	100000	10000	50000	20000	0.001273	0.000646	0.001574	0.000623
2007-Jun-21	91	32531	2	1000	100000	10000	50000	20000	0.000884	0.000465	0.001361	0.000437
2007-Jun-21	91	32536	2	1000	100000	10000	50000	20000	0.000901	0.000475	0.001346	0.000450
2007-Jun-21	91	32537	2	1000	100000	10000	50000	20000	0.000588	0.000335	0.001111	0.000294
2007-Jun-21	91	32539	2	1000	100000	10000	50000	20000	0.000738	0.000396	0.001230	0.000362
2007-Jun-21	91	32540	2	1000	100000	10000	50000	20000	0.001559	0.000817	0.001876	0.000823
2007-Jun-21	91	32541	2	1000	100000	10000	50000	20000	0.001782	0.000929	0.002002	0.000946
2007-Jun-21	91	32542	2	1000	100000	10000	50000	20000	0.001481	0.000785	0.001770	0.000781
2007-Jun-21	91	32544	2	1000	100000	10000	50000	20000	0.001408	0.000738	0.001816	0.000737
2007-Jun-21	91	32547	2	1000	100000	10000	50000	20000	0.001529	0.000800	0.001868	0.000806
2007-Jun-21	91	32548	2	1000	100000	10000	50000	20000	0.001375	0.000721	0.001801	0.000717
2007-Jun-21	91	32549	2	1000	100000	10000	50000	20000	0.001307	0.000689	0.001745	0.000682
2007-Jun-21	91	32564	2	1000	100000	10000	50000	20000	0.000800	0.000436	0.001337	0.000404
2007-Jun-21	91	32567	2	1000	100000	10000	50000	20000	0.000689	0.000371	0.001182	0.000335
2007-Jun-21	91	32569	2	1000	100000	10000	50000	20000	0.001535	0.000806	0.001849	0.000812
2007-Jun-21	91	32578	2	1000	100000	10000	50000	20000	0.001197	0.000638	0.001666	0.000621
2007-Jun-21	91	32579	2	1000	100000	10000	50000	20000	0.001545	0.000810	0.001850	0.000816

2007-Jun-21	91	32580	2	1000	100000	10000	50000	20000	0.001660	0.000868	0.001904	0.000881
2007-Jun-21	91	32588	2	1000	100000	10000	50000	20000	0.001090	0.000583	0.001571	0.000564
2007-Jun-21	91	32531	3	1000	100000	10000	50000	20000	0.008567	0.003798	0.001399	0.003849
2007-Jun-21	91	32536	3	1000	100000	10000	50000	20000	0.008546	0.003831	0.001384	0.003873
2007-Jun-21	91	32537	3	1000	100000	10000	50000	20000	0.006233	0.002497	0.001145	0.002531
2007-Jun-21	91	32539	3	1000	100000	10000	50000	20000	0.007333	0.003123	0.001265	0.003166
2007-Jun-21	91	32540	3	1000	100000	10000	50000	20000	0.013522	0.006664	0.001928	0.006701
2007-Jun-21	91	32541	3	1000	100000	10000	50000	20000	0.014857	0.007459	0.002056	0.007487
2007-Jun-21	91	32542	3	1000	100000	10000	50000	20000	0.012501	0.006066	0.001820	0.006100
2007-Jun-21	91	32544	3	1000	100000	10000	50000	20000	0.012814	0.006207	0.001867	0.006258
2007-Jun-21	91	32547	3	1000	100000	10000	50000	20000	0.013492	0.006653	0.001919	0.006696
2007-Jun-21	91	32548	3	1000	100000	10000	50000	20000	0.012625	0.006078	0.001851	0.006133
2007-Jun-21	91	32549	3	1000	100000	10000	50000	20000	0.012096	0.005786	0.001794	0.005840
2007-Jun-21	91	32564	3	1000	100000	10000	50000	20000	0.008215	0.003577	0.001376	0.003628
2007-Jun-21	91	32567	3	1000	100000	10000	50000	20000	0.006956	0.002907	0.001216	0.002953
2007-Jun-21	91	32569	3	1000	100000	10000	50000	20000	0.013303	0.006575	0.001899	0.006609
2007-Jun-21	91	32578	3	1000	100000	10000	50000	20000	0.011138	0.005170	0.001713	0.005218
2007-Jun-21	91	32579	3	1000	100000	10000	50000	20000	0.013372	0.006607	0.001900	0.006643
2007-Jun-21	91	32580	3	1000	100000	10000	50000	20000	0.014008	0.006998	0.001956	0.007029
2007-Jun-21	91	32588	3	1000	100000	10000	50000	20000	0.010371	0.004791	0.001615	0.004837
2007-Jun-21	93	34972	1	1000	100000	10000	50000	20000	0.003140	0.000589	0.001612	0.000467
2007-Jun-21	93	34973	1	1000	100000	10000	50000	20000	0.002856	0.000511	0.001475	0.000390
2007-Jun-21	93	34974	1	1000	100000	10000	50000	20000	0.003030	0.000545	0.001565	0.000422
2007-Jun-21	93	34972	2	1000	100000	10000	50000	20000	0.002628	0.000504	0.001608	0.000382
2007-Jun-21	93	34973	2	1000	100000	10000	50000	20000	0.002405	0.000447	0.001471	0.000326
2007-Jun-21	93	34974	2	1000	100000	10000	50000	20000	0.002548	0.000475	0.001561	0.000350
2007-Jun-21	93	34972	3	1000	100000	10000	50000	20000	0.013915	0.004766	0.001636	0.004972
2007-Jun-21	93	34973	3	1000	100000	10000	50000	20000	0.012231	0.003910	0.001497	0.004076
2007-Jun-21	93	34974	3	1000	100000	10000	50000	20000	0.013175	0.004310	0.001588	0.004504
2007-Jun-21	95	32703	1	1000	100000	10000	50000	20000	0.002384	0.000384	0.001184	0.000277
2007-Jun-21	95	32704	1	1000	100000	10000	50000	20000	0.002267	0.000360	0.001129	0.000255
2007-Jun-21	95	32709	1	1000	100000	10000	50000	20000	0.002075	0.000360	0.001023	0.000265
2007-Jun-21	95	32710	1	1000	100000	10000	50000	20000	0.002488	0.000406	0.001238	0.000296
2007-Jun-21	95	32712	1	1000	100000	10000	50000	20000	0.002456	0.000398	0.001221	0.000289
2007-Jun-21	95	32751	1	1000	100000	10000	50000	20000	0.002802	0.000485	0.001394	0.000376
2007-Jun-21	95	32768	1	1000	100000	10000	50000	20000	0.002467	0.000405	0.001227	0.000298
2007-Jun-21	95	32777	1	1000	100000	10000	50000	20000	0.002536	0.000420	0.001263	0.000312

2007-Jun-21	95	32789	1	1000	100000	10000	50000	20000	0.002449	0.000403	0.001209	0.000295
2007-Jun-21	95	32790	1	1000	100000	10000	50000	20000	0.002439	0.000400	0.001204	0.000292
2007-Jun-21	95	32792	1	1000	100000	10000	50000	20000	0.002199	0.000358	0.001087	0.000255
2007-Jun-21	95	32793	1	1000	100000	10000	50000	20000	0.002396	0.000392	0.001185	0.000285
2007-Jun-21	95	32794	1	1000	100000	10000	50000	20000	0.002409	0.000389	0.001193	0.000281
2007-Jun-21	95	32798	1	1000	100000	10000	50000	20000	0.002621	0.000435	0.001303	0.000325
2007-Jun-21	95	32801	1	1000	100000	10000	50000	20000	0.002376	0.000390	0.001172	0.000284
2007-Jun-21	95	32802	1	1000	100000	10000	50000	20000	0.002186	0.000347	0.001080	0.000243
2007-Jun-21	95	32803	1	1000	100000	10000	50000	20000	0.002383	0.000395	0.001174	0.000289
2007-Jun-21	95	32804	1	1000	100000	10000	50000	20000	0.002453	0.000400	0.001212	0.000291
2007-Jun-21	95	32805	1	1000	100000	10000	50000	20000	0.002495	0.000408	0.001237	0.000298
2007-Jun-21	95	32806	1	1000	100000	10000	50000	20000	0.002498	0.000411	0.001232	0.000302
2007-Jun-21	95	32807	1	1000	100000	10000	50000	20000	0.002486	0.000409	0.001226	0.000301
2007-Jun-21	95	32808	1	1000	100000	10000	50000	20000	0.002274	0.000365	0.001127	0.000259
2007-Jun-21	95	32809	1	1000	100000	10000	50000	20000	0.002348	0.000376	0.001161	0.000268
2007-Jun-21	95	32810	1	1000	100000	10000	50000	20000	0.002449	0.000401	0.001213	0.000293
2007-Jun-21	95	32811	1	1000	100000	10000	50000	20000	0.002526	0.000414	0.001251	0.000304
2007-Jun-21	95	32812	1	1000	100000	10000	50000	20000	0.002534	0.000418	0.001250	0.000308
2007-Jun-21	95	32814	1	1000	100000	10000	50000	20000	0.002693	0.000460	0.001328	0.000350
2007-Jun-21	95	32816	1	1000	100000	10000	50000	20000	0.002225	0.000362	0.001101	0.000259
2007-Jun-21	95	32817	1	1000	100000	10000	50000	20000	0.002522	0.000420	0.001246	0.000312
2007-Jun-21	95	32818	1	1000	100000	10000	50000	20000	0.002269	0.000363	0.001126	0.000257
2007-Jun-21	95	32819	1	1000	100000	10000	50000	20000	0.002521	0.000415	0.001249	0.000305
2007-Jun-21	95	32820	1	1000	100000	10000	50000	20000	0.002253	0.000364	0.001116	0.000259
2007-Jun-21	95	32821	1	1000	100000	10000	50000	20000	0.002583	0.000422	0.001280	0.000311
2007-Jun-21	95	32822	1	1000	100000	10000	50000	20000	0.002427	0.000397	0.001197	0.000289
2007-Jun-21	95	32824	1	1000	100000	10000	50000	20000	0.002393	0.000382	0.001185	0.000274
2007-Jun-21	95	32825	1	1000	100000	10000	50000	20000	0.002391	0.000399	0.001176	0.000293
2007-Jun-21	95	32826	1	1000	100000	10000	50000	20000	0.002368	0.000391	0.001169	0.000285
2007-Jun-21	95	32827	1	1000	100000	10000	50000	20000	0.002552	0.000422	0.001260	0.000312
2007-Jun-21	95	32828	1	1000	100000	10000	50000	20000	0.002383	0.000395	0.001175	0.000289
2007-Jun-21	95	32829	1	1000	100000	10000	50000	20000	0.002444	0.000403	0.001203	0.000295
2007-Jun-21	95	32830	1	1000	100000	10000	50000	20000	0.002277	0.000358	0.001129	0.000251
2007-Jun-21	95	32831	1	1000	100000	10000	50000	20000	0.002450	0.000416	0.001205	0.000310
2007-Jun-21	95	32832	1	1000	100000	10000	50000	20000	0.002635	0.000445	0.001297	0.000335
2007-Jun-21	95	32833	1	1000	100000	10000	50000	20000	0.002562	0.000440	0.001261	0.000332
2007-Jun-21	95	32834	1	1000	100000	10000	50000	20000	0.002123	0.000351	0.001048	0.000251

2007-Jun-21	95	32835	1	1000	100000	10000	50000	20000	0.002575	0.000425	0.001277	0.000315
2007-Jun-21	95	32836	1	1000	100000	10000	50000	20000	0.002472	0.000402	0.001227	0.000292
2007-Jun-21	95	32837	1	1000	100000	10000	50000	20000	0.002469	0.000395	0.001221	0.000285
2007-Jun-21	95	32839	1	1000	100000	10000	50000	20000	0.002388	0.000383	0.001182	0.000275
2007-Jun-21	95	32853	1	1000	100000	10000	50000	20000	0.002389	0.000385	0.001182	0.000277
2007-Jun-21	95	32854	1	1000	100000	10000	50000	20000	0.002551	0.000420	0.001262	0.000310
2007-Jun-21	95	32855	1	1000	100000	10000	50000	20000	0.002149	0.000338	0.001064	0.000233
2007-Jun-21	95	32856	1	1000	100000	10000	50000	20000	0.002436	0.000394	0.001206	0.000286
2007-Jun-21	95	32857	1	1000	100000	10000	50000	20000	0.002445	0.000402	0.001205	0.000294
2007-Jun-21	95	32858	1	1000	100000	10000	50000	20000	0.002216	0.000352	0.001098	0.000248
2007-Jun-21	95	32859	1	1000	100000	10000	50000	20000	0.002510	0.000411	0.001240	0.000301
2007-Jun-21	95	32860	1	1000	100000	10000	50000	20000	0.002366	0.000381	0.001177	0.000274
2007-Jun-21	95	32861	1	1000	100000	10000	50000	20000	0.002440	0.000393	0.001209	0.000284
2007-Jun-21	95	32862	1	1000	100000	10000	50000	20000	0.002349	0.000375	0.001160	0.000266
2007-Jun-21	95	32867	1	1000	100000	10000	50000	20000	0.002380	0.000392	0.001178	0.000286
2007-Jun-21	95	32868	1	1000	100000	10000	50000	20000	0.002320	0.000372	0.001151	0.000265
2007-Jun-21	95	32869	1	1000	100000	10000	50000	20000	0.002510	0.000411	0.001240	0.000301
2007-Jun-21	95	32872	1	1000	100000	10000	50000	20000	0.002332	0.000370	0.001152	0.000263
2007-Jun-21	95	32877	1	1000	100000	10000	50000	20000	0.002451	0.000392	0.001211	0.000282
2007-Jun-21	95	32878	1	1000	100000	10000	50000	20000	0.002123	0.000351	0.001048	0.000251
2007-Jun-21	95	32885	1	1000	100000	10000	50000	20000	0.002398	0.000386	0.001185	0.000277
2007-Jun-21	95	32886	1	1000	100000	10000	50000	20000	0.002093	0.000329	0.001035	0.000226
2007-Jun-21	95	32887	1	1000	100000	10000	50000	20000	0.002441	0.000392	0.001209	0.000283
2007-Jun-21	95	32890	1	1000	100000	10000	50000	20000	0.002520	0.000413	0.001245	0.000303
2007-Jun-21	95	32891	1	1000	100000	10000	50000	20000	0.002235	0.000363	0.001105	0.000259
2007-Jun-21	95	32893	1	1000	100000	10000	50000	20000	0.002632	0.000446	0.001297	0.000336
2007-Jun-21	95	32896	1	1000	100000	10000	50000	20000	0.002139	0.000339	0.001058	0.000235
2007-Jun-21	95	32897	1	1000	100000	10000	50000	20000	0.002118	0.000331	0.001048	0.000228
2007-Jun-21	95	32898	1	1000	100000	10000	50000	20000	0.002118	0.000331	0.001048	0.000228
2007-Jun-21	95	34734	1	1000	100000	10000	50000	20000	0.002584	0.000430	0.001286	0.000320
2007-Jun-21	95	34740	1	1000	100000	10000	50000	20000	0.002615	0.000442	0.001310	0.000333
2007-Jun-21	95	34760	1	1000	100000	10000	50000	20000	0.002571	0.000427	0.001283	0.000317
2007-Jun-21	95	34761	1	1000	100000	10000	50000	20000	0.002587	0.000425	0.001291	0.000313
2007-Jun-21	95	34777	1	1000	100000	10000	50000	20000	0.002378	0.000386	0.001187	0.000279
2007-Jun-21	95	34778	1	1000	100000	10000	50000	20000	0.002378	0.000386	0.001187	0.000279
2007-Jun-21	95	34786	1	1000	100000	10000	50000	20000	0.002942	0.000522	0.001459	0.000410
2007-Jun-21	95	34787	1	1000	100000	10000	50000	20000	0.003034	0.000582	0.001486	0.000472

2007-Jun-21	95	32703	2	1000	100000	10000	50000	20000	0.002015	0.000347	0.001182	0.000239
2007-Jun-21	95	32704	2	1000	100000	10000	50000	20000	0.001920	0.000328	0.001126	0.000222
2007-Jun-21	95	32709	2	1000	100000	10000	50000	20000	0.001747	0.000320	0.001021	0.000226
2007-Jun-21	95	32710	2	1000	100000	10000	50000	20000	0.002100	0.000364	0.001235	0.000254
2007-Jun-21	95	32712	2	1000	100000	10000	50000	20000	0.002073	0.000358	0.001218	0.000249
2007-Jun-21	95	32751	2	1000	100000	10000	50000	20000	0.002346	0.000422	0.001390	0.000312
2007-Jun-21	95	32768	2	1000	100000	10000	50000	20000	0.002080	0.000363	0.001224	0.000254
2007-Jun-21	95	32777	2	1000	100000	10000	50000	20000	0.002136	0.000373	0.001260	0.000265
2007-Jun-21	95	32789	2	1000	100000	10000	50000	20000	0.002066	0.000360	0.001206	0.000252
2007-Jun-21	95	32790	2	1000	100000	10000	50000	20000	0.002058	0.000358	0.001201	0.000250
2007-Jun-21	95	32792	2	1000	100000	10000	50000	20000	0.001860	0.000324	0.001085	0.000221
2007-Jun-21	95	32793	2	1000	100000	10000	50000	20000	0.002023	0.000352	0.001182	0.000245
2007-Jun-21	95	32794	2	1000	100000	10000	50000	20000	0.002036	0.000351	0.001190	0.000242
2007-Jun-21	95	32798	2	1000	100000	10000	50000	20000	0.002206	0.000386	0.001300	0.000275
2007-Jun-21	95	32801	2	1000	100000	10000	50000	20000	0.002005	0.000350	0.001170	0.000244
2007-Jun-21	95	32802	2	1000	100000	10000	50000	20000	0.001854	0.000317	0.001078	0.000213
2007-Jun-21	95	32803	2	1000	100000	10000	50000	20000	0.002011	0.000353	0.001171	0.000247
2007-Jun-21	95	32804	2	1000	100000	10000	50000	20000	0.002071	0.000359	0.001209	0.000250
2007-Jun-21	95	32805	2	1000	100000	10000	50000	20000	0.002105	0.000365	0.001234	0.000255
2007-Jun-21	95	32806	2	1000	100000	10000	50000	20000	0.002107	0.000367	0.001229	0.000258
2007-Jun-21	95	32807	2	1000	100000	10000	50000	20000	0.002097	0.000366	0.001224	0.000257
2007-Jun-21	95	32808	2	1000	100000	10000	50000	20000	0.001925	0.000331	0.001124	0.000225
2007-Jun-21	95	32809	2	1000	100000	10000	50000	20000	0.001987	0.000341	0.001158	0.000233
2007-Jun-21	95	32810	2	1000	100000	10000	50000	20000	0.002067	0.000360	0.001210	0.000251
2007-Jun-21	95	32811	2	1000	100000	10000	50000	20000	0.002130	0.000370	0.001248	0.000259
2007-Jun-21	95	32812	2	1000	100000	10000	50000	20000	0.002136	0.000373	0.001247	0.000263
2007-Jun-21	95	32814	2	1000	100000	10000	50000	20000	0.002262	0.000404	0.001324	0.000293
2007-Jun-21	95	32816	2	1000	100000	10000	50000	20000	0.001882	0.000328	0.001098	0.000224
2007-Jun-21	95	32817	2	1000	100000	10000	50000	20000	0.002124	0.000374	0.001243	0.000265
2007-Jun-21	95	32818	2	1000	100000	10000	50000	20000	0.001922	0.000330	0.001123	0.000224
2007-Jun-21	95	32819	2	1000	100000	10000	50000	20000	0.002125	0.000370	0.001246	0.000260
2007-Jun-21	95	32820	2	1000	100000	10000	50000	20000	0.001906	0.000330	0.001114	0.000225
2007-Jun-21	95	32821	2	1000	100000	10000	50000	20000	0.002179	0.000377	0.001277	0.000265
2007-Jun-21	95	32822	2	1000	100000	10000	50000	20000	0.002049	0.000356	0.001194	0.000248
2007-Jun-21	95	32824	2	1000	100000	10000	50000	20000	0.002024	0.000346	0.001182	0.000237
2007-Jun-21	95	32825	2	1000	100000	10000	50000	20000	0.002015	0.000356	0.001174	0.000250
2007-Jun-21	95	32826	2	1000	100000	10000	50000	20000	0.001998	0.000350	0.001166	0.000245

2007-Jun-21	95	32827	2	1000	100000	10000	50000	20000	0.002151	0.000376	0.001257	0.000265
2007-Jun-21	95	32828	2	1000	100000	10000	50000	20000	0.002010	0.000353	0.001172	0.000247
2007-Jun-21	95	32829	2	1000	100000	10000	50000	20000	0.002062	0.000360	0.001200	0.000252
2007-Jun-21	95	32830	2	1000	100000	10000	50000	20000	0.001931	0.000327	0.001127	0.000220
2007-Jun-21	95	32831	2	1000	100000	10000	50000	20000	0.002062	0.000368	0.001202	0.000262
2007-Jun-21	95	32832	2	1000	100000	10000	50000	20000	0.002216	0.000393	0.001294	0.000283
2007-Jun-21	95	32833	2	1000	100000	10000	50000	20000	0.002153	0.000387	0.001258	0.000280
2007-Jun-21	95	32834	2	1000	100000	10000	50000	20000	0.001795	0.000316	0.001045	0.000217
2007-Jun-21	95	32835	2	1000	100000	10000	50000	20000	0.002170	0.000379	0.001274	0.000268
2007-Jun-21	95	32836	2	1000	100000	10000	50000	20000	0.002087	0.000361	0.001224	0.000251
2007-Jun-21	95	32837	2	1000	100000	10000	50000	20000	0.002087	0.000357	0.001218	0.000246
2007-Jun-21	95	32839	2	1000	100000	10000	50000	20000	0.002019	0.000346	0.001179	0.000238
2007-Jun-21	95	32853	2	1000	100000	10000	50000	20000	0.002020	0.000347	0.001179	0.000239
2007-Jun-21	95	32854	2	1000	100000	10000	50000	20000	0.002151	0.000375	0.001259	0.000264
2007-Jun-21	95	32855	2	1000	100000	10000	50000	20000	0.001824	0.000310	0.001061	0.000206
2007-Jun-21	95	32856	2	1000	100000	10000	50000	20000	0.002058	0.000355	0.001203	0.000246
2007-Jun-21	95	32857	2	1000	100000	10000	50000	20000	0.002063	0.000360	0.001203	0.000252
2007-Jun-21	95	32858	2	1000	100000	10000	50000	20000	0.001878	0.000321	0.001096	0.000217
2007-Jun-21	95	32859	2	1000	100000	10000	50000	20000	0.002118	0.000368	0.001237	0.000257
2007-Jun-21	95	32860	2	1000	100000	10000	50000	20000	0.002001	0.000344	0.001174	0.000237
2007-Jun-21	95	32861	2	1000	100000	10000	50000	20000	0.002062	0.000355	0.001206	0.000245
2007-Jun-21	95	32862	2	1000	100000	10000	50000	20000	0.001989	0.000340	0.001157	0.000232
2007-Jun-21	95	32867	2	1000	100000	10000	50000	20000	0.002008	0.000352	0.001176	0.000245
2007-Jun-21	95	32868	2	1000	100000	10000	50000	20000	0.001964	0.000337	0.001149	0.000230
2007-Jun-21	95	32869	2	1000	100000	10000	50000	20000	0.002118	0.000368	0.001237	0.000257
2007-Jun-21	95	32872	2	1000	100000	10000	50000	20000	0.001974	0.000337	0.001149	0.000229
2007-Jun-21	95	32877	2	1000	100000	10000	50000	20000	0.002073	0.000355	0.001208	0.000244
2007-Jun-21	95	32878	2	1000	100000	10000	50000	20000	0.001795	0.000316	0.001045	0.000217
2007-Jun-21	95	32885	2	1000	100000	10000	50000	20000	0.002028	0.000349	0.001182	0.000240
2007-Jun-21	95	32886	2	1000	100000	10000	50000	20000	0.001778	0.000303	0.001032	0.000200
2007-Jun-21	95	32887	2	1000	100000	10000	50000	20000	0.002063	0.000354	0.001207	0.000244
2007-Jun-21	95	32890	2	1000	100000	10000	50000	20000	0.002126	0.000370	0.001242	0.000259
2007-Jun-21	95	32891	2	1000	100000	10000	50000	20000	0.001892	0.000329	0.001102	0.000224
2007-Jun-21	95	32893	2	1000	100000	10000	50000	20000	0.002213	0.000393	0.001294	0.000283
2007-Jun-21	95	32896	2	1000	100000	10000	50000	20000	0.001815	0.000310	0.001055	0.000207
2007-Jun-21	95	32897	2	1000	100000	10000	50000	20000	0.001799	0.000305	0.001046	0.000202
2007-Jun-21	95	32898	2	1000	100000	10000	50000	20000	0.001799	0.000305	0.001046	0.000202

2007-Jun-21	95	34734	2	1000	100000	10000	50000	20000	0.002176	0.000382	0.001283	0.000271
2007-Jun-21	95	34740	2	1000	100000	10000	50000	20000	0.002197	0.000390	0.001307	0.000280
2007-Jun-21	95	34760	2	1000	100000	10000	50000	20000	0.002165	0.000379	0.001280	0.000269
2007-Jun-21	95	34761	2	1000	100000	10000	50000	20000	0.002181	0.000379	0.001288	0.000267
2007-Jun-21	95	34777	2	1000	100000	10000	50000	20000	0.002008	0.000348	0.001184	0.000240
2007-Jun-21	95	34778	2	1000	100000	10000	50000	20000	0.002008	0.000348	0.001184	0.000240
2007-Jun-21	95	34786	2	1000	100000	10000	50000	20000	0.002459	0.000450	0.001456	0.000337
2007-Jun-21	95	34787	2	1000	100000	10000	50000	20000	0.002521	0.000490	0.001482	0.000381
2007-Jun-21	95	32703	3	1000	100000	10000	50000	20000	0.009286	0.002628	0.001202	0.002735
2007-Jun-21	95	32704	3	1000	100000	10000	50000	20000	0.008685	0.002363	0.001146	0.002456
2007-Jun-21	95	32709	3	1000	100000	10000	50000	20000	0.007996	0.002333	0.001038	0.002389
2007-Jun-21	95	32710	3	1000	100000	10000	50000	20000	0.009835	0.002863	0.001256	0.002986
2007-Jun-21	95	32712	3	1000	100000	10000	50000	20000	0.009683	0.002800	0.001239	0.002921
2007-Jun-21	95	32751	3	1000	100000	10000	50000	20000	0.011772	0.003859	0.001414	0.004035
2007-Jun-21	95	32768	3	1000	100000	10000	50000	20000	0.009800	0.002891	0.001246	0.003012
2007-Jun-21	95	32777	3	1000	100000	10000	50000	20000	0.010227	0.003095	0.001282	0.003233
2007-Jun-21	95	32789	3	1000	100000	10000	50000	20000	0.009581	0.002775	0.001226	0.002883
2007-Jun-21	95	32790	3	1000	100000	10000	50000	20000	0.009511	0.002735	0.001222	0.002841
2007-Jun-21	95	32792	3	1000	100000	10000	50000	20000	0.008330	0.002270	0.001104	0.002340
2007-Jun-21	95	32793	3	1000	100000	10000	50000	20000	0.009327	0.002668	0.001203	0.002770
2007-Jun-21	95	32794	3	1000	100000	10000	50000	20000	0.009349	0.002641	0.001210	0.002747
2007-Jun-21	95	32798	3	1000	100000	10000	50000	20000	0.010611	0.003237	0.001322	0.003385
2007-Jun-21	95	32801	3	1000	100000	10000	50000	20000	0.009227	0.002640	0.001190	0.002739
2007-Jun-21	95	32802	3	1000	100000	10000	50000	20000	0.008180	0.002149	0.001096	0.002219
2007-Jun-21	95	32803	3	1000	100000	10000	50000	20000	0.009236	0.002650	0.001191	0.002743
2007-Jun-21	95	32804	3	1000	100000	10000	50000	20000	0.009570	0.002743	0.001230	0.002853
2007-Jun-21	95	32805	3	1000	100000	10000	50000	20000	0.009838	0.002864	0.001256	0.002985
2007-Jun-21	95	32806	3	1000	100000	10000	50000	20000	0.009818	0.002866	0.001250	0.002981
2007-Jun-21	95	32807	3	1000	100000	10000	50000	20000	0.009772	0.002856	0.001245	0.002969
2007-Jun-21	95	32808	3	1000	100000	10000	50000	20000	0.008667	0.002359	0.001143	0.002446
2007-Jun-21	95	32809	3	1000	100000	10000	50000	20000	0.008995	0.002473	0.001178	0.002569
2007-Jun-21	95	32810	3	1000	100000	10000	50000	20000	0.009597	0.002772	0.001230	0.002883
2007-Jun-21	95	32811	3	1000	100000	10000	50000	20000	0.009989	0.002928	0.001270	0.003052
2007-Jun-21	95	32812	3	1000	100000	10000	50000	20000	0.009990	0.002935	0.001268	0.003054
2007-Jun-21	95	32814	3	1000	100000	10000	50000	20000	0.010934	0.003416	0.001347	0.003560
2007-Jun-21	95	32816	3	1000	100000	10000	50000	20000	0.008463	0.002322	0.001117	0.002396
2007-Jun-21	95	32817	3	1000	100000	10000	50000	20000	0.010008	0.002984	0.001264	0.003103

2007-Jun-21	95	32818	3	1000	100000	10000	50000	20000	0.008641	0.002341	0.001143	0.002427
2007-Jun-21	95	32819	3	1000	100000	10000	50000	20000	0.009998	0.002948	0.001268	0.003075
2007-Jun-21	95	32820	3	1000	100000	10000	50000	20000	0.008588	0.002353	0.001133	0.002432
2007-Jun-21	95	32821	3	1000	100000	10000	50000	20000	0.010269	0.003028	0.001299	0.003163
2007-Jun-21	95	32822	3	1000	100000	10000	50000	20000	0.009434	0.002697	0.001214	0.002801
2007-Jun-21	95	32824	3	1000	100000	10000	50000	20000	0.009223	0.002558	0.001202	0.002662
2007-Jun-21	95	32825	3	1000	100000	10000	50000	20000	0.009308	0.002704	0.001194	0.002799
2007-Jun-21	95	32826	3	1000	100000	10000	50000	20000	0.009203	0.002645	0.001186	0.002739
2007-Jun-21	95	32827	3	1000	100000	10000	50000	20000	0.010106	0.002990	0.001278	0.003114
2007-Jun-21	95	32828	3	1000	100000	10000	50000	20000	0.009268	0.002672	0.001192	0.002768
2007-Jun-21	95	32829	3	1000	100000	10000	50000	20000	0.009527	0.002753	0.001221	0.002857
2007-Jun-21	95	32830	3	1000	100000	10000	50000	20000	0.008614	0.002282	0.001146	0.002372
2007-Jun-21	95	32831	3	1000	100000	10000	50000	20000	0.009654	0.002884	0.001223	0.002987
2007-Jun-21	95	32832	3	1000	100000	10000	50000	20000	0.010579	0.003236	0.001316	0.003370
2007-Jun-21	95	32833	3	1000	100000	10000	50000	20000	0.010274	0.003166	0.001280	0.003286
2007-Jun-21	95	32834	3	1000	100000	10000	50000	20000	0.008014	0.002194	0.001063	0.002252
2007-Jun-21	95	32835	3	1000	100000	10000	50000	20000	0.010293	0.003075	0.001296	0.003210
2007-Jun-21	95	32836	3	1000	100000	10000	50000	20000	0.009717	0.002801	0.001245	0.002921
2007-Jun-21	95	32837	3	1000	100000	10000	50000	20000	0.009589	0.002699	0.001239	0.002813
2007-Jun-21	95	32839	3	1000	100000	10000	50000	20000	0.009230	0.002581	0.001199	0.002684
2007-Jun-21	95	32853	3	1000	100000	10000	50000	20000	0.009234	0.002587	0.001199	0.002689
2007-Jun-21	95	32854	3	1000	100000	10000	50000	20000	0.010115	0.002987	0.001281	0.003114
2007-Jun-21	95	32855	3	1000	100000	10000	50000	20000	0.007946	0.002023	0.001080	0.002086
2007-Jun-21	95	32856	3	1000	100000	10000	50000	20000	0.009522	0.002728	0.001224	0.002839
2007-Jun-21	95	32857	3	1000	100000	10000	50000	20000	0.009533	0.002750	0.001223	0.002854
2007-Jun-21	95	32858	3	1000	100000	10000	50000	20000	0.008357	0.002220	0.001115	0.002298
2007-Jun-21	95	32859	3	1000	100000	10000	50000	20000	0.009856	0.002859	0.001258	0.002979
2007-Jun-21	95	32860	3	1000	100000	10000	50000	20000	0.009196	0.002589	0.001195	0.002694
2007-Jun-21	95	32861	3	1000	100000	10000	50000	20000	0.009497	0.002686	0.001227	0.002799
2007-Jun-21	95	32862	3	1000	100000	10000	50000	20000	0.008954	0.002438	0.001177	0.002530
2007-Jun-21	95	32867	3	1000	100000	10000	50000	20000	0.009273	0.002665	0.001196	0.002763
2007-Jun-21	95	32868	3	1000	100000	10000	50000	20000	0.008904	0.002448	0.001169	0.002544
2007-Jun-21	95	32869	3	1000	100000	10000	50000	20000	0.009856	0.002859	0.001258	0.002979
2007-Jun-21	95	32872	3	1000	100000	10000	50000	20000	0.008887	0.002416	0.001169	0.002508
2007-Jun-21	95	32877	3	1000	100000	10000	50000	20000	0.009477	0.002649	0.001229	0.002759
2007-Jun-21	95	32878	3	1000	100000	10000	50000	20000	0.008014	0.002194	0.001063	0.002252
2007-Jun-21	95	32885	3	1000	100000	10000	50000	20000	0.009236	0.002575	0.001203	0.002674

2007-Jun-21	95	32886	3	1000	100000	10000	50000	20000	0.007664	0.001918	0.001050	0.001972
2007-Jun-21	95	32887	3	1000	100000	10000	50000	20000	0.009491	0.002678	0.001227	0.002790
2007-Jun-21	95	32890	3	1000	100000	10000	50000	20000	0.009915	0.002889	0.001263	0.003010
2007-Jun-21	95	32891	3	1000	100000	10000	50000	20000	0.008470	0.002306	0.001121	0.002379
2007-Jun-21	95	32893	3	1000	100000	10000	50000	20000	0.010575	0.003241	0.001316	0.003373
2007-Jun-21	95	32896	3	1000	100000	10000	50000	20000	0.007932	0.002045	0.001073	0.002107
2007-Jun-21	95	32897	3	1000	100000	10000	50000	20000	0.007794	0.001962	0.001064	0.002021
2007-Jun-21	95	32898	3	1000	100000	10000	50000	20000	0.007794	0.001962	0.001064	0.002021
2007-Jun-21	95	34734	3	1000	100000	10000	50000	20000	0.010413	0.003153	0.001305	0.003293
2007-Jun-21	95	34740	3	1000	100000	10000	50000	20000	0.010767	0.003381	0.001330	0.003534
2007-Jun-21	95	34760	3	1000	100000	10000	50000	20000	0.010402	0.003161	0.001302	0.003304
2007-Jun-21	95	34761	3	1000	100000	10000	50000	20000	0.010382	0.003097	0.001310	0.003239
2007-Jun-21	95	34777	3	1000	100000	10000	50000	20000	0.009334	0.002675	0.001205	0.002787
2007-Jun-21	95	34778	3	1000	100000	10000	50000	20000	0.009334	0.002675	0.001205	0.002787
2007-Jun-21	95	34786	3	1000	100000	10000	50000	20000	0.012506	0.004207	0.001481	0.004402
2007-Jun-21	95	34787	3	1000	100000	10000	50000	20000	0.013064	0.004643	0.001508	0.004829
2007-Jun-21	97	33848	1	1000	100000	10000	50000	20000	0.002617	0.000429	0.001298	0.000316
2007-Jun-21	97	34739	1	1000	100000	10000	50000	20000	0.002793	0.000472	0.001382	0.000356
2007-Jun-21	97	34741	1	1000	100000	10000	50000	20000	0.002426	0.000392	0.001201	0.000283
2007-Jun-21	97	34742	1	1000	100000	10000	50000	20000	0.002392	0.000380	0.001184	0.000270
2007-Jun-21	97	34743	1	1000	100000	10000	50000	20000	0.002600	0.000426	0.001281	0.000314
2007-Jun-21	97	34744	1	1000	100000	10000	50000	20000	0.002545	0.000416	0.001258	0.000305
2007-Jun-21	97	34745	1	1000	100000	10000	50000	20000	0.002392	0.000380	0.001184	0.000270
2007-Jun-21	97	34746	1	1000	100000	10000	50000	20000	0.002634	0.000429	0.001306	0.000316
2007-Jun-21	97	34747	1	1000	100000	10000	50000	20000	0.002352	0.000372	0.001165	0.000264
2007-Jun-21	97	34758	1	1000	100000	10000	50000	20000	0.002649	0.000433	0.001314	0.000319
2007-Jun-21	97	34769	1	1000	100000	10000	50000	20000	0.002702	0.000459	0.001327	0.000346
2007-Jun-21	97	34770	1	1000	100000	10000	50000	20000	0.002683	0.000447	0.001320	0.000334
2007-Jun-21	97	34771	1	1000	100000	10000	50000	20000	0.002709	0.000474	0.001330	0.000363
2007-Jun-21	97	34772	1	1000	100000	10000	50000	20000	0.002787	0.000465	0.001376	0.000350
2007-Jun-21	97	34773	1	1000	100000	10000	50000	20000	0.002831	0.000495	0.001397	0.000382
2007-Jun-21	97	33848	2	1000	100000	10000	50000	20000	0.002207	0.000383	0.001295	0.000270
2007-Jun-21	97	34739	2	1000	100000	10000	50000	20000	0.002349	0.000417	0.001379	0.000300
2007-Jun-21	97	34741	2	1000	100000	10000	50000	20000	0.002051	0.000354	0.001198	0.000244
2007-Jun-21	97	34742	2	1000	100000	10000	50000	20000	0.002026	0.000345	0.001181	0.000235
2007-Jun-21	97	34743	2	1000	100000	10000	50000	20000	0.002193	0.000380	0.001278	0.000268
2007-Jun-21	97	34744	2	1000	100000	10000	50000	20000	0.002148	0.000372	0.001255	0.000261

2007-Jun-21	97	34745	2	1000	100000	10000	50000	20000	0.002026	0.000345	0.001181	0.000235
2007-Jun-21	97	34746	2	1000	100000	10000	50000	20000	0.002222	0.000384	0.001303	0.000270
2007-Jun-21	97	34747	2	1000	100000	10000	50000	20000	0.001992	0.000339	0.001162	0.000230
2007-Jun-21	97	34758	2	1000	100000	10000	50000	20000	0.002234	0.000387	0.001310	0.000272
2007-Jun-21	97	34769	2	1000	100000	10000	50000	20000	0.002273	0.000404	0.001323	0.000292
2007-Jun-21	97	34770	2	1000	100000	10000	50000	20000	0.002260	0.000396	0.001317	0.000283
2007-Jun-21	97	34771	2	1000	100000	10000	50000	20000	0.002273	0.000413	0.001327	0.000303
2007-Jun-21	97	34772	2	1000	100000	10000	50000	20000	0.002346	0.000411	0.001372	0.000295
2007-Jun-21	97	34773	2	1000	100000	10000	50000	20000	0.002372	0.000431	0.001393	0.000318
2007-Jun-21	97	33848	3	1000	100000	10000	50000	20000	0.010438	0.003089	0.001318	0.003232
2007-Jun-21	97	34739	3	1000	100000	10000	50000	20000	0.011300	0.003481	0.001402	0.003632
2007-Jun-21	97	34741	3	1000	100000	10000	50000	20000	0.009387	0.002634	0.001218	0.002740
2007-Jun-21	97	34742	3	1000	100000	10000	50000	20000	0.009160	0.002501	0.001201	0.002603
2007-Jun-21	97	34743	3	1000	100000	10000	50000	20000	0.010261	0.003006	0.001300	0.003137
2007-Jun-21	97	34744	3	1000	100000	10000	50000	20000	0.010017	0.002912	0.001277	0.003036
2007-Jun-21	97	34745	3	1000	100000	10000	50000	20000	0.009160	0.002501	0.001201	0.002603
2007-Jun-21	97	34746	3	1000	100000	10000	50000	20000	0.010494	0.003095	0.001325	0.003240
2007-Jun-21	97	34747	3	1000	100000	10000	50000	20000	0.008976	0.002429	0.001182	0.002528
2007-Jun-21	97	34758	3	1000	100000	10000	50000	20000	0.010555	0.003120	0.001333	0.003262
2007-Jun-21	97	34769	3	1000	100000	10000	50000	20000	0.010811	0.003298	0.001346	0.003435
2007-Jun-21	97	34770	3	1000	100000	10000	50000	20000	0.010685	0.003204	0.001340	0.003342
2007-Jun-21	97	34771	3	1000	100000	10000	50000	20000	0.010970	0.003457	0.001350	0.003593
2007-Jun-21	97	34772	3	1000	100000	10000	50000	20000	0.011264	0.003446	0.001396	0.003604
2007-Jun-21	97	34773	3	1000	100000	10000	50000	20000	0.011691	0.003776	0.001417	0.003938
2007-Jun-21	99	33401	1	1000	100000	10000	50000	20000	0.005309	0.001405	0.002031	0.001304
2007-Jun-21	99	33402	1	1000	100000	10000	50000	20000	0.006667	0.002172	0.002337	0.002042
2007-Jun-21	99	33403	1	1000	100000	10000	50000	20000	0.004638	0.001233	0.001757	0.001127
2007-Jun-21	99	33404	1	1000	100000	10000	50000	20000	0.004602	0.001180	0.001764	0.001076
2007-Jun-21	99	33405	1	1000	100000	10000	50000	20000	0.004751	0.001233	0.001819	0.001130
2007-Jun-21	99	33406	1	1000	100000	10000	50000	20000	0.004917	0.001302	0.001872	0.001199
2007-Jun-21	99	33407	1	1000	100000	10000	50000	20000	0.005136	0.001325	0.001977	0.001222
2007-Jun-21	99	33408	1	1000	100000	10000	50000	20000	0.006028	0.001761	0.002216	0.001649
2007-Jun-21	99	33409	1	1000	100000	10000	50000	20000	0.005026	0.001349	0.001903	0.001242
2007-Jun-21	99	33410	1	1000	100000	10000	50000	20000	0.004725	0.001233	0.001804	0.001127
2007-Jun-21	99	33411	1	1000	100000	10000	50000	20000	0.004729	0.001218	0.001816	0.001115
2007-Jun-21	99	33412	1	1000	100000	10000	50000	20000	0.004893	0.001240	0.001886	0.001136
2007-Jun-21	99	33413	1	1000	100000	10000	50000	20000	0.004691	0.001204	0.001805	0.001102

2007-Jun-21	99	33414	1	1000	100000	10000	50000	20000	0.005013	0.001328	0.001908	0.001226
2007-Jun-21	99	33415	1	1000	100000	10000	50000	20000	0.004913	0.001302	0.001869	0.001198
2007-Jun-21	99	33416	1	1000	100000	10000	50000	20000	0.004985	0.001348	0.001885	0.001244
2007-Jun-21	99	33417	1	1000	100000	10000	50000	20000	0.004853	0.001275	0.001850	0.001169
2007-Jun-21	99	33418	1	1000	100000	10000	50000	20000	0.005127	0.001351	0.001950	0.001244
2007-Jun-21	99	33419	1	1000	100000	10000	50000	20000	0.004395	0.001086	0.001706	0.000984
2007-Jun-21	99	33420	1	1000	100000	10000	50000	20000	0.004772	0.001244	0.001821	0.001138
2007-Jun-21	99	33421	1	1000	100000	10000	50000	20000	0.004457	0.001082	0.001745	0.000981
2007-Jun-21	99	33422	1	1000	100000	10000	50000	20000	0.005019	0.001327	0.001907	0.001222
2007-Jun-21	99	33424	1	1000	100000	10000	50000	20000	0.005472	0.001656	0.001978	0.001537
2007-Jun-21	99	33425	1	1000	100000	10000	50000	20000	0.005074	0.001421	0.001894	0.001315
2007-Jun-21	99	33426	1	1000	100000	10000	50000	20000	0.005585	0.001729	0.001993	0.001601
2007-Jun-21	99	33427	1	1000	100000	10000	50000	20000	0.005367	0.001594	0.001945	0.001486
2007-Jun-21	99	33428	1	1000	100000	10000	50000	20000	0.005822	0.001812	0.002063	0.001694
2007-Jun-21	99	33429	1	1000	100000	10000	50000	20000	0.005961	0.001892	0.002106	0.001778
2007-Jun-21	99	33430	1	1000	100000	10000	50000	20000	0.005016	0.001252	0.001950	0.001149
2007-Jun-21	99	33431	1	1000	100000	10000	50000	20000	0.005869	0.001779	0.002118	0.001667
2007-Jun-21	99	33432	1	1000	100000	10000	50000	20000	0.006538	0.002208	0.002237	0.002078
2007-Jun-21	99	33433	1	1000	100000	10000	50000	20000	0.005980	0.001879	0.002115	0.001765
2007-Jun-21	99	33434	1	1000	100000	10000	50000	20000	0.005863	0.001807	0.002091	0.001689
2007-Jun-21	99	33435	1	1000	100000	10000	50000	20000	0.005239	0.001510	0.001927	0.001399
2007-Jun-21	99	33436	1	1000	100000	10000	50000	20000	0.005446	0.001572	0.002002	0.001459
2007-Jun-21	99	33437	1	1000	100000	10000	50000	20000	0.005368	0.001538	0.001978	0.001428
2007-Jun-21	99	33438	1	1000	100000	10000	50000	20000	0.006007	0.001678	0.002248	0.001566
2007-Jun-21	99	33439	1	1000	100000	10000	50000	20000	0.005539	0.001427	0.002137	0.001322
2007-Jun-21	99	33444	1	1000	100000	10000	50000	20000	0.005359	0.001588	0.001940	0.001474
2007-Jun-21	99	33445	1	1000	100000	10000	50000	20000	0.005445	0.001603	0.001976	0.001488
2007-Jun-21	99	33446	1	1000	100000	10000	50000	20000	0.006263	0.001998	0.002205	0.001878
2007-Jun-21	99	33447	1	1000	100000	10000	50000	20000	0.005521	0.001676	0.001979	0.001557
2007-Jun-21	99	33448	1	1000	100000	10000	50000	20000	0.005871	0.001798	0.002099	0.001678
2007-Jun-21	99	33454	1	1000	100000	10000	50000	20000	0.004943	0.001292	0.001892	0.001191
2007-Jun-21	99	33458	1	1000	100000	10000	50000	20000	0.004706	0.001194	0.001812	0.001088
2007-Jun-21	99	33459	1	1000	100000	10000	50000	20000	0.006251	0.001828	0.002305	0.001721
2007-Jun-21	99	33460	1	1000	100000	10000	50000	20000	0.004648	0.001234	0.001771	0.001132
2007-Jun-21	99	33461	1	1000	100000	10000	50000	20000	0.004824	0.001250	0.001852	0.001149
2007-Jun-21	99	33462	1	1000	100000	10000	50000	20000	0.005044	0.001400	0.001885	0.001292
2007-Jun-21	99	33463	1	1000	100000	10000	50000	20000	0.005285	0.001474	0.001975	0.001368

2007-Jun-21	99	33464	1	1000	100000	10000	50000	20000	0.004731	0.001243	0.001805	0.001141
2007-Jun-21	99	33465	1	1000	100000	10000	50000	20000	0.005812	0.001735	0.002116	0.001624
2007-Jun-21	99	33466	1	1000	100000	10000	50000	20000	0.005198	0.001441	0.001949	0.001337
2007-Jun-21	99	33467	1	1000	100000	10000	50000	20000	0.005159	0.001415	0.001936	0.001308
2007-Jun-21	99	33468	1	1000	100000	10000	50000	20000	0.005081	0.001325	0.001940	0.001219
2007-Jun-21	99	33469	1	1000	100000	10000	50000	20000	0.004921	0.001305	0.001867	0.001195
2007-Jun-21	99	33470	1	1000	100000	10000	50000	20000	0.004947	0.001252	0.001912	0.001149
2007-Jun-21	99	33474	1	1000	100000	10000	50000	20000	0.004978	0.001372	0.001868	0.001267
2007-Jun-21	99	33476	1	1000	100000	10000	50000	20000	0.005063	0.001192	0.002014	0.001091
2007-Jun-21	99	33477	1	1000	100000	10000	50000	20000	0.005432	0.001527	0.002019	0.001413
2007-Jun-21	99	33478	1	1000	100000	10000	50000	20000	0.004464	0.001088	0.001741	0.000984
2007-Jun-21	99	33480	1	1000	100000	10000	50000	20000	0.008409	0.003092	0.002764	0.002933
2007-Jun-21	99	33481	1	1000	100000	10000	50000	20000	0.005591	0.001705	0.002005	0.001592
2007-Jun-21	99	33482	1	1000	100000	10000	50000	20000	0.005395	0.001601	0.001954	0.001487
2007-Jun-21	99	33483	1	1000	100000	10000	50000	20000	0.006441	0.002106	0.002245	0.001977
2007-Jun-21	99	33484	1	1000	100000	10000	50000	20000	0.005553	0.001657	0.002004	0.001542
2007-Jun-21	99	33486	1	1000	100000	10000	50000	20000	0.005471	0.001643	0.001975	0.001532
2007-Jun-21	99	33487	1	1000	100000	10000	50000	20000	0.005865	0.001851	0.002066	0.001725
2007-Jun-21	99	33488	1	1000	100000	10000	50000	20000	0.006260	0.002027	0.002183	0.001908
2007-Jun-21	99	33493	1	1000	100000	10000	50000	20000	0.005693	0.001556	0.002150	0.001447
2007-Jun-21	99	33496	1	1000	100000	10000	50000	20000	0.005707	0.001743	0.002041	0.001626
2007-Jun-21	99	33497	1	1000	100000	10000	50000	20000	0.005781	0.001763	0.002070	0.001649
2007-Jun-21	99	33498	1	1000	100000	10000	50000	20000	0.005645	0.001707	0.002031	0.001592
2007-Jun-21	99	33499	1	1000	100000	10000	50000	20000	0.005444	0.001635	0.001961	0.001521
2007-Jun-21	99	33401	2	1000	100000	10000	50000	20000	0.003707	0.000843	0.002022	0.000752
2007-Jun-21	99	33402	2	1000	100000	10000	50000	20000	0.004567	0.001251	0.002326	0.001170
2007-Jun-21	99	33403	2	1000	100000	10000	50000	20000	0.003279	0.000755	0.001749	0.000664
2007-Jun-21	99	33404	2	1000	100000	10000	50000	20000	0.003261	0.000727	0.001757	0.000635
2007-Jun-21	99	33405	2	1000	100000	10000	50000	20000	0.003351	0.000753	0.001811	0.000662
2007-Jun-21	99	33406	2	1000	100000	10000	50000	20000	0.003453	0.000789	0.001864	0.000698
2007-Jun-21	99	33407	2	1000	100000	10000	50000	20000	0.003608	0.000805	0.001968	0.000711
2007-Jun-21	99	33408	2	1000	100000	10000	50000	20000	0.004168	0.001033	0.002206	0.000945
2007-Jun-21	99	33409	2	1000	100000	10000	50000	20000	0.003529	0.000816	0.001894	0.000724
2007-Jun-21	99	33410	2	1000	100000	10000	50000	20000	0.003339	0.000756	0.001796	0.000663
2007-Jun-21	99	33411	2	1000	100000	10000	50000	20000	0.003340	0.000747	0.001808	0.000654
2007-Jun-21	99	33412	2	1000	100000	10000	50000	20000	0.003456	0.000762	0.001878	0.000666
2007-Jun-21	99	33413	2	1000	100000	10000	50000	20000	0.003312	0.000739	0.001797	0.000646

2007-Jun-21	99	33414	2	1000	100000	10000	50000	20000	0.003516	0.000803	0.001899	0.000713
2007-Jun-21	99	33415	2	1000	100000	10000	50000	20000	0.003453	0.000790	0.001861	0.000699
2007-Jun-21	99	33416	2	1000	100000	10000	50000	20000	0.003493	0.000812	0.001877	0.000723
2007-Jun-21	99	33417	2	1000	100000	10000	50000	20000	0.003421	0.000777	0.001842	0.000685
2007-Jun-21	99	33418	2	1000	100000	10000	50000	20000	0.003605	0.000819	0.001942	0.000725
2007-Jun-21	99	33419	2	1000	100000	10000	50000	20000	0.003129	0.000679	0.001699	0.000584
2007-Jun-21	99	33420	2	1000	100000	10000	50000	20000	0.003372	0.000762	0.001814	0.000669
2007-Jun-21	99	33421	2	1000	100000	10000	50000	20000	0.003171	0.000677	0.001738	0.000581
2007-Jun-21	99	33422	2	1000	100000	10000	50000	20000	0.003528	0.000805	0.001899	0.000713
2007-Jun-21	99	33424	2	1000	100000	10000	50000	20000	0.003805	0.000978	0.001969	0.000892
2007-Jun-21	99	33425	2	1000	100000	10000	50000	20000	0.003541	0.000848	0.001885	0.000763
2007-Jun-21	99	33426	2	1000	100000	10000	50000	20000	0.003888	0.001020	0.001984	0.000933
2007-Jun-21	99	33427	2	1000	100000	10000	50000	20000	0.003716	0.000937	0.001937	0.000857
2007-Jun-21	99	33428	2	1000	100000	10000	50000	20000	0.004015	0.001054	0.002054	0.000975
2007-Jun-21	99	33429	2	1000	100000	10000	50000	20000	0.004082	0.001089	0.002097	0.001016
2007-Jun-21	99	33430	2	1000	100000	10000	50000	20000	0.003539	0.000768	0.001941	0.000671
2007-Jun-21	99	33431	2	1000	100000	10000	50000	20000	0.004042	0.001036	0.002109	0.000955
2007-Jun-21	99	33432	2	1000	100000	10000	50000	20000	0.004460	0.001262	0.002226	0.001190
2007-Jun-21	99	33433	2	1000	100000	10000	50000	20000	0.004101	0.001085	0.002105	0.001010
2007-Jun-21	99	33434	2	1000	100000	10000	50000	20000	0.004044	0.001052	0.002081	0.000972
2007-Jun-21	99	33435	2	1000	100000	10000	50000	20000	0.003654	0.000898	0.001919	0.000812
2007-Jun-21	99	33436	2	1000	100000	10000	50000	20000	0.003791	0.000932	0.001993	0.000846
2007-Jun-21	99	33437	2	1000	100000	10000	50000	20000	0.003738	0.000913	0.001969	0.000827
2007-Jun-21	99	33438	2	1000	100000	10000	50000	20000	0.004171	0.000993	0.002238	0.000899
2007-Jun-21	99	33439	2	1000	100000	10000	50000	20000	0.003880	0.000862	0.002127	0.000763
2007-Jun-21	99	33444	2	1000	100000	10000	50000	20000	0.003730	0.000940	0.001931	0.000856
2007-Jun-21	99	33445	2	1000	100000	10000	50000	20000	0.003789	0.000949	0.001967	0.000864
2007-Jun-21	99	33446	2	1000	100000	10000	50000	20000	0.004292	0.001151	0.002195	0.001075
2007-Jun-21	99	33447	2	1000	100000	10000	50000	20000	0.003835	0.000987	0.001971	0.000903
2007-Jun-21	99	33448	2	1000	100000	10000	50000	20000	0.004062	0.001052	0.002089	0.000969
2007-Jun-21	99	33454	2	1000	100000	10000	50000	20000	0.003470	0.000783	0.001884	0.000693
2007-Jun-21	99	33458	2	1000	100000	10000	50000	20000	0.003337	0.000738	0.001804	0.000642
2007-Jun-21	99	33459	2	1000	100000	10000	50000	20000	0.004295	0.001062	0.002294	0.000978
2007-Jun-21	99	33460	2	1000	100000	10000	50000	20000	0.003271	0.000750	0.001764	0.000662
2007-Jun-21	99	33461	2	1000	100000	10000	50000	20000	0.003394	0.000761	0.001844	0.000670
2007-Jun-21	99	33462	2	1000	100000	10000	50000	20000	0.003532	0.000841	0.001877	0.000753
2007-Jun-21	99	33463	2	1000	100000	10000	50000	20000	0.003683	0.000878	0.001967	0.000791

2007-Jun-21	99	33464	2	1000	100000	10000	50000	20000	0.003331	0.000757	0.001798	0.000667
2007-Jun-21	99	33465	2	1000	100000	10000	50000	20000	0.004011	0.001013	0.002107	0.000931
2007-Jun-21	99	33466	2	1000	100000	10000	50000	20000	0.003625	0.000860	0.001941	0.000773
2007-Jun-21	99	33467	2	1000	100000	10000	50000	20000	0.003610	0.000849	0.001928	0.000760
2007-Jun-21	99	33468	2	1000	100000	10000	50000	20000	0.003577	0.000807	0.001931	0.000712
2007-Jun-21	99	33469	2	1000	100000	10000	50000	20000	0.003474	0.000797	0.001859	0.000702
2007-Jun-21	99	33470	2	1000	100000	10000	50000	20000	0.003490	0.000768	0.001903	0.000672
2007-Jun-21	99	33474	2	1000	100000	10000	50000	20000	0.003484	0.000824	0.001860	0.000737
2007-Jun-21	99	33476	2	1000	100000	10000	50000	20000	0.003583	0.000741	0.002005	0.000637
2007-Jun-21	99	33477	2	1000	100000	10000	50000	20000	0.003800	0.000914	0.002010	0.000822
2007-Jun-21	99	33478	2	1000	100000	10000	50000	20000	0.003182	0.000682	0.001733	0.000585
2007-Jun-21	99	33480	2	1000	100000	10000	50000	20000	0.005665	0.001737	0.002751	0.001668
2007-Jun-21	99	33481	2	1000	100000	10000	50000	20000	0.003861	0.000996	0.001996	0.000917
2007-Jun-21	99	33482	2	1000	100000	10000	50000	20000	0.003750	0.000945	0.001946	0.000862
2007-Jun-21	99	33483	2	1000	100000	10000	50000	20000	0.004418	0.001213	0.002235	0.001134
2007-Jun-21	99	33484	2	1000	100000	10000	50000	20000	0.003856	0.000977	0.001995	0.000893
2007-Jun-21	99	33486	2	1000	100000	10000	50000	20000	0.003784	0.000963	0.001966	0.000883
2007-Jun-21	99	33487	2	1000	100000	10000	50000	20000	0.004057	0.001081	0.002056	0.000998
2007-Jun-21	99	33488	2	1000	100000	10000	50000	20000	0.004277	0.001162	0.002173	0.001090
2007-Jun-21	99	33493	2	1000	100000	10000	50000	20000	0.003968	0.000928	0.002140	0.000834
2007-Jun-21	99	33496	2	1000	100000	10000	50000	20000	0.003946	0.001019	0.002031	0.000938
2007-Jun-21	99	33497	2	1000	100000	10000	50000	20000	0.003987	0.001027	0.002060	0.000948
2007-Jun-21	99	33498	2	1000	100000	10000	50000	20000	0.003906	0.000999	0.002022	0.000918
2007-Jun-21	99	33499	2	1000	100000	10000	50000	20000	0.003777	0.000963	0.001952	0.000881
2007-Jun-21	99	33401	3	1000	100000	10000	50000	20000	0.020668	0.008510	0.002055	0.009054
2007-Jun-21	99	33402	3	1000	100000	10000	50000	20000	0.025432	0.011585	0.002363	0.012198
2007-Jun-21	99	33403	3	1000	100000	10000	50000	20000	0.017295	0.006882	0.001777	0.007268
2007-Jun-21	99	33404	3	1000	100000	10000	50000	20000	0.017246	0.006755	0.001785	0.007151
2007-Jun-21	99	33405	3	1000	100000	10000	50000	20000	0.017995	0.007165	0.001840	0.007591
2007-Jun-21	99	33406	3	1000	100000	10000	50000	20000	0.018736	0.007586	0.001893	0.008036
2007-Jun-21	99	33407	3	1000	100000	10000	50000	20000	0.019830	0.007998	0.002000	0.008513
2007-Jun-21	99	33408	3	1000	100000	10000	50000	20000	0.023317	0.010086	0.002241	0.010682
2007-Jun-21	99	33409	3	1000	100000	10000	50000	20000	0.019099	0.007768	0.001925	0.008226
2007-Jun-21	99	33410	3	1000	100000	10000	50000	20000	0.017777	0.007052	0.001825	0.007468
2007-Jun-21	99	33411	3	1000	100000	10000	50000	20000	0.017899	0.007090	0.001837	0.007514
2007-Jun-21	99	33412	3	1000	100000	10000	50000	20000	0.018626	0.007359	0.001908	0.007817
2007-Jun-21	99	33413	3	1000	100000	10000	50000	20000	0.017785	0.007046	0.001826	0.007467

2007-Jun-21	99	33414	3	1000	100000	10000	50000	20000	0.019168	0.007790	0.001930	0.008258
2007-Jun-21	99	33415	3	1000	100000	10000	50000	20000	0.018682	0.007551	0.001890	0.007998
2007-Jun-21	99	33416	3	1000	100000	10000	50000	20000	0.018989	0.007775	0.001907	0.008228
2007-Jun-21	99	33417	3	1000	100000	10000	50000	20000	0.018370	0.007356	0.001872	0.007793
2007-Jun-21	99	33418	3	1000	100000	10000	50000	20000	0.019545	0.007892	0.001973	0.008375
2007-Jun-21	99	33419	3	1000	100000	10000	50000	20000	0.016428	0.006286	0.001726	0.006660
2007-Jun-21	99	33420	3	1000	100000	10000	50000	20000	0.017965	0.007128	0.001843	0.007550
2007-Jun-21	99	33421	3	1000	100000	10000	50000	20000	0.016842	0.006444	0.001766	0.006847
2007-Jun-21	99	33422	3	1000	100000	10000	50000	20000	0.019092	0.007716	0.001929	0.008179
2007-Jun-21	99	33424	3	1000	100000	10000	50000	20000	0.020560	0.008871	0.002000	0.009342
2007-Jun-21	99	33425	3	1000	100000	10000	50000	20000	0.019298	0.008050	0.001915	0.008507
2007-Jun-21	99	33426	3	1000	100000	10000	50000	20000	0.020723	0.008975	0.002015	0.009427
2007-Jun-21	99	33427	3	1000	100000	10000	50000	20000	0.020286	0.008749	0.001967	0.009204
2007-Jun-21	99	33428	3	1000	100000	10000	50000	20000	0.021913	0.009682	0.002086	0.010172
2007-Jun-21	99	33429	3	1000	100000	10000	50000	20000	0.022696	0.010223	0.002129	0.010739
2007-Jun-21	99	33430	3	1000	100000	10000	50000	20000	0.019310	0.007626	0.001973	0.008125
2007-Jun-21	99	33431	3	1000	100000	10000	50000	20000	0.022496	0.009903	0.002142	0.010444
2007-Jun-21	99	33432	3	1000	100000	10000	50000	20000	0.024624	0.011429	0.002260	0.011972
2007-Jun-21	99	33433	3	1000	100000	10000	50000	20000	0.022714	0.010169	0.002138	0.010686
2007-Jun-21	99	33434	3	1000	100000	10000	50000	20000	0.022183	0.009772	0.002114	0.010283
2007-Jun-21	99	33435	3	1000	100000	10000	50000	20000	0.019752	0.008320	0.001949	0.008775
2007-Jun-21	99	33436	3	1000	100000	10000	50000	20000	0.020638	0.008739	0.002024	0.009225
2007-Jun-21	99	33437	3	1000	100000	10000	50000	20000	0.020356	0.008592	0.002000	0.009071
2007-Jun-21	99	33438	3	1000	100000	10000	50000	20000	0.023289	0.009846	0.002273	0.010447
2007-Jun-21	99	33439	3	1000	100000	10000	50000	20000	0.021603	0.008780	0.002161	0.009361
2007-Jun-21	99	33444	3	1000	100000	10000	50000	20000	0.020071	0.008573	0.001962	0.009019
2007-Jun-21	99	33445	3	1000	100000	10000	50000	20000	0.020458	0.008721	0.001998	0.009187
2007-Jun-21	99	33446	3	1000	100000	10000	50000	20000	0.023855	0.010772	0.002229	0.011330
2007-Jun-21	99	33447	3	1000	100000	10000	50000	20000	0.020650	0.008926	0.002001	0.009386
2007-Jun-21	99	33448	3	1000	100000	10000	50000	20000	0.022145	0.009684	0.002122	0.010193
2007-Jun-21	99	33454	3	1000	100000	10000	50000	20000	0.018950	0.007659	0.001914	0.008127
2007-Jun-21	99	33458	3	1000	100000	10000	50000	20000	0.017716	0.006919	0.001833	0.007343
2007-Jun-21	99	33459	3	1000	100000	10000	50000	20000	0.024542	0.010746	0.002330	0.011397
2007-Jun-21	99	33460	3	1000	100000	10000	50000	20000	0.017568	0.007070	0.001792	0.007472
2007-Jun-21	99	33461	3	1000	100000	10000	50000	20000	0.018424	0.007383	0.001874	0.007832
2007-Jun-21	99	33462	3	1000	100000	10000	50000	20000	0.019050	0.007861	0.001906	0.008302
2007-Jun-21	99	33463	3	1000	100000	10000	50000	20000	0.020222	0.008461	0.001998	0.008949

2007-Jun-21	99	33464	3	1000	100000	10000	50000	20000	0.017924	0.007191	0.001826	0.007610
2007-Jun-21	99	33465	3	1000	100000	10000	50000	20000	0.022329	0.009738	0.002140	0.010285
2007-Jun-21	99	33466	3	1000	100000	10000	50000	20000	0.019897	0.008295	0.001971	0.008776
2007-Jun-21	99	33467	3	1000	100000	10000	50000	20000	0.019628	0.008098	0.001958	0.008567
2007-Jun-21	99	33468	3	1000	100000	10000	50000	20000	0.019376	0.007781	0.001962	0.008264
2007-Jun-21	99	33469	3	1000	100000	10000	50000	20000	0.018548	0.007426	0.001889	0.007873
2007-Jun-21	99	33470	3	1000	100000	10000	50000	20000	0.018916	0.007494	0.001934	0.007966
2007-Jun-21	99	33474	3	1000	100000	10000	50000	20000	0.018882	0.007784	0.001889	0.008230
2007-Jun-21	99	33476	3	1000	100000	10000	50000	20000	0.019760	0.007657	0.002038	0.008198
2007-Jun-21	99	33477	3	1000	100000	10000	50000	20000	0.020613	0.008584	0.002042	0.009087
2007-Jun-21	99	33478	3	1000	100000	10000	50000	20000	0.016722	0.006362	0.001761	0.006750
2007-Jun-21	99	33480	3	1000	100000	10000	50000	20000	0.031906	0.015632	0.002793	0.016372
2007-Jun-21	99	33481	3	1000	100000	10000	50000	20000	0.021114	0.009235	0.002027	0.009707
2007-Jun-21	99	33482	3	1000	100000	10000	50000	20000	0.020266	0.008678	0.001976	0.009133
2007-Jun-21	99	33483	3	1000	100000	10000	50000	20000	0.024389	0.011103	0.002270	0.011674
2007-Jun-21	99	33484	3	1000	100000	10000	50000	20000	0.020897	0.008994	0.002027	0.009470
2007-Jun-21	99	33486	3	1000	100000	10000	50000	20000	0.020675	0.008968	0.001996	0.009433
2007-Jun-21	99	33487	3	1000	100000	10000	50000	20000	0.021886	0.009674	0.002088	0.010157
2007-Jun-21	99	33488	3	1000	100000	10000	50000	20000	0.023756	0.010819	0.002207	0.011354
2007-Jun-21	99	33493	3	1000	100000	10000	50000	20000	0.022096	0.009217	0.002175	0.009805
2007-Jun-21	99	33496	3	1000	100000	10000	50000	20000	0.021505	0.009399	0.002063	0.009887
2007-Jun-21	99	33497	3	1000	100000	10000	50000	20000	0.021910	0.009611	0.002093	0.010115
2007-Jun-21	99	33498	3	1000	100000	10000	50000	20000	0.021329	0.009277	0.002054	0.009765
2007-Jun-21	99	33499	3	1000	100000	10000	50000	20000	0.020439	0.008820	0.001983	0.009274
2007-Jun-21	101	33523	1	1000	100000	10000	50000	20000	0.002546	0.000470	0.001256	0.000372
2007-Jun-21	101	33524	1	1000	100000	10000	50000	20000	0.002705	0.000506	0.001336	0.000407
2007-Jun-21	101	33525	1	1000	100000	10000	50000	20000	0.002538	0.000454	0.001257	0.000354
2007-Jun-21	101	33526	1	1000	100000	10000	50000	20000	0.002315	0.000403	0.001148	0.000306
2007-Jun-21	101	33537	1	1000	100000	10000	50000	20000	0.002439	0.000428	0.001209	0.000328
2007-Jun-21	101	33539	1	1000	100000	10000	50000	20000	0.002362	0.000410	0.001172	0.000312
2007-Jun-21	101	33540	1	1000	100000	10000	50000	20000	0.002188	0.000356	0.001084	0.000256
2007-Jun-21	101	33541	1	1000	100000	10000	50000	20000	0.002360	0.000414	0.001170	0.000318
2007-Jun-21	101	33542	1	1000	100000	10000	50000	20000	0.002434	0.000425	0.001207	0.000327
2007-Jun-21	101	33543	1	1000	100000	10000	50000	20000	0.002550	0.000473	0.001258	0.000378
2007-Jun-21	101	33544	1	1000	100000	10000	50000	20000	0.002529	0.000469	0.001248	0.000374
2007-Jun-21	101	33574	1	1000	100000	10000	50000	20000	0.002548	0.000456	0.001261	0.000357
2007-Jun-21	101	33576	1	1000	100000	10000	50000	20000	0.002723	0.000527	0.001336	0.000430

2007-Jun-21	101	33593	1	1000	100000	10000	50000	20000	0.002451	0.000435	0.001215	0.000335
2007-Jun-21	101	34610	1	1000	100000	10000	50000	20000	0.002618	0.000523	0.001273	0.000429
2007-Jun-21	101	34639	1	1000	100000	10000	50000	20000	0.002572	0.000496	0.001264	0.000403
2007-Jun-21	101	34652	1	1000	100000	10000	50000	20000	0.002238	0.000432	0.001137	0.000342
2007-Jun-21	101	34653	1	1000	100000	10000	50000	20000	0.002369	0.000483	0.001194	0.000395
2007-Jun-21	101	34654	1	1000	100000	10000	50000	20000	0.002105	0.000374	0.001039	0.000286
2007-Jun-21	101	34655	1	1000	100000	10000	50000	20000	0.002526	0.000538	0.001262	0.000449
2007-Jun-21	101	34656	1	1000	100000	10000	50000	20000	0.002411	0.000470	0.001176	0.000382
2007-Jun-21	101	34667	1	1000	100000	10000	50000	20000	0.002377	0.000482	0.001200	0.000391
2007-Jun-21	101	34668	1	1000	100000	10000	50000	20000	0.002072	0.000392	0.001057	0.000305
2007-Jun-21	101	34669	1	1000	100000	10000	50000	20000	0.002550	0.000510	0.001243	0.000418
2007-Jun-21	101	34673	1	1000	100000	10000	50000	20000	0.002367	0.000458	0.001156	0.000368
2007-Jun-21	101	34674	1	1000	100000	10000	50000	20000	0.002383	0.000459	0.001164	0.000368
2007-Jun-21	101	34679	1	1000	100000	10000	50000	20000	0.002647	0.000532	0.001288	0.000434
2007-Jun-21	101	34680	1	1000	100000	10000	50000	20000	0.002239	0.000417	0.001098	0.000329
2007-Jun-21	101	34690	1	1000	100000	10000	50000	20000	0.002209	0.000436	0.001121	0.000350
2007-Jun-21	101	34691	1	1000	100000	10000	50000	20000	0.002343	0.000475	0.001182	0.000386
2007-Jun-21	101	33523	2	1000	100000	10000	50000	20000	0.002124	0.000402	0.001253	0.000304
2007-Jun-21	101	33524	2	1000	100000	10000	50000	20000	0.002251	0.000429	0.001332	0.000331
2007-Jun-21	101	33525	2	1000	100000	10000	50000	20000	0.002122	0.000392	0.001254	0.000292
2007-Jun-21	101	33526	2	1000	100000	10000	50000	20000	0.001944	0.000354	0.001145	0.000256
2007-Jun-21	101	33537	2	1000	100000	10000	50000	20000	0.002046	0.000374	0.001206	0.000273
2007-Jun-21	101	33539	2	1000	100000	10000	50000	20000	0.001982	0.000359	0.001169	0.000261
2007-Jun-21	101	33540	2	1000	100000	10000	50000	20000	0.001849	0.000321	0.001082	0.000221
2007-Jun-21	101	33541	2	1000	100000	10000	50000	20000	0.001978	0.000361	0.001168	0.000265
2007-Jun-21	101	33542	2	1000	100000	10000	50000	20000	0.002040	0.000371	0.001204	0.000272
2007-Jun-21	101	33543	2	1000	100000	10000	50000	20000	0.002123	0.000403	0.001255	0.000308
2007-Jun-21	101	33544	2	1000	100000	10000	50000	20000	0.002108	0.000400	0.001245	0.000305
2007-Jun-21	101	33574	2	1000	100000	10000	50000	20000	0.002130	0.000394	0.001258	0.000294
2007-Jun-21	101	33576	2	1000	100000	10000	50000	20000	0.002260	0.000443	0.001333	0.000346
2007-Jun-21	101	33593	2	1000	100000	10000	50000	20000	0.002053	0.000378	0.001212	0.000278
2007-Jun-21	101	34610	2	1000	100000	10000	50000	20000	0.002170	0.000435	0.001270	0.000344
2007-Jun-21	101	34639	2	1000	100000	10000	50000	20000	0.002135	0.000417	0.001261	0.000325
2007-Jun-21	101	34652	2	1000	100000	10000	50000	20000	0.001873	0.000368	0.001134	0.000280
2007-Jun-21	101	34653	2	1000	100000	10000	50000	20000	0.001972	0.000403	0.001191	0.000317
2007-Jun-21	101	34654	2	1000	100000	10000	50000	20000	0.001764	0.000325	0.001037	0.000239
2007-Jun-21	101	34655	2	1000	100000	10000	50000	20000	0.002093	0.000442	0.001259	0.000356

2007-Jun-21	101	34656	2	1000	100000	10000	50000	20000	0.002002	0.000395	0.001173	0.000308
2007-Jun-21	101	34667	2	1000	100000	10000	50000	20000	0.001982	0.000404	0.001197	0.000315
2007-Jun-21	101	34668	2	1000	100000	10000	50000	20000	0.001740	0.000337	0.001054	0.000252
2007-Jun-21	101	34669	2	1000	100000	10000	50000	20000	0.002115	0.000425	0.001240	0.000335
2007-Jun-21	101	34673	2	1000	100000	10000	50000	20000	0.001969	0.000386	0.001153	0.000299
2007-Jun-21	101	34674	2	1000	100000	10000	50000	20000	0.001984	0.000387	0.001161	0.000299
2007-Jun-21	101	34679	2	1000	100000	10000	50000	20000	0.002196	0.000442	0.001285	0.000348
2007-Jun-21	101	34680	2	1000	100000	10000	50000	20000	0.001868	0.000356	0.001095	0.000270
2007-Jun-21	101	34690	2	1000	100000	10000	50000	20000	0.001845	0.000368	0.001118	0.000284
2007-Jun-21	101	34691	2	1000	100000	10000	50000	20000	0.001952	0.000398	0.001179	0.000311
2007-Jun-21	101	33523	3	1000	100000	10000	50000	20000	0.010729	0.003645	0.001275	0.003789
2007-Jun-21	101	33524	3	1000	100000	10000	50000	20000	0.011662	0.004100	0.001355	0.004269
2007-Jun-21	101	33525	3	1000	100000	10000	50000	20000	0.010630	0.003529	0.001276	0.003676
2007-Jun-21	101	33526	3	1000	100000	10000	50000	20000	0.009357	0.002919	0.001165	0.003029
2007-Jun-21	101	33537	3	1000	100000	10000	50000	20000	0.009957	0.003160	0.001227	0.003284
2007-Jun-21	101	33539	3	1000	100000	10000	50000	20000	0.009666	0.003066	0.001189	0.003191
2007-Jun-21	101	33540	3	1000	100000	10000	50000	20000	0.008458	0.002377	0.001101	0.002467
2007-Jun-21	101	33541	3	1000	100000	10000	50000	20000	0.009696	0.003109	0.001188	0.003233
2007-Jun-21	101	33542	3	1000	100000	10000	50000	20000	0.010040	0.003233	0.001224	0.003367
2007-Jun-21	101	33543	3	1000	100000	10000	50000	20000	0.010907	0.003789	0.001277	0.003944
2007-Jun-21	101	33544	3	1000	100000	10000	50000	20000	0.010755	0.003705	0.001266	0.003854
2007-Jun-21	101	33574	3	1000	100000	10000	50000	20000	0.010669	0.003544	0.001280	0.003691
2007-Jun-21	101	33576	3	1000	100000	10000	50000	20000	0.011795	0.004239	0.001356	0.004405
2007-Jun-21	101	33593	3	1000	100000	10000	50000	20000	0.010088	0.003255	0.001233	0.003384
2007-Jun-21	101	34610	3	1000	100000	10000	50000	20000	0.011285	0.004097	0.001292	0.004246
2007-Jun-21	101	34639	3	1000	100000	10000	50000	20000	0.011151	0.004003	0.001283	0.004159
2007-Jun-21	101	34652	3	1000	100000	10000	50000	20000	0.009678	0.003272	0.001155	0.003391
2007-Jun-21	101	34653	3	1000	100000	10000	50000	20000	0.010497	0.003764	0.001212	0.003895
2007-Jun-21	101	34654	3	1000	100000	10000	50000	20000	0.008543	0.002717	0.001055	0.002814
2007-Jun-21	101	34655	3	1000	100000	10000	50000	20000	0.011383	0.004252	0.001281	0.004397
2007-Jun-21	101	34656	3	1000	100000	10000	50000	20000	0.010263	0.003638	0.001193	0.003765
2007-Jun-21	101	34667	3	1000	100000	10000	50000	20000	0.010453	0.003698	0.001218	0.003826
2007-Jun-21	101	34668	3	1000	100000	10000	50000	20000	0.008803	0.002879	0.001073	0.002975
2007-Jun-21	101	34669	3	1000	100000	10000	50000	20000	0.010971	0.003974	0.001261	0.004113
2007-Jun-21	101	34673	3	1000	100000	10000	50000	20000	0.009963	0.003469	0.001173	0.003587
2007-Jun-21	101	34674	3	1000	100000	10000	50000	20000	0.010029	0.003480	0.001181	0.003600
2007-Jun-21	101	34679	3	1000	100000	10000	50000	20000	0.011348	0.004091	0.001307	0.004240

2007-Jun-21	101	34680	3	1000	100000	10000	50000	20000	0.009290	0.003120	0.001114	0.003229
2007-Jun-21	101	34690	3	1000	100000	10000	50000	20000	0.009662	0.003350	0.001138	0.003469
2007-Jun-21	101	34691	3	1000	100000	10000	50000	20000	0.010328	0.003668	0.001199	0.003795
2007-Jun-21	103	33701	1	1000	100000	10000	50000	20000	0.003008	0.000768	0.001472	0.000682
2007-Jun-21	103	33702	1	1000	100000	10000	50000	20000	0.002560	0.000582	0.001276	0.000498
2007-Jun-21	103	33703	1	1000	100000	10000	50000	20000	0.002814	0.000678	0.001388	0.000592
2007-Jun-21	103	33704	1	1000	100000	10000	50000	20000	0.003891	0.001187	0.001790	0.001092
2007-Jun-21	103	33705	1	1000	100000	10000	50000	20000	0.003415	0.000950	0.001615	0.000859
2007-Jun-21	103	33706	1	1000	100000	10000	50000	20000	0.002781	0.000655	0.001378	0.000568
2007-Jun-21	103	33707	1	1000	100000	10000	50000	20000	0.003374	0.000941	0.001581	0.000846
2007-Jun-21	103	33708	1	1000	100000	10000	50000	20000	0.003159	0.000820	0.001510	0.000722
2007-Jun-21	103	33709	1	1000	100000	10000	50000	20000	0.002518	0.000557	0.001262	0.000472
2007-Jun-21	103	33710	1	1000	100000	10000	50000	20000	0.002576	0.000582	0.001286	0.000497
2007-Jun-21	103	33711	1	1000	100000	10000	50000	20000	0.002829	0.000668	0.001406	0.000580
2007-Jun-21	103	33712	1	1000	100000	10000	50000	20000	0.003026	0.000773	0.001474	0.000688
2007-Jun-21	103	33713	1	1000	100000	10000	50000	20000	0.002954	0.000728	0.001446	0.000637
2007-Jun-21	103	33714	1	1000	100000	10000	50000	20000	0.002585	0.000571	0.001299	0.000486
2007-Jun-21	103	33715	1	1000	100000	10000	50000	20000	0.005173	0.001915	0.002108	0.001776
2007-Jun-21	103	33716	1	1000	100000	10000	50000	20000	0.002616	0.000588	0.001303	0.000503
2007-Jun-21	103	33728	1	1000	100000	10000	50000	20000	0.002551	0.000587	0.001265	0.000505
2007-Jun-21	103	33729	1	1000	100000	10000	50000	20000	0.002551	0.000587	0.001265	0.000505
2007-Jun-21	103	33730	1	1000	100000	10000	50000	20000	0.002552	0.000573	0.001281	0.000489
2007-Jun-21	103	33731	1	1000	100000	10000	50000	20000	0.002678	0.000613	0.001340	0.000528
2007-Jun-21	103	33732	1	1000	100000	10000	50000	20000	0.002475	0.000546	0.001239	0.000462
2007-Jun-21	103	33733	1	1000	100000	10000	50000	20000	0.002552	0.000573	0.001281	0.000489
2007-Jun-21	103	33734	1	1000	100000	10000	50000	20000	0.002690	0.000625	0.001334	0.000540
2007-Jun-21	103	33736	1	1000	100000	10000	50000	20000	0.003220	0.000900	0.001510	0.000812
2007-Jun-21	103	33737	1	1000	100000	10000	50000	20000	0.003598	0.001074	0.001637	0.000976
2007-Jun-21	103	33738	1	1000	100000	10000	50000	20000	0.003659	0.001098	0.001644	0.000980
2007-Jun-21	103	33740	1	1000	100000	10000	50000	20000	0.003382	0.000945	0.001590	0.000850
2007-Jun-21	103	33741	1	1000	100000	10000	50000	20000	0.005061	0.001722	0.002195	0.001596
2007-Jun-21	103	33742	1	1000	100000	10000	50000	20000	0.002521	0.000557	0.001262	0.000472
2007-Jun-21	103	33743	1	1000	100000	10000	50000	20000	0.002527	0.000572	0.001260	0.000487
2007-Jun-21	103	33744	1	1000	100000	10000	50000	20000	0.002968	0.000741	0.001438	0.000649
2007-Jun-21	103	33747	1	1000	100000	10000	50000	20000	0.002779	0.000652	0.001375	0.000565
2007-Jun-21	103	33755	1	1000	100000	10000	50000	20000	0.002488	0.000531	0.001254	0.000444
2007-Jun-21	103	33756	1	1000	100000	10000	50000	20000	0.002612	0.000565	0.001316	0.000476

2007-Jun-21	103	33757	1	1000	100000	10000	50000	20000	0.002265	0.000452	0.001152	0.000365
2007-Jun-21	103	33758	1	1000	100000	10000	50000	20000	0.002254	0.000456	0.001146	0.000372
2007-Jun-21	103	33759	1	1000	100000	10000	50000	20000	0.002562	0.000568	0.001279	0.000483
2007-Jun-21	103	33760	1	1000	100000	10000	50000	20000	0.002536	0.000556	0.001272	0.000472
2007-Jun-21	103	33761	1	1000	100000	10000	50000	20000	0.002479	0.000533	0.001246	0.000447
2007-Jun-21	103	33762	1	1000	100000	10000	50000	20000	0.002676	0.000604	0.001335	0.000518
2007-Jun-21	103	33763	1	1000	100000	10000	50000	20000	0.002490	0.000532	0.001253	0.000446
2007-Jun-21	103	33764	1	1000	100000	10000	50000	20000	0.002541	0.000554	0.001272	0.000468
2007-Jun-21	103	33765	1	1000	100000	10000	50000	20000	0.002385	0.000506	0.001202	0.000422
2007-Jun-21	103	33766	1	1000	100000	10000	50000	20000	0.002430	0.000529	0.001218	0.000445
2007-Jun-21	103	33767	1	1000	100000	10000	50000	20000	0.003155	0.000805	0.001522	0.000714
2007-Jun-21	103	33769	1	1000	100000	10000	50000	20000	0.002393	0.000498	0.001211	0.000412
2007-Jun-21	103	33770	1	1000	100000	10000	50000	20000	0.002434	0.000516	0.001222	0.000429
2007-Jun-21	103	33771	1	1000	100000	10000	50000	20000	0.002419	0.000511	0.001219	0.000427
2007-Jun-21	103	33772	1	1000	100000	10000	50000	20000	0.002535	0.000565	0.001262	0.000479
2007-Jun-21	103	33773	1	1000	100000	10000	50000	20000	0.002619	0.000581	0.001310	0.000494
2007-Jun-21	103	33774	1	1000	100000	10000	50000	20000	0.002599	0.000576	0.001304	0.000491
2007-Jun-21	103	33775	1	1000	100000	10000	50000	20000	0.002480	0.000532	0.001251	0.000446
2007-Jun-21	103	33776	1	1000	100000	10000	50000	20000	0.002612	0.000592	0.001303	0.000506
2007-Jun-21	103	33777	1	1000	100000	10000	50000	20000	0.002605	0.000586	0.001300	0.000500
2007-Jun-21	103	33778	1	1000	100000	10000	50000	20000	0.002421	0.000509	0.001222	0.000424
2007-Jun-21	103	33779	1	1000	100000	10000	50000	20000	0.002432	0.000521	0.001226	0.000437
2007-Jun-21	103	33780	1	1000	100000	10000	50000	20000	0.002478	0.000531	0.001250	0.000445
2007-Jun-21	103	33781	1	1000	100000	10000	50000	20000	0.002537	0.000553	0.001274	0.000467
2007-Jun-21	103	33782	1	1000	100000	10000	50000	20000	0.002617	0.000589	0.001309	0.000503
2007-Jun-21	103	33784	1	1000	100000	10000	50000	20000	0.002552	0.000573	0.001281	0.000489
2007-Jun-21	103	33785	1	1000	100000	10000	50000	20000	0.003071	0.000777	0.001475	0.000682
2007-Jun-21	103	33786	1	1000	100000	10000	50000	20000	0.003271	0.000870	0.001557	0.000779
2007-Jun-21	103	34660	1	1000	100000	10000	50000	20000	0.002615	0.000555	0.001316	0.000465
2007-Jun-21	103	34677	1	1000	100000	10000	50000	20000	0.002375	0.000497	0.001194	0.000410
2007-Jun-21	103	34681	1	1000	100000	10000	50000	20000	0.002773	0.000614	0.001384	0.000521
2007-Jun-21	103	34682	1	1000	100000	10000	50000	20000	0.002448	0.000506	0.001235	0.000418
2007-Jun-21	103	34683	1	1000	100000	10000	50000	20000	0.002404	0.000497	0.001215	0.000410
2007-Jun-21	103	34684	1	1000	100000	10000	50000	20000	0.002411	0.000506	0.001218	0.000420
2007-Jun-21	103	34685	1	1000	100000	10000	50000	20000	0.002413	0.000501	0.001217	0.000413
2007-Jun-21	103	34688	1	1000	100000	10000	50000	20000	0.002454	0.000503	0.001238	0.000414
2007-Jun-21	103	34689	1	1000	100000	10000	50000	20000	0.002959	0.000702	0.001450	0.000605

2007-Jun-21	103	34695	1	1000	100000	10000	50000	20000	0.002669	0.000614	0.001319	0.000527
2007-Jun-21	103	34697	1	1000	100000	10000	50000	20000	0.002351	0.000486	0.001189	0.000401
2007-Jun-21	103	34698	1	1000	100000	10000	50000	20000	0.002368	0.000483	0.001201	0.000396
2007-Jun-21	103	33701	2	1000	100000	10000	50000	20000	0.002442	0.000597	0.001468	0.000521
2007-Jun-21	103	33702	2	1000	100000	10000	50000	20000	0.002105	0.000468	0.001273	0.000389
2007-Jun-21	103	33703	2	1000	100000	10000	50000	20000	0.002300	0.000536	0.001384	0.000457
2007-Jun-21	103	33704	2	1000	100000	10000	50000	20000	0.003103	0.000884	0.001785	0.000812
2007-Jun-21	103	33705	2	1000	100000	10000	50000	20000	0.002751	0.000723	0.001611	0.000648
2007-Jun-21	103	33706	2	1000	100000	10000	50000	20000	0.002278	0.000521	0.001375	0.000440
2007-Jun-21	103	33707	2	1000	100000	10000	50000	20000	0.002723	0.000717	0.001577	0.000639
2007-Jun-21	103	33708	2	1000	100000	10000	50000	20000	0.002573	0.000637	0.001506	0.000551
2007-Jun-21	103	33709	2	1000	100000	10000	50000	20000	0.002077	0.000452	0.001259	0.000371
2007-Jun-21	103	33710	2	1000	100000	10000	50000	20000	0.002120	0.000469	0.001283	0.000389
2007-Jun-21	103	33711	2	1000	100000	10000	50000	20000	0.002317	0.000531	0.001402	0.000449
2007-Jun-21	103	33712	2	1000	100000	10000	50000	20000	0.002457	0.000601	0.001470	0.000525
2007-Jun-21	103	33713	2	1000	100000	10000	50000	20000	0.002412	0.000572	0.001442	0.000489
2007-Jun-21	103	33714	2	1000	100000	10000	50000	20000	0.002130	0.000463	0.001295	0.000381
2007-Jun-21	103	33715	2	1000	100000	10000	50000	20000	0.004069	0.001379	0.002102	0.001300
2007-Jun-21	103	33716	2	1000	100000	10000	50000	20000	0.002153	0.000475	0.001300	0.000394
2007-Jun-21	103	33728	2	1000	100000	10000	50000	20000	0.002095	0.000471	0.001262	0.000394
2007-Jun-21	103	33729	2	1000	100000	10000	50000	20000	0.002095	0.000471	0.001262	0.000394
2007-Jun-21	103	33730	2	1000	100000	10000	50000	20000	0.002101	0.000463	0.001278	0.000383
2007-Jun-21	103	33731	2	1000	100000	10000	50000	20000	0.002198	0.000492	0.001336	0.000411
2007-Jun-21	103	33732	2	1000	100000	10000	50000	20000	0.002042	0.000444	0.001236	0.000364
2007-Jun-21	103	33733	2	1000	100000	10000	50000	20000	0.002101	0.000463	0.001278	0.000383
2007-Jun-21	103	33734	2	1000	100000	10000	50000	20000	0.002206	0.000500	0.001331	0.000420
2007-Jun-21	103	33736	2	1000	100000	10000	50000	20000	0.002596	0.000686	0.001506	0.000613
2007-Jun-21	103	33737	2	1000	100000	10000	50000	20000	0.002887	0.000806	0.001633	0.000731
2007-Jun-21	103	33738	2	1000	100000	10000	50000	20000	0.002952	0.000825	0.001640	0.000734
2007-Jun-21	103	33740	2	1000	100000	10000	50000	20000	0.002728	0.000720	0.001586	0.000641
2007-Jun-21	103	33741	2	1000	100000	10000	50000	20000	0.004002	0.001256	0.002188	0.001174
2007-Jun-21	103	33742	2	1000	100000	10000	50000	20000	0.002079	0.000452	0.001259	0.000371
2007-Jun-21	103	33743	2	1000	100000	10000	50000	20000	0.002081	0.000461	0.001257	0.000382
2007-Jun-21	103	33744	2	1000	100000	10000	50000	20000	0.002423	0.000581	0.001434	0.000499
2007-Jun-21	103	33747	2	1000	100000	10000	50000	20000	0.002278	0.000519	0.001371	0.000438
2007-Jun-21	103	33755	2	1000	100000	10000	50000	20000	0.002060	0.000436	0.001251	0.000352
2007-Jun-21	103	33756	2	1000	100000	10000	50000	20000	0.002157	0.000461	0.001312	0.000376

2007-Jun-21	103	33757	2	1000	100000	10000	50000	20000	0.001889	0.000380	0.001149	0.000295
2007-Jun-21	103	33758	2	1000	100000	10000	50000	20000	0.001876	0.000381	0.001144	0.000299
2007-Jun-21	103	33759	2	1000	100000	10000	50000	20000	0.002112	0.000461	0.001276	0.000380
2007-Jun-21	103	33760	2	1000	100000	10000	50000	20000	0.002092	0.000453	0.001269	0.000371
2007-Jun-21	103	33761	2	1000	100000	10000	50000	20000	0.002050	0.000437	0.001242	0.000354
2007-Jun-21	103	33762	2	1000	100000	10000	50000	20000	0.002201	0.000487	0.001331	0.000405
2007-Jun-21	103	33763	2	1000	100000	10000	50000	20000	0.002060	0.000437	0.001250	0.000354
2007-Jun-21	103	33764	2	1000	100000	10000	50000	20000	0.002099	0.000452	0.001269	0.000369
2007-Jun-21	103	33765	2	1000	100000	10000	50000	20000	0.001975	0.000417	0.001199	0.000336
2007-Jun-21	103	33766	2	1000	100000	10000	50000	20000	0.002008	0.000432	0.001215	0.000352
2007-Jun-21	103	33767	2	1000	100000	10000	50000	20000	0.002565	0.000627	0.001518	0.000546
2007-Jun-21	103	33769	2	1000	100000	10000	50000	20000	0.001986	0.000412	0.001208	0.000329
2007-Jun-21	103	33770	2	1000	100000	10000	50000	20000	0.002018	0.000425	0.001219	0.000341
2007-Jun-21	103	33771	2	1000	100000	10000	50000	20000	0.002003	0.000421	0.001216	0.000339
2007-Jun-21	103	33772	2	1000	100000	10000	50000	20000	0.002091	0.000458	0.001258	0.000377
2007-Jun-21	103	33773	2	1000	100000	10000	50000	20000	0.002159	0.000471	0.001306	0.000388
2007-Jun-21	103	33774	2	1000	100000	10000	50000	20000	0.002141	0.000467	0.001301	0.000385
2007-Jun-21	103	33775	2	1000	100000	10000	50000	20000	0.002051	0.000436	0.001247	0.000353
2007-Jun-21	103	33776	2	1000	100000	10000	50000	20000	0.002149	0.000477	0.001300	0.000396
2007-Jun-21	103	33777	2	1000	100000	10000	50000	20000	0.002144	0.000473	0.001297	0.000392
2007-Jun-21	103	33778	2	1000	100000	10000	50000	20000	0.002006	0.000420	0.001219	0.000337
2007-Jun-21	103	33779	2	1000	100000	10000	50000	20000	0.002012	0.000427	0.001222	0.000346
2007-Jun-21	103	33780	2	1000	100000	10000	50000	20000	0.002050	0.000435	0.001246	0.000353
2007-Jun-21	103	33781	2	1000	100000	10000	50000	20000	0.002095	0.000451	0.001271	0.000368
2007-Jun-21	103	33782	2	1000	100000	10000	50000	20000	0.002153	0.000475	0.001306	0.000394
2007-Jun-21	103	33784	2	1000	100000	10000	50000	20000	0.002101	0.000463	0.001278	0.000383
2007-Jun-21	103	33785	2	1000	100000	10000	50000	20000	0.002505	0.000607	0.001471	0.000523
2007-Jun-21	103	33786	2	1000	100000	10000	50000	20000	0.002648	0.000671	0.001553	0.000592
2007-Jun-21	103	34660	2	1000	100000	10000	50000	20000	0.002165	0.000456	0.001312	0.000369
2007-Jun-21	103	34677	2	1000	100000	10000	50000	20000	0.001972	0.000412	0.001191	0.000328
2007-Jun-21	103	34681	2	1000	100000	10000	50000	20000	0.002288	0.000498	0.001380	0.000409
2007-Jun-21	103	34682	2	1000	100000	10000	50000	20000	0.002034	0.000420	0.001232	0.000334
2007-Jun-21	103	34683	2	1000	100000	10000	50000	20000	0.001997	0.000413	0.001212	0.000328
2007-Jun-21	103	34684	2	1000	100000	10000	50000	20000	0.001999	0.000418	0.001215	0.000335
2007-Jun-21	103	34685	2	1000	100000	10000	50000	20000	0.002004	0.000415	0.001214	0.000330
2007-Jun-21	103	34688	2	1000	100000	10000	50000	20000	0.002040	0.000419	0.001235	0.000332
2007-Jun-21	103	34689	2	1000	100000	10000	50000	20000	0.002428	0.000558	0.001446	0.000469

2007-Jun-21	103	34695	2	1000	100000	10000	50000	20000	0.002193	0.000493	0.001316	0.000411
2007-Jun-21	103	34697	2	1000	100000	10000	50000	20000	0.001953	0.000404	0.001186	0.000321
2007-Jun-21	103	34698	2	1000	100000	10000	50000	20000	0.001969	0.000403	0.001198	0.000318
2007-Jun-21	103	33701	3	1000	100000	10000	50000	20000	0.015312	0.006666	0.001494	0.006883
2007-Jun-21	103	33702	3	1000	100000	10000	50000	20000	0.012498	0.004980	0.001295	0.005156
2007-Jun-21	103	33703	3	1000	100000	10000	50000	20000	0.014002	0.005836	0.001408	0.006032
2007-Jun-21	103	33704	3	1000	100000	10000	50000	20000	0.020111	0.009692	0.001815	0.009920
2007-Jun-21	103	33705	3	1000	100000	10000	50000	20000	0.017372	0.007914	0.001638	0.008131
2007-Jun-21	103	33706	3	1000	100000	10000	50000	20000	0.013775	0.005647	0.001399	0.005851
2007-Jun-21	103	33707	3	1000	100000	10000	50000	20000	0.016819	0.007572	0.001604	0.007771
2007-Jun-21	103	33708	3	1000	100000	10000	50000	20000	0.015448	0.006576	0.001533	0.006783
2007-Jun-21	103	33709	3	1000	100000	10000	50000	20000	0.012180	0.004737	0.001281	0.004911
2007-Jun-21	103	33710	3	1000	100000	10000	50000	20000	0.012536	0.004958	0.001305	0.005136
2007-Jun-21	103	33711	3	1000	100000	10000	50000	20000	0.014084	0.005798	0.001427	0.006008
2007-Jun-21	103	33712	3	1000	100000	10000	50000	20000	0.015333	0.006668	0.001496	0.006881
2007-Jun-21	103	33713	3	1000	100000	10000	50000	20000	0.014656	0.006145	0.001467	0.006358
2007-Jun-21	103	33714	3	1000	100000	10000	50000	20000	0.012627	0.004956	0.001318	0.005146
2007-Jun-21	103	33715	3	1000	100000	10000	50000	20000	0.024984	0.012979	0.002136	0.013114
2007-Jun-21	103	33716	3	1000	100000	10000	50000	20000	0.012726	0.005033	0.001323	0.005213
2007-Jun-21	103	33728	3	1000	100000	10000	50000	20000	0.012433	0.004987	0.001284	0.005153
2007-Jun-21	103	33729	3	1000	100000	10000	50000	20000	0.012433	0.004987	0.001284	0.005153
2007-Jun-21	103	33730	3	1000	100000	10000	50000	20000	0.012502	0.004951	0.001301	0.005136
2007-Jun-21	103	33731	3	1000	100000	10000	50000	20000	0.013265	0.005362	0.001360	0.005563
2007-Jun-21	103	33732	3	1000	100000	10000	50000	20000	0.011917	0.004619	0.001258	0.004784
2007-Jun-21	103	33733	3	1000	100000	10000	50000	20000	0.012502	0.004951	0.001301	0.005136
2007-Jun-21	103	33734	3	1000	100000	10000	50000	20000	0.013236	0.005370	0.001354	0.005557
2007-Jun-21	103	33736	3	1000	100000	10000	50000	20000	0.016130	0.007313	0.001531	0.007492
2007-Jun-21	103	33737	3	1000	100000	10000	50000	20000	0.017843	0.008315	0.001660	0.008498
2007-Jun-21	103	33738	3	1000	100000	10000	50000	20000	0.017397	0.007848	0.001668	0.008030
2007-Jun-21	103	33740	3	1000	100000	10000	50000	20000	0.016937	0.007645	0.001613	0.007850
2007-Jun-21	103	33741	3	1000	100000	10000	50000	20000	0.025572	0.012894	0.002225	0.013132
2007-Jun-21	103	33742	3	1000	100000	10000	50000	20000	0.012196	0.004751	0.001281	0.004925
2007-Jun-21	103	33743	3	1000	100000	10000	50000	20000	0.012232	0.004813	0.001279	0.004983
2007-Jun-21	103	33744	3	1000	100000	10000	50000	20000	0.014551	0.006097	0.001459	0.006290
2007-Jun-21	103	33747	3	1000	100000	10000	50000	20000	0.013692	0.005579	0.001396	0.005780
2007-Jun-21	103	33755	3	1000	100000	10000	50000	20000	0.011878	0.004484	0.001273	0.004650
2007-Jun-21	103	33756	3	1000	100000	10000	50000	20000	0.012656	0.004881	0.001335	0.005066

2007-Jun-21	103	33757	3	1000	100000	10000	50000	20000	0.010498	0.003704	0.001169	0.003851
2007-Jun-21	103	33758	3	1000	100000	10000	50000	20000	0.010564	0.003804	0.001164	0.003951
2007-Jun-21	103	33759	3	1000	100000	10000	50000	20000	0.012365	0.004821	0.001298	0.004992
2007-Jun-21	103	33760	3	1000	100000	10000	50000	20000	0.012307	0.004793	0.001291	0.004970
2007-Jun-21	103	33761	3	1000	100000	10000	50000	20000	0.011854	0.004505	0.001264	0.004669
2007-Jun-21	103	33762	3	1000	100000	10000	50000	20000	0.013116	0.005229	0.001355	0.005421
2007-Jun-21	103	33763	3	1000	100000	10000	50000	20000	0.011907	0.004513	0.001272	0.004679
2007-Jun-21	103	33764	3	1000	100000	10000	50000	20000	0.012220	0.004705	0.001291	0.004878
2007-Jun-21	103	33765	3	1000	100000	10000	50000	20000	0.011354	0.004266	0.001221	0.004422
2007-Jun-21	103	33766	3	1000	100000	10000	50000	20000	0.011609	0.004438	0.001237	0.004593
2007-Jun-21	103	33767	3	1000	100000	10000	50000	20000	0.015705	0.006750	0.001544	0.006957
2007-Jun-21	103	33769	3	1000	100000	10000	50000	20000	0.011364	0.004213	0.001229	0.004375
2007-Jun-21	103	33770	3	1000	100000	10000	50000	20000	0.011507	0.004285	0.001241	0.004450
2007-Jun-21	103	33771	3	1000	100000	10000	50000	20000	0.011557	0.004352	0.001238	0.004517
2007-Jun-21	103	33772	3	1000	100000	10000	50000	20000	0.012147	0.004706	0.001281	0.004876
2007-Jun-21	103	33773	3	1000	100000	10000	50000	20000	0.012697	0.004963	0.001330	0.005147
2007-Jun-21	103	33774	3	1000	100000	10000	50000	20000	0.012678	0.004982	0.001324	0.005165
2007-Jun-21	103	33775	3	1000	100000	10000	50000	20000	0.011939	0.004550	0.001270	0.004726
2007-Jun-21	103	33776	3	1000	100000	10000	50000	20000	0.012704	0.005030	0.001323	0.005207
2007-Jun-21	103	33777	3	1000	100000	10000	50000	20000	0.012669	0.005001	0.001320	0.005181
2007-Jun-21	103	33778	3	1000	100000	10000	50000	20000	0.011537	0.004314	0.001241	0.004482
2007-Jun-21	103	33779	3	1000	100000	10000	50000	20000	0.011677	0.004445	0.001244	0.004609
2007-Jun-21	103	33780	3	1000	100000	10000	50000	20000	0.011925	0.004544	0.001269	0.004720
2007-Jun-21	103	33781	3	1000	100000	10000	50000	20000	0.012272	0.004745	0.001293	0.004925
2007-Jun-21	103	33782	3	1000	100000	10000	50000	20000	0.012779	0.005060	0.001329	0.005246
2007-Jun-21	103	33784	3	1000	100000	10000	50000	20000	0.012502	0.004951	0.001301	0.005136
2007-Jun-21	103	33785	3	1000	100000	10000	50000	20000	0.014973	0.006299	0.001497	0.006491
2007-Jun-21	103	33786	3	1000	100000	10000	50000	20000	0.016339	0.007203	0.001580	0.007404
2007-Jun-21	103	34660	3	1000	100000	10000	50000	20000	0.012518	0.004731	0.001336	0.004915
2007-Jun-21	103	34677	3	1000	100000	10000	50000	20000	0.011111	0.004074	0.001212	0.004220
2007-Jun-21	103	34681	3	1000	100000	10000	50000	20000	0.013376	0.005196	0.001404	0.005391
2007-Jun-21	103	34682	3	1000	100000	10000	50000	20000	0.011519	0.004221	0.001254	0.004382
2007-Jun-21	103	34683	3	1000	100000	10000	50000	20000	0.011326	0.004156	0.001233	0.004311
2007-Jun-21	103	34684	3	1000	100000	10000	50000	20000	0.011434	0.004254	0.001237	0.004411
2007-Jun-21	103	34685	3	1000	100000	10000	50000	20000	0.011335	0.004157	0.001235	0.004309
2007-Jun-21	103	34688	3	1000	100000	10000	50000	20000	0.011509	0.004193	0.001257	0.004349
2007-Jun-21	103	34689	3	1000	100000	10000	50000	20000	0.014329	0.005786	0.001471	0.005984

2007-Jun-21	103	34695	3	1000	100000	10000	50000	20000	0.012928	0.005154	0.001339	0.005327
2007-Jun-21	103	34697	3	1000	100000	10000	50000	20000	0.011060	0.004049	0.001207	0.004199
2007-Jun-21	103	34698	3	1000	100000	10000	50000	20000	0.011119	0.004030	0.001219	0.004185
2007-Jun-21	105	33801	1	1000	100000	10000	50000	20000	0.002592	0.000436	0.001295	0.000329
2007-Jun-21	105	33802	1	1000	100000	10000	50000	20000	0.002953	0.000575	0.001451	0.000472
2007-Jun-21	105	33803	1	1000	100000	10000	50000	20000	0.002713	0.000477	0.001351	0.000374
2007-Jun-21	105	33804	1	1000	100000	10000	50000	20000	0.002613	0.000452	0.001305	0.000348
2007-Jun-21	105	33805	1	1000	100000	10000	50000	20000	0.002542	0.000433	0.001268	0.000329
2007-Jun-21	105	33806	1	1000	100000	10000	50000	20000	0.002599	0.000448	0.001294	0.000344
2007-Jun-21	105	33807	1	1000	100000	10000	50000	20000	0.002540	0.000434	0.001264	0.000332
2007-Jun-21	105	33809	1	1000	100000	10000	50000	20000	0.002709	0.000470	0.001348	0.000363
2007-Jun-21	105	33810	1	1000	100000	10000	50000	20000	0.002710	0.000483	0.001345	0.000379
2007-Jun-21	105	33811	1	1000	100000	10000	50000	20000	0.002765	0.000489	0.001376	0.000385
2007-Jun-21	105	33813	1	1000	100000	10000	50000	20000	0.002679	0.000458	0.001336	0.000351
2007-Jun-21	105	33815	1	1000	100000	10000	50000	20000	0.002420	0.000405	0.001206	0.000303
2007-Jun-21	105	33820	1	1000	100000	10000	50000	20000	0.003049	0.000541	0.001516	0.000428
2007-Jun-21	105	33823	1	1000	100000	10000	50000	20000	0.003541	0.000721	0.001739	0.000610
2007-Jun-21	105	33827	1	1000	100000	10000	50000	20000	0.003078	0.000537	0.001530	0.000419
2007-Jun-21	105	33830	1	1000	100000	10000	50000	20000	0.002661	0.000444	0.001329	0.000336
2007-Jun-21	105	33831	1	1000	100000	10000	50000	20000	0.002473	0.000407	0.001233	0.000302
2007-Jun-21	105	33835	1	1000	100000	10000	50000	20000	0.002886	0.000521	0.001435	0.000416
2007-Jun-21	105	33836	1	1000	100000	10000	50000	20000	0.002740	0.000454	0.001366	0.000341
2007-Jun-21	105	33837	1	1000	100000	10000	50000	20000	0.002798	0.000469	0.001393	0.000356
2007-Jun-21	105	33838	1	1000	100000	10000	50000	20000	0.002985	0.000517	0.001492	0.000402
2007-Jun-21	105	33839	1	1000	100000	10000	50000	20000	0.002773	0.000473	0.001386	0.000363
2007-Jun-21	105	33840	1	1000	100000	10000	50000	20000	0.002493	0.000417	0.001245	0.000313
2007-Jun-21	105	33841	1	1000	100000	10000	50000	20000	0.002743	0.000466	0.001368	0.000355
2007-Jun-21	105	33843	1	1000	100000	10000	50000	20000	0.003043	0.000533	0.001512	0.000417
2007-Jun-21	105	33844	1	1000	100000	10000	50000	20000	0.002782	0.000465	0.001390	0.000352
2007-Jun-21	105	33845	1	1000	100000	10000	50000	20000	0.002896	0.000495	0.001445	0.000381
2007-Jun-21	105	33846	1	1000	100000	10000	50000	20000	0.002661	0.000451	0.001330	0.000344
2007-Jun-21	105	33847	1	1000	100000	10000	50000	20000	0.002858	0.000494	0.001424	0.000385
2007-Jun-21	105	33849	1	1000	100000	10000	50000	20000	0.002447	0.000424	0.001215	0.000323
2007-Jun-21	105	33850	1	1000	100000	10000	50000	20000	0.002825	0.000488	0.001412	0.000378
2007-Jun-21	105	33851	1	1000	100000	10000	50000	20000	0.002908	0.000497	0.001453	0.000382
2007-Jun-21	105	33853	1	1000	100000	10000	50000	20000	0.002632	0.000426	0.001311	0.000313
2007-Jun-21	105	33854	1	1000	100000	10000	50000	20000	0.002812	0.000469	0.001397	0.000353

2007-Jun-21	105	33855	1	1000	100000	10000	50000	20000	0.002878	0.000500	0.001423	0.000385
2007-Jun-21	105	33856	1	1000	100000	10000	50000	20000	0.002757	0.000456	0.001369	0.000340
2007-Jun-21	105	33858	1	1000	100000	10000	50000	20000	0.002706	0.000447	0.001348	0.000334
2007-Jun-21	105	33859	1	1000	100000	10000	50000	20000	0.003008	0.000522	0.001500	0.000407
2007-Jun-21	105	33860	1	1000	100000	10000	50000	20000	0.002592	0.000451	0.001289	0.000348
2007-Jun-21	105	33863	1	1000	100000	10000	50000	20000	0.002795	0.000504	0.001388	0.000402
2007-Jun-21	105	33867	1	1000	100000	10000	50000	20000	0.002418	0.000382	0.001200	0.000272
2007-Jun-21	105	33868	1	1000	100000	10000	50000	20000	0.002679	0.000455	0.001335	0.000345
2007-Jun-21	105	33877	1	1000	100000	10000	50000	20000	0.002914	0.000499	0.001454	0.000385
2007-Jun-21	105	33880	1	1000	100000	10000	50000	20000	0.002819	0.000486	0.001413	0.000376
2007-Jun-21	105	33881	1	1000	100000	10000	50000	20000	0.002846	0.000491	0.001418	0.000380
2007-Jun-21	105	33882	1	1000	100000	10000	50000	20000	0.002400	0.000383	0.001195	0.000275
2007-Jun-21	105	33883	1	1000	100000	10000	50000	20000	0.002400	0.000383	0.001195	0.000275
2007-Jun-21	105	33884	1	1000	100000	10000	50000	20000	0.002701	0.000447	0.001345	0.000334
2007-Jun-21	105	33885	1	1000	100000	10000	50000	20000	0.002754	0.000465	0.001376	0.000354
2007-Jun-21	105	33888	1	1000	100000	10000	50000	20000	0.002856	0.000485	0.001425	0.000371
2007-Jun-21	105	33896	1	1000	100000	10000	50000	20000	0.002714	0.000452	0.001352	0.000340
2007-Jun-21	105	33897	1	1000	100000	10000	50000	20000	0.002727	0.000459	0.001359	0.000348
2007-Jun-21	105	33898	1	1000	100000	10000	50000	20000	0.002927	0.000497	0.001459	0.000380
2007-Jun-21	105	34759	1	1000	100000	10000	50000	20000	0.002671	0.000435	0.001323	0.000321
2007-Jun-21	105	33801	2	1000	100000	10000	50000	20000	0.002178	0.000385	0.001291	0.000277
2007-Jun-21	105	33802	2	1000	100000	10000	50000	20000	0.002447	0.000481	0.001448	0.000379
2007-Jun-21	105	33803	2	1000	100000	10000	50000	20000	0.002267	0.000413	0.001348	0.000308
2007-Jun-21	105	33804	2	1000	100000	10000	50000	20000	0.002189	0.000395	0.001301	0.000290
2007-Jun-21	105	33805	2	1000	100000	10000	50000	20000	0.002134	0.000380	0.001265	0.000275
2007-Jun-21	105	33806	2	1000	100000	10000	50000	20000	0.002178	0.000392	0.001291	0.000287
2007-Jun-21	105	33807	2	1000	100000	10000	50000	20000	0.002130	0.000381	0.001261	0.000277
2007-Jun-21	105	33809	2	1000	100000	10000	50000	20000	0.002268	0.000409	0.001345	0.000302
2007-Jun-21	105	33810	2	1000	100000	10000	50000	20000	0.002264	0.000417	0.001342	0.000312
2007-Jun-21	105	33811	2	1000	100000	10000	50000	20000	0.002309	0.000422	0.001373	0.000317
2007-Jun-21	105	33813	2	1000	100000	10000	50000	20000	0.002246	0.000400	0.001333	0.000293
2007-Jun-21	105	33815	2	1000	100000	10000	50000	20000	0.002035	0.000359	0.001203	0.000256
2007-Jun-21	105	33820	2	1000	100000	10000	50000	20000	0.002544	0.000465	0.001512	0.000351
2007-Jun-21	105	33823	2	1000	100000	10000	50000	20000	0.002917	0.000591	0.001734	0.000482
2007-Jun-21	105	33827	2	1000	100000	10000	50000	20000	0.002575	0.000465	0.001526	0.000347
2007-Jun-21	105	33830	2	1000	100000	10000	50000	20000	0.002236	0.000392	0.001326	0.000283
2007-Jun-21	105	33831	2	1000	100000	10000	50000	20000	0.002083	0.000363	0.001230	0.000257

2007-Jun-21	105	33835	2	1000	100000	10000	50000	20000	0.002404	0.000446	0.001431	0.000340
2007-Jun-21	105	33836	2	1000	100000	10000	50000	20000	0.002305	0.000402	0.001363	0.000288
2007-Jun-21	105	33837	2	1000	100000	10000	50000	20000	0.002351	0.000414	0.001389	0.000299
2007-Jun-21	105	33838	2	1000	100000	10000	50000	20000	0.002498	0.000449	0.001488	0.000333
2007-Jun-21	105	33839	2	1000	100000	10000	50000	20000	0.002325	0.000414	0.001382	0.000303
2007-Jun-21	105	33840	2	1000	100000	10000	50000	20000	0.002096	0.000369	0.001242	0.000264
2007-Jun-21	105	33841	2	1000	100000	10000	50000	20000	0.002302	0.000409	0.001364	0.000297
2007-Jun-21	105	33843	2	1000	100000	10000	50000	20000	0.002545	0.000461	0.001508	0.000344
2007-Jun-21	105	33844	2	1000	100000	10000	50000	20000	0.002338	0.000411	0.001386	0.000296
2007-Jun-21	105	33845	2	1000	100000	10000	50000	20000	0.002427	0.000433	0.001442	0.000318
2007-Jun-21	105	33846	2	1000	100000	10000	50000	20000	0.002232	0.000396	0.001327	0.000288
2007-Jun-21	105	33847	2	1000	100000	10000	50000	20000	0.002392	0.000430	0.001420	0.000319
2007-Jun-21	105	33849	2	1000	100000	10000	50000	20000	0.002053	0.000371	0.001212	0.000270
2007-Jun-21	105	33850	2	1000	100000	10000	50000	20000	0.002365	0.000425	0.001408	0.000314
2007-Jun-21	105	33851	2	1000	100000	10000	50000	20000	0.002438	0.000434	0.001449	0.000319
2007-Jun-21	105	33853	2	1000	100000	10000	50000	20000	0.002221	0.000382	0.001307	0.000268
2007-Jun-21	105	33854	2	1000	100000	10000	50000	20000	0.002365	0.000415	0.001394	0.000298
2007-Jun-21	105	33855	2	1000	100000	10000	50000	20000	0.002413	0.000436	0.001419	0.000320
2007-Jun-21	105	33856	2	1000	100000	10000	50000	20000	0.002321	0.000405	0.001366	0.000288
2007-Jun-21	105	33858	2	1000	100000	10000	50000	20000	0.002277	0.000397	0.001344	0.000283
2007-Jun-21	105	33859	2	1000	100000	10000	50000	20000	0.002516	0.000453	0.001496	0.000337
2007-Jun-21	105	33860	2	1000	100000	10000	50000	20000	0.002170	0.000392	0.001286	0.000289
2007-Jun-21	105	33863	2	1000	100000	10000	50000	20000	0.002329	0.000432	0.001385	0.000329
2007-Jun-21	105	33867	2	1000	100000	10000	50000	20000	0.002048	0.000348	0.001198	0.000236
2007-Jun-21	105	33868	2	1000	100000	10000	50000	20000	0.002249	0.000400	0.001331	0.000290
2007-Jun-21	105	33877	2	1000	100000	10000	50000	20000	0.002442	0.000436	0.001450	0.000320
2007-Jun-21	105	33880	2	1000	100000	10000	50000	20000	0.002360	0.000424	0.001410	0.000312
2007-Jun-21	105	33881	2	1000	100000	10000	50000	20000	0.002384	0.000428	0.001414	0.000316
2007-Jun-21	105	33882	2	1000	100000	10000	50000	20000	0.002029	0.000346	0.001192	0.000238
2007-Jun-21	105	33883	2	1000	100000	10000	50000	20000	0.002029	0.000346	0.001192	0.000238
2007-Jun-21	105	33884	2	1000	100000	10000	50000	20000	0.002272	0.000396	0.001342	0.000283
2007-Jun-21	105	33885	2	1000	100000	10000	50000	20000	0.002311	0.000409	0.001373	0.000297
2007-Jun-21	105	33888	2	1000	100000	10000	50000	20000	0.002396	0.000425	0.001421	0.000310
2007-Jun-21	105	33896	2	1000	100000	10000	50000	20000	0.002283	0.000400	0.001349	0.000287
2007-Jun-21	105	33897	2	1000	100000	10000	50000	20000	0.002291	0.000405	0.001356	0.000292
2007-Jun-21	105	33898	2	1000	100000	10000	50000	20000	0.002456	0.000436	0.001455	0.000318
2007-Jun-21	105	34759	2	1000	100000	10000	50000	20000	0.002253	0.000389	0.001320	0.000274

2007-Jun-21	105	33801	3	1000	100000	10000	50000	20000	0.010656	0.003337	0.001314	0.003491
2007-Jun-21	105	33802	3	1000	100000	10000	50000	20000	0.012944	0.004725	0.001473	0.004912
2007-Jun-21	105	33803	3	1000	100000	10000	50000	20000	0.011542	0.003876	0.001371	0.004052
2007-Jun-21	105	33804	3	1000	100000	10000	50000	20000	0.010944	0.003568	0.001324	0.003726
2007-Jun-21	105	33805	3	1000	100000	10000	50000	20000	0.010489	0.003324	0.001287	0.003470
2007-Jun-21	105	33806	3	1000	100000	10000	50000	20000	0.010803	0.003487	0.001314	0.003639
2007-Jun-21	105	33807	3	1000	100000	10000	50000	20000	0.010501	0.003353	0.001283	0.003500
2007-Jun-21	105	33809	3	1000	100000	10000	50000	20000	0.011364	0.003722	0.001368	0.003890
2007-Jun-21	105	33810	3	1000	100000	10000	50000	20000	0.011462	0.003847	0.001365	0.004011
2007-Jun-21	105	33811	3	1000	100000	10000	50000	20000	0.011817	0.003998	0.001397	0.004182
2007-Jun-21	105	33813	3	1000	100000	10000	50000	20000	0.011202	0.003625	0.001356	0.003794
2007-Jun-21	105	33815	3	1000	100000	10000	50000	20000	0.009817	0.003016	0.001224	0.003145
2007-Jun-21	105	33820	3	1000	100000	10000	50000	20000	0.013130	0.004486	0.001539	0.004702
2007-Jun-21	105	33823	3	1000	100000	10000	50000	20000	0.016223	0.006297	0.001764	0.006573
2007-Jun-21	105	33827	3	1000	100000	10000	50000	20000	0.013060	0.004341	0.001552	0.004552
2007-Jun-21	105	33830	3	1000	100000	10000	50000	20000	0.010978	0.003445	0.001349	0.003609
2007-Jun-21	105	33831	3	1000	100000	10000	50000	20000	0.009968	0.003010	0.001251	0.003145
2007-Jun-21	105	33835	3	1000	100000	10000	50000	20000	0.012523	0.004356	0.001456	0.004561
2007-Jun-21	105	33836	3	1000	100000	10000	50000	20000	0.011213	0.003462	0.001387	0.003631
2007-Jun-21	105	33837	3	1000	100000	10000	50000	20000	0.011525	0.003617	0.001413	0.003791
2007-Jun-21	105	33838	3	1000	100000	10000	50000	20000	0.012685	0.004200	0.001514	0.004407
2007-Jun-21	105	33839	3	1000	100000	10000	50000	20000	0.011624	0.003762	0.001406	0.003942
2007-Jun-21	105	33840	3	1000	100000	10000	50000	20000	0.010182	0.003153	0.001263	0.003294
2007-Jun-21	105	33841	3	1000	100000	10000	50000	20000	0.011372	0.003619	0.001388	0.003790
2007-Jun-21	105	33843	3	1000	100000	10000	50000	20000	0.012921	0.004310	0.001534	0.004517
2007-Jun-21	105	33844	3	1000	100000	10000	50000	20000	0.011495	0.003609	0.001410	0.003785
2007-Jun-21	105	33845	3	1000	100000	10000	50000	20000	0.012152	0.003941	0.001467	0.004132
2007-Jun-21	105	33846	3	1000	100000	10000	50000	20000	0.011072	0.003541	0.001350	0.003707
2007-Jun-21	105	33847	3	1000	100000	10000	50000	20000	0.012123	0.004015	0.001445	0.004211
2007-Jun-21	105	33849	3	1000	100000	10000	50000	20000	0.010022	0.003179	0.001233	0.003308
2007-Jun-21	105	33850	3	1000	100000	10000	50000	20000	0.011939	0.003925	0.001433	0.004113
2007-Jun-21	105	33851	3	1000	100000	10000	50000	20000	0.012216	0.003962	0.001474	0.004156
2007-Jun-21	105	33853	3	1000	100000	10000	50000	20000	0.010497	0.003086	0.001330	0.003230
2007-Jun-21	105	33854	3	1000	100000	10000	50000	20000	0.011453	0.003530	0.001418	0.003696
2007-Jun-21	105	33855	3	1000	100000	10000	50000	20000	0.011862	0.003799	0.001444	0.003966
2007-Jun-21	105	33856	3	1000	100000	10000	50000	20000	0.011125	0.003370	0.001390	0.003526
2007-Jun-21	105	33858	3	1000	100000	10000	50000	20000	0.011009	0.003366	0.001368	0.003528

2007-Jun-21	105	33859	3	1000	100000	10000	50000	20000	0.012807	0.004264	0.001522	0.004472
2007-Jun-21	105	33860	3	1000	100000	10000	50000	20000	0.010835	0.003540	0.001308	0.003696
2007-Jun-21	105	33863	3	1000	100000	10000	50000	20000	0.012062	0.004172	0.001409	0.004362
2007-Jun-21	105	33867	3	1000	100000	10000	50000	20000	0.009287	0.002538	0.001218	0.002643
2007-Jun-21	105	33868	3	1000	100000	10000	50000	20000	0.011036	0.003483	0.001354	0.003641
2007-Jun-21	105	33877	3	1000	100000	10000	50000	20000	0.012270	0.004002	0.001475	0.004198
2007-Jun-21	105	33880	3	1000	100000	10000	50000	20000	0.011943	0.003933	0.001434	0.004121
2007-Jun-21	105	33881	3	1000	100000	10000	50000	20000	0.011980	0.003922	0.001439	0.004109
2007-Jun-21	105	33882	3	1000	100000	10000	50000	20000	0.009387	0.002655	0.001213	0.002771
2007-Jun-21	105	33883	3	1000	100000	10000	50000	20000	0.009387	0.002655	0.001213	0.002771
2007-Jun-21	105	33884	3	1000	100000	10000	50000	20000	0.011000	0.003374	0.001365	0.003534
2007-Jun-21	105	33885	3	1000	100000	10000	50000	20000	0.011450	0.003645	0.001397	0.003820
2007-Jun-21	105	33888	3	1000	100000	10000	50000	20000	0.011917	0.003822	0.001446	0.004009
2007-Jun-21	105	33896	3	1000	100000	10000	50000	20000	0.011100	0.003434	0.001372	0.003599
2007-Jun-21	105	33897	3	1000	100000	10000	50000	20000	0.011242	0.003536	0.001379	0.003703
2007-Jun-21	105	33898	3	1000	100000	10000	50000	20000	0.012191	0.003901	0.001480	0.004091
2007-Jun-21	105	34759	3	1000	100000	10000	50000	20000	0.010654	0.003153	0.001343	0.003299
2007-Jun-21	107	32007	1	1000	100000	10000	50000	20000	0.000373	0.000216	0.000748	0.000167
2007-Jun-21	107	32112	1	1000	100000	10000	50000	20000	0.000449	0.000253	0.000869	0.000200
2007-Jun-21	107	32131	1	1000	100000	10000	50000	20000	0.000528	0.000287	0.000957	0.000235
2007-Jun-21	107	32138	1	1000	100000	10000	50000	20000	0.000350	0.000211	0.000743	0.000157
2007-Jun-21	107	32139	1	1000	100000	10000	50000	20000	0.000478	0.000267	0.000931	0.000210
2007-Jun-21	107	32140	1	1000	100000	10000	50000	20000	0.000345	0.000208	0.000733	0.000155
2007-Jun-21	107	32147	1	1000	100000	10000	50000	20000	0.000416	0.000240	0.000836	0.000185
2007-Jun-21	107	32148	1	1000	100000	10000	50000	20000	0.000489	0.000273	0.000926	0.000218
2007-Jun-21	107	32149	1	1000	100000	10000	50000	20000	0.000472	0.000265	0.000910	0.000209
2007-Jun-21	107	32157	1	1000	100000	10000	50000	20000	0.000468	0.000263	0.000917	0.000206
2007-Jun-21	107	32177	1	1000	100000	10000	50000	20000	0.000493	0.000273	0.000925	0.000219
2007-Jun-21	107	32178	1	1000	100000	10000	50000	20000	0.000483	0.000269	0.000915	0.000214
2007-Jun-21	107	32181	1	1000	100000	10000	50000	20000	0.000480	0.000266	0.000914	0.000212
2007-Jun-21	107	32185	1	1000	100000	10000	50000	20000	0.000342	0.000207	0.000732	0.000154
2007-Jun-21	107	32187	1	1000	100000	10000	50000	20000	0.000396	0.000227	0.000761	0.000179
2007-Jun-21	107	32189	1	1000	100000	10000	50000	20000	0.000496	0.000274	0.000914	0.000222
2007-Jun-21	107	32193	1	1000	100000	10000	50000	20000	0.000493	0.000274	0.000940	0.000217
2007-Jun-21	107	32666	1	1000	100000	10000	50000	20000	0.000383	0.000224	0.000779	0.000172
2007-Jun-21	107	32007	2	1000	100000	10000	50000	20000	0.000332	0.000210	0.000747	0.000161
2007-Jun-21	107	32112	2	1000	100000	10000	50000	20000	0.000398	0.000244	0.000868	0.000192

2007-Jun-21	107	32131	2	1000	100000	10000	50000	20000	0.000465	0.000275	0.000955	0.000223
2007-Jun-21	107	32138	2	1000	100000	10000	50000	20000	0.000313	0.000206	0.000742	0.000153
2007-Jun-21	107	32139	2	1000	100000	10000	50000	20000	0.000423	0.000258	0.000929	0.000202
2007-Jun-21	107	32140	2	1000	100000	10000	50000	20000	0.000309	0.000203	0.000732	0.000151
2007-Jun-21	107	32147	2	1000	100000	10000	50000	20000	0.000370	0.000233	0.000834	0.000179
2007-Jun-21	107	32148	2	1000	100000	10000	50000	20000	0.000433	0.000263	0.000924	0.000208
2007-Jun-21	107	32149	2	1000	100000	10000	50000	20000	0.000418	0.000255	0.000909	0.000201
2007-Jun-21	107	32157	2	1000	100000	10000	50000	20000	0.000415	0.000254	0.000915	0.000198
2007-Jun-21	107	32177	2	1000	100000	10000	50000	20000	0.000436	0.000262	0.000923	0.000209
2007-Jun-21	107	32178	2	1000	100000	10000	50000	20000	0.000428	0.000258	0.000914	0.000205
2007-Jun-21	107	32181	2	1000	100000	10000	50000	20000	0.000425	0.000256	0.000913	0.000203
2007-Jun-21	107	32185	2	1000	100000	10000	50000	20000	0.000307	0.000202	0.000731	0.000150
2007-Jun-21	107	32187	2	1000	100000	10000	50000	20000	0.000351	0.000218	0.000760	0.000172
2007-Jun-21	107	32189	2	1000	100000	10000	50000	20000	0.000438	0.000263	0.000912	0.000212
2007-Jun-21	107	32193	2	1000	100000	10000	50000	20000	0.000436	0.000263	0.000939	0.000209
2007-Jun-21	107	32666	2	1000	100000	10000	50000	20000	0.000341	0.000218	0.000778	0.000166
2007-Jun-21	107	32007	3	1000	100000	10000	50000	20000	0.003236	0.001058	0.000768	0.001031
2007-Jun-21	107	32112	3	1000	100000	10000	50000	20000	0.003981	0.001363	0.000892	0.001344
2007-Jun-21	107	32131	3	1000	100000	10000	50000	20000	0.004675	0.001680	0.000983	0.001670
2007-Jun-21	107	32138	3	1000	100000	10000	50000	20000	0.003000	0.000914	0.000762	0.000879
2007-Jun-21	107	32139	3	1000	100000	10000	50000	20000	0.004290	0.001449	0.000955	0.001433
2007-Jun-21	107	32140	3	1000	100000	10000	50000	20000	0.002951	0.000903	0.000752	0.000868
2007-Jun-21	107	32147	3	1000	100000	10000	50000	20000	0.003637	0.001180	0.000857	0.001154
2007-Jun-21	107	32148	3	1000	100000	10000	50000	20000	0.004298	0.001479	0.000950	0.001460
2007-Jun-21	107	32149	3	1000	100000	10000	50000	20000	0.004180	0.001427	0.000934	0.001409
2007-Jun-21	107	32157	3	1000	100000	10000	50000	20000	0.004177	0.001395	0.000941	0.001378
2007-Jun-21	107	32177	3	1000	100000	10000	50000	20000	0.004365	0.001519	0.000949	0.001505
2007-Jun-21	107	32178	3	1000	100000	10000	50000	20000	0.004281	0.001474	0.000940	0.001458
2007-Jun-21	107	32181	3	1000	100000	10000	50000	20000	0.004269	0.001476	0.000939	0.001461
2007-Jun-21	107	32185	3	1000	100000	10000	50000	20000	0.002929	0.000888	0.000751	0.000852
2007-Jun-21	107	32187	3	1000	100000	10000	50000	20000	0.003418	0.001178	0.000781	0.001152
2007-Jun-21	107	32189	3	1000	100000	10000	50000	20000	0.004344	0.001547	0.000938	0.001530
2007-Jun-21	107	32193	3	1000	100000	10000	50000	20000	0.004391	0.001511	0.000965	0.001496
2007-Jun-21	107	32666	3	1000	100000	10000	50000	20000	0.003309	0.001066	0.000800	0.001036
2007-Jun-21	109	32004	1	1000	100000	10000	50000	20000	0.000552	0.000304	0.000861	0.000260
2007-Jun-21	109	32033	1	1000	100000	10000	50000	20000	0.000437	0.000246	0.000792	0.000200
2007-Jun-21	109	32080	1	1000	100000	10000	50000	20000	0.000844	0.000440	0.001131	0.000400

2007-Jun-21	109	32082	1	1000	100000	10000	50000	20000	0.000629	0.000351	0.000943	0.000307
2007-Jun-21	109	32084	1	1000	100000	10000	50000	20000	0.000638	0.000349	0.001004	0.000305
2007-Jun-21	109	32085	1	1000	100000	10000	50000	20000	0.000646	0.000346	0.000983	0.000301
2007-Jun-21	109	32086	1	1000	100000	10000	50000	20000	0.000634	0.000350	0.000949	0.000309
2007-Jun-21	109	32092	1	1000	100000	10000	50000	20000	0.000433	0.000244	0.000786	0.000198
2007-Jun-21	109	32095	1	1000	100000	10000	50000	20000	0.000476	0.000273	0.000784	0.000232
2007-Jun-21	109	32145	1	1000	100000	10000	50000	20000	0.000389	0.000224	0.000762	0.000175
2007-Jun-21	109	32259	1	1000	100000	10000	50000	20000	0.000339	0.000202	0.000663	0.000156
2007-Jun-21	109	32260	1	1000	100000	10000	50000	20000	0.000299	0.000183	0.000616	0.000138
2007-Jun-21	109	32004	2	1000	100000	10000	50000	20000	0.000483	0.000283	0.000859	0.000241
2007-Jun-21	109	32033	2	1000	100000	10000	50000	20000	0.000386	0.000235	0.000790	0.000190
2007-Jun-21	109	32080	2	1000	100000	10000	50000	20000	0.000730	0.000402	0.001128	0.000366
2007-Jun-21	109	32082	2	1000	100000	10000	50000	20000	0.000545	0.000322	0.000941	0.000282
2007-Jun-21	109	32084	2	1000	100000	10000	50000	20000	0.000554	0.000324	0.001002	0.000283
2007-Jun-21	109	32085	2	1000	100000	10000	50000	20000	0.000563	0.000321	0.000981	0.000279
2007-Jun-21	109	32086	2	1000	100000	10000	50000	20000	0.000550	0.000323	0.000947	0.000285
2007-Jun-21	109	32092	2	1000	100000	10000	50000	20000	0.000382	0.000234	0.000785	0.000188
2007-Jun-21	109	32095	2	1000	100000	10000	50000	20000	0.000416	0.000255	0.000782	0.000217
2007-Jun-21	109	32145	2	1000	100000	10000	50000	20000	0.000346	0.000216	0.000761	0.000169
2007-Jun-21	109	32259	2	1000	100000	10000	50000	20000	0.000301	0.000194	0.000662	0.000150
2007-Jun-21	109	32260	2	1000	100000	10000	50000	20000	0.000267	0.000178	0.000615	0.000134
2007-Jun-21	109	32004	3	1000	100000	10000	50000	20000	0.004372	0.001707	0.000883	0.001681
2007-Jun-21	109	32033	3	1000	100000	10000	50000	20000	0.003705	0.001342	0.000812	0.001315
2007-Jun-21	109	32080	3	1000	100000	10000	50000	20000	0.006620	0.002852	0.001160	0.002839
2007-Jun-21	109	32082	3	1000	100000	10000	50000	20000	0.005053	0.002039	0.000968	0.002016
2007-Jun-21	109	32084	3	1000	100000	10000	50000	20000	0.005431	0.002194	0.001030	0.002180
2007-Jun-21	109	32085	3	1000	100000	10000	50000	20000	0.005247	0.002113	0.001008	0.002094
2007-Jun-21	109	32086	3	1000	100000	10000	50000	20000	0.005127	0.002114	0.000973	0.002090
2007-Jun-21	109	32092	3	1000	100000	10000	50000	20000	0.003635	0.001311	0.000806	0.001283
2007-Jun-21	109	32095	3	1000	100000	10000	50000	20000	0.003905	0.001540	0.000803	0.001508
2007-Jun-21	109	32145	3	1000	100000	10000	50000	20000	0.003376	0.001150	0.000782	0.001124
2007-Jun-21	109	32259	3	1000	100000	10000	50000	20000	0.002793	0.000930	0.000679	0.000895
2007-Jun-21	109	32260	3	1000	100000	10000	50000	20000	0.002432	0.000762	0.000631	0.000723
2007-Jun-21	111	34945	1	1000	100000	10000	50000	20000	0.003741	0.000780	0.001532	0.000683
2007-Jun-21	111	34946	1	1000	100000	10000	50000	20000	0.004244	0.001000	0.001678	0.000903
2007-Jun-21	111	34947	1	1000	100000	10000	50000	20000	0.004144	0.000949	0.001656	0.000852
2007-Jun-21	111	34948	1	1000	100000	10000	50000	20000	0.003912	0.000876	0.001571	0.000779

2007-Jun-21	111	34949	1	1000	100000	10000	50000	20000	0.005191	0.001377	0.001979	0.001275
2007-Jun-21	111	34950	1	1000	100000	10000	50000	20000	0.003937	0.000894	0.001575	0.000798
2007-Jun-21	111	34951	1	1000	100000	10000	50000	20000	0.004883	0.001306	0.001852	0.001204
2007-Jun-21	111	34952	1	1000	100000	10000	50000	20000	0.005431	0.001543	0.002008	0.001435
2007-Jun-21	111	34953	1	1000	100000	10000	50000	20000	0.004153	0.000904	0.001680	0.000806
2007-Jun-21	111	34954	1	1000	100000	10000	50000	20000	0.004087	0.000883	0.001658	0.000785
2007-Jun-21	111	34979	1	1000	100000	10000	50000	20000	0.003947	0.000901	0.001577	0.000806
2007-Jun-21	111	34981	1	1000	100000	10000	50000	20000	0.003971	0.000889	0.001597	0.000794
2007-Jun-21	111	34982	1	1000	100000	10000	50000	20000	0.004642	0.001125	0.001824	0.001029
2007-Jun-21	111	34983	1	1000	100000	10000	50000	20000	0.004180	0.000915	0.001690	0.000816
2007-Jun-21	111	34984	1	1000	100000	10000	50000	20000	0.004201	0.000922	0.001694	0.000822
2007-Jun-21	111	34985	1	1000	100000	10000	50000	20000	0.004331	0.000996	0.001726	0.000898
2007-Jun-21	111	34986	1	1000	100000	10000	50000	20000	0.003792	0.000786	0.001556	0.000688
2007-Jun-21	111	34987	1	1000	100000	10000	50000	20000	0.004188	0.000889	0.001707	0.000789
2007-Jun-21	111	34988	1	1000	100000	10000	50000	20000	0.004381	0.000942	0.001781	0.000842
2007-Jun-21	111	34945	2	1000	100000	10000	50000	20000	0.002721	0.000520	0.001526	0.000420
2007-Jun-21	111	34946	2	1000	100000	10000	50000	20000	0.003031	0.000632	0.001671	0.000537
2007-Jun-21	111	34947	2	1000	100000	10000	50000	20000	0.002969	0.000606	0.001649	0.000509
2007-Jun-21	111	34948	2	1000	100000	10000	50000	20000	0.002819	0.000567	0.001565	0.000471
2007-Jun-21	111	34949	2	1000	100000	10000	50000	20000	0.003633	0.000829	0.001970	0.000738
2007-Jun-21	111	34950	2	1000	100000	10000	50000	20000	0.002831	0.000575	0.001568	0.000480
2007-Jun-21	111	34951	2	1000	100000	10000	50000	20000	0.003427	0.000790	0.001844	0.000701
2007-Jun-21	111	34952	2	1000	100000	10000	50000	20000	0.003776	0.000914	0.001999	0.000828
2007-Jun-21	111	34953	2	1000	100000	10000	50000	20000	0.002992	0.000587	0.001672	0.000485
2007-Jun-21	111	34954	2	1000	100000	10000	50000	20000	0.002949	0.000576	0.001651	0.000474
2007-Jun-21	111	34979	2	1000	100000	10000	50000	20000	0.002836	0.000579	0.001571	0.000484
2007-Jun-21	111	34981	2	1000	100000	10000	50000	20000	0.002856	0.000574	0.001590	0.000477
2007-Jun-21	111	34982	2	1000	100000	10000	50000	20000	0.003284	0.000697	0.001816	0.000602
2007-Jun-21	111	34983	2	1000	100000	10000	50000	20000	0.003010	0.000593	0.001683	0.000491
2007-Jun-21	111	34984	2	1000	100000	10000	50000	20000	0.003025	0.000597	0.001686	0.000495
2007-Jun-21	111	34985	2	1000	100000	10000	50000	20000	0.003095	0.000632	0.001718	0.000534
2007-Jun-21	111	34986	2	1000	100000	10000	50000	20000	0.002758	0.000525	0.001549	0.000423
2007-Jun-21	111	34987	2	1000	100000	10000	50000	20000	0.003025	0.000583	0.001700	0.000477
2007-Jun-21	111	34988	2	1000	100000	10000	50000	20000	0.003153	0.000612	0.001774	0.000505
2007-Jun-21	111	34945	3	1000	100000	10000	50000	20000	0.013912	0.004788	0.001551	0.005113
2007-Jun-21	111	34946	3	1000	100000	10000	50000	20000	0.016053	0.006029	0.001699	0.006419
2007-Jun-21	111	34947	3	1000	100000	10000	50000	20000	0.015676	0.005787	0.001676	0.006170

2007-Jun-21	111	34948	3	1000	100000	10000	50000	20000	0.014635	0.005275	0.001590	0.005619
2007-Jun-21	111	34949	3	1000	100000	10000	50000	20000	0.020084	0.008219	0.002002	0.008740
2007-Jun-21	111	34950	3	1000	100000	10000	50000	20000	0.014733	0.005355	0.001594	0.005700
2007-Jun-21	111	34951	3	1000	100000	10000	50000	20000	0.018640	0.007580	0.001874	0.008036
2007-Jun-21	111	34952	3	1000	100000	10000	50000	20000	0.020757	0.008763	0.002031	0.009265
2007-Jun-21	111	34953	3	1000	100000	10000	50000	20000	0.015676	0.005632	0.001700	0.006015
2007-Jun-21	111	34954	3	1000	100000	10000	50000	20000	0.015423	0.005507	0.001679	0.005888
2007-Jun-21	111	34979	3	1000	100000	10000	50000	20000	0.014785	0.005398	0.001596	0.005743
2007-Jun-21	111	34981	3	1000	100000	10000	50000	20000	0.014932	0.005418	0.001616	0.005773
2007-Jun-21	111	34982	3	1000	100000	10000	50000	20000	0.017892	0.006960	0.001846	0.007414
2007-Jun-21	111	34983	3	1000	100000	10000	50000	20000	0.015814	0.005706	0.001710	0.006099
2007-Jun-21	111	34984	3	1000	100000	10000	50000	20000	0.015863	0.005727	0.001714	0.006117
2007-Jun-21	111	34985	3	1000	100000	10000	50000	20000	0.016449	0.006130	0.001746	0.006533
2007-Jun-21	111	34986	3	1000	100000	10000	50000	20000	0.014112	0.004849	0.001575	0.005179
2007-Jun-21	111	34987	3	1000	100000	10000	50000	20000	0.015841	0.005626	0.001728	0.006020
2007-Jun-21	111	34988	3	1000	100000	10000	50000	20000	0.016706	0.006025	0.001803	0.006454
2007-Jun-21	113	32530	1	1000	100000	10000	50000	20000	0.001478	0.000747	0.001671	0.000733
2007-Jun-21	113	32561	1	1000	100000	10000	50000	20000	0.002144	0.001106	0.001992	0.001104
2007-Jun-21	113	32562	1	1000	100000	10000	50000	20000	0.002226	0.001135	0.002067	0.001142
2007-Jun-21	113	32563	1	1000	100000	10000	50000	20000	0.002047	0.001032	0.002016	0.001037
2007-Jun-21	113	32565	1	1000	100000	10000	50000	20000	0.001019	0.000502	0.001350	0.000473
2007-Jun-21	113	32566	1	1000	100000	10000	50000	20000	0.001878	0.000948	0.001926	0.000946
2007-Jun-21	113	32570	1	1000	100000	10000	50000	20000	0.000664	0.000344	0.001120	0.000295
2007-Jun-21	113	32571	1	1000	100000	10000	50000	20000	0.001128	0.000572	0.001483	0.000545
2007-Jun-21	113	32572	1	1000	100000	10000	50000	20000	0.001082	0.000550	0.001458	0.000520
2007-Jun-21	113	32583	1	1000	100000	10000	50000	20000	0.000912	0.000470	0.001364	0.000431
2007-Jun-21	113	32530	2	1000	100000	10000	50000	20000	0.001259	0.000664	0.001667	0.000656
2007-Jun-21	113	32561	2	1000	100000	10000	50000	20000	0.001813	0.000952	0.001988	0.000966
2007-Jun-21	113	32562	2	1000	100000	10000	50000	20000	0.001883	0.000981	0.002062	0.001004
2007-Jun-21	113	32563	2	1000	100000	10000	50000	20000	0.001737	0.000902	0.002012	0.000919
2007-Jun-21	113	32565	2	1000	100000	10000	50000	20000	0.000878	0.000458	0.001347	0.000433
2007-Jun-21	113	32566	2	1000	100000	10000	50000	20000	0.001595	0.000832	0.001922	0.000840
2007-Jun-21	113	32570	2	1000	100000	10000	50000	20000	0.000581	0.000325	0.001118	0.000278
2007-Jun-21	113	32571	2	1000	100000	10000	50000	20000	0.000968	0.000519	0.001480	0.000495
2007-Jun-21	113	32572	2	1000	100000	10000	50000	20000	0.000930	0.000501	0.001455	0.000474
2007-Jun-21	113	32583	2	1000	100000	10000	50000	20000	0.000788	0.000435	0.001361	0.000397
2007-Jun-21	113	32530	3	1000	100000	10000	50000	20000	0.011578	0.005549	0.001714	0.005598

2007-Jun-21	113	32561	3	1000	100000	10000	50000	20000	0.014763	0.007416	0.002041	0.007441
2007-Jun-21	113	32562	3	1000	100000	10000	50000	20000	0.015569	0.007927	0.002117	0.007953
2007-Jun-21	113	32563	3	1000	100000	10000	50000	20000	0.014969	0.007521	0.002066	0.007564
2007-Jun-21	113	32565	3	1000	100000	10000	50000	20000	0.008599	0.003820	0.001386	0.003880
2007-Jun-21	113	32566	3	1000	100000	10000	50000	20000	0.013976	0.006914	0.001974	0.006959
2007-Jun-21	113	32570	3	1000	100000	10000	50000	20000	0.006024	0.002302	0.001151	0.002335
2007-Jun-21	113	32571	3	1000	100000	10000	50000	20000	0.009543	0.004320	0.001522	0.004377
2007-Jun-21	113	32572	3	1000	100000	10000	50000	20000	0.009262	0.004132	0.001497	0.004188
2007-Jun-21	113	32583	3	1000	100000	10000	50000	20000	0.008170	0.003453	0.001401	0.003505
2007-Jun-21	115	34223	1	1000	100000	10000	50000	20000	0.003296	0.000766	0.001637	0.000669
2007-Jun-21	115	34229	1	1000	100000	10000	50000	20000	0.002986	0.000682	0.001491	0.000591
2007-Jun-21	115	34230	1	1000	100000	10000	50000	20000	0.002534	0.000544	0.001277	0.000458
2007-Jun-21	115	34231	1	1000	100000	10000	50000	20000	0.002755	0.000598	0.001395	0.000510
2007-Jun-21	115	34232	1	1000	100000	10000	50000	20000	0.002965	0.000679	0.001483	0.000589
2007-Jun-21	115	34233	1	1000	100000	10000	50000	20000	0.002931	0.000676	0.001462	0.000587
2007-Jun-21	115	34234	1	1000	100000	10000	50000	20000	0.002606	0.000555	0.001318	0.000468
2007-Jun-21	115	34235	1	1000	100000	10000	50000	20000	0.002969	0.000686	0.001484	0.000597
2007-Jun-21	115	34236	1	1000	100000	10000	50000	20000	0.002875	0.000702	0.001390	0.000607
2007-Jun-21	115	34237	1	1000	100000	10000	50000	20000	0.002618	0.000552	0.001329	0.000463
2007-Jun-21	115	34238	1	1000	100000	10000	50000	20000	0.003089	0.000729	0.001536	0.000638
2007-Jun-21	115	34239	1	1000	100000	10000	50000	20000	0.002778	0.000612	0.001402	0.000524
2007-Jun-21	115	34240	1	1000	100000	10000	50000	20000	0.003234	0.000779	0.001606	0.000689
2007-Jun-21	115	34241	1	1000	100000	10000	50000	20000	0.003062	0.000697	0.001537	0.000606
2007-Jun-21	115	34242	1	1000	100000	10000	50000	20000	0.002984	0.000674	0.001505	0.000585
2007-Jun-21	115	34272	1	1000	100000	10000	50000	20000	0.003094	0.000723	0.001541	0.000631
2007-Jun-21	115	34274	1	1000	100000	10000	50000	20000	0.003081	0.000709	0.001536	0.000615
2007-Jun-21	115	34275	1	1000	100000	10000	50000	20000	0.003131	0.000730	0.001561	0.000637
2007-Jun-21	115	34276	1	1000	100000	10000	50000	20000	0.002532	0.000544	0.001276	0.000457
2007-Jun-21	115	34277	1	1000	100000	10000	50000	20000	0.002867	0.000643	0.001445	0.000555
2007-Jun-21	115	34278	1	1000	100000	10000	50000	20000	0.002802	0.000632	0.001403	0.000545
2007-Jun-21	115	34284	1	1000	100000	10000	50000	20000	0.003054	0.000701	0.001523	0.000607
2007-Jun-21	115	34285	1	1000	100000	10000	50000	20000	0.002997	0.000689	0.001500	0.000596
2007-Jun-21	115	34286	1	1000	100000	10000	50000	20000	0.003094	0.000678	0.001559	0.000580
2007-Jun-21	115	34287	1	1000	100000	10000	50000	20000	0.003183	0.000712	0.001599	0.000615
2007-Jun-21	115	34288	1	1000	100000	10000	50000	20000	0.003120	0.000661	0.001579	0.000561
2007-Jun-21	115	34289	1	1000	100000	10000	50000	20000	0.003159	0.000687	0.001595	0.000588
2007-Jun-21	115	34292	1	1000	100000	10000	50000	20000	0.003118	0.000721	0.001562	0.000627

2007-Jun-21	115	34293	1	1000	100000	10000	50000	20000	0.003041	0.000675	0.001530	0.000580
2007-Jun-21	115	34295	1	1000	100000	10000	50000	20000	0.003231	0.000746	0.001607	0.000649
2007-Jun-21	115	34223	2	1000	100000	10000	50000	20000	0.002698	0.000609	0.001633	0.000517
2007-Jun-21	115	34229	2	1000	100000	10000	50000	20000	0.002450	0.000545	0.001487	0.000459
2007-Jun-21	115	34230	2	1000	100000	10000	50000	20000	0.002095	0.000445	0.001273	0.000362
2007-Jun-21	115	34231	2	1000	100000	10000	50000	20000	0.002271	0.000486	0.001391	0.000400
2007-Jun-21	115	34232	2	1000	100000	10000	50000	20000	0.002431	0.000542	0.001479	0.000457
2007-Jun-21	115	34233	2	1000	100000	10000	50000	20000	0.002402	0.000539	0.001458	0.000455
2007-Jun-21	115	34234	2	1000	100000	10000	50000	20000	0.002154	0.000454	0.001315	0.000370
2007-Jun-21	115	34235	2	1000	100000	10000	50000	20000	0.002433	0.000547	0.001480	0.000462
2007-Jun-21	115	34236	2	1000	100000	10000	50000	20000	0.002356	0.000554	0.001386	0.000469
2007-Jun-21	115	34237	2	1000	100000	10000	50000	20000	0.002166	0.000452	0.001325	0.000366
2007-Jun-21	115	34238	2	1000	100000	10000	50000	20000	0.002526	0.000577	0.001532	0.000492
2007-Jun-21	115	34239	2	1000	100000	10000	50000	20000	0.002286	0.000494	0.001398	0.000410
2007-Jun-21	115	34240	2	1000	100000	10000	50000	20000	0.002636	0.000613	0.001601	0.000529
2007-Jun-21	115	34241	2	1000	100000	10000	50000	20000	0.002511	0.000557	0.001533	0.000470
2007-Jun-21	115	34242	2	1000	100000	10000	50000	20000	0.002448	0.000540	0.001501	0.000454
2007-Jun-21	115	34272	2	1000	100000	10000	50000	20000	0.002532	0.000574	0.001537	0.000488
2007-Jun-21	115	34274	2	1000	100000	10000	50000	20000	0.002526	0.000566	0.001532	0.000477
2007-Jun-21	115	34275	2	1000	100000	10000	50000	20000	0.002563	0.000580	0.001557	0.000492
2007-Jun-21	115	34276	2	1000	100000	10000	50000	20000	0.002094	0.000444	0.001273	0.000361
2007-Jun-21	115	34277	2	1000	100000	10000	50000	20000	0.002355	0.000516	0.001442	0.000432
2007-Jun-21	115	34278	2	1000	100000	10000	50000	20000	0.002302	0.000508	0.001399	0.000425
2007-Jun-21	115	34284	2	1000	100000	10000	50000	20000	0.002505	0.000560	0.001519	0.000471
2007-Jun-21	115	34285	2	1000	100000	10000	50000	20000	0.002458	0.000550	0.001496	0.000463
2007-Jun-21	115	34286	2	1000	100000	10000	50000	20000	0.002548	0.000548	0.001554	0.000455
2007-Jun-21	115	34287	2	1000	100000	10000	50000	20000	0.002614	0.000572	0.001595	0.000479
2007-Jun-21	115	34288	2	1000	100000	10000	50000	20000	0.002577	0.000540	0.001575	0.000442
2007-Jun-21	115	34289	2	1000	100000	10000	50000	20000	0.002603	0.000557	0.001591	0.000461
2007-Jun-21	115	34292	2	1000	100000	10000	50000	20000	0.002554	0.000574	0.001558	0.000486
2007-Jun-21	115	34293	2	1000	100000	10000	50000	20000	0.002501	0.000544	0.001526	0.000453
2007-Jun-21	115	34295	2	1000	100000	10000	50000	20000	0.002647	0.000594	0.001603	0.000503
2007-Jun-21	115	34223	3	1000	100000	10000	50000	20000	0.016589	0.006852	0.001662	0.007123
2007-Jun-21	115	34229	3	1000	100000	10000	50000	20000	0.014944	0.006089	0.001513	0.006335
2007-Jun-21	115	34230	3	1000	100000	10000	50000	20000	0.012236	0.004681	0.001296	0.004867
2007-Jun-21	115	34231	3	1000	100000	10000	50000	20000	0.013672	0.005389	0.001416	0.005618
2007-Jun-21	115	34232	3	1000	100000	10000	50000	20000	0.014911	0.006103	0.001506	0.006348

2007-Jun-21	115	34233	3	1000	100000	10000	50000	20000	0.014693	0.006023	0.001483	0.006258
2007-Jun-21	115	34234	3	1000	100000	10000	50000	20000	0.012703	0.004882	0.001338	0.005088
2007-Jun-21	115	34235	3	1000	100000	10000	50000	20000	0.014946	0.006143	0.001506	0.006387
2007-Jun-21	115	34236	3	1000	100000	10000	50000	20000	0.013776	0.005595	0.001410	0.005775
2007-Jun-21	115	34237	3	1000	100000	10000	50000	20000	0.012769	0.004881	0.001349	0.005093
2007-Jun-21	115	34238	3	1000	100000	10000	50000	20000	0.015629	0.006521	0.001559	0.006775
2007-Jun-21	115	34239	3	1000	100000	10000	50000	20000	0.013834	0.005509	0.001423	0.005740
2007-Jun-21	115	34240	3	1000	100000	10000	50000	20000	0.016608	0.007083	0.001629	0.007357
2007-Jun-21	115	34241	3	1000	100000	10000	50000	20000	0.015494	0.006357	0.001560	0.006619
2007-Jun-21	115	34242	3	1000	100000	10000	50000	20000	0.015129	0.006187	0.001528	0.006445
2007-Jun-21	115	34272	3	1000	100000	10000	50000	20000	0.015615	0.006476	0.001564	0.006728
2007-Jun-21	115	34274	3	1000	100000	10000	50000	20000	0.015412	0.006299	0.001559	0.006547
2007-Jun-21	115	34275	3	1000	100000	10000	50000	20000	0.015824	0.006559	0.001584	0.006816
2007-Jun-21	115	34276	3	1000	100000	10000	50000	20000	0.012235	0.004680	0.001296	0.004867
2007-Jun-21	115	34277	3	1000	100000	10000	50000	20000	0.014438	0.005854	0.001467	0.006095
2007-Jun-21	115	34278	3	1000	100000	10000	50000	20000	0.013918	0.005602	0.001424	0.005822
2007-Jun-21	115	34284	3	1000	100000	10000	50000	20000	0.015222	0.006190	0.001546	0.006435
2007-Jun-21	115	34285	3	1000	100000	10000	50000	20000	0.015025	0.006136	0.001523	0.006380
2007-Jun-21	115	34286	3	1000	100000	10000	50000	20000	0.015369	0.006096	0.001582	0.006352
2007-Jun-21	115	34287	3	1000	100000	10000	50000	20000	0.015979	0.006455	0.001623	0.006727
2007-Jun-21	115	34288	3	1000	100000	10000	50000	20000	0.015387	0.005968	0.001603	0.006234
2007-Jun-21	115	34289	3	1000	100000	10000	50000	20000	0.015733	0.006234	0.001619	0.006500
2007-Jun-21	115	34292	3	1000	100000	10000	50000	20000	0.015780	0.006512	0.001585	0.006775
2007-Jun-21	115	34293	3	1000	100000	10000	50000	20000	0.015172	0.006073	0.001553	0.006330
2007-Jun-21	115	34295	3	1000	100000	10000	50000	20000	0.016209	0.006657	0.001631	0.006919
2007-Jun-21	117	32701	1	1000	100000	10000	50000	20000	0.002303	0.000382	0.001189	0.000275
2007-Jun-21	117	32707	1	1000	100000	10000	50000	20000	0.002395	0.000409	0.001232	0.000301
2007-Jun-21	117	32708	1	1000	100000	10000	50000	20000	0.002361	0.000400	0.001215	0.000293
2007-Jun-21	117	32714	1	1000	100000	10000	50000	20000	0.002232	0.000373	0.001150	0.000268
2007-Jun-21	117	32715	1	1000	100000	10000	50000	20000	0.002264	0.000378	0.001166	0.000272
2007-Jun-21	117	32716	1	1000	100000	10000	50000	20000	0.002264	0.000378	0.001166	0.000272
2007-Jun-21	117	32718	1	1000	100000	10000	50000	20000	0.002151	0.000361	0.001106	0.000258
2007-Jun-21	117	32719	1	1000	100000	10000	50000	20000	0.002151	0.000361	0.001106	0.000258
2007-Jun-21	117	32730	1	1000	100000	10000	50000	20000	0.002248	0.000375	0.001157	0.000270
2007-Jun-21	117	32732	1	1000	100000	10000	50000	20000	0.002226	0.000388	0.001139	0.000287
2007-Jun-21	117	32733	1	1000	100000	10000	50000	20000	0.002309	0.000395	0.001188	0.000289
2007-Jun-21	117	32746	1	1000	100000	10000	50000	20000	0.002201	0.000363	0.001135	0.000257

2007-Jun-21	117	32747	1	1000	100000	10000	50000	20000	0.002347	0.000401	0.001205	0.000295
2007-Jun-21	117	32750	1	1000	100000	10000	50000	20000	0.002323	0.000393	0.001196	0.000287
2007-Jun-21	117	32752	1	1000	100000	10000	50000	20000	0.002399	0.000403	0.001236	0.000295
2007-Jun-21	117	32762	1	1000	100000	10000	50000	20000	0.002362	0.000409	0.001211	0.000303
2007-Jun-21	117	32765	1	1000	100000	10000	50000	20000	0.002299	0.000395	0.001180	0.000289
2007-Jun-21	117	32766	1	1000	100000	10000	50000	20000	0.002242	0.000400	0.001142	0.000297
2007-Jun-21	117	32771	1	1000	100000	10000	50000	20000	0.002256	0.000386	0.001159	0.000283
2007-Jun-21	117	32772	1	1000	100000	10000	50000	20000	0.002530	0.000477	0.001285	0.000373
2007-Jun-21	117	32773	1	1000	100000	10000	50000	20000	0.002212	0.000376	0.001137	0.000273
2007-Jun-21	117	32779	1	1000	100000	10000	50000	20000	0.002363	0.000398	0.001219	0.000290
2007-Jun-21	117	32791	1	1000	100000	10000	50000	20000	0.002399	0.000403	0.001236	0.000295
2007-Jun-21	117	32795	1	1000	100000	10000	50000	20000	0.002144	0.000357	0.001105	0.000254
2007-Jun-21	117	32799	1	1000	100000	10000	50000	20000	0.002239	0.000375	0.001154	0.000270
2007-Jun-21	117	32701	2	1000	100000	10000	50000	20000	0.001956	0.000345	0.001186	0.000238
2007-Jun-21	117	32707	2	1000	100000	10000	50000	20000	0.002028	0.000365	0.001229	0.000257
2007-Jun-21	117	32708	2	1000	100000	10000	50000	20000	0.002001	0.000358	0.001212	0.000251
2007-Jun-21	117	32714	2	1000	100000	10000	50000	20000	0.001897	0.000337	0.001148	0.000232
2007-Jun-21	117	32715	2	1000	100000	10000	50000	20000	0.001924	0.000341	0.001163	0.000235
2007-Jun-21	117	32716	2	1000	100000	10000	50000	20000	0.001924	0.000341	0.001163	0.000235
2007-Jun-21	117	32718	2	1000	100000	10000	50000	20000	0.001828	0.000326	0.001103	0.000223
2007-Jun-21	117	32719	2	1000	100000	10000	50000	20000	0.001828	0.000326	0.001103	0.000223
2007-Jun-21	117	32730	2	1000	100000	10000	50000	20000	0.001910	0.000339	0.001155	0.000233
2007-Jun-21	117	32732	2	1000	100000	10000	50000	20000	0.001884	0.000345	0.001136	0.000244
2007-Jun-21	117	32733	2	1000	100000	10000	50000	20000	0.001956	0.000353	0.001185	0.000247
2007-Jun-21	117	32746	2	1000	100000	10000	50000	20000	0.001873	0.000330	0.001133	0.000224
2007-Jun-21	117	32747	2	1000	100000	10000	50000	20000	0.001988	0.000357	0.001203	0.000252
2007-Jun-21	117	32750	2	1000	100000	10000	50000	20000	0.001971	0.000353	0.001194	0.000246
2007-Jun-21	117	32752	2	1000	100000	10000	50000	20000	0.002034	0.000362	0.001233	0.000253
2007-Jun-21	117	32762	2	1000	100000	10000	50000	20000	0.001999	0.000364	0.001208	0.000258
2007-Jun-21	117	32765	2	1000	100000	10000	50000	20000	0.001948	0.000353	0.001177	0.000247
2007-Jun-21	117	32766	2	1000	100000	10000	50000	20000	0.001895	0.000353	0.001140	0.000252
2007-Jun-21	117	32771	2	1000	100000	10000	50000	20000	0.001912	0.000345	0.001156	0.000242
2007-Jun-21	117	32772	2	1000	100000	10000	50000	20000	0.002124	0.000410	0.001282	0.000307
2007-Jun-21	117	32773	2	1000	100000	10000	50000	20000	0.001877	0.000338	0.001135	0.000235
2007-Jun-21	117	32779	2	1000	100000	10000	50000	20000	0.002004	0.000357	0.001216	0.000249
2007-Jun-21	117	32791	2	1000	100000	10000	50000	20000	0.002034	0.000362	0.001233	0.000253
2007-Jun-21	117	32795	2	1000	100000	10000	50000	20000	0.001824	0.000324	0.001102	0.000221

2007-Jun-21	117	32799	2	1000	100000	10000	50000	20000	0.001902	0.000338	0.001151	0.000233
2007-Jun-21	117	32701	3	1000	100000	10000	50000	20000	0.009318	0.002624	0.001207	0.002734
2007-Jun-21	117	32707	3	1000	100000	10000	50000	20000	0.009838	0.002890	0.001251	0.003009
2007-Jun-21	117	32708	3	1000	100000	10000	50000	20000	0.009639	0.002793	0.001233	0.002908
2007-Jun-21	117	32714	3	1000	100000	10000	50000	20000	0.008924	0.002477	0.001168	0.002569
2007-Jun-21	117	32715	3	1000	100000	10000	50000	20000	0.009079	0.002530	0.001184	0.002628
2007-Jun-21	117	32716	3	1000	100000	10000	50000	20000	0.009079	0.002530	0.001184	0.002628
2007-Jun-21	117	32718	3	1000	100000	10000	50000	20000	0.008520	0.002333	0.001123	0.002413
2007-Jun-21	117	32719	3	1000	100000	10000	50000	20000	0.008520	0.002333	0.001123	0.002413
2007-Jun-21	117	32730	3	1000	100000	10000	50000	20000	0.008998	0.002504	0.001175	0.002598
2007-Jun-21	117	32732	3	1000	100000	10000	50000	20000	0.009019	0.002633	0.001156	0.002722
2007-Jun-21	117	32733	3	1000	100000	10000	50000	20000	0.009392	0.002721	0.001206	0.002823
2007-Jun-21	117	32746	3	1000	100000	10000	50000	20000	0.008741	0.002373	0.001153	0.002465
2007-Jun-21	117	32747	3	1000	100000	10000	50000	20000	0.009635	0.002830	0.001224	0.002946
2007-Jun-21	117	32750	3	1000	100000	10000	50000	20000	0.009449	0.002716	0.001215	0.002825
2007-Jun-21	117	32752	3	1000	100000	10000	50000	20000	0.009831	0.002849	0.001255	0.002973
2007-Jun-21	117	32762	3	1000	100000	10000	50000	20000	0.009666	0.002850	0.001229	0.002959
2007-Jun-21	117	32765	3	1000	100000	10000	50000	20000	0.009305	0.002682	0.001198	0.002781
2007-Jun-21	117	32766	3	1000	100000	10000	50000	20000	0.009067	0.002678	0.001159	0.002761
2007-Jun-21	117	32771	3	1000	100000	10000	50000	20000	0.009195	0.002672	0.001177	0.002776
2007-Jun-21	117	32772	3	1000	100000	10000	50000	20000	0.010779	0.003532	0.001305	0.003660
2007-Jun-21	117	32773	3	1000	100000	10000	50000	20000	0.008906	0.002527	0.001155	0.002621
2007-Jun-21	117	32779	3	1000	100000	10000	50000	20000	0.009665	0.002793	0.001238	0.002912
2007-Jun-21	117	32791	3	1000	100000	10000	50000	20000	0.009831	0.002849	0.001255	0.002973
2007-Jun-21	117	32795	3	1000	100000	10000	50000	20000	0.008487	0.002305	0.001122	0.002387
2007-Jun-21	117	32799	3	1000	100000	10000	50000	20000	0.008994	0.002514	0.001171	0.002612
2007-Jun-21	119	32162	1	1000	100000	10000	50000	20000	0.002098	0.000340	0.001038	0.000241
2007-Jun-21	119	33513	1	1000	100000	10000	50000	20000	0.002386	0.000406	0.001179	0.000304
2007-Jun-21	119	33514	1	1000	100000	10000	50000	20000	0.002544	0.000442	0.001261	0.000337
2007-Jun-21	119	33521	1	1000	100000	10000	50000	20000	0.002344	0.000403	0.001158	0.000302
2007-Jun-21	119	33538	1	1000	100000	10000	50000	20000	0.002436	0.000429	0.001198	0.000327
2007-Jun-21	119	33585	1	1000	100000	10000	50000	20000	0.002103	0.000345	0.001049	0.000248
2007-Jun-21	119	33597	1	1000	100000	10000	50000	20000	0.002379	0.000402	0.001179	0.000300
2007-Jun-21	119	34484	1	1000	100000	10000	50000	20000	0.002297	0.000382	0.001138	0.000280
2007-Jun-21	119	34785	1	1000	100000	10000	50000	20000	0.002547	0.000444	0.001259	0.000339
2007-Jun-21	119	32162	2	1000	100000	10000	50000	20000	0.001777	0.000309	0.001035	0.000209
2007-Jun-21	119	33513	2	1000	100000	10000	50000	20000	0.002007	0.000359	0.001176	0.000257

2007-Jun-21	119	33514	2	1000	100000	10000	50000	20000	0.002134	0.000386	0.001258	0.000282
2007-Jun-21	119	33521	2	1000	100000	10000	50000	20000	0.001972	0.000356	0.001156	0.000255
2007-Jun-21	119	33538	2	1000	100000	10000	50000	20000	0.002043	0.000374	0.001195	0.000273
2007-Jun-21	119	33585	2	1000	100000	10000	50000	20000	0.001777	0.000312	0.001046	0.000214
2007-Jun-21	119	33597	2	1000	100000	10000	50000	20000	0.002002	0.000356	0.001176	0.000254
2007-Jun-21	119	34484	2	1000	100000	10000	50000	20000	0.001937	0.000341	0.001136	0.000239
2007-Jun-21	119	34785	2	1000	100000	10000	50000	20000	0.002137	0.000388	0.001256	0.000283
2007-Jun-21	119	32162	3	1000	100000	10000	50000	20000	0.007896	0.002111	0.001053	0.002181
2007-Jun-21	119	33513	3	1000	100000	10000	50000	20000	0.009517	0.002885	0.001196	0.002998
2007-Jun-21	119	33514	3	1000	100000	10000	50000	20000	0.010423	0.003310	0.001280	0.003447
2007-Jun-21	119	33521	3	1000	100000	10000	50000	20000	0.009318	0.002819	0.001176	0.002925
2007-Jun-21	119	33538	3	1000	100000	10000	50000	20000	0.009837	0.003097	0.001215	0.003213
2007-Jun-21	119	33585	3	1000	100000	10000	50000	20000	0.008099	0.002265	0.001065	0.002342
2007-Jun-21	119	33597	3	1000	100000	10000	50000	20000	0.009505	0.002872	0.001196	0.002987
2007-Jun-21	119	34484	3	1000	100000	10000	50000	20000	0.009026	0.002633	0.001155	0.002736
2007-Jun-21	119	34785	3	1000	100000	10000	50000	20000	0.010400	0.003294	0.001278	0.003430
2007-Jun-21	121	32008	1	1000	100000	10000	50000	20000	0.000396	0.000226	0.000738	0.000181
2007-Jun-21	121	32060	1	1000	100000	10000	50000	20000	0.000165	0.000112	0.000395	0.000078
2007-Jun-21	121	32062	1	1000	100000	10000	50000	20000	0.000208	0.000136	0.000463	0.000098
2007-Jun-21	121	32064	1	1000	100000	10000	50000	20000	0.000279	0.000169	0.000580	0.000128
2007-Jun-21	121	32071	1	1000	100000	10000	50000	20000	0.000296	0.000177	0.000591	0.000136
2007-Jun-21	121	32094	1	1000	100000	10000	50000	20000	0.000274	0.000169	0.000579	0.000126
2007-Jun-21	121	32008	2	1000	100000	10000	50000	20000	0.000351	0.000217	0.000737	0.000173
2007-Jun-21	121	32060	2	1000	100000	10000	50000	20000	0.000150	0.000111	0.000395	0.000077
2007-Jun-21	121	32062	2	1000	100000	10000	50000	20000	0.000187	0.000133	0.000462	0.000096
2007-Jun-21	121	32064	2	1000	100000	10000	50000	20000	0.000249	0.000165	0.000579	0.000124
2007-Jun-21	121	32071	2	1000	100000	10000	50000	20000	0.000264	0.000171	0.000590	0.000131
2007-Jun-21	121	32094	2	1000	100000	10000	50000	20000	0.000245	0.000164	0.000578	0.000123
2007-Jun-21	121	32008	3	1000	100000	10000	50000	20000	0.003333	0.001163	0.000757	0.001137
2007-Jun-21	121	32060	3	1000	100000	10000	50000	20000	0.001312	0.000359	0.000405	0.000321
2007-Jun-21	121	32062	3	1000	100000	10000	50000	20000	0.001628	0.000477	0.000473	0.000435
2007-Jun-21	121	32064	3	1000	100000	10000	50000	20000	0.002337	0.000740	0.000594	0.000707
2007-Jun-21	121	32071	3	1000	100000	10000	50000	20000	0.002471	0.000818	0.000606	0.000787
2007-Jun-21	121	32094	3	1000	100000	10000	50000	20000	0.002284	0.000715	0.000593	0.000679
2007-Jun-21	123	32347	1	1000	100000	10000	50000	20000	0.000367	0.000207	0.000631	0.000171
2007-Jun-21	123	32348	1	1000	100000	10000	50000	20000	0.000327	0.000188	0.000587	0.000152
2007-Jun-21	123	32356	1	1000	100000	10000	50000	20000	0.000368	0.000212	0.000637	0.000173

2007-Jun-21	123	32357	1	1000	100000	10000	50000	20000	0.000238	0.000145	0.000491	0.000110
2007-Jun-21	123	32359	1	1000	100000	10000	50000	20000	0.000499	0.000284	0.000815	0.000242
2007-Jun-21	123	32347	2	1000	100000	10000	50000	20000	0.000323	0.000196	0.000630	0.000161
2007-Jun-21	123	32348	2	1000	100000	10000	50000	20000	0.000289	0.000179	0.000586	0.000144
2007-Jun-21	123	32356	2	1000	100000	10000	50000	20000	0.000324	0.000200	0.000636	0.000163
2007-Jun-21	123	32357	2	1000	100000	10000	50000	20000	0.000212	0.000141	0.000490	0.000106
2007-Jun-21	123	32359	2	1000	100000	10000	50000	20000	0.000435	0.000265	0.000813	0.000225
2007-Jun-21	123	32347	3	1000	100000	10000	50000	20000	0.003002	0.001126	0.000647	0.001101
2007-Jun-21	123	32348	3	1000	100000	10000	50000	20000	0.002681	0.000974	0.000601	0.000948
2007-Jun-21	123	32356	3	1000	100000	10000	50000	20000	0.002923	0.001065	0.000653	0.001035
2007-Jun-21	123	32357	3	1000	100000	10000	50000	20000	0.001972	0.000635	0.000503	0.000605
2007-Jun-21	123	32359	3	1000	100000	10000	50000	20000	0.004057	0.001559	0.000836	0.001532
2007-Jun-21	125	32026	1	1000	100000	10000	50000	20000	0.000240	0.000156	0.000550	0.000112
2007-Jun-21	125	32054	1	1000	100000	10000	50000	20000	0.000325	0.000197	0.000690	0.000147
2007-Jun-21	125	32083	1	1000	100000	10000	50000	20000	0.000193	0.000132	0.000466	0.000092
2007-Jun-21	125	32697	1	1000	100000	10000	50000	20000	0.000301	0.000187	0.000651	0.000138
2007-Jun-21	125	32026	2	1000	100000	10000	50000	20000	0.000217	0.000154	0.000550	0.000110
2007-Jun-21	125	32054	2	1000	100000	10000	50000	20000	0.000291	0.000192	0.000689	0.000143
2007-Jun-21	125	32083	2	1000	100000	10000	50000	20000	0.000175	0.000131	0.000465	0.000091
2007-Jun-21	125	32697	2	1000	100000	10000	50000	20000	0.000270	0.000182	0.000650	0.000134
2007-Jun-21	125	32026	3	1000	100000	10000	50000	20000	0.001969	0.000560	0.000564	0.000516
2007-Jun-21	125	32054	3	1000	100000	10000	50000	20000	0.002784	0.000859	0.000707	0.000824
2007-Jun-21	125	32083	3	1000	100000	10000	50000	20000	0.001503	0.000397	0.000477	0.000350
2007-Jun-21	125	32697	3	1000	100000	10000	50000	20000	0.002523	0.000757	0.000667	0.000716
2007-Jun-21	127	32105	1	1000	100000	10000	50000	20000	0.001947	0.000315	0.000974	0.000223
2007-Jun-21	127	32114	1	1000	100000	10000	50000	20000	0.002299	0.000442	0.001179	0.000350
2007-Jun-21	127	32115	1	1000	100000	10000	50000	20000	0.002984	0.000708	0.001395	0.000612
2007-Jun-21	127	32116	1	1000	100000	10000	50000	20000	0.003393	0.000844	0.001572	0.000745
2007-Jun-21	127	32117	1	1000	100000	10000	50000	20000	0.002496	0.000508	0.001269	0.000416
2007-Jun-21	127	32118	1	1000	100000	10000	50000	20000	0.003212	0.000773	0.001494	0.000673
2007-Jun-21	127	32119	1	1000	100000	10000	50000	20000	0.002288	0.000450	0.001169	0.000360
2007-Jun-21	127	32120	1	1000	100000	10000	50000	20000	0.002299	0.000421	0.001134	0.000330
2007-Jun-21	127	32121	1	1000	100000	10000	50000	20000	0.002919	0.000651	0.001386	0.000557
2007-Jun-21	127	32122	1	1000	100000	10000	50000	20000	0.002254	0.000405	0.001115	0.000314
2007-Jun-21	127	32123	1	1000	100000	10000	50000	20000	0.002403	0.000433	0.001192	0.000338
2007-Jun-21	127	32124	1	1000	100000	10000	50000	20000	0.002123	0.000381	0.001089	0.000288
2007-Jun-21	127	32125	1	1000	100000	10000	50000	20000	0.003055	0.000726	0.001431	0.000630

2007-Jun-21	127	32126	1	1000	100000	10000	50000	20000	0.003334	0.000880	0.001517	0.000781
2007-Jun-21	127	32127	1	1000	100000	10000	50000	20000	0.002454	0.000485	0.001245	0.000392
2007-Jun-21	127	32128	1	1000	100000	10000	50000	20000	0.002207	0.000380	0.001094	0.000286
2007-Jun-21	127	32129	1	1000	100000	10000	50000	20000	0.002451	0.000453	0.001208	0.000359
2007-Jun-21	127	32130	1	1000	100000	10000	50000	20000	0.001721	0.000278	0.000860	0.000191
2007-Jun-21	127	32132	1	1000	100000	10000	50000	20000	0.003018	0.000742	0.001383	0.000636
2007-Jun-21	127	32141	1	1000	100000	10000	50000	20000	0.002390	0.000461	0.001214	0.000366
2007-Jun-21	127	32168	1	1000	100000	10000	50000	20000	0.001956	0.000347	0.000967	0.000262
2007-Jun-21	127	32169	1	1000	100000	10000	50000	20000	0.002864	0.000653	0.001408	0.000556
2007-Jun-21	127	32170	1	1000	100000	10000	50000	20000	0.002995	0.000666	0.001424	0.000570
2007-Jun-21	127	32173	1	1000	100000	10000	50000	20000	0.002242	0.000395	0.001113	0.000304
2007-Jun-21	127	32174	1	1000	100000	10000	50000	20000	0.002704	0.000526	0.001326	0.000432
2007-Jun-21	127	32175	1	1000	100000	10000	50000	20000	0.002187	0.000373	0.001084	0.000280
2007-Jun-21	127	32176	1	1000	100000	10000	50000	20000	0.002602	0.000552	0.001313	0.000461
2007-Jun-21	127	32180	1	1000	100000	10000	50000	20000	0.002027	0.000331	0.001014	0.000236
2007-Jun-21	127	32190	1	1000	100000	10000	50000	20000	0.001711	0.000275	0.000860	0.000189
2007-Jun-21	127	32198	1	1000	100000	10000	50000	20000	0.002415	0.000452	0.001192	0.000360
2007-Jun-21	127	32706	1	1000	100000	10000	50000	20000	0.002281	0.000379	0.001131	0.000279
2007-Jun-21	127	32713	1	1000	100000	10000	50000	20000	0.002411	0.000391	0.001195	0.000285
2007-Jun-21	127	32720	1	1000	100000	10000	50000	20000	0.002328	0.000381	0.001155	0.000277
2007-Jun-21	127	32721	1	1000	100000	10000	50000	20000	0.002219	0.000368	0.001100	0.000268
2007-Jun-21	127	32722	1	1000	100000	10000	50000	20000	0.002219	0.000368	0.001100	0.000268
2007-Jun-21	127	32723	1	1000	100000	10000	50000	20000	0.002352	0.000398	0.001163	0.000297
2007-Jun-21	127	32724	1	1000	100000	10000	50000	20000	0.002250	0.000376	0.001116	0.000277
2007-Jun-21	127	32725	1	1000	100000	10000	50000	20000	0.002336	0.000379	0.001158	0.000275
2007-Jun-21	127	32728	1	1000	100000	10000	50000	20000	0.002334	0.000383	0.001156	0.000280
2007-Jun-21	127	32738	1	1000	100000	10000	50000	20000	0.002459	0.000417	0.001214	0.000313
2007-Jun-21	127	32739	1	1000	100000	10000	50000	20000	0.002274	0.000367	0.001124	0.000264
2007-Jun-21	127	32744	1	1000	100000	10000	50000	20000	0.002174	0.000352	0.001078	0.000252
2007-Jun-21	127	32753	1	1000	100000	10000	50000	20000	0.002414	0.000389	0.001196	0.000283
2007-Jun-21	127	32759	1	1000	100000	10000	50000	20000	0.001954	0.000351	0.001001	0.000260
2007-Jun-21	127	32763	1	1000	100000	10000	50000	20000	0.002296	0.000383	0.001139	0.000283
2007-Jun-21	127	32764	1	1000	100000	10000	50000	20000	0.002201	0.000366	0.001086	0.000267
2007-Jun-21	127	32774	1	1000	100000	10000	50000	20000	0.002243	0.000368	0.001113	0.000267
2007-Jun-21	127	32105	2	1000	100000	10000	50000	20000	0.001648	0.000286	0.000971	0.000194
2007-Jun-21	127	32114	2	1000	100000	10000	50000	20000	0.001923	0.000377	0.001176	0.000286
2007-Jun-21	127	32115	2	1000	100000	10000	50000	20000	0.002443	0.000560	0.001391	0.000474

2007-Jun-21	127	32116	2	1000	100000	10000	50000	20000	0.002761	0.000658	0.001568	0.000571
2007-Jun-21	127	32117	2	1000	100000	10000	50000	20000	0.002076	0.000424	0.001265	0.000334
2007-Jun-21	127	32118	2	1000	100000	10000	50000	20000	0.002625	0.000609	0.001490	0.000519
2007-Jun-21	127	32119	2	1000	100000	10000	50000	20000	0.001911	0.000381	0.001166	0.000293
2007-Jun-21	127	32120	2	1000	100000	10000	50000	20000	0.001920	0.000362	0.001131	0.000272
2007-Jun-21	127	32121	2	1000	100000	10000	50000	20000	0.002399	0.000524	0.001382	0.000436
2007-Jun-21	127	32122	2	1000	100000	10000	50000	20000	0.001886	0.000351	0.001113	0.000260
2007-Jun-21	127	32123	2	1000	100000	10000	50000	20000	0.002009	0.000374	0.001189	0.000279
2007-Jun-21	127	32124	2	1000	100000	10000	50000	20000	0.001791	0.000334	0.001086	0.000242
2007-Jun-21	127	32125	2	1000	100000	10000	50000	20000	0.002498	0.000574	0.001428	0.000487
2007-Jun-21	127	32126	2	1000	100000	10000	50000	20000	0.002704	0.000677	0.001513	0.000594
2007-Jun-21	127	32127	2	1000	100000	10000	50000	20000	0.002046	0.000409	0.001242	0.000318
2007-Jun-21	127	32128	2	1000	100000	10000	50000	20000	0.001854	0.000335	0.001091	0.000241
2007-Jun-21	127	32129	2	1000	100000	10000	50000	20000	0.002044	0.000387	0.001205	0.000294
2007-Jun-21	127	32130	2	1000	100000	10000	50000	20000	0.001460	0.000254	0.000858	0.000169
2007-Jun-21	127	32132	2	1000	100000	10000	50000	20000	0.002474	0.000585	0.001380	0.000492
2007-Jun-21	127	32141	2	1000	100000	10000	50000	20000	0.002000	0.000393	0.001211	0.000299
2007-Jun-21	127	32168	2	1000	100000	10000	50000	20000	0.001642	0.000304	0.000964	0.000220
2007-Jun-21	127	32169	2	1000	100000	10000	50000	20000	0.002359	0.000525	0.001404	0.000435
2007-Jun-21	127	32170	2	1000	100000	10000	50000	20000	0.002461	0.000536	0.001420	0.000446
2007-Jun-21	127	32173	2	1000	100000	10000	50000	20000	0.001878	0.000344	0.001110	0.000253
2007-Jun-21	127	32174	2	1000	100000	10000	50000	20000	0.002242	0.000440	0.001323	0.000347
2007-Jun-21	127	32175	2	1000	100000	10000	50000	20000	0.001838	0.000330	0.001082	0.000236
2007-Jun-21	127	32176	2	1000	100000	10000	50000	20000	0.002154	0.000454	0.001310	0.000366
2007-Jun-21	127	32180	2	1000	100000	10000	50000	20000	0.001713	0.000299	0.001012	0.000205
2007-Jun-21	127	32190	2	1000	100000	10000	50000	20000	0.001452	0.000252	0.000858	0.000166
2007-Jun-21	127	32198	2	1000	100000	10000	50000	20000	0.002012	0.000385	0.001189	0.000294
2007-Jun-21	127	32706	2	1000	100000	10000	50000	20000	0.001923	0.000339	0.001128	0.000238
2007-Jun-21	127	32713	2	1000	100000	10000	50000	20000	0.002035	0.000351	0.001192	0.000245
2007-Jun-21	127	32720	2	1000	100000	10000	50000	20000	0.001965	0.000341	0.001152	0.000238
2007-Jun-21	127	32721	2	1000	100000	10000	50000	20000	0.001872	0.000329	0.001098	0.000230
2007-Jun-21	127	32722	2	1000	100000	10000	50000	20000	0.001872	0.000329	0.001098	0.000230
2007-Jun-21	127	32723	2	1000	100000	10000	50000	20000	0.001979	0.000353	0.001160	0.000251
2007-Jun-21	127	32724	2	1000	100000	10000	50000	20000	0.001896	0.000335	0.001113	0.000236
2007-Jun-21	127	32725	2	1000	100000	10000	50000	20000	0.001973	0.000341	0.001155	0.000236
2007-Jun-21	127	32728	2	1000	100000	10000	50000	20000	0.001970	0.000344	0.001153	0.000240
2007-Jun-21	127	32738	2	1000	100000	10000	50000	20000	0.002067	0.000368	0.001211	0.000264

2007-Jun-21	127	32739	2	1000	100000	10000	50000	20000	0.001923	0.000332	0.001121	0.000228
2007-Jun-21	127	32744	2	1000	100000	10000	50000	20000	0.001839	0.000318	0.001076	0.000218
2007-Jun-21	127	32753	2	1000	100000	10000	50000	20000	0.002039	0.000350	0.001193	0.000243
2007-Jun-21	127	32759	2	1000	100000	10000	50000	20000	0.001652	0.000310	0.000998	0.000221
2007-Jun-21	127	32763	2	1000	100000	10000	50000	20000	0.001935	0.000341	0.001136	0.000241
2007-Jun-21	127	32764	2	1000	100000	10000	50000	20000	0.001857	0.000327	0.001083	0.000229
2007-Jun-21	127	32774	2	1000	100000	10000	50000	20000	0.001894	0.000331	0.001110	0.000229
2007-Jun-21	127	32105	3	1000	100000	10000	50000	20000	0.007415	0.002017	0.000988	0.002081
2007-Jun-21	127	32114	3	1000	100000	10000	50000	20000	0.010062	0.003431	0.001197	0.003561
2007-Jun-21	127	32115	3	1000	100000	10000	50000	20000	0.013196	0.005346	0.001414	0.005503
2007-Jun-21	127	32116	3	1000	100000	10000	50000	20000	0.015456	0.006573	0.001594	0.006771
2007-Jun-21	127	32117	3	1000	100000	10000	50000	20000	0.011220	0.004065	0.001287	0.004218
2007-Jun-21	127	32118	3	1000	100000	10000	50000	20000	0.014339	0.005899	0.001515	0.006080
2007-Jun-21	127	32119	3	1000	100000	10000	50000	20000	0.010051	0.003484	0.001186	0.003611
2007-Jun-21	127	32120	3	1000	100000	10000	50000	20000	0.009542	0.003170	0.001151	0.003287
2007-Jun-21	127	32121	3	1000	100000	10000	50000	20000	0.012901	0.005075	0.001405	0.005238
2007-Jun-21	127	32122	3	1000	100000	10000	50000	20000	0.009293	0.003030	0.001132	0.003142
2007-Jun-21	127	32123	3	1000	100000	10000	50000	20000	0.010058	0.003341	0.001209	0.003475
2007-Jun-21	127	32124	3	1000	100000	10000	50000	20000	0.008860	0.002741	0.001105	0.002843
2007-Jun-21	127	32125	3	1000	100000	10000	50000	20000	0.013650	0.005587	0.001451	0.005753
2007-Jun-21	127	32126	3	1000	100000	10000	50000	20000	0.015052	0.006543	0.001538	0.006707
2007-Jun-21	127	32127	3	1000	100000	10000	50000	20000	0.010862	0.003826	0.001264	0.003969
2007-Jun-21	127	32128	3	1000	100000	10000	50000	20000	0.008863	0.002728	0.001110	0.002828
2007-Jun-21	127	32129	3	1000	100000	10000	50000	20000	0.010314	0.003500	0.001225	0.003637
2007-Jun-21	127	32130	3	1000	100000	10000	50000	20000	0.006342	0.001623	0.000873	0.001658
2007-Jun-21	127	32132	3	1000	100000	10000	50000	20000	0.012910	0.005160	0.001403	0.005292
2007-Jun-21	127	32141	3	1000	100000	10000	50000	20000	0.010362	0.003514	0.001232	0.003644
2007-Jun-21	127	32168	3	1000	100000	10000	50000	20000	0.007755	0.002384	0.000981	0.002452
2007-Jun-21	127	32169	3	1000	100000	10000	50000	20000	0.013071	0.005112	0.001428	0.005282
2007-Jun-21	127	32170	3	1000	100000	10000	50000	20000	0.013278	0.005226	0.001444	0.005402
2007-Jun-21	127	32173	3	1000	100000	10000	50000	20000	0.009226	0.002967	0.001129	0.003085
2007-Jun-21	127	32174	3	1000	100000	10000	50000	20000	0.011810	0.004295	0.001345	0.004468
2007-Jun-21	127	32175	3	1000	100000	10000	50000	20000	0.008768	0.002678	0.001100	0.002782
2007-Jun-21	127	32176	3	1000	100000	10000	50000	20000	0.011927	0.004507	0.001333	0.004673
2007-Jun-21	127	32180	3	1000	100000	10000	50000	20000	0.007817	0.002182	0.001029	0.002257
2007-Jun-21	127	32190	3	1000	100000	10000	50000	20000	0.006356	0.001634	0.000873	0.001676
2007-Jun-21	127	32198	3	1000	100000	10000	50000	20000	0.010226	0.003516	0.001210	0.003649

2007-Jun-21	127	32706	3	1000	100000	10000	50000	20000	0.008964	0.002623	0.001147	0.002720
2007-Jun-21	127	32713	3	1000	100000	10000	50000	20000	0.009492	0.002747	0.001213	0.002864
2007-Jun-21	127	32720	3	1000	100000	10000	50000	20000	0.009139	0.002639	0.001172	0.002747
2007-Jun-21	127	32721	3	1000	100000	10000	50000	20000	0.008672	0.002511	0.001117	0.002600
2007-Jun-21	127	32722	3	1000	100000	10000	50000	20000	0.008672	0.002511	0.001117	0.002600
2007-Jun-21	127	32723	3	1000	100000	10000	50000	20000	0.009355	0.002816	0.001180	0.002923
2007-Jun-21	127	32724	3	1000	100000	10000	50000	20000	0.008874	0.002620	0.001132	0.002716
2007-Jun-21	127	32725	3	1000	100000	10000	50000	20000	0.009114	0.002600	0.001175	0.002704
2007-Jun-21	127	32728	3	1000	100000	10000	50000	20000	0.009121	0.002626	0.001173	0.002729
2007-Jun-21	127	32738	3	1000	100000	10000	50000	20000	0.009856	0.003008	0.001232	0.003127
2007-Jun-21	127	32739	3	1000	100000	10000	50000	20000	0.008767	0.002453	0.001140	0.002545
2007-Jun-21	127	32744	3	1000	100000	10000	50000	20000	0.008350	0.002315	0.001094	0.002399
2007-Jun-21	127	32753	3	1000	100000	10000	50000	20000	0.009498	0.002739	0.001214	0.002858
2007-Jun-21	127	32759	3	1000	100000	10000	50000	20000	0.007894	0.002329	0.001016	0.002393
2007-Jun-21	127	32763	3	1000	100000	10000	50000	20000	0.009093	0.002697	0.001156	0.002801
2007-Jun-21	127	32764	3	1000	100000	10000	50000	20000	0.008514	0.002439	0.001102	0.002519
2007-Jun-21	127	32774	3	1000	100000	10000	50000	20000	0.008717	0.002486	0.001129	0.002577
2007-Jun-21	129	32326	1	1000	100000	10000	50000	20000	0.000305	0.000180	0.000612	0.000138
2007-Jun-21	129	32327	1	1000	100000	10000	50000	20000	0.000248	0.000152	0.000521	0.000114
2007-Jun-21	129	32346	1	1000	100000	10000	50000	20000	0.000775	0.000402	0.001065	0.000364
2007-Jun-21	129	32355	1	1000	100000	10000	50000	20000	0.000499	0.000267	0.000821	0.000227
2007-Jun-21	129	32358	1	1000	100000	10000	50000	20000	0.000348	0.000201	0.000656	0.000159
2007-Jun-21	129	32326	2	1000	100000	10000	50000	20000	0.000271	0.000174	0.000611	0.000134
2007-Jun-21	129	32327	2	1000	100000	10000	50000	20000	0.000222	0.000148	0.000521	0.000111
2007-Jun-21	129	32346	2	1000	100000	10000	50000	20000	0.000671	0.000367	0.001063	0.000333
2007-Jun-21	129	32355	2	1000	100000	10000	50000	20000	0.000437	0.000251	0.000819	0.000213
2007-Jun-21	129	32358	2	1000	100000	10000	50000	20000	0.000308	0.000193	0.000655	0.000152
2007-Jun-21	129	32326	3	1000	100000	10000	50000	20000	0.002583	0.000844	0.000627	0.000816
2007-Jun-21	129	32327	3	1000	100000	10000	50000	20000	0.002056	0.000641	0.000534	0.000610
2007-Jun-21	129	32346	3	1000	100000	10000	50000	20000	0.006230	0.002673	0.001092	0.002665
2007-Jun-21	129	32355	3	1000	100000	10000	50000	20000	0.004255	0.001632	0.000843	0.001624
2007-Jun-21	129	32358	3	1000	100000	10000	50000	20000	0.002913	0.001016	0.000672	0.000989
2007-Jun-21	131	32422	1	1000	100000	10000	50000	20000	0.000598	0.000317	0.001028	0.000268
2007-Jun-21	131	32433	1	1000	100000	10000	50000	20000	0.000679	0.000353	0.001090	0.000308
2007-Jun-21	131	32434	1	1000	100000	10000	50000	20000	0.000749	0.000386	0.001155	0.000342
2007-Jun-21	131	32435	1	1000	100000	10000	50000	20000	0.000821	0.000421	0.001200	0.000380
2007-Jun-21	131	32439	1	1000	100000	10000	50000	20000	0.000532	0.000300	0.000964	0.000251

2007-Jun-21	131	32454	1	1000	100000	10000	50000	20000	0.001067	0.000542	0.001383	0.000505
2007-Jun-21	131	32459	1	1000	100000	10000	50000	20000	0.000972	0.000508	0.001376	0.000469
2007-Jun-21	131	32461	1	1000	100000	10000	50000	20000	0.002685	0.001428	0.002112	0.001420
2007-Jun-21	131	32538	1	1000	100000	10000	50000	20000	0.000542	0.000287	0.000975	0.000238
2007-Jun-21	131	32550	1	1000	100000	10000	50000	20000	0.002115	0.001057	0.002015	0.001056
2007-Jun-21	131	32422	2	1000	100000	10000	50000	20000	0.000524	0.000301	0.001026	0.000253
2007-Jun-21	131	32433	2	1000	100000	10000	50000	20000	0.000593	0.000332	0.001088	0.000289
2007-Jun-21	131	32434	2	1000	100000	10000	50000	20000	0.000652	0.000361	0.001153	0.000319
2007-Jun-21	131	32435	2	1000	100000	10000	50000	20000	0.000713	0.000390	0.001198	0.000352
2007-Jun-21	131	32439	2	1000	100000	10000	50000	20000	0.000467	0.000285	0.000962	0.000237
2007-Jun-21	131	32454	2	1000	100000	10000	50000	20000	0.000922	0.000493	0.001380	0.000462
2007-Jun-21	131	32459	2	1000	100000	10000	50000	20000	0.000839	0.000466	0.001373	0.000429
2007-Jun-21	131	32461	2	1000	100000	10000	50000	20000	0.002264	0.001186	0.002107	0.001211
2007-Jun-21	131	32538	2	1000	100000	10000	50000	20000	0.000477	0.000274	0.000973	0.000226
2007-Jun-21	131	32550	2	1000	100000	10000	50000	20000	0.001803	0.000923	0.002010	0.000936
2007-Jun-21	131	32422	3	1000	100000	10000	50000	20000	0.005266	0.001970	0.001055	0.001983
2007-Jun-21	131	32433	3	1000	100000	10000	50000	20000	0.005914	0.002332	0.001119	0.002352
2007-Jun-21	131	32434	3	1000	100000	10000	50000	20000	0.006438	0.002604	0.001186	0.002628
2007-Jun-21	131	32435	3	1000	100000	10000	50000	20000	0.006871	0.002862	0.001232	0.002884
2007-Jun-21	131	32439	3	1000	100000	10000	50000	20000	0.004765	0.001775	0.000989	0.001771
2007-Jun-21	131	32454	3	1000	100000	10000	50000	20000	0.008427	0.003704	0.001418	0.003725
2007-Jun-21	131	32459	3	1000	100000	10000	50000	20000	0.008188	0.003500	0.001413	0.003527
2007-Jun-21	131	32461	3	1000	100000	10000	50000	20000	0.016316	0.008467	0.002161	0.008460
2007-Jun-21	131	32538	3	1000	100000	10000	50000	20000	0.004967	0.001800	0.001002	0.001823
2007-Jun-21	131	32550	3	1000	100000	10000	50000	20000	0.014794	0.007373	0.002063	0.007408
2007-Jun-21	133	32427	1	1000	100000	10000	50000	20000	0.000470	0.000263	0.000881	0.000212
2007-Jun-21	133	32428	1	1000	100000	10000	50000	20000	0.000677	0.000355	0.001102	0.000307
2007-Jun-21	133	32437	1	1000	100000	10000	50000	20000	0.001033	0.000541	0.001398	0.000502
2007-Jun-21	133	32462	1	1000	100000	10000	50000	20000	0.000409	0.000237	0.000803	0.000187
2007-Jun-21	133	32463	1	1000	100000	10000	50000	20000	0.000524	0.000288	0.000958	0.000236
2007-Jun-21	133	32427	2	1000	100000	10000	50000	20000	0.000416	0.000252	0.000880	0.000203
2007-Jun-21	133	32428	2	1000	100000	10000	50000	20000	0.000592	0.000334	0.001100	0.000288
2007-Jun-21	133	32437	2	1000	100000	10000	50000	20000	0.000888	0.000492	0.001395	0.000457
2007-Jun-21	133	32462	2	1000	100000	10000	50000	20000	0.000364	0.000229	0.000802	0.000180
2007-Jun-21	133	32463	2	1000	100000	10000	50000	20000	0.000463	0.000275	0.000957	0.000225
2007-Jun-21	133	32427	3	1000	100000	10000	50000	20000	0.004103	0.001437	0.000904	0.001427
2007-Jun-21	133	32428	3	1000	100000	10000	50000	20000	0.005842	0.002262	0.001131	0.002276

2007-Jun-21	133	32437	3	1000	100000	10000	50000	20000	0.008412	0.003622	0.001435	0.003649
2007-Jun-21	133	32462	3	1000	100000	10000	50000	20000	0.003506	0.001173	0.000824	0.001150
2007-Jun-21	133	32463	3	1000	100000	10000	50000	20000	0.004578	0.001629	0.000984	0.001624